

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

06/02/2018 10:47

JOB-NO: 85008104

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD CONTACT: 0
 ADDRESS: 50 UBI AVENUE 3 0
 #01-12 NIL
 SINGAPORE 408866

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SLE3694J TRANS: AUTO
 MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)
 OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.
 JOB-CODE: TP SA: Ding Auto User 1

CHASSIS: MR053REH104555029
 ENGINE: 1ZR587193

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	1.00	2,200.00	0.00	2,200.00		Y	500
2 R&R REAR WINDSCREEN	1.00	150.00	0.00	150.00		Y	X
3 R&R REAR SUSPENSION AND AXLE	1.00	250.00	0.00	250.00		Y	X
4 R&R REAR RIM AND TYRE INCLUDING BALANCING	1.00	100.00	0.00	100.00		Y	30
5 R&R REAR WHEEL ALIGNMENT	1.00	150.00	0.00	150.00		Y	80
6 CHECK WIRING	1.00	80.00	0.00	80.00		Y	20
7 RUSH PROOFING	1.00	80.00	0.00	80.00		Y	30
8 TOWING WITH DOLLY WHEEL	1.00	150.00	0.00	150.00		Y	X
9 SPRAY REAR BUMPER, REAR FENDER, REAR DOOR RHS	1.00	800.00	0.00	800.00		Y	600
10 R&R REAR FENDER TRIM, TYRE BOARD	1.00	80.00	0.00	80.00		Y	X
TOTAL:		4,040.00	0.00	4,040.00			
MATERIALS							
1 REAR BUMPER	1.00	485.55	0.00	485.55	L	Y	ok
2 REAR BUMPER SIDE RETAINER LONG RHS	1.00	104.40	0.00	104.40	L	Y	re
3 REAR BUMPER SIDE RETAINER SHORT RHS	1.00	79.20	0.00	79.20	L	Y	7
4 REAR FENDER RHS	1.00	1,084.90	0.00	1,084.90	L	Y	Rp
5 REAR FENDER INNERSHIELD RHS	1.00	67.75	0.00	67.75	L	Y	10
6 REAR RIM RHS * check price	1.00	1,644.45	0.00	1,644.45	L	Y	out
7 REAR ABSORBER RHS	1.00	285.85	0.00	285.85	L	Y	X
8 REAR DOOR RHS	1.00	1,198.50	0.00	1,198.50	L	Y	Rp
9 REAR AXLE	1.00	2,355.85	0.00	2,355.85	L	Y	X
10 REAR TYRE RHS	1.00	180.00	0.00	180.00	S	Y	X
11 REAR WINDSCREEN DAMPER	1.00	50.00	0.00	50.00	S	Y	X
12 REAR WINDSCREEN SEALANT	1.00	50.00	0.00	50.00	S	Y	X
TOTAL:		7,586.45	0.00	7,586.45			
TOTAL PARTS & LABOUR :		11,626.45	0.00	11,626.45			

EXCESS/LOADING:\$ 0.00

No. Of Day: 4

RE-SURVEY: BEFORE/AFTER PAINTING
 PART-BY-PART OR LUMP SUM: \$ 0

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

DATE OF SURVEY: 8/2/18 *Lumpsum Resurvey after repair*
SURVEYED BY: Tanpin *sur@khants.com*
CONTACT NO: 9749574 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX: