

REF:

003 / 17418007624 / A16/

ASSIGNMENT

From:

Date:

Estimated Cost:

OO / TP / WS / TP RES / OO RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

1001K.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14 8/5

days

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLH1091X Yr Regn: 2016 Oct

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3

cc 1385

Colour:

Silver.

A/C: Insured / Std / NI / NA

Sp. Reading:

39457.

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WPAU2228V261109935.

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size:

F: 205/55R16.

R: 205/55R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

01/02/18

Survey held at

Premium.

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

DDALG.

SLH 1091X - X

09/2/18 @ 12:06pm revert to Under via Menden.

9/2/18 @ 15:04pm authorise repair excess \$600/-

12/2/18 @ 9:50am inform premium authorise repair excess \$600/-

Partby Part \$23,487.60 (Red: 3899.40 27%)

RECEIVED 04 MAY 2018

Date/Time, File Pass to?

1) 415 Typist

Date/Time, File Return to?

2)



Prel. Report



Final Report

Days Of Repair:

14

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) S + RS \$

) Photo

) Other

Add Fee:



Site Insp \$



Interview \$



Tech. Invs \$



Weekend \$

Report Format:

00

Lump Sum / I.B.I: (\$ 23487.60

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18002624/Atb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 08-02-2018



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLH 1091X
Policy No. 2100487444-01	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	07/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/01/2018	Inspection Date	07/02/2018
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 09 Feb 2018

Preliminary Advice

Vehicle No	: SLH1091X	Accident Date	: 31/01/2018
Make	: AUDI A3	Policy No.	: 2100487444-01
Assignment Date	: 08/02/2018	Excess	: S\$0.00
Date of Inspection	: 07/02/2018	Est. Duration of Repair	: 14.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,587.00
Revised Amount	:S\$	17,337.00
Check Items (Estimated)	:S\$	531.00
Total	:S\$	17,868.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	108,000.00
COE / PARF Rebate	:S\$	57,219.00
Salvage Value	:S\$	
Margin for Repair	:S\$	50,781.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 12 February 2018 9:50 AM
To: Shiau Chan (LKKAuto); Claims; SUR
Subject: RE: SLH 1091 X Own Damage Claims

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLH 1091X (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Friday, 9 February 2018 1:19 PM
To: Claims <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SLH 1091 X Own Damage Claims

Dear Tony,

Please be informed that we are pending for insurance's approval. Once approve, we will send you an email.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Friday, 9 February 2018 12:41 PM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: SLH 1091 X Own Damage Claims

Dear all,

Any update for this case?

View Received Message

This mail is associated with :

*SLH1091X (69120787625G)
OO
Jan 31 2018 12:30PM
[LIM TECK CHYE, VINCENT]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 09/02/2018 15:04 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$17337.00) - SLH1091X - Claim Handler: Loo, Tong Shing

Approved:17337.00:Re-Inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5957B
Vehicle Details	
Vehicle No.:	SLH1091X
Vehicle to be Exported:	No
Intended De-registration Date:	09 Feb 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.4 TFSI (ATTRACTION)
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	CZC572502
Chassis No.:	WAUZZZ8V2G1109935
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$25,069.00
Original Registration Date:	25 Oct 2016
First Registration Date:	25 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$17,097.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Oct 2026
PARF Rebate Amount:	\$12,822.00
Intended COE Rebate Details	
COE Expiry Date:	24 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,991.00
COE Rebate Amount:	\$44,397.00
Total Rebate Amount:	\$57,219.00

The information contained herein is correct as at 09 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/01/2018 19:01
Date Of Accident	31/01/2018 12:30
Exact Location Of Accident	CIVIC CENTRE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH1091X
Insured/Policyholder	
Name Of Registered Owner	LIM TECK CHYE, VINCENT
NRIC No	S7935957B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93864473
Alternative Phone No	OTHERS-93864473

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.4 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100487444-01
Cover Note Number	

Driver

Name of Driver	LIM TECK CHYE, VINCENT
NRIC No	S7935957B
Date Of Birth	14/11/1979
Occupation	INDOOR
Date Of Driving Pass	09/11/2001
Driving Experience	16 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93864473
Fax Number	
Contact Number	OTHERS-93864473
Email Address	NOEMAIL

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

20/3/2018

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name: Tony Fong
NIC/FIN No: 67040475




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S7935957B**
 Name: **LIM TECK CHYE, VINCENT**
 (LIN DECAI, VINCENT)

Birth Date: **14 Nov 1979**
 Issue Date: **25 Oct 2003**



000949349J

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7935957B



Name

LIM TECK CHYE, VINCENT
(LIN DECAI, VINCENT)

林 德 村

Race

CHINESE

Date of birth

14-11-1979

Sex

M

S7935957B

Country of birth

SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: **09 Nov 2001**

NP 428A

Licence No: **S7935957B**



4498334



NRIC No: **S7935957B**



Date of Issue: **15-12-2009**

AFT BLK 384 BUKIT BATOK WEST AVENUE 5 #26-320
SINGAPORE 650384

Date: **15-12-2009**

No: **7332441**



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LIM TECK CHYE,VINCENT(LIN DECAI,VINCENT)
Period of Insurance : 25 Oct 2017 To 24 Oct 2018
Engine No. : CZC572502
Chassis No. : WAUZZZ8V2G1109935

Vehicle No. : SLH1091X
Policy No. : 2100487444-01
Endorsement No. :
Issued Date : 26 Sep 2017

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.4 TFSI (Attraction)
Engine Capacity/Tonnage : 1,395.00 CC Sum Insured : Market Value First Year of Registration : 2016
Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 35 years old and above.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LIM TECK CHYE,VINCENT(LIN DECAI,VINCENT) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1.Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63962323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), and Motor Vehicles (Third Party Risks) Rules, 1956 (Malaysia).

0594125300

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

0594125300

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no-one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Vins/Summons/Correspondence from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 3 working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Premium Automobiles Pte. Ltd.

Activation Hotline: 64741223

55 Ubi Road 1 Singapore 408699

Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 1pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.)

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0148/2018/CCS
Date	:	2-Feb-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Lim Teck Chye, Vincent
Address	:	Blk 384 Bukit Batok West Avenue 5 #26-320 Singapore 650384
Telephone	:	HP +65 93864473
Type of Claim	:	Own Damage Claims
Policy No.	:	2100487444-01
Vehicle No	:	SLH 1091 X
Model Code	:	Audi A3 SEDAN 1.4 TFSI
Model / Year	:	Oct-16
Engine No	:	CZC 572502
Chassis No	:	WAUZZZ8V2G1109935
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	31-Jan-18
Place of Accident	:	Civic Centre Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLH 1091 X.

S/n	Nature of Jobs	Estimated Charges
1	To remove and reinstall rear parking aid. Check function.	S/N \$ 280.00
2	To remove and transfer both lhs front and rear door's multi-lock system and power window devices.	S/N \$ 560.00
3	To remove and reinstall rear seats, back rest, ABCD pillar trims, roof liner, hat trays, carpets, curtain airbag and sill trims.	S/N \$ 1,400.00
4	To remove and renew lhs quarter glass and rear windscreen for fender renewal.	S/N \$ 600.00
5	To dislodge and reinstall rear wire harness for tail lights, fuse units, battery manager, fuse and relay trays, and electrical components.	S/N \$ 1,400.00
SUB-TOTAL LABOUR CHARGES		: \$ 4,240.00

415
t

0.0
0.0

4,000.00
3,500.00
280.00
192.00
1,250.00
=

2.00

0.0

1,752.00
111.20
165.60
114.00
20.32
1,750.00
111.20
1,604.80
401.20
563.20
29.12
516.00
100.00
200.00
180.00
140.00
180.00
280.00
174.56
1,630.40
=

10,023.60

0.0

10,025.60
9,002.00
560.00
280.00
1,400.00
600.00
1,400.00
=

23,487.60

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLH 1091 X.

S/n	Nature of Jobs	Estimate Charges
6	To dismantle lhs front and rear doors, rear bumper and rear lid. Cut out and weld lhs rear fender. Renew lhs front and rear doors, and rear bumper. Align to position. Reinstall all parts removed.	\$ 6,300.00
7	To respray lhs front and rear doors, door handles, lhs rear fender, lhs sill panel, door entrance, roof channel, drain panel, end panelling and rear bumper. To carry out joint sealer works and stone chip treatment.	\$ 6,000.00
8	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.0
9	To carry out diagnostic checks.	S/N \$ 192.0
TOTAL LABOUR CHARGES		: \$ 17,012.0

119/2
a

2,198.00
139.00
207.00
26.00
2,190.00
139.00
2,006.00
502.00
704.00
37.00
645.00
100.00
200.00
180.00
140.00
180.00
= 9,585.00
9865
0.00
3,500.00
3,500.00
280.00
192.00
= 7,472.00
0.00
9865
9,585.00
7,472.00
= 17,057.00
17337
0.00
43.00
43.00
45.00
400.00
= 531.00

Ch

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLH 1091 X.**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR - LH <i>Dented</i>	S 2,190.00	✓ 1752
2	FRONT DOOR SEAL - LH <i>new</i>	S 139.00	✓ 111.20
3	BONDING AGENT <i>Not New</i>	S 43.00	? X
4	FRONT DOOR CATCH - LH <i>new</i>	S 92.00	+ X
5	FRONT DOOR HANDLE - LH <i>cut</i>	S 207.00	✓ 16560
6	FRONT DOOR HANDLE MOUNTING BAR - LH <i>Damaged.</i>	S 143.00	+ 114
7	FRONT DOOR HANDLE CAP - LH <i>cut</i>	S 26.00	✓ 2032
8	FRONT WINDOW REGULATOR - LH <i>new</i>	S 232.00	X
9	REAR DOOR - LH <i>Dented</i>	S 2,190.00	✓ 1752
10	REAR DOOR SEAL - LH <i>new</i>	S 139.00	✓ 111.20
11	BONDING AGENT <i>Not New</i>	S 43.00	? X
12	REAR DOOR CATCH - LH <i>new</i>	S 82.00	X
13	REAR DOOR HANDLE - LH <i>Pyro</i>	S 207.00	+ X
14	REAR DOOR SLIDE VALVE - LH <i>new</i>	S 11.00	+ X
15	REAR DOOR HANDLE CAP - LH <i>new</i>	S 26.00	+ X
16	REAR DOOR HANDLE MOUNTING BAR - LH <i>new</i>	S 143.00	+ X
17	REAR WINDOW REGULATOR - LH <i>new</i>	S 220.00	+ X
18	REAR WINDOW GUIDE RAIL - LH <i>Not New</i>	S 45.00	? X
19	REAR FENDER - LH <i>Dented</i>	S 2,006.00	✓ 1604 80
20	REAR 1/4 GLASS - LH <i>de</i>	S 502.00	✓ 401.20
SUB-TOTAL SPARE PARTS CHARGES		\$ 8,686.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLH 1091 X.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
21	REAR WINDSCREEN <i>Ren</i>	\$	704.00	✓ 563.20
22	GLASS PRIMER <i>ren</i>	2 \$	37.00	✓ 29.12
23	REAR BUMPER <i>Rye</i>	\$	1,619.00	+
24	REAR BUMPER GUIDE - LH <i>ren</i>	\$	57.00	+
25	REAR WHEEL HOUSING LINER - LH <i>ren</i>	\$	215.00	+
26	WHEEL HOUSING LINER ATTACHMENT PARTS <i>ren</i>	\$	77.00	+
27	REAR SEAT GROMMET SET <i>ren</i>	\$	55.00	+
28	ALUMINIUM RIM - LH REAR <i>ren</i>	\$	645.00	✓ 516
29	1/4 GLASS SEALANT <i>3 ren</i>	S/N \$	100.00	✓ ✓
30	REAR WINDSCREEN SEALANT	S/N \$	200.00	✓
31	ACRYLIC SEALER <i>3 ren</i>	S/N \$	180.00	✓ ✓
32	CAVITY WAX	S/N \$	140.00	✓
33	STONE CHIP	S/N \$	180.00	✓
34	METAL FILLER POWDER <i>ren</i>	S/N \$	280.00	✓
35	SUNDRIES <i>Nec.</i>	\$	400.00	? ✓ 174.56
TOTAL SPARE PARTS CHARGES		:	\$ 13,575.00	
TOTAL LABOUR CHARGES			\$ 17,012.00	
GRAND TOTAL			<u>\$ 30,587.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ly
Surveyed Date : 07/02/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 14 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-8902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0148/2018/CCS
21-Feb-18
CHANG
1 of 1
SLH 1091 X
Audi A3 SEDAN 1.4 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	To cut and weld LHS sill panel.	\$ 1,800.00	\$ 1,250.00
TOTAL LABOURS :		\$ 1,800.00	\$ 1,250.00
Parts			
1	SILL PANEL - LH <i>Dented</i>	\$ 2,038.00	\$ 1,630.40
TOTAL PARTS :		\$ 2,038.00	\$ 1,630.40
GRAND TOTAL :		\$ 3,838.00	\$ 2,880.40

For Premium Automobiles Pte Ltd



Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0148/2018/CCS
Date : 2-Feb-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

14 days - ok - jb - 2 Apr 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lim Teck Chye, Vincent
Address : Blk 384 Bukit Batok West Avenue 5
#26-320
Singapore 650384
Telephone : HP +65 93864473
Type of Claim : Own Damage Claims
Policy No. : 2100487444-01
Vehicle No : **SLH 1091 X**
Model Code : Audi A3 SEDAN 1.4 TFSI
Model / Year : Oct-16
Engine No : CZC 572502
Chassis No : WAUZZZ8V2G1109935
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 31-Jan-18
Place of Accident : Civic Centre Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6386 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLH 1091 X.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid. Check function.	S/N \$	280.00	\$ 280.00
2	To remove and transfer both lhs front and rear door's multi-lock system and power window devices.	S/N \$	560.00	\$ 560.00
3	To remove and reinstall rear seats, back rest, ABCD pillar trims, roof liner, hat trays, carpets, curtain airbag and sill trims.	S/N \$	1,400.00	\$ 1,400.00
4	To remove and renew lhs quarter glass and rear windscreen for fender renewal.	S/N \$	600.00	\$ 600.00
5	To dislodge and reinstall rear wire harness for tail lights, fuse units, battery manager, fuse and relay trays, and electrical components.	S/N \$	1,400.00	\$ 1,400.00
SUB-TOTAL LABOUR CHARGES		:	\$ 4,240.00	\$ 4,240.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLH 1091 X.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		<i>cf</i>		\$ 4,240.00
6	To dismantle lhs front and rear doors, rear bumper and rear lid. Cut out and weld lhs rear fender. Renew lhs front and rear doors, and rear bumper. Align to position. Reinstall all parts removed.		\$ 6,300.00	\$ 4,000.00
7	To respray lhs front and rear doors, door handles, lhs rear fender, lhs sill panel, door entrance, roof channel, drain panel, end panelling and rear bumper. To carry out joint sealer works and stone chip treatment.		\$ 6,000.00	\$ 3,500.00
8	To renew lhs rear rim and carry out wheel alignment.	S/N	\$ 280.00	\$ 280.00
9	<i>Added labour charges</i>		\$ 1,800.00	\$ 1,250.00
10	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 18,812.00	\$ 13,462.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLH 1091 X.**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR - LH	\$ 2,190.00	\$ 1,752.00
2	FRONT DOOR SEAL - LH	\$ 139.00	\$ 111.20
3	BONDING AGENT	\$ 43.00	
4	FRONT DOOR CATCH - LH	\$ 92.00	
5	FRONT DOOR HANDLE - LH	\$ 207.00	\$ 165.60
6	FRONT DOOR HANDLE MOUNTING BAR - LH	\$ 143.00	\$ 114.00
7	FRONT DOOR HANDLE CAP - LH	\$ 26.00	\$ 20.32
8	FRONT WINDOW REGULATOR - LH	\$ 232.00	
9	REAR DOOR - LH	\$ 2,190.00	\$ 1,752.00
10	REAR DOOR SEAL - LH	\$ 139.00	\$ 111.20
11	BONDING AGENT	\$ 43.00	
12	REAR DOOR CATCH - LH	\$ 82.00	
13	REAR DOOR HANDLE - LH	\$ 207.00	
14	REAR DOOR SLIDE VALVE - LH	\$ 11.00	
15	REAR DOOR HANDLE CAP - LH	\$ 26.00	
16	REAR DOOR HANDLE MOUNTING BAR - LH	\$ 143.00	
17	REAR WINDOW REGULATOR - LH	\$ 220.00	
18	REAR WINDOW GUIDE RAIL - LH	\$ 45.00	
19	REAR FENDER - LH	\$ 2,006.00	\$ 1,604.80
20	REAR 1/4 GLASS - LH	\$ 502.00	\$ 401.20
SUB-TOTAL SPARE PARTS CHARGES		\$ 8,686.00	\$ 6,032.32

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLH 1091 X.**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
		<i>c/f</i>	\$ 6,032.32
21	REAR WINDSCREEN	\$ 704.00	\$ 563.20
22	GLASS PRIMER	2 \$ 37.00	\$ 29.12
23	REAR BUMPER	\$ 1,619.00	
24	REAR BUMPER GUIDE - LH	\$ 57.00	
25	REAR WHEEL HOUSING LINER - LH	\$ 215.00	
26	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 77.00	
27	REAR SEAT GROMMET SET	\$ 55.00	
28	ALUMINIUM RIM - LH REAR	\$ 645.00	\$ 516.00
29	1/4 GLASS SEALANT	S/N \$ 100.00	\$ 100.00
30	REAR WINDSCREEN SEALANT	S/N \$ 200.00	\$ 200.00
31	ACRYLIC SEALER	S/N \$ 180.00	\$ 180.00
32	CAVITY WAX	S/N \$ 140.00	\$ 140.00
33	STONE CHIP	S/N \$ 180.00	\$ 180.00
34	METAL FILLER POWDER	S/N \$ 280.00	\$ 280.00
35	<i>Added parts - see attached</i>	2038.99	\$ 1,630.40
36	SUNDRIES	\$ 400.00	\$ 174.56
	TOTAL SPARE PARTS CHARGES	\$ 13,575.00	\$ 10,025.60
	TOTAL LABOUR CHARGES	\$ 18,812.00	\$ 13,462.00
	GRAND TOTAL	\$ 32,387.00	\$ 23,487.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLH 1091 X

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0148/2018/MAS

2th May 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLH 1091 X, Audi A3 SEDAN 1.4 TFSI

With reference to the above mentioned vehicle, no. **SLH 1091 X**, claimant, **Mr. Lim Teck Chye, Vincent**, please find the related document as per attached.

1. A copy of the Original invoice no. 85012397 - \$24,489.73
2. A copy of letter of Discharge duly signed by client

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer generated document. No signature is required.

Norah Khai

Claims Dept

Encls

AXA Insurance – SLH 1091 X

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 684 11183

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S7935957B**
 Name: **LIM TECK CHYE, VINCENT**
 (LIN DECAI, VINCENT)
 Birth Date: **14 Nov 1979**
 Issue Date: **25 Oct 2003**

000949349J

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7935957B



Name: **LIM TECK CHYE, VINCENT**
 (LIN DECAI, VINCENT)
林德材
 Race: **CHINESE**
 Date of birth: **14-11-1979** Sex: **M**
 Country of birth: **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of
 which unladen does not exceed 2500 kilograms

PASS DATE

09 Nov 2001

NP 428A



Licence No: S7935957B



NRIC No: S7935957B



Date of issue
15-12-2009

APT BLK 384 BUKIT BATOK WEST AVENUE 5 #26-320
 SINGAPORE 650384
 NRIC No:

Date:

No: **7332441**



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LIM TECK CHYE, VINCENT (LIN DECAI, VINCENT)
Period of Insurance : 25 Oct 2017 To 24 Oct 2018
Engine No. : CZC572502
Chassis No. : WAUZZZ8V2G1109935

Vehicle No. : SLH1091X
Policy No. : 2100487444-01
Endorsement No. :
Issued Date : 28 Sep 2017

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.4 TFSI (Attraction)
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 35 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$500 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LIM TECK CHYE, VINCENT (LIN DECAI, VINCENT) - \$500 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

*1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1967 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938
Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SPF04A



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2223
Main Telex: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telex: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408811
Telephone: 6388 2223
Telex: 6475 1023

Customer Service
Service Appointment
24 Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6388 2223
6828 1233

Page 1 20:11

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012397 Date : 27/04/2018 Order : SLH1091X Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLH1091X (V 30766) Regn Date: 25/10/2016 Mileage: 40111 WIP No.: 54350
Model: A3 SEDAN 1.4 TFSI (ATTRACTION) Chassis: WAUZZZ8V261109935 Engine: C2C 572502 Dept: U
VSB No.:
You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR PARKING AID, CHECK FUNCTION.	280.00	1.00	280.00
Q	ETC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER BOTH LHS FRONT AND REAR DOO MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.	560.00	1.00	560.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR SEATS, BACK REST, ABC PILLAR TRIMS, ROOF LINER, HAT TRAYS, CARPETS, CURT AIRBAG AND SILL TRIMS.	1400.00	1.00	1,400.00
S	BODYWORK	M: TO REMOVE AND RENEW LHS QUARTER GLASS AND REAR WINDSCREEN FOR FENDER RENEWAL.	600.00	1.00	600.00
S	BODYWORK	M: TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TA LIGHTS, FUSE UNITS, BATTERY MANAGER, FUSE & RELAY	1400.00	1.00	1,400.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2221
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2221
Telefax: 6475 1021

Ubi Service Centre
55 Ubi Road 1
Singapore 408721
Telephone: 6388 1211
Telefax: 6388 1211

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6886 2323
9628 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 20:11

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012397 Date : 27/04/2016 Order : SLH1091X Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLH1091X (V 38766) Regn Date: 25/10/2016 Mileage: 40111 WIP No.: 54350
Model: A3 SEDAN 1.4 TFSI (ATTRACTION) Chassis: WAUZZZ8V261109935 Engine: CZC 572502 Dept: U
VSB No.:
You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	TRAYS AND ELECTRICAL COMPONENTS. M: TO DISMANTLE LHS BOTH DOORS, REAR BUMPER AND REAR LID. CUT OUT AND WELD LHS REAR FENDER. RENEW LHS BOTH DOORS AND REPAIR REAR BUMPER. ALIGN TO POSITI REINSTALL ALL PARTS REMOVED.	4000.00	1.00	4,000.00
S	BODYWORK	M: TO RESPRAY LHS BOTH DOORS, DOOR HANDLES, LHS REAR FENDER, LHS SILL PANEL, REAR BUMPER AND END PANELLING. TO CARRY OUT JOINT SEALER WORKS AND STD CHIP TREATMENT.	3500.00	1.00	3,500.00
S	BODYWORK	M: TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMEN	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECKS.	192.00	1.00	192.00
S	BODYWORK	M: TO SUPPLY 1/4 GLASS SEALANT, REAR WINDSCREEN SEALA ACRYLIC SEALANT, CAVITY WAX, STONE CHIP AND METAL	1000.00	1.00	1,000.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6475 1023

Ubi Service Centre
33 Ubi Road 1
Singapore 408723
Telephone: 6386 2223
Telefax: 6386 2223

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2223
6386 1233

Page 3 20:11

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012397 Date : 27/04/2016 Order : SLH1091X Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLH1091X (V 30766) Regn Date: 25/10/2015 Mileage: 40111 WIP No.: 54350
Model: A3 SEDAN 1.4 TFSI (ATTRACTION) Chassis: WAUZZZ8V2G1109935 Engine: CZC 572502 Dept: U
VSB No.:
You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	FILLER POWDER. M: TO CUT OUT AND WELD LHS SILL PANEL.	1250.00	1.00	1,250.00
X	ABV060102580	RIM 16" 7BP(A)	Less 020%	1.00	645.00
X	ABV5809847	SECTION(V)	Less 020%	1.00	2038.00
X	ABV5809837	SUBPART	Less 020%	1.00	2006.00
X	ABV5845297K NV8	SIDE WINDOW	Less 020%	1.00	501.50
X	ABV5833051A	DOOR	Less 020%	1.00	2190.00
X	ABV5831051B	DOOR	Less 020%	1.00	2190.00
X	ABV5845501E NV8	REARWINDOW	Less 020%	1.00	704.00
X	ABK0837199	CLIP	Less 020%	16.00	0.70
X	ABV5837911C	SEAL	Less 020%	1.00	139.00
X	ABV5839911C	SEAL	Less 020%	1.00	139.00
X	ABV0839885	SUPPORT	Less 020%	1.00	142.50
X	ABV0837167B GRU	HOUSING	Less 020%	1.00	25.40
X	ABV0837205A GRU	HANDLE	Less 020%	2.00	207.00
X	AD 00920002	PRIMER (DG)	Less 020%	2.00	18.20

Parts 8,945.60
Labour 0.00
Sublet 14,542.00
Menus 0.00
Lubricant 0.00

Sub-Total 22,887.60

7% GST 1,602.13

Grand Total 24,489.73



Received by

For & on behalf of
Premium Automobiles Pte Ltd

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Feb 2018		08 Feb 2018 19:03 Edit Adj Rpt	S\$23,487.60 Edit Estimates	S\$23,487.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LIM TECK CHYE, VINCENT. ID: S7935957B. Tel: +6593864473. Email: NOEMAIL								
Vehicle Reg. No.:	SLH1091X	Date of Loss:	31/01/2018 12:00 - :59 [15 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 6912078762SG	Policy/Cover Note No.:	2100487444-01 (Comprehensive)						
		Excess:	S\$600.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 20/02/2018]								
Driver/Custodian:	LIM TECK CHYE, VINCENT (38 / Male), NRIC: S7935957B, Tel: +6593864473								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (23/04/2018): Alert - Adj Mandate Approved (S\$23487.60) - SLH1091X - Claim Handler: Loo, Tong ... - AIG_SG (09/02/2018): Alert - Adj Mandate Approved (S\$17337.00) - SLH1091X - Claim Handler: Loo, Tong ... - AIG_SG (09/02/2018): SLH1091X / OD / 31/01/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH1091X (69120787625G)
 OD
 Jan 31 2018 12:30PM
 [LIM TECK CHYE, VINCENT]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Assessment Reports														1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print		
1	09/02/18 12:06	Adjuster Immediate Advice												Load HTM			
2	23/04/18 11:15	Adjuster Immediate Advice												Load HTM			
Photos/Images														3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print		
1	09/02/18 11:23	General View												Load JPG	☒		
2	09/02/18 11:23	Chassis Number												Load JPG	☒		
3	09/02/18 11:23	General View												Load JPG	☒		
4	09/02/18 11:23	General View												Load JPG	☒		
5	09/02/18 11:23	General View												Load JPG	☒		
6	09/02/18 11:23	General View												Load JPG	☒		
7	09/02/18 11:23	General View												Load JPG	☒		
8	09/02/18 11:23	General View												Load JPG	☒		
9	09/02/18 11:23	General View												Load JPG	☒		
10	09/02/18 11:23	General View												Load JPG	☒		
11	09/02/18 11:23	General View												Load JPG	☒		
12	09/02/18 11:23	General View												Load JPG	☒		
13	09/02/18 11:23	General View												Load JPG	☒		
14	09/02/18 11:23	General View												Load JPG	☒		
15	09/02/18 11:23	General View												Load JPG	☒		
16	09/02/18 11:23	General View												Load JPG	☒		
17	09/02/18 11:23	General View												Load JPG	☒		
18	09/02/18 11:23	General View												Load JPG	☒		
19	09/02/18 11:23	General View												Load JPG	☒		
20	09/02/18 11:23	General View												Load JPG	☒		
21	09/02/18 11:23	General View												Load JPG	☒		
22	09/02/18 11:23	General View												Load JPG	☒		
23	09/02/18 11:23	General View												Load JPG	☒		
24	09/02/18 11:23	General View												Load JPG	☒		
25	09/02/18 11:23	General View												Load JPG	☒		
26	19/04/18 19:21	Reinspection Photo												Load JPG	☒		
27	19/04/18 19:21	Reinspection Photo												Load JPG	☒		
28	19/04/18 19:21	Reinspection Photo												Load JPG	☒		
29	19/04/18 19:21	Reinspection Photo												Load JPG	☒		
30	19/04/18 19:21	Reinspection Photo												Load JPG	☒		
31	19/04/18 19:21	Reinspection Photo												Load JPG	☒		
32	19/04/18 19:21	Reinspection Photo												Load JPG	☒		
33	19/04/18 19:21	Reinspection Photo												Load JPG	☒		
34	19/04/18 19:21	Reinspection Photo												Load JPG	☒		
35	19/04/18 19:21	Reinspection Photo												Load JPG	☒		
36	19/04/18 19:21	Reinspection Photo												Load JPG	☒		
37	19/04/18 19:21	Reinspection Photo												Load JPG	☒		
38	19/04/18 19:21	Reinspection Photo												Load JPG	☒		
Documentation														1 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print		

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/02/18 11:24	Singapore Accident Statement	 Load PDF	
2	09/02/18 11:24	Certificate of Insurance	 Load PDF	
3	09/02/18 11:24	Driver's Driving License	 Load PDF	
4	09/02/18 11:24	WORKSHOP ESTIMATE	 Load PDF	
5	23/04/18 11:12	SUPPLEMENTARY	 Load PDF	
6	23/04/18 11:12	ESTIMATE 2	 Load PDF	
7	14/05/18 17:12	WORKSHOP INVOICE	 Load PDF	
8	14/05/18 17:12	DISCHARGE VOUCHER	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	31/01/18 19:17	Accident Statement	 Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	31/01/18 19:14	Accident Photo	 Load JPG	☒
2	31/01/18 19:14	Accident Photo	 Load JPG	☒
3	31/01/18 19:14	Accident Photo	 Load JPG	☒
4	31/01/18 19:14	Accident Photo	 Load JPG	☒
5	31/01/18 19:14	Accident Photo	 Load JPG	☒
6	31/01/18 19:14	Accident Photo	 Load JPG	☒
7	31/01/18 19:14	Accident Photo	 Load JPG	☒
8	31/01/18 19:14	Accident Photo	 Load JPG	☒
9	31/01/18 19:14	Accident Photo	 Load JPG	☒
10	31/01/18 19:14	Accident Photo	 Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	31/01/18 19:09	Sketch Plan	 Load JPG	☒
2	31/01/18 19:09	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18002624/ATBQ2

Date: 14/05/2018

REFERENCE

Insured/Claimant: LIM TECK CHYE, VINCENT Policy No: 2100487444-01
Date of Loss: 31/01/2018 Nature of Claim: OD Claim No: 6912078762SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH1091X**
Make & Model: AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A) Engine No: CZC572502
Reg. Date: 25/10/2016 (Man. Year: 2016) Chassis No: WAUZZZ8V2G1109935
Colour: Silver Odometer: 39457 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$108,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,205.40	10,025.60	5,179.80	34.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,812.00	13,462.00	5,350.00	28.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,017.40	23,487.60	10,529.80	30.95
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	33,417.40	22,887.60	10,529.80	31.51
+ GST 7.00/7.00% (S\$)	2,339.22	1,602.13	737.09	31.51
Nett Amount (S\$)	35,756.62	24,489.73	11,266.89	31.51

INSPECTION

Date of Assignment: 08/02/2018
Date Inspected: 07/02/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -LH	Dented	2,190.00 FS	*1,752.00 FS
2	1		*FRONT DOOR SEAL -LH	Necessary	139.00 FS	*111.20 FS
3	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
4	1		*FRONT DOOR CATCH -LH	Not Necessary	92.00 FS	*- FS
5	1		*FRONT DOOR HANDLE -LH	Cut	207.00 FS	*165.60 FS
6	1		*FRONT DOOR HANDLE MOUNTING BAR -LH	Damaged	143.00 FS	*114.00 FS
7	1		*FRONT DOOR HANDLE CAP -LH	Cut	26.00 FS	*20.32 FS
8	1		*FRONT WINDOW REGULATOR -LH	Not Necessary	232.00 FS	*- FS
9	1		*REAR DOOR -LH	Dented	2,190.00 FS	*1,752.00 FS
10	1		*REAR DOOR SEAL -LH	Necessary	139.00 FS	*111.20 FS
11	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
12	1		*REAR DOOR CATCH -LH	Not Necessary	82.00 FS	*- FS
13	1		*REAR DOOR HANDLE -LH	Repair	207.00 FS	*- FS
14	1		*REAR DOOR SLIDE VALVE -LH	Not Necessary	11.00 FS	*- FS
15	1		*REAR DOOR HANDLE CAP -LH	Not Necessary	26.00 FS	*- FS
16	1		*REAR DOOR HANDLE MOUNTING BAR-LH	Not Necessary	143.00 FS	*- FS
17	1		*REAR WINDOW REGULATOR -LH	Not Necessary	220.00 FS	*- FS
18	1		*REAR WINDOW GUIDE RAIL -LH	Not Necessary	45.00 FS	*- FS
19	1		*REAR FENDER -LH	Dented	2,006.00 FS	*1,604.80 FS
20	1		*REAR 1/4 GLASS -LH	Necessary	502.00 FS	*401.20 FS
21	1		*REAR WINDSCREEN	Necessary	704.00 FS	*563.20 FS
22	2		*GLASS PRIMER	Necessary	37.00 FS	*29.12 FS
23	1		*REAR BUMPER	Repair	1,619.00 FS	*- FS
24	1		*REAR BUMPER GUIDE-LH	Not Necessary	57.00 FS	*- FS
25	1		*REAR WHEEL HOUSING LINER -LH	Not Necessary	215.00 FS	*- FS
26	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	77.00 FS	*- FS
27	1		*SET REAR SEAT GROMMET	Not Necessary	55.00 FS	*- FS
28	1		*ALUMINIUM RIM -LH REAR	Bent	645.00 FS	*516.00 FS
29	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
30	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
31	1		*ACRYLIC SEALER	Necessary	180.00 FS	*180.00 FS
32	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
33	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
34	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
35	1		*SUNDRIES	Necessary	400.00 FS	*174.56 FS
36	1		*SILL PANEL -LH	Dented	1,630.40 FS	*1,630.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	15,205.40	10,025.60
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT AND WELD LHS SILL PANEL	New	1,800.00	1,250.00
2	TO REMOVE AND REINSTALL REAR PARKING AID .CHECK FUNCTION	New	280.00	280.00
3	TO REMOVE AND TRANSFER BOTH LHS FRONT AND REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	New	560.00	560.00
4	TO REMOVE AND REINSTALL REAR SEATS ,BACK REST ,ABCD PILLAR TRIMS ,ROOF LINER ,HAT TRAYS ,CARPETS ,CURTAIN AIRBAG AND SILL PANEL TRIMS	New	1,400.00	1,400.00
5	TO REMOVE AND RENEW LHS QUARTER GLASS AND REAR WINDSCREEN FOR FENDER RENEWAL	New	600.00	600.00
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS ,FUSE UNITS ,BATTERY ,MANAGER ,FUSE AND RELAY TRAYS AND ELECTRICAL COMPONENTS	New	1,400.00	1,400.00
7	TO DISMANTLE LHS FRONT AND REAR DOORS ,REAR BUMPER AND REAR LID ,CUT OUT AND WELD LHS REAR FENDER .RENEW LHS FRONT AND REAR DOORS AND REAR BUMPER .ALIGN TO POSITION .REINSTALL ALL PARTS REMOVED	New	6,300.00	4,000.00
8	TO RESPRAY LHS FRONT AND REAR DOORS ,DOOR HANDLES ,LHS REAR FENDER ,LHS SILL PANEL ,DOOR ENTRANCE ,ROOF CHANNEL ,DRAIN PANEL,END PANELLING AND REAR BUMPER .TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	6,000.00	3,500.00
9	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
10	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			18,812.00	13,462.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >