

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTR%	DISC.OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	12	1			REAR DOOR WEATHER STRIP LH			Necessary	95		20		76	Reviewing	
	13	1			REAR DOOR REGULATOR LH			Serviceable	0		20		0	Reviewing	
	14	1			REAR DOOR LOCK MECHANISM LH			Serviceable	0		20		0	Reviewing	
	15	1			SIDE SKIRT LH			Cut	320		20		256	Reviewing	
	16	1			SET SIDE SKIRT LH CLIPS			Necessary	40		20		32	Reviewing	
	17	1			REAR FENDER ARCH GARNISH LH			Cut	163		20		130.4	Reviewing	
	18	1			REAR FENDER ARCH GARNISH CLIPS LH			Necessary	50		20		40	Reviewing	
	19	1			REAR RIM LH			Cut	450		20		360	Reviewing	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA, FRONT DOOR LH, CENTER PILLAR LH, REAR DOOR LH, REAR FENDER LH,	800	0	0	Reviewing		
	2		TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT.	30	0	0	Reviewing		
	3		TO RUST PROOF AFFECTED AREAS	40	0	0	Reviewing		
	4		TO REMOVE AND TRANSFER FRONT DOOR COMPONENTS LHS.	0	0	0	Reviewing		

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Sum Insured		0
Market Value		0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Type		▼
License Issue Date		mm/dd/yyyy
License Expiration Date		mm/dd/yyyy
Address	44 BENOH RD BLOCK B, Singapore	
Address type	Personal Correspondence	▼
Gender	Male	▼
Marital status	Unknown	▼
Identification #	S1445303B	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	8/29/18 10:25 AM	2400	2400	Open	Share	Clone
KADRI Maleen	2/9/18 12:01 PM	3044	3044	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Immediate Advice with Mandate.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 23, 2018
LKK Survey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	April 19, 2018
LKK Resurvey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	April 19, 2018
TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	February 20, 2018
Preliminary Advice.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	February 14, 2018
EMAIL_msg	Letters and Correspondence	Workshop	KADRI Mateen	February 9, 2018
GIA REPORT OF SLF9115U (TP).PDF	Reports & Statement	GIA Report	KADRI Mateen	February 9, 2018
TP VIDEO.MP4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	February 9, 2018
GIA REPORT OF SUB8806K (INSU).PDF	Reports & Statement	GIA Report	KADRI Mateen	February 9, 2018