



SLF9115U

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 8/2/2018

Vehicle Reg. No. : SLF9115U
Vehicle Reg. Date: 15-Sep-2016
Make / Model : H. VEZEL 1.5X CVT
Engine No. : L15B4404848
Chassis No. : RU11204848

COST OF CLAIMS

Parts Cost / List Items :	\$	5,530.00
Plus/Less 20%	\$	1,106.00
Total Cost / List :	\$	4,424.00
Special Nett Items :	\$	350.00
Total Parts Amount :	\$	4,774.00
Total Labour Amount :	\$	2,780.00
Gross Total :	\$	7,554.00
GST % : 7%	\$	528.78
Nett Amount :	\$	8,082.78

Surveyor Name and Company :

Tanjin 97495749
Date of survey : 12/2/18 @ 1440
Part by Part / Lump Sum : 6 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : sur@khant.com
Fax No :
HP No :

This claim is handled by : EZEL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLF9115U**

Vehicle Reg. Date: **9/15/2016**

Make / Model : **H. VEZEL 1.5X CVT**

Engine No. : **L15B4404848**

Chassis No. : **RU11204848**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Front door LH	Rp	\$ 1,350.00		
2	1	Front door sticker LH	X	\$ 46.00		
3	1	Rear door LH	bt	\$ 1,042.00		
4	1	Rear door front rubber LH	?	\$ 40.00		
5	1	Rear door bottom rubber LH	?	\$ 40.00		
6	1	Rear door back rubber LH	?	\$ 32.00		
7	1	Rear door sticker LH	nei	\$ 46.00		
8	1	Rear door hinge upper LH	Rp	\$ 72.00		
9	1	Rear door hinge lower LH	Rp	\$ 75.00		
10	1	Rear door stopper LH	X	\$ 20.00		
11	1	Rear door moulding LH	X	\$ 85.00		
12	1	Rear door weather strip LH	nei	\$ 95.00		
13	1	Rear door regulator LH	?	\$ 477.00		
14	1	Rear door lock mechanism LH	X	\$ 377.00		
15	1	Side Skirt LH	art	\$ 520.00		
16	1set	Side skirt LH clips	nei	\$ 50.00		
17	1	Rear fender arch garnish LH	art	\$ 163.00		
18	1	Rear fender arch garnish clips LH	nei	\$ 50.00		
19	1	Rear rim LH	art	\$ 950.00	450	
20	1	TYRE 215/60R16 (RR LH)	X		\$ 350.00	
21	1	0				
22	1	0				
23	1	0				
24	0	0				
25	0	0				
26	0	0				
27	0	0				
28	0	0				
29	0	0				
30	0	0				
31	0	0				
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

Chassis No. : RU11204848

Estimates on Labour

[illegible]