

22/03/2002

ASS. REC. BY:

REF: CS/FCI18002670/4qbnz Special Instruction:

Surveyor: Marcus ASSIGNMENT (Office)From (Person): LS Serene Ter of FCI Date/Time: 9/2/18 @ 3:55pm

Estimated Cost: _____ Bill to: _____

OD (IP) WS/TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJK 8893K Insured: SH 8539Tat Workshop m/s Lee Brothers Tel: 65095521of 1 Kaki Bk + Ave 6 #02-47 Auto bayPolicy No: D-18088936 MFSH Claim No: D18001230 MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 7/2/18
(Client's Record)CA / REV / REP. / REV 24 HRS lwp

H.O.D. Endorsement: _____

Date/Time: 9:41am @ 12/2/18 Person Contacted: Men Vehicle IN OUT

Date/Time Action/Instruction (✓) Estimate

SJK 8893K - XSH 8539T - CC3 / AIG / 2003838 / H1a2blyD.O.A: 22/2/1212/2/18 @ 5:30pm revised to Serene by email.MV: \$20K (est); LTA: \$15172; NV: \$4828

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GLA / PR Seen

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



Preli. Report

1) 23/2/2018



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

) S + RS. \$

) Photos

) Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

78

4500

160

50

50

83

343

RECEIVED 23 FEB 2018

10/1/18 confirmed L/S \$4500 with Jason
(Ref to 4396.92, 427.7)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FC118002670/Uqb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-02-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 8539T	Veh. Inspected	SJK 8893K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	09/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	07/02/2018	Inspection Date	09/02/2018
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001230MFSH

Date: 12 February 2018

Our Ref: CS/FCI18002670/Uqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJK 8893K.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 09/02/2018 at the premises of M/s LEE BROTHERS, and have the following to report:-

Workshop Estimate Amount	: S\$ 8,896.92 .
Revised Estimate Amount	: S\$ 5,873.72 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

Survey Department Check List (Case Handler)

Reference No. : 19/KE18092670/UGB
Policy Type: OD / TP / TP RES / TL / EVA

STK 8993K

Case Handler

Typist

Admin (Cathy): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	☒			
C Customer Code	☒			
N Assign From	☒			
C Assign Date	☒			
C Veh No (Inspected)	☒			
C Veh No (Insured)	☒			
C D.O.A	☒			
C Policy No	☒			
C Claim No	☒			
C Insurance Authorisation (CA /REV/REP)	☒			
C Report Type	☒			
C Weekend Charges	☒			
N Survey held at/Repairer				
C Excess				

Surveyor (Mavan): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No	☒			
C Regn Month/Year	☒			
N Vehicle Type	☒			
N Make & Model	☒			
C Engine Capacity. (C.C)	☒			
N Colour	☒			
C Odometer. (Sp.Reading)	☒			
C Chassis No	☒			
N General Condition	☒			
N Steering	☒			
N Brake	☒			
N Modification (Modi)	☒			
C Tyre Size	☒			
N Tyre Make	☒			
C Tyre Balance	☒			
C Date of Inspection	☒			
N Survey held	☒			
N Des.of Damages	☒			

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded	☒		
--	-------------------------------------	--	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition	☒		
C Market Value for OD cases			
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)			
C Days of repair	☒		
C Finalised Amount	☒		
C Re-inspection Cases to Finalize within 5 Days			

(4) System - (Views/Merimen)

C Resurvey photo Uploaded	☒		
---------------------------	-------------------------------------	--	--

Check By: Cathy 23/2/18
Case Handler Date

MOTOR SURVEY ASSIGNMENT

Date	08-02-2018	Our Ref No. D18001230MFSH
Accident Date	07-02-2018	Claim Type. Third Party
Insured Vehicle	SH8539T	Third Party Vehicle. SJK8893K
Survey Location	1 KAKI BUKIT AVE 6 #02-47 AUTOBAY	
Contact Person.	JASON LEE	
Contact No.	65095521/ 0	Fax No. 65095523
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED (NO EST. PROVIDED)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LEE BROTHERS AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234858)



PRI Documents



Close



PRI Header Details

Claim No	D18001230MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & LEE BROT
Workshop Name	LEE BROTHERS AUTOMOTIVE PTE LTD (Contact Person : JASON LEE)	Survey Location & Contact Details	1 KAKI BUKIT AVE 6 #02-47 AUTOBAY Mobile: 0 , Phone: 65095521 , Fax: 65095523 EmailId: SALES@LEEBROTHERS.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM PROVIDED)		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH8539T	TP Vehicle No	SJK8893K
PRI Recieved Date	08-02-2018 09:54:14 PM	Surveyor Appointed Date	09-02-2018 03:55:10 PM	Surveyor Accept Date	12-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	12-02-2018	Upload Survey Report *:	Choose File
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select Year ▾
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 12 February 2018 5:30 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001230MFSH/1
Attachments: CSFCI18002670Uqb.pdf

Dear Serene,

Enclosed herewith preliminary advice of SJK 8893K.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 12 February 2018 9:48 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001230MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 9 February 2018 3:55 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001230MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2876H

Vehicle Details

Vehicle No.: SJK8893K
Vehicle to be Exported: Yes
Intended De-registration Date: 07 Feb 2018
Vehicle Make: HONDA
Vehicle Model: HONDA CRV 2.4L AT
Primary Colour: Black
Manufacturing Year: 2008
Engine No.: K24Z12763701
Chassis No.: JHLRE48508C213448
Maximum Power Output: 125.0 kW (167 bhp)
Open Market Value: \$28,656.00
Original Registration Date: 19 Sep 2008
First Registration Date: 19 Sep 2008
Transfer Count: 0
Actual ARF Paid: \$28,656.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 18 Sep 2018
PARF Rebate Amount: \$14,328.00

Intended COE Rebate Details

COE Expiry Date: 18 Sep 2018
COE Category: B - Car (1601cc & above)

COE Period(Years):	10
QP Paid:	\$13,890.00
COE Rebate Amount:	\$852.00
Total Rebate Amount:	\$15,180.00

The information contained herein is correct as at 07 Feb 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2876H
Vehicle Details	
Vehicle No.:	SJK8893K
Vehicle to be Exported:	No
Intended De-registration Date:	09 Feb 2018
Vehicle Make:	HONDA
Vehicle Model:	HONDA CRV 2.4L AT
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	K24Z12763701
Chassis No.:	JHLRE48508C213448
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$28,656.00
Original Registration Date:	19 Sep 2008
First Registration Date:	19 Sep 2008
Transfer Count:	0
Actual ARF Paid:	\$28,656.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Sep 2018
PARF Rebate Amount:	\$14,328.00
Intended COE Rebate Details	
COE Expiry Date:	18 Sep 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$13,890.00
COE Rebate Amount:	\$844.00
Total Rebate Amount:	\$15,172.00

The information contained herein is correct as at 09 Feb 2018

OK

Free Car Valuation

Unsure of how much your car is worth?

Let us tell you how much is the value - no charges & no obligations!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

07/10 Mercedes Benz ML350 4MATIC, Well Maintained



Luxurious SUV, Stylish And
Rapid Way Of Transporting
Loads Of Baggage/Groceries.
Shine Connect - StarAd

• Free VICOM evaluation
 • Free grooming and 6 months maintenance
 • In-house workshop ensures quality service
 • Member of SVTA and hire purchase association
 • 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted 20 results/page

7 vehicles

Honda CR-V

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda CR-V		Any	Any	2008	Any	Any	Any	Available



Honda CR-V 2.0A (New 5-yr COE)

\$45,800

\$9,150 /yr

09-Jun-2008

1,997 cc

127,000 km

SUV

Available

Lowest Price In The Whole Market! Superb Condition, No Repairs Needed, Don't Hesitate To Call Us And View This SUV, Don't Miss It! Bank And In House Loan Available. 10 Year COE Can Also Be Arrange.

Posted: 08-Feb-2018 Tags: 2008 Honda CR-V, 2008 Honda CRV, Honda CR-V, Honda CRV, Honda, CR-V, CRV, Used Honda



Honda CR-V 2.0A

\$18,300

N.A

01-Apr-2008

1,997 cc

-

SUV

Available

Cheapest Honda CRV In The Market To Buy And Renew COE! Paper Value Now About \$14,240. Car Body Worth \$3,500 To \$4,000. Selling Only \$18,300! To Renew COE For 5 Years, Just Add \$25,289. Total Only \$43,...

Posted: 08-Feb-2018 Tags: 2008 Honda CR-V, 2008 Honda CRV, Honda CR-V, Honda CRV, Honda, CR-V, CRV, Used Honda



Honda CR-V 2.0A

\$20,500

N.A

08-Aug-2008

1,997 cc

-

SUV

Available

Almost Brand New Condition, Price Can't Be Negotiable. If Find Any A Fault -\$200 Feel Free To Contact To View The Car At 60 Kaki Bukit Eunos Tech Park.

Posted: 05-Feb-2018 Tags: 2008 Honda CR-V, 2008 Honda CRV, Honda CR-V, Honda CRV, Honda, CR-V, CRV, Used Honda



Honda CR-V 2.0A (New 5-yr COE)

\$47,888

\$9,570 /yr

24-Apr-2008

1,997 cc

113,098 km

SUV

Available

Yet Another Beautiful And Well Maintained Car! High Loan And Trade In Avail! Lowest Int Rates At 3.28%! Awarded Most Comfortable Suv In Town! No Unnecessary Or Misc Cost Involved! Hurry Call Now To En...

Posted: 03-Feb-2018 Tags: 2008 Honda CR-V, 2008 Honda CRV, Honda CR-V, Honda CRV, Honda, CR-V, CRV, Used Honda

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Buy Tyres Online!
 Latest Special Offers from Tyrepack



Honda CR-V 2.0A

\$20,500

\$14,120 /yr

10-Sep-2008

1,997 cc

176,000 km

SUV

Available

No Repair Needed, Call To Arrange For Viewing And Test Drive, Reasonable Offer Will Be Considered.

Posted: 27-Jan-2018 Tags: 2008 Honda CR-V, 2008 Honda CRV, Honda CR-V, Honda CRV, Honda, CR-V, CRV, Used Honda



Honda CR-V 2.0A

\$19,900

N.A

24-Apr-2008

1,997 cc

116,699 km

SUV

Available

Lowest Mileage In The Market. Beautiful Black Int, Well Maintained By Owner. Selling Due To Upgrading. Very Spacious Car Boot. Highly Recommended For Family User. Good For Short Term Usage Or Future ...

Posted: 19-Jan-2018 Tags: 2008 Honda CR-V, 2008 Honda CRV, Honda CR-V, Honda CRV, Honda, CR-V, CRV, Used Honda



Honda CR-V 2.0A (New 5-yr COE)

\$47,800

\$9,550 /yr

06-May-2008

1,997 cc

99,500 km

SUV

Available

Cheapest, Low Mileage, The Most Beautiful CR-V In The Market. Well Maintained. Most Sought Honda Black In Black Interior. Come View And We Discuss Further, Thanks.

Posted: 16-Dec-2017 Tags: 2008 Honda CR-V, 2008 Honda CRV, Honda CR-V, Honda CRV, Honda, CR-V, CRV, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

SH8539T

ESTIMATE

DATE : 08//02/2018

VEHICLE NO : SJK8893K

MAKE/MODEL : HONDA CVR

ACC DATE : 07/02/2018

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
LIST ITEMS			
1	1 REAR WINDSCREEN MOULDING <i>nel</i>	49.50	49.50 ✓
2	1 REAR TAIL GATE <i>DD/2nd</i>	1,107.70	1,107.70 ✓
3	1 REAR TAIL GATE RUBBER <i>7~11</i>	140.00	140.00 ✓
4	1 REAR TAIL GATE LOCK <i>7~11</i>	234.80	234.80 ✓
5	1 REAR TAIL GATE LOCK CATCH <i>11</i>	27.20	27.20 X
6	1 REAR TAIL GATE INNER TRIM <i>de/cne</i>	197.90	197.90 ✓
7	1 REAR TAIL GATE OUTER GARNISH <i>de/7.11</i>	393.20	393.20 ✓
8	1 REAR TAIL GATE OUTER OPEN HANDLE <i>11</i>	108.70	108.70 X
9	1 REAR TAIL GATE LOGO <i>11</i>	22.20	22.20 X
10	1 REAR TAIL GATE EMBLEM CRV <i>nel</i>	39.60	39.60 ✓
11	1 REAR BUMPER <i>DD/2nd</i>	648.00	648.00 ✓
12	2 REAR BUMPER SIDE RH/LH <i>70.1</i>	181.80	<u>363.60</u> ✓
13	2 REAR BUMPER REFLECTOR RH / LH <i>0/5 BND</i>	26.00	52.00 172
14	2 REAR BUMPER SIDE RETAINER RH / LH <i>11</i>	34.00	68.00 X
15	1 REAR EXHAUST BOX <i>12</i>	636.20	636.20 X
16	1 REAR EXHAUST CHROME PIPE <i>12</i>	120.00	120.00 ✓
17	2 REAR EXHAUST MOULDING <i>11</i>	15.40	30.80 X
18	1 REAR END PANEL <i>15.40 280</i>	560.00	560.00 ✓
19	1 REAR END PANEL GARNISH <i>7~11</i>	196.30	196.30 ✓
20	1 REAR SPARE TYRE PANEL <i>12</i>	1,094.40	1,094.40 X
21	2 REAR FENDER INNER TRIM RH / LH <i>11</i>	312.40	<u>624.80</u> X

LESS 20%

40766
3261.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SPECIAL NETT ITEMS

1	1	(SET) REAR BUMPER CLIP <i>neu</i>	45.00	45.00	✓
2	1	(SET) REAR BUMPER REVERSE SENSOR <i>shut</i>	280.00	280.00	<i>200</i>
				<u>325.00</u>	

LABOUR CHARGES :

1	TO KNOCK OUT DENT, CUT/WELD REAR PANEL , SPARE TYRE PANEL AND REPLACE ACCIDENT PARTS	1,600.00	<i>1000</i>
2	TO SPRAY PAINTING ON ACCIDENT PORTION	1,000.00	<i>850</i>
3	TO CHECK WIRING	30.00	✓
4	TO REMOVE AND REPLACE REVERSE SENCOR	120.00	<i>50</i>
5	TO REMOVE AND REFIT CUSHION	180.00	<i>80</i>
6	TO REMOVE AND REPLACE REAR EXHAUST BOX	180.00	<i>60</i>
7	TO TUFF KOTE	90.00	<i>60</i>
		<u>3,200.00</u>	
TOTAL:			

5636.48
4509

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ *8896.92*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002670/Uqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8539T	Veh. Inspected	SJK 8893K	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001230MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	09/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CRV (A)	c.c	2354	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JHLRE48508C213448	Colour	BLACK	
Odometer	187250	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/60 R16	PIRELLI	6 mm	
L/H Front Tyre	235/60 R16	PIRELLI	6 mm	
R/H Rear Tyre	235/60 R16	PIRELLI	6 mm	
L/H Rear Tyre	235/60 R16	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/02/2018	Inspection Date	09/02/2018	
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 8893K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN MOULDING	NECESSARY	49.50	49.50
1	REAR TAIL GATE	DENTED / BENT	1,107.70	1,107.70
1	REAR TAIL GATE RUBBER	TWISTED	140.00	140.00
1	REAR TAIL GATE LOCK	TWISTED	234.80	234.80
1	REAR TAIL GATE LOCK CATCH	NOT NECESSARY	27.20	-
1	REAR TAIL GATE INNER TRIM	DEFORMED / CRACKED	197.90	197.90
1	REAR TAIL GATE OUTER GARNISH	DEFORMED / TORN	393.20	393.20
1	REAR TAIL GATE OUTER OPEN HANDLE	NOT NECESSARY	108.70	-
1	REAR TAIL GATE LOGO	NOT NECESSARY	22.20	-
1	REAR TAIL GATE EMBLEM CRV	NECESSARY	39.60	39.60
1	REAR BUMPER	DENTED / DEFORMED	648.00	648.00
2	REAR BUMPER SIDE RH/LH @\$181.80	TORN	363.60	363.60
2	REAR BUMPER REFLECTOR RH/LH @\$26.00	O/S BROKEN	52.00	26.00
2	REAR BUMPER SIDE RETAINER RH/LH @\$34.00	NOT NECESSARY	68.00	-
1	REAR EXHAUST BOX	TO REPAIR SEE LABOUR	636.20	-
1	REAR EXHAUST CHROME PIPE	DENTED	120.00	120.00
2	REAR EXHAUST MOULDING @\$15.40	NOT NECESSARY	30.80	-
1	REAR END PANEL	BADLY DENTED	560.00	560.00
1	REAR END PANEL GARNISH	TWISTED	196.30	196.30
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,094.40	-
2	REAR FENDER INNER TRIM RH/LH @\$312.40	NOT NECESSARY	624.80	-
	LESS 20% DISCOUNT		-1,342.98	-815.32
			5,371.92	3,261.28
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	45.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			325.00	245.00

Report Ref No. CS/FC118002670/Uqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO KNOCK OUT DENT, CUT/WELD REAR PANEL, SPARE TYRE PANEL AND REPLACE ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF REAR EXHAUST BOX AND REAR SPARE TYRE PANEL.		1,600.00	1,000.00
	TO SPRAY PAINTING ON ACCIDENT PORTION.		1,000.00	850.00
	TO CHECK WIRING.		30.00	30.00
	TO REMOVE AND REPLACE REVERSE SENSOR.		120.00	50.00
	TO REMOVE AND REFIT CUSHION.		180.00	80.00
	TO REMOVE AND REPLACE REAR EXHAUST BOX.		180.00	60.00
	TO TUFF KOTE.		90.00	60.00
			3,200.00	2,130.00
	GRAND TOTAL		8,896.92	5,636.28
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,500.00

Report Ref No. CS/FCI18002670/Uqbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.