



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd


Online Service Booking :
www.toyotasingapore.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Account Detail	Account No S1000007/ICLPI1	Customer Detail
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	Document No 0	Mr Cheng Teck Soon 201D Compassvale Drive #10-557 Singapore 544201 Mobile: 96218574
	Document Date 08/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	30/11/2016	SLJ1704B	0	16017	7DS/SLJ1704B/06021:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W80J006052	2ZR1859832	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SLB8222X ACC DATE:06/02/2018 DRIVE IN:07/02/2018 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30.00
2	S	BP-SUBLET REAR NUMBER PLATE				80.00
3	S	BP-SUBLET DRILL HOLE & INSTALL REVERSE SENSOR				169.50
4	S	BP-SUBLET CHECK LIGHTING & CONDUCT WATER LEAK TEST				169.50
5	S	BP-SUBLET SEALANT - REAR TAILGATE				80.00
6	S	BP-SUBLET REMOVE & INSTALL REAR COMPARTMENT CARPET , GARNISH A TRIMMING TO ASSIST REPAIR				339.00
7	S	BP-SUBLET REMOVE & INSTALL TAILGATE TOP SPOILER				115.26
8	S	BP-SUBLET REPLACE REAR WINDSCREEN GLASS				436.00
9	S	BP-SUBLET SUPPLY & INSTALL REAR WINDSCREEN 3M SOLA R FILM				480.00
10	S	BP-SUBLET TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE				339.00
11	S	BP-SUBLET REMOVE & INSTALL REAR REVERSE CAMERA				339.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	Amount Due
		Others	

PLEASE TEAR ALONG PERFORATED LINE

3607193

3607193

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE **08/02/2018**
TIME **08:14**

VEHICLE NO **SLJ1704B**

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188


Account Detail				Account No		Customer Detail			
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia				S1000007/ICLP11		Mr Cheng Teck Soon 201D Compassvale Drive #10-557 Singapore 544201 Mobile: 96218574			
				Document No					
				0					
				Document Date					
				08/02/2018					

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	30/11/2016	SLJ1704B	0	16017	7DS/SLJ1704B/06021

Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
JTDGG20W80J006052	22R1859832	60	Sam San Joi		--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	S	BP-SUBLET REPLACE TAILGATE, REAR WINDSCREEN, EMBLEM, ETC STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				1356 3390.00
13	S	BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS				1668 2780.00
14	1	T52159-68907 REAR BUMPER COVER, <i>de</i>	1.00	574.90		574.90
15	2	T52576-68020 L/R SIDE BPR RETAINER, <i>= 1pc</i>	1.00	44.40		44.40
16	3	T52575-68020 R/R SIDE BPR RETAINER <i>= 1pc</i>	1.00	44.40		44.40
17	4	S52161-0K040 CLIPS	10.00	3.90		39.00
18	5	T58307-68031 REAR LOWER FLR PANEL, <i>?</i>	1.00	520.00		520.00
19	6	T67935-68020 BO PLATE BACK DOOR <i>1pc</i>	1.00	288.70		288.70
20	7	T67005-68041 PANEL ASSY, BACK DOOR <i>5 pc</i>	1.00	1428.40		1428.40
21	8	T67881-68030 WEATHERSTRIP, BACK <i>1pc</i>	1.00	325.80		325.80
22	9	T68105-68071 REAR BACK DOOR GLASS, <i>1pc</i>	1.00	1009.20		1009.20
23	0	T67750-68020 B1 REAR BACK DOOR BOARD, <i>?</i>	1.00	352.40		352.40
24	1	T69350-28151 LOCK ASSY, BACK DOOR <i>X</i>	1.00	399.60		399.60
25	2	T90975-02086 FRONT BONNET EMBLEM, <i>1pc</i>	1.00	72.20		72.20
26	3	T75444-68010 PLATE, LUGGAGE COMPT (VALVE MATI) <i>1pc</i>	1.00	39.70		39.70
27	4	T76811-68130 GARNISH, BACK DOOR, <i>X NN</i>	1.00	281.00		281.00
28	5	T76817-50010 CLIP, BACK DOOR <i>X</i>	4.00	1.90		7.60
29	6	T75819-33010 CLIP, LUGGAGE <i>X NN</i>	2.00	3.30		6.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	Amount Due
		Others	

PLEASE TEAR ALONG PERFORATED LINE

3607194

3607194

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 08/02/2018
TIME 08:14

VEHICLE NO SLJ1704B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motor



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Account Detail		Account No S1000007/ICLPI1	Customer Detail
Lompac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		Document No 0	Mr Cheng Teck Soon 201D Compassvale Drive #10-557 Singapore 544201 Mobile: 96218574
		Document Date 08/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	ZGE20R	30/11/2016	SLJ1704B	0	16017 :7DS/SLJ1704B/06021:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W80J006052	22R1859832	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	7	T08826-08609 SUPER FAST URETHANE BLACK / 4 MC.	1.00	90.08		90.08
31	8	T08826-08682 SINGLE STEP PRIMER /	1.00	173.44		173.44
32	9	SP2061-12010 16 070 SENSOR ?	1.00	151.60		151.60
33	0	T75443-ELGAN ELEGANCE EMBLEM / MC	1.00	40.00		40.00

5 Days.
before paint photos.
Guo Qiao - 82880282
05/3/18

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total 14,636.28
Please acknowledge receipt of vehicle parts of the following: • To survey before/after spray painting • To spray damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	Parts	5,889.02	GST 7.00%
	Labour	30.00	
	Materials	8,717.26	Less
	Lubrication/Fluid	0.00	
	Others	0.00	
		Amount Due	15,660.82

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO **SLJ1704B**

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

3607195

3607195