



Co Reg No : 1967000862
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyotasingsapore.com.sg

Toyota Bodycare Centre

17 Ubi Road 4

Singapore 409611

Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007/ICLP11	Mr Cheng Teck Soon 201D Compassvale Drive #10-557 Singapore 544201 Mobile: 96218574
	Document No	
	Document Date	
	0	
	08/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	ZGE20R	30/11/2016	SLJ1704B	0	16017 :7DS/SLJ1704B/06021:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W80J006052	2ZR1859832	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SLB8222X ACC DATE:06/02/2018 DRIVE IN:07/02/2018 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00
2	S	BP-SUBLET REAR NUMBER PLATE				80.00
3	S	BP-SUBLET DRILL HOLE & INSTALL REVERSE SENSOR				169.50
4	S	BP-SUBLET CHECK LIGHTING & CONDUCT WATER LEAK TEST				169.50
5	S	BP-SUBLET SEALANT - REAR TAILGATE				80.00
6	S	BP-SUBLET REMOVE & INSTALL REAR COMPARTMENT CARPET , GARNISH A TRIMMING TO ASSIST REPAIR				339.00
7	S	BP-SUBLET REMOVE & INSTALL TAILGATE TOP SPOILER				115.26
8	S	BP-SUBLET REPLACE REAR WINDSCREEN GLASS				436.00
9	S	BP-SUBLET SUPPLY & INSTALL REAR WINDSCREEN 3M SOLA R FILM				480.00
10	S	BP-SUBLET TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE				339.00
11	S	BP-SUBLET REMOVE & INSTALL REAR REVERSE CAMERA				339.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3607193

TO SECURITY GUARD

3607193

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 08/02/2018
TIME 08:14

VEHICLE NO SLJ1704B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188


Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	Mr Cheng Teck Soon 201D Compassvale Drive #10-557 Singapore 544201 Mobile: 96218574
	Document No	
	Document Date	
	0	
	08/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	ZGE20R	30/11/2016	SLJ1704B	0	16017 7DS/SLJ1704B/06021:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W80J006052	2ZR1859832	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	S	BP-SUBLET REPLACE TAILGATE, REAR WINDSCREEN, EMBLEM, ETCSTRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				3390.00
13	S	BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS				2780.00
14	1	T52159-68907 REAR BUMPER COVER,	1.00	574.90		574.90
15	2	T52576-68020 L/R SIDE BPR RETAINER,	1.00	44.40		44.40
16	3	T52575-68020 R/R SIDE BPR RETAINER	1.00	44.40		44.40
17	4	S52161-OK040 CLIPS	10.00	3.90		39.00
18	5	T58307-68031 REAR LOWER FLR PANEL,	1.00	520.00		520.00
19	6	T67935-68020 BO PLATE BACK DOOR	1.00	288.70		288.70
20	7	T67005-68041 PANEL ASSY, BACK DOOR	1.00	1428.40		1428.40
21	8	T67881-68030 WEATHERSTRIP, BACK	1.00	325.80		325.80
22	9	T68105-68071 REAR BACK DOOR GLASS,	1.00	1009.20		1009.20
23	0	T67750-68020 B1 REAR BACK DOOR BOARD,	1.00	352.40		352.40
24	1	T69350-28151 LOCK ASSY, BACK DOOR	1.00	399.60		399.60
25	2	T90975-02086 FRONT BONNET EMBLEM,	1.00	72.20		72.20
26	3	T75444-68010 PLATE, LUGGAGE COMPT (VALVE MATI	1.00	39.70		39.70
27	4	T76811-68130 GARNISH, BACK DOOR,	1.00	281.00		281.00
28	5	T76817-50010 CLIP, BACK DOOR	4.00	1.90		7.60
29	6	T75819-33010 CLIP, LUGGAGE	2.00	3.30		6.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3607194

TO SECURITY GUARD

3607194

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 08/02/2018
TIME 08:14

VEHICLE NO SLJ1704B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007/ICLPI1	Mr Cheng Teck Soon 201D Compassvale Drive #10-557 Singapore 544201 Mobile: 96218574
	Document No 0	
	Document Date 08/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	ZGE20R	30/11/2016	SLJ1704B	0	16017 :7DS/SLJ1704B/06021:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W80J006052	22R1859832	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	7	T08826-08609 SUPER FAST URETHANE BLACK	1.00	90.08		90.08
31	8	T08826-08682 SINGLE STEP PRIMER	1.00	173.44		173.44
32	9	SPZ061-12010 16 070 SENSOR	1.00	151.60		151.60
33	0	T75443-ELGAN ELEGANCE EMBLEM	1.00	40.00		40.00
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	14,636.28
	Please acknowledge receipt of vehicle	Parts 5,889.02	GST 7.00%	1,024.54
		Labour 30.00	Less	0.00
		Materials 8,717.26		
		Lubrication/Fluid 0.00		
		Others 0.00		
			Amount Due	15,660.82

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 08/02/2018
TIME 08:14

VEHICLE NO SLJ1704B

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors