

INS CASE OWNER: Sim CC 4 / LCR1 800 2704, K pa342

Surveyor: Kenneth DOI: 10/2/18 Date / Time: 9/2/18

Registered in Merimen: 9/2/18

Pre-assign / CCU / FTE

Insured Vehicle No.: SJS 4459R Claim No.: 958784722856

Name of Insured: LCRP P/L Policy No.: 999995011

Insured Tel No.: HP: 812/18 Make / Model: Honda Stream

Excess Sec II : SS D.O.A.: 8/2/18 Place of Accident: Sembawang Way

Is driver the owner? (YES / NO) Nature of Accident: AMIR HAMZAH BIN ABDULHAJ

If NO, Driver Name / Age: AMIR HAMZAH BIN ABDULHAJ OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.: SGV 45924 (V/L: YES / NO) Insured Liability: % Final? Yes / No

INSRS: Cheng Hoe INSRS: INSRS: INSRS:

WSP: WSP: WSP: WSP:

Tel: Tel: Tel: Tel:

Liability: Liability: Liability: Liability:

RMKS: RMKS: RMKS: RMKS:

Date / Time		STAGE	DATE / PIC
22/2	SGV 45924 - X; SJS 4459R - X	Non-Reporting ltr (1st):	
22/2		Non-Reporting ltr (2nd):	
22/2		Non-Reporting ltr (Final):	
22/2		Notification ltr (if non-pickup):	
22/2		Call OI:	
22/2		After call ltr to OI:	
22/2		Documentation Check List:	
22/2		Notification ltr (if non-pickup):	
22/2		After call ltr to OI:	
22/2		Authorisation To Act:	
22/2		Release Voucher:	
22/2		Final Repair Bill:	
22/2		Car Rental Invoice:	
22/2		Towing Invoice:	
22/2		LTA / GIA:	
22/2		Medical Bill:	
22/2		PIR:	
22/2		Mandate/Reject Instruction:	
22/2		LOD:	
22/2		Payment Breakdown Form:	
22/2		Post-Repair Photos:	
22/2		Others:	

PRELIMINARY ADVICE Date/Time: 22/2 Sent By: Cheng Hoe

FINALIZATION Date/Time: 22/2 Confirm with: June Confirm by: Cheng Hoe

Repair Cost: SS 2738.50 (days) Reduction: % Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: 22/2 Confirm with: June Email ☐ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27 IF NO or B 28, Ass. Lia:

Repair Cost: SS 2738.50

Loss of Rental (LOR): SS 400 (days) TP is a Learning car.

Loss of Use (LOU): SS 400 (days)

Loss of Income (LOI): SS 400 (days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search: SS 8.00

Medical: SS -

Disbursement: SS - (e.g. Tow/ Independent)

Legal Cost: SS -

Total: SS 3136.50 Global Sum SS:

FINAL PAYMENT Date/Time: 22/2 Confirm with: June Email ☐ Call ☐

Payee 1: SS 3136.50 Name 1: Cheng Hoe Motor Pte Ltd

Payee 2: (Strike if N.A.) SS - Name 2:

Payee 3: (Strike if N.A.) SS - Name 3:

ASS. REC. BY:

REF:

1161

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGV 459214

Yr Regn:

06, 07

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Vios

c.c.

1497

Colour

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

527403

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR05314Y9305008073

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fellken

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

8/2/18

D.O.I.

10/2/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12 File pass to Customer

11 Day @ 25501 Cc. from Time

Penal
(4 x 100)

(Fee) \$ 1379.59 / 35%

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

5 - RS - SI

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/LCR18002704/Kpa3		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 09-02-2018		
		Code : LCR		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJS 4459R	Veh. Inspected	SGV 4592H	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	09/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/02/2018	Inspection Date	10/02/2018	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST 201001158E RCB NO:201001158E

SGV4592H
 TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department \ THE MOTOR

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 08/02/2018

TP Veh Reg No: SJS4459R

Estimate No: ES1890147

Date: 09 Feb 2018

Policy No: 5021518520-10

Veh Reg No: SGV4592H

Make/Model: TOYOTA VIOS 1.5J M

Chassis No: MR053HY9305008073

Engine No: 1NZX564007

Reg. Date: 15/06/2007

*Not Authorized
 11/2/18 @ 2550f
 Return After Paint*

Estimate Repair Cost to Vehicle No :SGV4592H

PAGE:1

Description	U/Price	Quantity	List Price SS	Amount SS
List Price				
1 REAR BUMPER	427.50	1 PC	427.50	✓
2 REAR BUMPER RH SIDE RETAINER	92.33	1 PC	92.33	✓
3 REAR BUMPER RH REFLECTOR	82.81	1 PC	82.81	✓
4 REAR BUMPER CLIPS	3.50	6 PC	21.00	✓
5 REAR BOOT	510.85	1 PC	510.85	✓
6 REAR BOOT LOGO	50.20	1 PC	50.20	✓
7 REAR BOOT EMBLEM 'VIOS'	47.40	1 PC	47.40	✓
8 REAR BOOT EMBLEM 'J'	37.20	1 PC	37.20	✓
9 REAR BOOT INNER LOCK	100.30	1 PC	100.30	X
10 RH TAIL LAMP	277.60	1 PCS	277.60	✓
11 REAR EXHAUST PIPE	595.00	1 PCS	595.00	X
12 REAR PANEL	571.00	1 PC	571.00	✓
			2,813.19	
	Less 25%		703.30	2,109.89
Special Net				
13 REVERSE SENSOR	200.00	1 PC	200.00	✓
			200.00	200.00
Labour				
14 REMOVE AND REFIX REAR BUMPER ASSY, TAIL LAMP, REAR BOOT AND ATTACHMENT. TO CUTTING, WELDING AND RENEW REAR PANEL. KNOCK AND REPAIR REAR RH FENDER, REAR RH TAIL LAMP PANEL AND REALIGN THE SAME	750.00	1 LA	750.00	850
15 PUTTY AND RESPRAY ON REAR PANEL, REAR RH FENDER, REAR PANEL, REAR BUMPER, BOOT AND ALL AFFECTED AREA.	750.00	1 LA	750.00	650
16 REMOVE AND REFIX REAR EXHAUST AND CHECK LEAKING	60.00	1 LA	60.00	✓
17 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,620.00	1,620.00
			Total	SS 3,929.89
			Add GST @ 7%	275.09
			Total Amount Payable	SS 4,204.98

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Thursday, 22 February 2018 3:42 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June) (chmotor@singnet.com.sg)
Subject: Your ref: SGV 4592H *Our Ref: CC4/LCR18002704/Kpa3 [ACCIDENT INVOLVING SJS 4459R(AIG) & SGV 4592H ON 08/02/2018]

Your ref: **SGV 4592H**
Our Ref: CC4/LCR18002704/Kpa3

Without Prejudice

Dear Sirs,

ACCIDENT INVOLVING SJS 4459R(AIG) & SGV 4592H ON 08/02/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SGV4592H
Vehicle Type :	L10 - For Instruction Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	VIOS J MANUAL
Chassis No. :	MR053HY9305008073
Propellant :	Petrol
Engine No. :	1NZX564007
Engine Capacity :	1497 cc
Maximum Power Output :	80.0 kW (107 bhp)
Maximum Laden Weight :	1485 kg
Unladen Weight :	1075 kg
Year Of Manufacture :	2007
Original Registration Date :	15 Jun 2007
Lifespan Expiry Date :	-
COE Category :	A - Car (1600cc & below)
PQP Paid :	\$50,665.00
COE Expiry Date :	31 May 2027
Road Tax Expiry Date :	14 Jun 2018
Inspection Due Date :	14 Jun 2018
Intended Transfer Date :	09 Feb 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-

PAYMENT ADVICE

Your Ref : AIG Vehicle no.	: SJS4459H
Claimant Vehicle No.	: SGV4592H
Date of Accident	: 08/02/2018
Traffic Accident involving vehicle/s No.	: JUNCTION OF SEMBAWANG WAY & SEMBAWANG DRIVE

BREAKDOWN OF PAYMENT/S

<u>S/No.</u>	<u>Items</u>	<u>Amount</u>	<u>Remark</u>
1	Repair cost	\$ 2,728.50	/
2	Loss of Income (741119V CAR)	\$ 400.00	\$100 X 4 days /
3	LTA Search	\$ 8.00	/
TOTAL		\$ 3,136.50	

All payment should be made payable to Cheng Hoe Motor Pte Ltd.

Service Adviser : LKK
Contact No. : 6256 3561

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 5 September 2018 10:13 AM
To: Cheng Hoe Motor Pte Ltd (Yishun-June) (chmotor@singnet.com.sg)
Cc: Admin A
Subject: RE: Your ref: SGV 4592H *Our Ref: CC4/LCR18002704/Kpa3 [ACCIDENT INVOLVING SJS 4459R(AIG) & SGV 4592H ON 08/02/2018]

Without Prejudice

Hi June,

We refer to the above matter.

We confirmed settlement at \$3,136.50(all-in).

We will proceed to close file.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 22 February 2018 3:42 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June) (chmotor@singnet.com.sg) <chmotor@singnet.com.sg>
Subject: Your ref: SGV 4592H *Our Ref: CC4/LCR18002704/Kpa3 [ACCIDENT INVOLVING SJS 4459R(AIG) & SGV 4592H ON 08/02/2018]

Your ref: **SGV 4592H**
Our Ref: CC4/LCR18002704/Kpa3

Without Prejudice

Dear Sirs,

ACCIDENT INVOLVING SJS 4459R(AIG) & SGV 4592H ON 08/02/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Thursday, 22 February 2018 3:39 PM
To: 'Eileen, May Hwee Yap'
Subject: ACCIDENT INVOLVING SJS 4459R(AIG) & SGV 4592H ON 08/02/2018

Your Ref: **SJS 4459R**
Our Ref: CC4/LCR18002704/Kpa3

Dear Sirs/Madam,

ACCIDENT INVOLVING SJS 4459R(AIG) & SGV 4592H ON 08/02/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SGV 4592H against your insurance policy.

Based on the accident report and accident scenario, liability is down against us.
We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


AUTHORISATION TO ACT
(AIG Asia Pacific - Express Third Party Claim)

I, Yeo Kiang Wang (the third party claimant) of 31 Jalan
Leban Singapore 577568 (address), owner of SGV4592H (vehicle no.) hereby
authorize CHENG HOE MOTOR PTE LTD ("the workshop") to act for me with respect to
my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SGV4592H that
was damaged pursuant to the accident which occurred on 8/2/2018 (date) along Junction of
Sembawang Way & Sembawang Drive (location) involving vehicle no/s SJS4459H ("the accident").


I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the
workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s
being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice
and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is
concerned.

Dated this 9 (day) of Feb (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

This Discharge Voucher applies strictly for Claimant's claim for property damages only does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident. This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

RELEASE VOUCHER

(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

"We/I, **CHENG HOE MOTOR PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$2728.50** (Repair Cost), **S\$400.00** (Loss of Use), **S\$2.00** (Disbursement), for vehicle no **SGV4592H** that was damaged pursuant to the accident which occurred **08/02/2018** (date) along **Junction of Sembawang Way & Sembawang Drive** (location) involving vehicle no/s **SJS4459R**. This is pursuant to the inspection conducted on **10/02/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **Yeo Kiang Wang** ("the third party claimant") of vehicle no. **SGV4592H** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage **SGV4592H** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 05 (day) of 09 (month) 2018 (year)



KSC

Signed by appointed surveyor



Signed by "the workshop" (with chop)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/YS
Claim Type: Third Party
Accident Date: 08/02/2018
TP Veh Reg No: SJS4459R

NO: CL8180919
Date: 21 Aug 2018
Policy No: 5021518520-10
Veh Reg No: SGV4592H
Make/Model: TOYOTA VIOS 1.5J M
Job No: JC1598122

Description

To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges.
(As recommended by your appointed surveyor)

Quantity	List Price	PAGE:1
1 PC	SS 2,550.00	Amount SS 2,550.00

Total	SS 2,550.00
Add GST @ 7%	178.50
Total Amount payable	SS 2,728.50

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE

A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS

COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 058358

TEL : 6538 7411 & FAX : 6534 1011

TO : CHENG HOE MOTOR PTE LTD	BILL NO: B029 / 2018
YOUR REF:	
OUR REF : ACS.CH.LTA.2018 (FEB 2018)	DATE : 9/3/18

TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary/ possible, attendance preparation examination of documents relating thereto; correspondence, attendance, perusal, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.

LTANET SEARCHES FOR THE MONTH FEB 2018

S/NO	TP NO.	CHM	DOA
1	3/2/2018	SLE974X	SGZ4074R
2	5/2/2018	SKM6524S	GBG4736Z
3	5/2/2018	SKV5769L	SLL5110C
4	6/2/2018	SBW9300E	SJF2449B
5	9/2/2018	SJS4459R	SGV4592H
6	10/2/2018	xxd1322j	YN4265G
7	10/2/2018	GBD821C	YN6641R
8	12/2/2018	SGP37	SFY4005H
9	13/2/2018	SKU2593B	SDR2929R
10	15/2/2018	SKT8599B	SJG3893P
11	15/2/2018	SLT4994M	SKV5807K
12	14/2/2018	SLF3948Y	GBE8014H
13	14/2/2018	SKN3652U	PA5471X
14	14/2/2018	SJN3081D	SLM6975L
15	20/2/2018	SJU1420K	SCK5599M
16	20/2/2018	GBG7444X	SJP2389M
17	21/2/2018	SJQ8082C	EJ8182T
18	24/2/2018	SJK4238D	SJP3113K
19	24/2/2018	PA9778K	SJG8660L
20	26/2/2018	SL86900X	SJV3116
21	26/2/2018	SKC2450A	EJ9989B
22	27/2/2018	SLM3053S	SJX2413J

sub-total c/f

1 176.00

M/s. A.C. SYED & PARTNERS
ADVOCATES & SOLICITORS
SINGAPORE

We reserved the right to forward a subsequent bill for any
disbursements omitted herein.

E. & O.E.

Enquire Vehicle & Owner Information (Vehicle No. SJS4459R As At 08 Feb 2018 / 18:05:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: CHM-SGV4592

Current Owner Details

Owner ID Type: Company

Owner ID: 201624597K

Owner Name: LCRF PTE LTD

Registered Address Type: Private Residential (non-Condo Apt / non-House)

Registered Block/House No.: 60

Registered Street Name: ANSON ROAD

Registered Unit No.: # 11 - 01

Registered Building Name: MAPLETREE ANSON

Registered Postal Code: 079914

Current Vehicle Details

Vehicle No.: SJS4459R

Make Description/Model: HONDA / STREAM 1.8L A

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Feb 2018 Edit Reg		09 Feb 2018 00:00 Edit Adj Rpt	\$2,550.00 Edit Estimates	\$2,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Main Claimant:	YEO KIANG WANG, ID: S1334465E								
Vehicle Reg. No.:	SGV4592H	Date of Loss:	08/02/2018 18:00 - :59 [127 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9587747228SG	Policy/Cover Note No.:	999995011 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJS4459R	Policy No. (Claimant):	5021518520-10						
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kang, Sam-PL] Sam.Kang@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 21/02/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGV4592H (9587747228SG)
[SJS4459R]
TP
YEO KIANG WANG
Feb 8 2018 6:10PM
[LCRF PTE LTD]
Cheng Hoe Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View View in Browser

Letters/Correspondences

1 per page v ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	<input type="checkbox"/>

Photos/Images

3 per page v ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	05/09/18 10:02	Chassis Number	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	05/09/18 10:02	Odometer Reading	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	05/09/18 10:02	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	05/09/18 10:05	Reinspection Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	05/09/18 10:05	Reinspection Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	05/09/18 10:05	Reinspection Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27	05/09/18 10:05	Reinspection Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28	05/09/18 10:05	Reinspection Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
29	05/09/18 10:05	Reinspection Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
30	05/09/18 10:05	Reinspection Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
31	05/09/18 10:05	Reinspection Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
32	05/09/18 10:05	Reinspection Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
33	05/09/18 10:05	Reinspection Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
34	05/09/18 10:05	Reinspection Photo	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	05/09/18 10:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	05/09/18 10:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	05/09/18 10:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	05/09/18 10:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	05/09/18 10:06	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
40	05/09/18 10:06	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
41	05/09/18 10:06	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
42	05/09/18 10:06	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/02/18 16:31	TP GIA REPORT	Load PDF	
2	20/02/18 19:58	TP ESTIMATE - MARKED	Load PDF	
3	05/09/18 10:07	TP Vehicle Details	Load PDF	
4	10/09/18 11:32	WORKSHOP INVOICE	Load PDF	
5	10/09/18 11:32	AUTHORISATION TO ACT FORM	Load PDF	
6	10/09/18 11:32	Release Voucher	Load PDF	
7	10/09/18 11:32	LTA SEARCH	Load PDF	
8	10/09/18 11:32	LETTER TO OI	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/02/18 08:36	OI GIA report	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJS4459R (Insd veh)	Model:	TOYOTA VIOS 1.5 J (M)
	SGV4592H (TP veh)		
Date of Accident:	08/02/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	4,204.98	
Final Repair Cost	:	\$	2,728.50	
Loss of Use	:	\$	400.00	4.00 days at \$100.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	8.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	3,136.50	
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)				
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____(%)		
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____100_____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	:	\$ 3,136.50
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

10 Sep
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR18002704/KPA3Q2

Date: 10/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 999995011

Claimant Vehicle No: SGV4592H

Insured Vehicle No: SJS4459R

Date of Loss: 08/02/2018

Nature of Claim: TP

Claim No: 9587747228SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGV4592H**

Make & Model: TOYOTA VIOS, 1.5 J (M)

Engine No: 1NZX564007

Reg. Date: 15/06/2007 (Man. Year: 2007)

Chassis No: MR053HY9305008073

Colour: Metallic Blue

Odometer: 527403 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size: 195/55 R15

Front Left Side: Falken 4 mm

Rear Left Side: Falken 4 mm

Front Right Side: Falken 4 mm

Rear Right Side: Falken 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,309.89	1,788.42	521.47	22.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	1,420.00	200.00	12.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,929.89	3,208.42	721.47	18.36
Approved Total (Overridden) (S\$)		2,550.00		
(S\$)	3,929.89	2,550.00	1,379.89	35.11
+ GST 7.00/7.00% (S\$)	275.09	178.50	96.59	35.11
Nett Amount (S\$)	4,204.98	2,728.50	1,476.48	35.11
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		3,136.50		

INSPECTION

Date of Assignment: 09/02/2018

Date Inspected: 10/02/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial

Park A
Singapore 768761

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	427.50 FL	*427.50 FL
2	1		*REAR BUMPER RH SIDE RETAINER	Distorted	92.33 FL	*92.33 FL
3	1		*REAR BUMPER RH REFLECTOR	Cracked	82.81 FL	*82.81 FL
4	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
5	1		*REAR BOOT	Buckled	510.85 FL	*510.85 FL
6	1		*REAR BOOT LOGO	Necessary	50.20 FL	*50.20 FL
7	1		*REAR BOOT EMBLEM VIOS	Necessary	47.40 FL	*47.40 FL
8	1		*REAR BOOT EMBLEM J	Necessary	37.20 FL	*37.20 FL
9	1		*REAR BOOT INNER LOCK	Repair	100.30 FL	*- FL
10	1		*RH TAIL LAMP	Cut	277.60 FL	*277.60 FL
11	1		*REAR EXHAUST PIPE	Repair	595.00 FL	*- FL
12	1		*REAR PANEL	Bent	571.00 FL	*571.00 FL
13	1		*REVERSE SENSOR	Dented	200.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	3,013.19	2,317.89
- List Item Discount on L Items 25.00/25.00% (\$\$)	703.30	529.47
Total Parts (\$\$)	2,309.89	1,788.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX REAR BUMPER ASSY ,TAIL LAMP ,REAR BOOT AND ATTACHMENT ,TO CUTTING ,WELDING AND RENEW REAR PANEL ,KNOCK AND REPAIR REAR RH FENDER ,REAR RH TAIL LAMP PANEL AND REALIGN THE SAME	New	750.00	650.00
2	PUTTY AND RESPRAY ON REAR PANEL ,REAR RH FENDER ,REAR PANEL,REAR BUMPER ,BOOT AND ALL AFFECTED AREA	New	750.00	650.00
3	REMOVE AND REFIX REAR EXHAUST AND CHECK LIEAKING	New	60.00	60.00
4	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (S\$)			1,620.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >