

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S7805854D
CHOY ZHEN YI
NO

SINGAPORE
TEL : FAX :
PH : 96469781
ATTN :

Term:

ESTIMATE BILL

Number : EB00004742
Date : 12/2/2018
Case No : AD00009560
Vehicle No : SJE9966J
Chassis : WDD2462422J287837
Year of Mfr : 2014
Policy No : MU005421
Model : MERCEDES BENZ
B180 (R16 BI)

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT HEADLIGHT RH <i>See</i>	1.0	2,385.00	10	2,146.50
2	FRONT HEADLIGHT PANEL RH <i>R</i>	1.0	590.00	10	531.00
3	FRONT HEADLIGHT NOZZEL RH	1.0	170.00	10	153.00
4	FRONT HEADLIGHT NOZZEL COVER RH <i>m.s</i>	1.0	90.00	10	81.00
5	FRONT HEADLIGHT NOZZEL PIPE RH	1.0	56.00	10	50.40
6	FRONT HEADLIGHT NOZZE JOINT RH	1.0	190.00	10	171.00
7	FRONT BUMPER <i>Deep cut</i>	1.0	1,350.00	10	1,215.00
8	FRONT BUMPER LAMP RH <i>in</i>	1.0	480.00	10	432.00
9	FRONT BUMPER LAMP GRILLE COVER RH <i>in</i>	1.0	62.00	10	55.80
10	FRONT BUMPER CHROME LH <i>in</i>	1.0	100.00	10	90.00
11	FORNT BUMPER CHROME RH <i>in</i>	1.0	100.00	10	90.00
12	FRONT BUMPER SENSOR RH	3.0	260.00	10	702.00
13	FRONT BUMPER SENSOR ECU <i>in</i>	1.0	1,405.00	10	1,264.50
14	FRONT FENDER SHIELD RH <i>in</i>	1.0	170.00	10	153.00
15	FRONT ENGINE LOWER DUST COVER <i>in</i>	1.0	260.00	10	234.00
List Price - Parts Sub Total					7,369.20
16	FRONT FENDER RH -REPAIR <i>in</i>	1.0			
17	FRONT SUPPORT PANEL - REPAIR <i>in</i>	1.0			
Special Nett Price - Parts Sub Total					0.00
Parts Total					7,369.20
18	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,000.00	0 <i>350</i>	1,000.00
19	SPRAY PAINT ON THE AFFECTED AREAS	1.0	800.00	0 <i>400</i>	800.00
20	WIRING	1.0	40.00	0 <i>20</i>	40.00
Labour 1 Sub Total					1,840.00
SINGAPORE DOLLARS : NINE THOUSAND EIGHT HUNDRED FIFTY-THREE AND CENTS EIGHTY-FOUR ONLY			Less Excess		0.00
			SUBTOTAL		9,209.20
			GST 7.00%		644.64
			TOTAL		9,853.84

Date of accident : 09/02/2018 02:50 PM. Place : ALONG TAMPINES CENTRAL CC CAR PARK

E. & O. E.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

CUSTOMER SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD



AUTHORISED SIGNATURE

* N = Item not subjected to CSI

Page 1 of 1

Issued by : MAVIS