

REPAIR ESTIMATE

12/2/2018 14:40

VEHICLE NO : SHC 1019E

MAKE :

MODEL : TOYOTA PRIUS

Chong

Aris

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR BUMPER X			\$ 458.60	
REAR BUMPER RE-INFORCEMENT X			\$ 318.80	
REAR BUMPER UNDER COVER X			\$ 552.60	
REAR BUMPER SIDE RETAINER X			\$ 112.70	
REAR BUMPER SPONGE X			\$ 143.40	
REAR BUMPER UNDER SIDE COVER (LH) X			\$ 232.00	
REAR BUMPER CLIPS X			\$ 22.00	
RETAINER, REAR BUMPER, SIDE, LH X			\$ 94.80	
SEAL, REAR BUMPER SIDE, LH X			\$ 148.40	
REAR FENDER, LH X repair			\$ 817.50	
REAR FENDER SHEILD (LH) X			\$ 134.20	
Sub Total			\$ 3,035.00	
LESS 25%			\$ 758.75	
DISCOUNTED TOTAL			\$ 2,276.25	
REAR BUMPER REVERSE SENSOR X			\$ 135.70	NETT
REAR BUMPER RUBBER MAT X			\$ 50.00	NETT
FRONT DOOR COMFORT LOGO X			\$ 75.00	NETT
REAR DOOR COMFORT & APPS STICKER			\$ 80.00	NETT
			\$ 340.70	
Labour Charge			\$ 200	
Panel Beating			\$ 1,000.00	
Spray Painting Charge			\$ 600.00	760
Wiring Charge			\$ 50.00	X
Tuff Kote			\$ 50.00	X
Remove/Refix Cushion & Upholstery Rear			\$ 150.00	X
Remove/Refix Rear Windscreen Glass			\$ 120.00	X
Remove/Refix Reverse Sensor			\$ 120.00	X
TOTAL LABOUR			\$ 2,090.00	
ESTIMATE TOTAL			\$ 4,706.95	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

TOTAL LABOUR

Acknowledged by Repairer

ESTIMATE TOTAL

Date:

Kali (1/1/18)

13/2/18 10:15h

2 Days

P/P

After Repair

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.