

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SJV8262Z

Chassis No : JHMGE68509S221755

Model : JAZZ 1.3 AT 09M W/O ALLOYWHEEL

Owner's Name : LEE YOW SHING

Ins Policy No. :

Date of Accident :

Document No. : SQT18000777 Page 1

Date : 22. Feb 2018

Customer No. : WA006

Svc Advisor :

Engine No : L13Z11021757

Date | Time : 22. Feb 2018 3:18:16 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: POLICY/CLAIMS NO: OWNER: ACC DATE: SURVEYED BY: DATE: AUTHORIZED ON : REF NO : SUPPLEMENTARY PANEL R FR KENDER						
76841-TF0-G01	TANKWASHER	1	411.30	35	267.34	18.71	286.05 (4) 64
75490-TF0-J00	GARNISH ASSYR FR CORNER	1	58.40	35	37.96	2.66	40.62 (4)
90672-SCC-003	HOLDERROD	1	39.90	35	25.93	1.82	27.75 (4)
90682-SEA-003	CLIP ABUMPER	1	3.20	35	2.08	0.15	2.23 (4)
		3	2.30	35	4.48	0.31	4.79 (4)
Sum Item					70.45 377.79	4.94 73.65	75.39 361.44

Survey By _____

Date & Time _____

Excess _____

Status _____

Signature _____

Total Amount 377.79 73.65 361.44

Total (Inclusive of GST) 70.45 4.94 75.39

~~75.39~~
361.44

Printed on 22/2/2018 3:20:08 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)