



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/AXA18002874/ea3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 13-02-2018	
		Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHF 708R	Veh. Inspected	SLA 3331C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/02/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

19.03.18
 Sunny
 rummy



Performance Motors Limited

A member of the Rine Darby Group
 Co. Reg. No. 197401559M GST Reg. No M2-0020081-X

303, Alexandra Road
 Rine Darby Performance Centre
 Singapore 159941
 Tel. 63190100 (Sales & Admin)
 63190111 (AfterSales)
 Fax. 64747770

180, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Tel. 63190888 (AfterSales)
 Fax. 63449773

319, Alexandra Road
 Rine Darby Business Centre
 Singapore 159944
 Tel. 63190538 (AfterSales)
 63190533/310 (Motorrad)
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

07 FEB 2018

Estimate No. : b1 45810	Page No. : 1 of 1
Date Estimated : 07/02/2018	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Troy Ng Bee Thong Wolskel Road singapore 358022	- ACCOUNT - 40000 Cash Sales - Service Singapore
----------------------------------------------------------------------------------	--------------------------------------------------------

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLA3331C	V791395	09/09/2016	216d CAT	0

DESCRIPTION

Replace rear bumper and remove attachment etc include knock on accident dent

VALUE
 850, ~~1,708.00~~

Spray painting on rear bumper

938, ~~1,058.00~~

To check electrical wiring systems and lightings at the rear section for proper function.

150, ~~177.00~~

Sundries. Nu

80.00

40.00

LKK A...

the Repair of ...

- To ...
- To ...
- Parts ...
- Third party ...
- No illegal ...
- Supplementary ...

Acknowledged by Repairer: _____
 Signature: _____
 Date: _____

Total Labour 1: 2,995.00

DESCRIPTION

REAR BUMPER PANEL PRIMED (PDC)
 REAR BUMPER CARRIER
 SUPPORT CENTER REAR BUMPER
 LEFT PROTECT FOIL
 RIGHT PROTECT FOIL
 SET MOUNTS PDC SENSOR REAR
 ULTRASONIC SENSOR MINERALWEISS(WA96)

QTY PRIC

1 966.25
 1 423.80
 1 37.35
 1 2.00
 1 2.00
 1 62.95
 4 368.80

VALUE

966.25
 423.80
 37.35
 2.00
 2.00
 62.95
 1,475.20

Total Parts : 2,969.55

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
 Date & Time 19/03/18 @ 1955 Excess 00
 Surveyor's Name RASUL Sign _____
 Surveyor's Tel 90010068 Authorized Yes/No _____
 Authorized Date _____ Time _____
 RESURVEY PARTS PHOTO BY SURVEYOR Yes/No _____

Labour 1	:	2,995.00
Parts	:	2,969.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	417.52
Grand Total	:	6,382.07

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
 ** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Straits Times Group
Co. Reg. No. 192401559W, GST Reg. No. M2-0020881-4



FINAL REPORT

Estimate No. : b1 45810
Date Estimated : 07/02/2018
Prepared By : Chua Kee Sin

Page No. :

#REPAIR FOR -
Troy Ng Bee Thong

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Wolskel Road

singapore 358022

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SLA3331C	V791395	09/09/2016	216d CAT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To make good the rear bumper include removing attachments to facilitate repairs and knocking out dents caused by the accident	850.00		850.00	
To spray paint rear bumper	934.00		934.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
Sundries.	40.00		40.00	
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT

SUPPLEMENTARY ITEMS

Total Labour :	1,974.00
Total Parts :	
Total Labour & Parts :	1,974.00
Deduction for Excess :	
Total Repair Costs less Excess:	1,974.00
GST @7%:	138.18
Grand Total :	2,112.18

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Monday, 19 February 2018 2:29 PM
To: 'PBSP'; Mei Kwan (LKKAuto)
Cc: Admin A
Subject: RE: REQ FOR DIRECT SETTLEMENT- SLA3331C AND SHF708R(AXA) ON 06/02/2017

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents for us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Tuesday, 13 February 2018 12:21 PM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: Re: REQ FOR DIRECT SETTLEMENT- SLA3331C AND SHF708R(AXA) ON 06/02/2017

Dear Motor Claims,

Please let us have your reply on liability.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Friday, 9 February 2018 11:45:56 AM
To: PBSP
Cc: 甯瑀 @; CS A Team
Subject: RE: REQ FOR DIRECT SETTLEMENT- SLA3331C AND SHF708R(AXA) ON 06/02/2017

Dear Caroline,

We refer to the above matter.

Please be informed that currently still pending for AXA's instruction.

We will check and revert to you in due course.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]
Sent: Friday, 9 February, 2018 10:36 AM
To: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: Fw: REQ FOR DIRECT SETTLEMENT- SLA3331C AND SHF708R(AXA) ON 06/02/2017

Dear Motor Claims,

Please let us have your reply on liability.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP
Sent: Wednesday, 7 February 2018 11:58 AM
To: motor.survey@axa.com.sg
Subject: REQ FOR DIRECT SETTLEMENT- SLA3331C AND SHF708R(AXA) ON 06/02/2017

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

Print Sent Message

This mail is associated with :

***SLA3331C (C0470022)**
[SHF708R]

TP
TROY NG BEE THONG
Feb 6 2018 6:00PM
[TRANS-CAB SERVICES PTE LTD]
Performance Motors Limited

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 18/10/2018 12:14 PM.
To richard.angbs@axa.com.sg; stacey.ng@axa.com.sg
CC AXA_SG; ashersng@lkkauto.com
Subject [MANDATE REQUEST] Re: New TP Assignment - C0470022/P1680520

Hi Sir,

We refer to the above matter.

The accident occurred when insured rear ended third party vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer at \$2,262.18 (all-in).

For your approval in merimen please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<-- Original Message -->

From: AXA_SG

To: LKK_HQ;sur@lkkauto.com;assignments@lkkauto.com

CC: AXA_SG

Sent On: 12/02/2018 10:30 PM

Subject: New TP Assignment - C0470022/P1680520

Dear LKK Auto Consultants Pte Ltd,

Please survey the vehicle and proceed for direct settlement if damages consistent.

Workshop Name: Performance Motors Limited

Policy Number: P1680520

Vehicle Number: SLA3331C

Date of Accident:06/02/2018

Estimated Claim Amount:

Excess: 5000.00

Claim Handler Name: Stacey Ng

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S6922570E

Name: TROY NG BEE THONG

Birth Date: 04 Jul 1969

Issue Date: 21 Jun 2012



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S6922570E



Name: TROY NG BEE THONG

Race: CHINESE

Date of birth: 04-07-1969

Sex: M

S6922570E



Country/Place of birth: SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg

EFFECTIVE DATE

14 Apr 1969



Licence No: S6922570E

NP 428A

5544291



NRIC No: S6922570E



Date of issue: 10-12-2018

Address: 237 WOLSKEL ROAD
SINGAPORE 358022



FA7

AXA Insurance Pte Ltd
8 Shenton Way
#27-01
Singapore 068811
Attention: Motor Claims

"Without Prejudice"

Your Ref:

Our Ref:

Date:

Subject:

02 August 2018

ACCIDENT INVOLVING VEHICLES SLA3331C & SHF708R ON 06.02.2018

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	:	S\$	2112.18
Loss of use	:	S\$	150.00 (S\$ 50.00 x 3 days)
Total	:	S\$	2262.18

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill
3. Copy of Identification Card & Driving License
4. Copy of Letter of Authorisation

Performance Motors
Limited
1800-Call-BMW
(1800-2255-2618)

www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel AfterSales
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel AfterSales
6319 0527
Fax 6479 6824

380
Kampong Ayer Rd
East Coast Centre
Singapore 438180
Tel AfterSales
6319 0888
Fax 6344 1332

Registered office
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No.
197401559A

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

Teng Wai Khan
Customer Service Manager, Body & Paint

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 27 February 2018 3:48 PM
To: 'claims@transcab.com.sg'
Cc: 'carrisalee@ava-ins.com'; 'icewong@ava-ins.com'; 'ireneng@ava-ins.com'; 'foonghon@ava-ins.com'
Subject: ACCIDENT INVOLVING SHF 708R & SLA 3331C ALONG/AT BKE BEFORE SLE SLIPROAD ON 06/02/2018

27 FEB 2018

Transcab Taxi
Singapore

Dear Sir,

OUR REF : CC4/AXA18002874/ea3
YOUR REF : P1680520 (SHF 708R)
ACCIDENT INVOLVING SHF 708R & SLA 3331C ALONG/AT BKE BEFORE SLE SLIPROAD ON 06/02/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy. We also wish to advise that there is an excess of **S\$5000.00** attached with Third Party Claims.

As Insurers, AXA shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following to cst@axa.com.sg **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons

in connection with this accident, please forward it to us immediately. You may email it to cst@axa.com.sg or deliver it by hand to our Customer Care Centre.

- This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact our Claims Service Team at 1800-880 4888 at our operating hours 9:00am to 5:30pm or cst@axa.com.sg. Please quote our claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants

phone: 6841-6051 | email: ashersng@lkkauto.com |

fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This is a computer generated letter and no signature is required.

cc Motor Claims Department
AXA Insurance Pte Ltd

LETTER OF AUTHORISATION

ACCIDENT INVOLVING SLA 3331C & SHF 708R ON 6.2.2018

I, Troy Ng Bee Thang owner of Vehicle Registration No. SLA 3331C
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.

Signed by:


Name: Troy Ng Bee Thang (Date) 7/2/18
NRIC No.: S6922570E

In the presence of:

CHUA KEE SIN
Performance Motors Limited
303 Aljunied Road
Sime Darby Performance Centre
Singapore 150141


Name: CHUA KEE SIN (Date) 7/2/2018
NRIC No.: @ 1046hw



redefining / insurance



CLAIM REF : L0470001
INSURED : TONY NG, SINGAPORE PTE LTD

DISCHARGE VOUCHER

We/I [Tony Ng, Pte. Lim.], NRIC NO. S4035108 hereby agree to accept the sum of dollars [Two thousand two hundred sixty two and cents eighteen only] (S\$ 2,262.18), paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. [S1E 708C] as a result of an accident along [KJE] on [06.02.2018] of which we/I were/was the driver/ owner/ hirer/ passenger/ rider/ pillion/ insurer of motor vehicle no. [S1A 353AC].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. [S1E 708C] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [S1E 708C].

Dated this 1st day of Nov 2017

Claimant's Signature : _____

NRIC no./ Company Stamp : _____

Occupation/ Business : _____

Address : _____

Telephone No. : _____

Witness's Name : _____

Witness's Signature : _____

Witness's NRIC No. : _____

[Handwritten signature of Tony Ng]
Tony Ng
S4035108

CHUA ICE SIN
S1E 708C
[Handwritten signature of witness]

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401519M GST Reg. No M2-0020081-z

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438100
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190529 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



SERVICE TAX INVOICE

Repair Order No. : B1 1251855	Page No. : 1 of 1
Date IN : 19/03/2018	Invoice Number : 1990976 / WSB
Cust. Svc. Advisor: Chua Kee Sin	Invoice Date : 26/07/2018
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mr Troy Ng Bee Thong

237.00

Wolskel Road

singapore 358022

- INVOICE TO - 238

AXA Insurance Pte Ltd

8 Shenton Way

#24-01 AXA Tower

Singapore 068811

REGN. NO. SLA3331C	CHASSIS NO. V791395	REGN. DATE 09/09/2016	MODEL 216D CAT	MILEAGE 40146
-----------------------	------------------------	--------------------------	-------------------	------------------

- - - - LABOUR 1 - - - -

	NETT
To make good the rear bumper including to remove and install body parts in order to carry out painting job.	850.00
To respray rear bumper.	934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00
Sundries.	40.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 6.2.2018. 3RD PARTY CAR : SHF708R.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO CONSULTANTS PTE LTD ON 19.3.2018 AT 1.55 PM. AUTHORISED REPAIR BY MS ASHER SNG FROM LKK ON 19.2.2018 VIA E-MAIL.	
PROPOSE LOSS OF USE = \$50X3. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00
Total Labour 1:	1,974.00

Labour Charges : 1,934.00	Total Labour & Parts Charges : S\$ 1,974.00
Parts Charges : 0.00	Less Insurance Excess : S\$ 0.00
Lubricant/Misc : 40.00	Invoice Total Amount Exclude GST : S\$ 1,974.00
	GST @ 7% : S\$ 138.18
	Invoice Total Amount Include GST : S\$ 2,112.18

Computer generated invoice. No signature is required.

Amount Payable Include GST : S\$ 2,112.18

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Feb 2018		12 Feb 2018 22:30 Edit Adj Rpt	S\$1,974.00 Edit Estimates	S\$1,974.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878X								
Main Claimant:	TROY NG BEE THONG , ID: S6922570E								
Vehicle Reg. No.:	SLA3331C	Date of Loss:	06/02/2018 18:00 - :59 [16 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0470022	Policy/Cover Note No.:	P1680520 (Third Party Only)						
Vehicle Reg. No. (Insured):	SHF708R	Policy No. (Claimant):	-						
		Excess:	S\$5,000.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Stacey Ng - 6880 4351]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 22/02/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AXA_SG (07/11/2018): Alert - Adj Mandate Approved (S\$2262.18) - SLA3331C - Claim Handler: Stacey Ng AXA_SG (12/02/2018): New TP Assignment - C0470022/P1680520 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLA3331C (C0470022)
[SHF708R]
TP
TROY NG BEE THONG
Feb 6 2018 6:00PM
[TRANS-CAB SERVICES PTE LTD]
Performance Motors Limited

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser v		
Letters/Correspondences										1 per page v	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit			
Assessment Reports										1 per page v	<input checked="" type="checkbox"/>	
No	Finalized On	AXA Insurance Pte Ltd (HQ)						Thumbnail	Print			
1	12/02/18 22:29	Accident Statement <small>Front:SC - Reg. No: SHF708R, Claimant: TRANS-CAB SERVICES PTE LTD</small>							Load HTM			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	20/03/18 19:26	Adjuster Immediate Advice							Load HTM			
Photos/Images										3 per page v	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	19/07/18 14:27	LKK Survey Photo							Load PDF			
Documentation										1 per page v	<input checked="" type="checkbox"/>	
No	Finalized On	AXA Insurance Pte Ltd (HQ)						Thumbnail	Print			
1	07/02/18 12:36	EMAIL_ABS							Load PDF			
2	07/02/18 12:36	ESTIMATE_ABS							Load TIF			
3	07/02/18 12:36	TP GIA REPORT_ABS							Load PDF			
4	07/02/18 12:39	MAIL TO TP_ABS							Load PDF			
5	07/02/18 13:36	MAIL FROM TP_ABS							Load PDF			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	27/02/18 15:48	LETTER TO OI							Load PDF			
2	21/03/18 11:49	TP ESTIMATE - MARKED							Load PDF			
3	18/10/18 12:12	Immediate Advice with Mandate							Load PDF			
4	19/11/18 08:18	WORKSHOP INVOICE							Load PDF			
5	19/11/18 08:18	AUTHORISATION TO ACT FORM							Load PDF			
6	19/11/18 08:18	DISCHARGE VOUCHER							Load PDF			
7	19/11/18 08:18	LOD							Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)					
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>					
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>					

LKK Auto Consultants Pte Ltd

(Co. Reg. No. 199807198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18002874/R1EA3Q2
Date: 19/11/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd	Policy No: P1680520	
Claimant Vehicle No : SLA3331C	Insured Vehicle No : SHF708R	
Date of Loss: 06/02/2018	Nature of Claim: TP	Claim No: C0470022

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA3331C		
Make & Model:	BMW 216D, 1.5 D Active Tourer (F45) (A)	Engine No:	32519652B37C15A
Reg. Date:	09/09/2016 (Man. Year: 2016)	Chassis No:	WBA2B320X0V791395
Colour:	White	Odometer:	32252 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,049.55	40.00	3,009.55	98.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,915.00	1,934.00	981.00	33.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,964.55	1,974.00	3,990.55	66.90
+ GST 7.00/7.00% (S\$)	417.52	138.18	279.34	66.90
Nett Amount (S\$)	6,382.07	2,112.18	4,269.89	66.90
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
	Nett Liability (S\$)	2,262.18		

INSPECTION

Date of Assignment:	12/02/2018	
Date Inspected:	19/03/2018 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2018)
Parts: M1-MPV	BMW 216D 1.5 D Active Tourer (F45) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA3331C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUDNRIES (CONSISTENT)	Necessary	80.00 F	*40.00 F
2	1		*REAR BUMPER PANEL PRIMED (PDC) (CONSISTENT)	Repair	966.25 F	*- F
3	1		*REAR BUMPER CARRIER (CONSISTENT)	Not Necessary	423.80 F	*- F
4	1		*SUPPORT CENTER REAR BUMPER (CONSISTENT)	Not Necessary	37.35 F	*- F
5	1		*LEFT PROTECT FOIL (CONSISTENT)	Not Necessary	2.00 F	*- F
6	1		*RIGHT PROTECT FOIL (CONSISTENT)	Not Necessary	2.00 F	*- F
7	1		*SET MOUNTS PDC SENSOR REAR (CONSISTENT)	Not Necessary	62.95 F	*- F
8	4		*ULTRASONIC SENSOR MINERALWEISS (WA96)	Not Necessary	1,475.20 F	*- F
Total Parts (S\$)					3,049.55	40.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT	New	1,700.00	850.00
2	SPRAY PAINTING ON REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			2,915.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >