

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)SHP (COP)
12/3 10am

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

13 FEB 2018

Estimate No. : b1 45916
Date Estimated : 13/02/2018
Prepared By : Merina Chia San San

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -Cheong Gim Hin Samuel
36 Tomlinson Road
#12-42

Singapore 247856

- ACCOUNT - 40000Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT2999S	P836839	30/12/2015	216d G TOURER	0

DESCRIPTIONVALUETo replace rear bumper, bootlid including attachments
etc and to knock out dented area caused by accident~~1700 2,580.00~~

To paint rear bumper and bootlid

~~1731 1,923.00~~To remove and install boot compartment carpet and garnish
to facilitate repairs.~~X 271.00~~To check electrical wiring systems and lightings at the
rear section for proper function.~~150 177.00~~To transfer lock mechanism from old to new bootlid
including conduct checks on new bootlid central locking
system for proper function.~~451 531.00~~

To replace rear windscreen glass

~~? 574.00~~

To conduct water leak test.

~~? 75.00~~

To supply and install front or rear windscreen solar film.

~~? 531.00~~

Sundries.

~~? 150.00~~Total Labour 1: **6,782.00**DESCRIPTIONQTY PRICVALUE

BOOTLID

1 1,174.95

~~1,174.95~~

LH TRUNK LID HINGE

1 75.90

~~? 75.90~~

RH TRUNK LID HINGE

1 75.90

~~? 75.90~~

RR BUMPER LH SIDE GUIDE

1 60.00

~~? 60.00~~

RR BUMPER RH SIDE GUIDE

1 60.00

~~? 60.00~~

REAR BUMPER CARRIER

1 423.80

~~? 423.80~~

SUPPORT

1 59.25

~~? 59.25~~

RR BUMPER LH INNER SIDE GUIDE

1 65.90

~~? 65.90~~

RR BUMPER RH INNER SIDE GUIDE

1 65.90

~~? 65.90~~

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45916
Date Estimated : 13/02/2018
Prepared By : Merina Chia San San

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT2999S	P836839	30/12/2015	216d G TOURER	0

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER TRIM STRIP (CHROM)	1	105.65	105.65
REAR BUMPER PANEL PRIMED (LINES PDC	1	966.25	966.25
REAR BUMPER TOWING FLAP EYE PRIMED	1	41.80	41.80
BADGE (BMW)	1	69.50	69.50
STRIKER BOOT LID	1	55.75	55.75
LOCK TRUNK LID	1	189.10	189.10
ACTUATION UNIT	1	586.65	586.65
REAR WINDOW	1	655.40	655.40
HOOK AND LOOP FASTENER	8	2.80	22.40
BOOTLID SEALING	1	91.65	91.65
ULTRASONIC SENSOR BLACK	2	248.70	497.40
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20
Bracket	1	35.80	35.80
(DG) CLEANER R1 (100ML)	1	23.85	23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85

Total Parts : 5,713.95

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 12/03/18 @ 1100 Excess S\$ _____Surveyor's Name Rashid Sign _____Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommended 5-6 days

Labour 1 : 6,782.00

Parts : 5,713.95

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 874.72

Grand Total : 13,370.67

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **