



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 24/12/2018

### Survey Details:

Date of loss	5-Feb-18
Date of appointment	12-Feb-18
Date of survey	14-Feb-18
Location of survey	AH LIM MOTOR COMPANY

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SDV 618E
Make and Model	MERCEDES BENZ SLK200 AK - 1796cc
Date of registration	3-Oct-08
Excess	
Market Value (est)	\$0.00
Parf Rebate (est)	\$0.00
Nett Loss (est)	\$0.00

### Repair details:

Initial Estimate	\$ 1,902.40
------------------	-------------

### Proposed/Revised repair cost:

Parts	\$ 110.40
Check items (estimate)	\$ -
Labour	\$ 610.00
<b>Total</b>	<b>\$ 720.40</b>
<b>Lump Sum(if applicable)</b>	<b>\$ -</b>

Number of days for repair	<u>2 DAYS</u>
---------------------------	---------------



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

*We have not authorized repairs. CONFLICTIN VERSIONS. Both drivers reported that the other vehicle cut lane. An email were sent out to the Insured to notify TP claim and NCD issues. No evidence from both parties. TP LOD IN. For mandate approval.*

**Mandate:**

Liability(TP)	50%	
Proposed Repair Cost	\$ 770.83	w/gst
Loss of Use	\$ 100.00	\$100 x 2 days
Loss of Rental	\$ -	no. of days
Loss of Income	\$ -	no. of days
LTA search fees	\$ 7.45	
Others	\$ -	
<b>Proposed Total</b>	<b>\$ 878.28</b>	
	<b>\$ 492.87</b>	<b>50%</b>