

SUPREME AUTO SERVICE PTE LTD

176 Sin Ming Drive, #02-01 Sin Ming Autocare Singapore 575721

•Tel: 6452 8211 • Fax: 6451 7420

ALG Asia Pacific Insurance P/L

Attn: Motor Claims Department

12/2/18

Dear Sir,

RE : Request for PRI for SKZ 8376K **in an accident involving** SKS 7909C
@ New Bridge Rd, opp Chinatown point on 12/1/17 @ 1320 hrs.

We have been authorised by McQueen Rentals P/L, the registered owner of motor vehicle: SKZ 8376K at the material time of accident to make a claim against your insured.

Please give us the list of panel of your 10 survey firms for our selection to inspect the above said vehicle or you may assign our choice from either one of the 3 survey firms,

- 1) Premier Appraiser Services
- 2) LKK Auto Consultants Pte Ltd
- 3) AJAX Inspection Services Pte Ltd

We will direct settle the claims with you if the survey is conduct by either of one the firms mentioned.

Kindly contact us at 64528211 before coming to ensure the vehicle is in the workshop.

Thank you.

Yours Sincerely,




Supreme Auto Service Pte Ltd
Email: admin@supremc.sg

SKETCH PLAN

A. SK28576K

B. SK57909C



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along new bridge road on lane one. As I was approaching chicktown point, I decided to change from lane 1 to 2 due to the congestion. I did all the necessary checks and slowly moved into my lane. I then proceeded to lane 2 which was clear and safe to do so. My car was then hit by SK57909C which was changing lane from 3 to 2. Under no circumstances was I able to see SK57909C approaching but on the contrary, SK57909C was able to see me slowly moving into my lane.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: