

**COMFORTDELGRO ENGINEERING PTE LTD**  
**REPAIR ESTIMATE\***

*Ju.*

VEHICLE NO : SHA 2050S

*AIG/LKK*  
*Rear*

DATE 12/2/2018 13:56

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover ✓			\$ 225.00
	<b>SUB TOTAL</b>			<b>\$ 1,907.35</b>
	<b>LESS 20%</b>			<b>\$ 381.47</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,525.88</b>
	Rear Bumper Reverse Sensor X			\$ 135.70 <b>Nett</b>
	Rear Bumper Advertisement Logo ✓			\$ 50.00 <b>Nett</b>
				<b>\$ 185.70</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>380.00</del> <sup>200</sup>
	Spray Painting Charge			\$ <del>200.00</del> <sup>180</sup>
	Wiring Charge			\$ <del>50.00</del> X
	R/Refix Reverse Sensor			\$ <del>120.00</del> X
	<b>TOTAL LABOUR</b>			<b>\$ 750.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,461.58</b>

*Kalun LKK*  
*12/2/18 1500h*  
*2 Days*  
*43*  
*After Repair photo*

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplementary items must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.