



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: JHMGK5850GX201197
License No: SKX4515Z
Mileage: 31975
Engine No: L15B31020354

Document No: SVO18009625
Printed By: JASONHENG
Order Date: 14. February 2018
Order Time: 12:27:52 PM
Service Advisor: JASON HENG

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	THIRD PARTY CLAIMS (J/NO: 10342)						
	OWNER: TAN KIAN WEE KENNETH						
	OWNER INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 2/2/18						
	SURVEYED BY:						
	DATE:						
	TP INSURER:						
	TP VEH:						
	ADDITIONAL PART						
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.20 ✓	25	8.40	0.59	8.99
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.30 ✓	25	9.45	0.66	10.11
73226-SZW-000	DAMPERSTD 5X5	1	8.30 ✓	25	6.22	0.44	6.66
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00 ✓		120.00	8.40	128.40
04715-T5B-000ZZ	FACERR.BUMPER	1	492.60 ✓	25	369.45	25.86	395.31
71507-T5A-000	GARNISHL.RR.BUMPER	1	14.00 ✓	25	10.50	0.74	11.24
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50 ✓	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50 ✓	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	5	2.00 ✓	25	7.50	0.53	8.03
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00 ✓		320.00	22.40	342.40
74940-TZ5-A01	BUZZER ASSYSMART	1	59.30 ✓	25	44.47	3.11	47.58
38387-TZ5-A01	ANTENNA ASSYL.F.	1	58.10 ✓	25	43.57	3.05	46.62
68100-TAS-Z50ZZ	TAILGATE COMP	1	716.30 ✓	25	537.22	37.61	574.83
75722-T5L-T01	EMBLEMRR.	1	10.50 ✓	25	7.87	0.55	8.42
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30 ✓	25	69.22	4.85	74.07
74800-T5S-K61	LOCK ASSY,TAILGATE	1	77.10 ✓	25	57.82	4.05	61.87
66100-TAR-T10ZZ	PANEL COMPRR.	1	314.00 ✓	25	235.50	16.49	251.99
84640-T5A-003ZA	LINING ASSYRR.PANEL	1	60.80 ✓	25	45.60	3.19	48.79
33550-T5A-J02	TAILLIGHT ASSYL.	1	217.40 ✓	25	163.05	11.41	174.46
04711-T5A-000ZZ	FACEFR.BUMPER	1	494.70 ✓	25	371.02	25.97	396.99
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	2	45.00 ✓		90.00	6.30	96.30
71145-T5A-000	BASEFR.LICENCE PLATE	1	50.90 ✓	25	38.17	2.67	40.84
71193-T5A-000	SPACERR.FR.BUMPER	1	10.40 ✓	25	7.80	0.55	8.35
71198-T5A-000	SPACERL.FR.BUMPER	1	10.40 ✓	25	7.80	0.55	8.35
91505-TM8-003	CLIPBUMPER	17	2.00 ✓	25	25.50	1.79	27.29
33150-T5A-J21	HEADLIGHT ASSYL.	1	1,118.60 ✓	25	838.95	58.73	897.68
71140-T5A-000	BRACKETR.HEADLIGHT	1	23.60 ✓	25	17.70	1.24	18.94
71190-T5A-000	BRACKETL.HEADLIGHT	1	21.90 ✓	25	16.42	1.15	17.57
71120-TAS-003	GRILLE ASSYFR.	1	288.90 ✓	25	216.67	15.17	231.84
71130-T5A-000ZZ	BEAM COMPFR.BUMPER	1	219.40 ✓	25	164.55	11.52	176.07
60400-T5B-310ZZ	BULKHEAD COMPFR.	1	374.30 ✓	25	280.72	19.65	300.37
80100-T5B-003	CONDENSER ASSY	1	704.40 ✓	25	528.30	36.98	565.28
08CLA-P9911LK8	COOLANTANTI-FREEZE	5	23.20 ?	25	87.00	6.09	93.09
84441-T5A-003ZB	POCKETTAILGATE LINING PULL	1	5.00 S	25	3.75	0.26	4.01
	SUM PARTS:				4,767.43	333.75	5,101.18
BOSUN		1	50.00 ✓		50.00	3.50	53.50



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: JHMGK5850GX201197
License No: SKX4515Z
Mileage: 31975
Engine No: L15B31020354

Document No: SVO18009625
Printed By: JASONHENG
Order Date: 14. February 2018
Order Time: 12:27:52 PM
Service Advisor: JASON HENG

	SUNDRIES						
BG02R		1	280.00	✓	280.00	19.60	299.60
	REPLACE RR. WINDSCREEN.(N)						
BODAMKIT		1	80.00	✓	80.00	5.60	85.60
	WINDSCREEN DAM KIT.						
BML01I		1	140.00	✓	140.00	9.80	149.80
	INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)						
BML02I		1	140.00	✓	140.00	9.80	149.80
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BA02R		1	120.00	✓	120.00	8.40	128.40
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BOJSE		1	80.00	✓	80.00	5.60	85.60
	BODY JOINT SEALANT FOR TAILGATE						
BOJSE		1	80.00	✓	80.00	5.60	85.60
	BODY JOINT SEALANT FOR END PANEL						
BOMISC1		1	160.00	✓	160.00	11.20	171.20
	RESET & CALIBRATE SMART ENTRY SYSTEM (N)						
BOMISC1		1	160.00	✓	160.00	11.20	171.20
	RESET & CALIBRATE REAR VIEW CAMERA (N)						
BKTG02R		1	560.00	✓	560.00	39.20	599.20
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)						
BMI03D		1	420.00	✓	420.00	29.40	449.40
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)						
BMA01D		1	280.00	✓	280.00	19.60	299.60
	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS. VACUUM & RECHARGE A/C GAS.(N)						
BMC01D		1	230.00	✓	230.00	16.10	246.10
	REMOVE & INSTALL RADIATOR WITH FITTINGS. PRESSURE TEST COOLING SYSTEM.(N)						
BKRP02M		1	2,240.00	✓	2,240.00	156.80	2,396.80
	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.						
BP05R		1	2,250.00	✓	2,250.00	157.50	2,407.50
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZM003 / MSIG INSURANCE
Chassis No: JHMGK5850GX201197
License No: SKX4515Z
Mileage: 31975
Engine No: L15B31020354

Document No: SVO18009625
Printed By: JASONHENG
Order Date: 14. February 2018
Order Time: 12:27:52 PM
Service Advisor: JASON HENG

BKBH01M	CUT OFF & RENEW BULKHEAD. STRAIGHTEN ALIGN CHASSIS & RENEW DAMAGE PARTS.	1	2,240.00 ✓	2,240.00	156.80	2,396.80
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	2,250.00 ✓	2,250.00	157.50	2,407.50
SUM LABOUR:				11,760.00	823.20	12,583.20
TOTAL SGD				16,527.43	1,156.95	17,684.38

Total Payable (SGD) **17,684.38**

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: S8500377A / TAN KIAN WEE
Chassis No: JHMGK5850GX201197
License No: SKX4515Z
Mileage: 31975
Engine No: L15B31020354

Document No: SVO18009625
Printed By: JASONHENG
Order Date: 14. February 2018
Order Time: 12:27:52 PM
Service Advisor: JASON HENG

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	SUPPLEMENTARY PARTS						
84441-T5A-003ZB	POCKETTAILGATE LINING PULL	1	5.00	25	3.75	0.26	4.01
	SUM PARTS:				3.75	0.26	4.01
	TOTAL SGD				3.75	0.26	4.01
	Total Payable (SGD)						4.01

GST Amount is calculated from individual line(s)