

Smaller

REF:

ALG AXA ALG.

CC3/ALH18002944/Grber

ASSIGNMENT

From: _____ Date: 05-01-2017

Estimated Cost: _____

OD / PR / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLK 7667E

at Workshop m/s Premium

of 55 Ubi Road 1

Insured: _____

Policy No. 2100 495812-00000

Claims No. 2048035928 SG

Sum Insured: _____ Excess: \$600

(Client's Record)

Make of Veh: _____

(Policy Condition)

4pm

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$120k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLK 7667E Yr Regn: 27 Dec 2016

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 cc 999

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 3197 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: UAU888 SL8H 1028102

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. _____ D.O.I. 05-04-17

Survey held at w/s 4pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Confirm \$5808, 6 days
Red: \$14699, 72h.

W 2 Invoice received

RECEIVED 5 FEB 2018

Date/Time: File Pass to?

☐

: Preli. Report

1) typist

☒

: Final Report

Date/Time: File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: -

Survey Fee: 200

Transportation: _____

) \$ + RS \$ _____

) Photos 10

) Others _____

TOTAL

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Report Format: OD

Lump Sum / I.B.I.: (\$ 5808)

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18002994/Grb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 14-02-2018



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLK 7667E
Policy No. 2100495812	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	05/04/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 27/03/2017	Inspection Date 05/04/2017
Survey held at PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/03/2017 18:09
Date Of Accident	27/03/2017 07:00
Exact Location Of Accident	MANDAI EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK7667E
Insured/Policyholder	
Name Of Registered Owner	MARINA BINTE ABU BAKAR
NRIC No	S7616041D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96616946
Alternative Phone No	Others-96616946

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.0 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100495812-00000
Cover Note Number	

Driver

Name of Driver	MARINA BINTE ABU BAKAR
NRIC No	S7616041D
Date Of Birth	25/05/1976
Occupation	INDOOR
Date Of Driving Pass	12/05/2007
Driving Experience	9 YEARS AND 10 MONTHS

Gender	FEMALE
Mobile Number	(LOCAL) +65-96616946
Fax Number	
Contact Number	OTHERS-96616946
E-Mail Address	NOEMAIL
Address	95 YISHUN AVE 1 #01-28
Postcode	S769137
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	UNKNOWN - TP HIT INSURED ON RHS REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ON THE LEFT LANE ALONG MANDAI ROAD WHEN SUDDENLY I FELT AN IMPACT AT MY VEHICLE'S REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC4030G
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	

1. 2. 3.

Address

Postcode

Insurance Company Name

AXA Insurance Pte Ltd

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A > SLK 100 TE
B > FC 4030 G

Alarida Ex 4

Sketch Plan #2

Describe Circumstances of the Accident

I was driving on the left lane along Mandai Road when suddenly I felt an impact at my vehicle's rear portion.

Declaration

We declare the foregoing particulars are true in every respect

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: UPA117-42351 Vehicle Registration No: SLK 7667E
Name(as shown in NRIC): MARINA BINTE ABU BAKAR
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
NRIC/Passport No: S7616041 D
Address: 95 YISHUN AVE. 1 #01-28 THE ESTUARY S(769137)
Contact (Tel): - (M/P): 96616946
(Email): rinmab@gmail.com
Date of Accident: 21/03/2017 Time of Accident: after h
Place of Accident: Marina Fall
Insurance Company: AIG

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

to change my report from a third party claim to claiming my own
policy.

[Signature]
Signature of Vehicle Owner / Driver

Date: 15 Aug 2017

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7616041D



Name

MARINA BINTE ABU BAKAR



مارينا بنت ابو باكر

Race

MALAY

Date of Birth

25-05-1976

Sex

F

Country of Birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



25 May 1976

12 May 2007



3337514

NRIC No. S7616041D



Blood Group

Date of issue

17-03-2003

95 YISHUN AVENUE 1 #01-28
SINGAPORE 769137

S7616041D

19/02/2014

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3A Motor cars without clutch pedals (Auto) <= 3000kg 12 May 2007
with <= 7 passengers, exclusive of the driver; and
other motor vehicles without clutch pedals <= 2500kg

NP 428A





HOTLINE TEL: (65) 6419 3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

OWN DAMAGE EXCESS S\$600.00 (1)
WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

CERTIFICATE NO. 2100495812-00000

SUM INSURED Market Value
INSURING WITH COE/PARF Yes

- 1) VEHICLE REGISTRATION NO. SLK7667E
2) NAME OF INSURED MARINA BINTE ABU BAKAR
3) EFFECTIVE DATE OF THE COMMENCEMENT 27 Dec 2016
OF INSURANCE FOR THE PURPOSES OF THE ACT
4) DATE OF EXPIRY OF INSURANCE 26 Dec 2017
5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *

SUBJECT TO AGE CONDITION :All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER NA

HIRE PURCHASE COMPANY United Overseas Bank Limited
/ EMPLOYER'S LOAN

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 10 Jan 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-265
PREMIUM LEASING -CKK
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE
CENTRE SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

PRLLYY.

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 6041D

Vehicle Details

Vehicle No.: SLK7667E

Vehicle to be Exported: No

Intended De-registration Date: 25 Aug 2017

Vehicle Make: AUDI

Vehicle Model: A3 SEDAN 1.0 TFSI S TRONIC (LED)

Primary Colour: Red

Manufacturing Year: 2016

Engine No.: CHZ158624

Chassis No.: WAUZZZ8V8H1028102

Maximum Power Output: 85.0 kW (113 bhp)

Open Market Value: \$24,592.00

Original Registration Date: 27 Dec 2016

First Registration Date: 27 Dec 2016

Transfer Count: 0

Actual ARF Paid: \$16,429.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 26 Dec 2026

PARF Rebate Amount: \$12,321.00

Intended COE Rebate Details

COE Expiry Date: 26 Dec 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$49,751.00

COE Rebate Amount: \$46,447.00

Total Rebate Amount: \$58,768.00

The information contained herein is correct as at 25 Aug 2017

OK

Land Transport  Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 20 Aug 2017 at 12:36 AM

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0307/2017/JT
Date	:	15-Aug-17

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Marina Binte Abu Bakar
Address	:	95 Yishun Avenue 1 #01-28 Singapore 769137
Telephone	:	(HP) 96616946
Type of Claim	:	Own Damage Claims
Policy No.	:	2100495812-00000
Vehicle No	:	SLK 7667 E
Model Code	:	Audi A3 SEDAN 1.0 TFSI
Model / Year	:	Dec-16
Engine No	:	CHZ 158624
Chassis No	:	WAUZZZ8V8H1028102
Mileage	:	-
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	27-Mar-17
Place of Accident	:	Mandai Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLK 7667 E.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00	/ /
2	To renew rhs 1/4 glass and rear windscreen to facillitate fender renewal.	S/N \$ 600.00	X NN
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00	700 /
4	To remove and reinstall rear seat, back tray, abcd pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00	X NN
5	To dismantle rear bumper and rear lid. Cut out and reweld rhs rear fender. Renew rear bumper. Reinstall all parts removed.	\$ 4,800.00	2000 /
6	To respray rear bumper, rhs rear fender, rhs sill panel, door entrance, drain panel, roof channel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 4,100.00	1650 /
7	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00	/ /
8	To carry out diagnostic checks.	S/N \$ 192.00	/ /
TOTAL LABOUR CHARGES		: \$ 13,052.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 7667 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER X Repair X NN	\$ 1,567.00	
2	REAR BUMPER GUIDE - RH	\$ 54.00	
3	REAR FENDER - RH X Repair	\$ 1,938.00	
4	REAR WHEEL HOUSING LINER - RH X	\$ 208.00	
5	WHEEL HOUSING LINER ATTACHMENT PARTS X	\$ 75.00	
6	REAR 1/4 GLASS - RH X	\$ 455.00	
7	REAR WINDSCREEN X	\$ 675.00	
8	GLASS PRIMER X	2 \$ 36.00	
9	REAR FENDER SOUND ABSORBER X NN	\$ 213.00	
10	ROOF MOLDING CLIP SET X	\$ 51.00	
11	REAR SEAT GROMMET SET X	\$ 45.00	
12	ALUMINIUM RIM - RH REAR X - Cut	\$ 658.00	526.00
13	1/4 GLASS SEALANT X	S/N \$ 100.00	
14	REAR WINDSCREEN SEALANT X	S/N \$ 200.00	
15	ACRYLIC SEALER X / MBL. NN	S/N \$ 180.00	150
16	CAVITY WAX X	S/N \$ 140.00	
17	STONE CHIP X	S/N \$ 180.00	
18	METAL FILLER POWDER X	S/N \$ 280.00	
19	SUNDRIES X NN	\$ 400.00	
TOTAL SPARE PARTS		: \$ 7,455.00	
TOTAL LABOUR CHARGES		: \$ 13,052.00	
GRAND TOTAL		: \$ 20,507.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Gue Qiang.
Surveyed Date :
Authorised Date : 05/4/17
Excess Cost :
Liability : before permit photo & after paint photos
Remarks : 6 ~~7~~ Days.
Authorise Repair

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg


Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0307/2017/JT
Date : 15-Aug-17

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120



Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Marina Binte Abu Bakar
Address : 95 Yishun Avenue 1
#01-28
Singapore 769137
Telephone : (HP) 96616946
Type of Claim : Own Damage Claims
Policy No. : 2100495812-00000
Vehicle No : **SLK 7667 E**
Model Code : Audi A3 SEDAN 1.0 TFSI
Model / Year : Dec-16
Engine No : CHZ 158624
Chassis No : WAUZZZ8V8H1028102
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Mar-17
Place of Accident : Mandai Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLK 7667 E.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$	280.00	\$ 280.00
2	To renew rhs 1/4 glass and rear windscreen to facillitate fender renewal.	S/N \$	600.00	nn
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	\$ 700.00
4	To remove and reinstall rear seat, back tray, abcd pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbag etc.	S/N \$	1,400.00	nn
5	To dismantle rear bumper and rear lid. Cut out and reweld rhs rear fender. Renew rear bumper. Reinstall all parts removed.	\$	4,800.00	\$ 2,000.00
6	To respray rear bumper, rhs rear fender, rhs sill panel, door entrance, drain panel, roof channel and end panelling. To carry out stone chip treatment and joint sealer works.	\$	4,100.00	\$ 1,650.00
7	To renew rhs rear rim and carry out wheel alignment.	S/N \$	280.00	\$ 280.00
8	To carry out diagnostic checks.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 13,052.00	\$ 5,102.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 7667 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,567.00	
2	REAR BUMPER GUIDE - RH	\$ 54.00	
3	REAR FENDER - RH	\$ 1,938.00	
4	REAR WHEEL HOUSING LINER - RH	\$ 208.00	
5	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 75.00	
6	REAR 1/4 GLASS - RH	\$ 455.00	
7	REAR WINDSCREEN	\$ 675.00	
8	GLASS PRIMER	2 \$ 36.00	
9	REAR FENDER SOUND ABSORBER	\$ 213.00	
10	ROOF MOLDING CLIP SET	\$ 51.00	
11	REAR SEAT GROMMET SET	\$ 45.00	
12	ALUMINIUM RIM - RH REAR	\$ 658.00	\$ 526.00
13	1/4 GLASS SEALANT	S/N \$ 100.00	
14	REAR WINDSCREEN SEALANT	S/N \$ 200.00	
15	ACRYLIC SEALER - (<i>Nec - fender opened for repair</i>)	S/N \$ 180.00	\$ 180.00
16	CAVITY WAX	S/N \$ 140.00	
17	STONE CHIP	S/N \$ 180.00	
18	METAL FILLER POWDER	S/N \$ 280.00	
19	SUNDRIES	\$ 400.00	
TOTAL SPARE PARTS		: \$ 7,455.00	\$ 706.00
TOTAL LABOUR CHARGES		: \$ 13,052.00	\$ 5,102.00
GRAND TOTAL		: \$ 20,507.00	\$ 5,808.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Janice Lee (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Monday, October 16, 2017 7:53 PM
To: Guo Qiang (LKKAUTO); Janice Lee (LKKAUTO); SUR; Carrine Leong; Nora Khai
Subject: FINAL REVISION SLK7667E - OD AIG - SURVEYED 5 APRIL 17
Attachments: PA03072017 - SLK 7667 E - A3 SEDAN 1.0 TFSI - RHS (AIG).xls

Hi Guo Qiang and all,

Revised estimate is attached.

Please confirm repair cost of \$5808.00 @ 6 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLK 7667 E

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/10307/2017/MAS

22 Feb 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLK 7667 E, Audi A3 Sedan 1.0 TFSI

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no **SLK 7667 E**, claimant,
Ms. Marina Binte Abu Bakar, please find the related document per attached.

1. A copy of the Original invoice no. 85012166 – S\$5,572.56
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai

Claims Dept

Encls

AIG – SLK 7667 E



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408679
Telephone 6388 2323
Telefax 6641 1123

Customer Service
Service Appointment 6366 2323
24 hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

Page 1 10:36

INSURANCE INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012166 Date : 21/02/2018 Order : SLK7667E Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLK7667E (V 32182) Regn Date: 27/12/2016 Mileage: 10932 WIP No.: 18259
Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V8H1028102 Engine: CHZ 158624 Dept: U
VSB No.:
You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	280.00	1.00	280.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	700.00	1.00	700.00
S	BODYWORK	M: TO DISMANTLE REAR BUMPER AND REAR LID. CUT OUT AND REWELD RHS REAR FENDER. REPAIR REAR BUMPER. REINST ALL PARTS REMOVED.	2000.00	1.00	2,000.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER, RHS REAR FENDER AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	1650.00	1.00	1,650.00
S	BODYWORK	M:	280.00	1.00	280.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408899
Telephone 6388 2323

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INSURANCE INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 10:36

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012166 Date : 21/02/2018 Order : SLK7667E Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	---

Regn No.: SLK7667E (V 32182) Regn Date: 27/12/2016 Mileage: 10932 WIP No.: 18259
 Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V8H1028102 Engine: CHZ 158624 Dept: U
 VSB No.:
 You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMEN M:	180.00	1.00	180.00
S	BODYWORK	TO SUPPLY ACRYLIC SEALER. M:	192.00	1.00	192.00
X	ABV0601025DC	TO CARRY OUT DIAGNOSTIC CHECKS. WHEEL Less 020%	1.00	657.50	526.00

Parts 526.00
 Labour 0.00
 Sublet 5,282.00
 Menus 0.00
 Lubricant 0.00

Sub-Total 5,208.00

7% GST 364.56

Grand Total 5,572.56



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLK 7667 E

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0307/2017/MAS
15 Sept 2017

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 Sedan 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V8H1028102
Vehicle Regn No. : **SLK 7667 E**
Vehicle Mileage : 8376 KM
Vehicle Owner : Ms. Marina Binte Abu Bakar
Certificate No : 2100495812-00000
Policy Excess : S\$642.00 (inclusive GST)
Accident Date : 27 Mar 2017
Place : Mandai Rd
Repair Cost : \$ 5,572.56
WIP No. : 18259
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733


Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :



18/09/2017

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7616041D



Name

MARINA BINTE ABU BAKAR



مارينا بنت ابو باكر

Race

MALAY

Date of Birth

25-05-1976

Sex

F

Country of Birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



MARINA BINTE ABU

Birth Date: 25 May 1976

Issue Date: 12 May 2007



3337514

NRIC No. S7616041D



Blood Group

Date of issue

17-03-2003

85 YISHUN AVENUE 1 #01-28
SINGAPORE 789137

S7616041D

19/02/2014


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3A Motor cars without clutch pedals (Auto) =< 3000kg
with =< 7 passengers, exclusive of the driver; and
other motor vehicles without clutch pedals =< 2500kg

12 May 2007

NP 428A



Licence No: S7616041D



HOTLINE TEL: (65) 6419 3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

OWN DAMAGE EXCESS S\$600.00 (1)

CERTIFICATE NO. 2100495812-00000

WINDSCREEN EXCESS S\$100.00
(for policies with effect from 1st November 2002)

SUM INSURED Market Value

INSURING WITH COE/PARF Yes

1) VEHICLE REGISTRATION NO.

SLK7667E

2) NAME OF INSURED

MARINA BINTE ABU BAKAR

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

27 Dec 2016

4) DATE OF EXPIRY OF INSURANCE

26 Dec 2017

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *

SUBJECT TO AGE CONDITION :All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER NA

HIRE PURCHASE COMPANY United Overseas Bank Limited
/ EMPLOYER'S LOAN

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 10 Jan 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-265
PREMIUM LEASING - CCK
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE
CENTRE SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

PRLLYY.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Apr 2017		25 Aug 2017 15:42 Edit Adj Rpt	S\$5,808.00 Edit Estimates	S\$5,808.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]		
Insured:	MARINA BINTE ABU BAKAR, ID: S7616041D, Tel: +6596616946, Email: NOEMAIL					
Vehicle Reg. No.:	SLK7667E	Date of Loss:	27/03/2017 07:00 - :59			
Claim Type:	OD / 8048035928SG	Policy/Cover Note No.:	2100495812 (Comprehensive)			
		Excess:	S\$600.00			
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911					
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 06/09/2017]					
Driver/Custodian:	MARINA BINTE ABU BAKAR (40 / Female), NRIC: S7616041D, Tel: +6596616946					

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (29/08/2017): SLK7667E / OD / 27/03/2017 / Coverage & Excess update 			

ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SLK7667E (8048035928SG)**
OD

Mar 27 2017 7:00AM
[MARINA BINTE ABU BAKAR]
Premium Automobiles Pte Ltd

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#) | [Upload Video](#) | [Upload Audio](#)

View [View in Browser](#) ▼



Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/08/17 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
2	25/08/17 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
3	25/08/17 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
4	25/08/17 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
5	25/08/17 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
6	25/08/17 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
7	25/08/17 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
8	25/08/17 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
9	25/08/17 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
10	25/08/17 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
11	25/08/17 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
12	25/08/17 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
13	25/08/17 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
14	25/08/17 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
15	25/08/17 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
16	25/08/17 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
17	25/08/17 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
18	25/08/17 17:15	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/08/17 17:14	WORKSHOP EST	Load PDF	
2	28/08/17 17:31	Certificate of Insurance	Load PDF	
3	28/08/17 17:31	NRIC AND DL	Load PDF	
4	26/02/18 12:56	Discharge Voucher	Load PDF	
5	26/02/18 12:56	Workshop Invoice	Load PDF	

Linked Accident Report Documents

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	27/03/17 18:54	Accident Statement	Load HTM	
2	15/08/17 16:37	Addendum Sheet	Load JPG	<input checked="" type="checkbox"/>
3	15/08/17 16:38	Accident Statement Addm. #1	Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	27/03/17 18:15	Accident Photo		Load JPG	
2	27/03/17 18:15	Accident Photo		Load JPG	
3	27/03/17 18:15	Accident Photo		Load JPG	
4	27/03/17 18:15	Accident Photo		Load JPG	
5	27/03/17 18:15	Accident Photo		Load JPG	
6	27/03/17 18:15	Accident Photo		Load JPG	
7	27/03/17 18:15	Accident Photo		Load JPG	

Documentation				1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	27/03/17 18:48	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	27/03/17 18:48	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

//

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18002994/GRBE2**Date:** 26/02/2018**REFERENCE**

Insured/Claimant:	MARINA BINTE ABU BAKAR	Policy No:	2100495812	
Date of Loss:	27/03/2017	Nature of Claim:	OD	Claim No: 8048035928SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK7667E	Engine No:	CHZ158624
Make & Model:	AUDI A3, 999cc TFSI (A)	Chassis No:	WAUZZZ8V8H1028102
Reg. Date:	27/12/2016 (Man. Year: 2016)	Odometer:	3197 km
Colour:	Red		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,455.00	706.00	6,749.00	90.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,052.00	5,102.00	7,950.00	60.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,507.00	5,808.00	14,699.00	71.68
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	19,907.00	5,208.00	14,699.00	73.84
+ GST 7.00/7.00% (S\$)	1,393.49	364.56	1,028.93	73.84
Nett Amount (S\$)	21,300.49	5,572.56	15,727.93	73.84

INSPECTION

Date of Assignment:	25/08/2017		
Date Inspected:	05/04/2017	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

Adjuster: XING GUO QIANG**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,567.00 F	*- F
2	1		*REAR BUMPER GUIDE - RH	Not Necessary	54.00 F	*- F
3	1		*REAR FENDER - RH	Repair	1,938.00 F	*- F
4	1		*REAR WHEEL HOUSING LINER - RH	Not Necessary	208.00 F	*- F
5	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	75.00 F	*- F
6	1		*REAR 1/4 GLASS - RH	Not Necessary	455.00 F	*- F
7	1		*REAR WINDSCREEN	Not Necessary	675.00 F	*- F
8	2		*GLASS PRIMER	Not Necessary	36.00 F	*- F
9	1		*REAR FENDER SOUND ABSORBER	Not Necessary	213.00 F	*- F
10	1		*SET ROOF MOLDING CLIP	Not Necessary	51.00 F	*- F
11	1		*SET REAR SEAT GROMMET	Not Necessary	45.00 F	*- F
12	1		*ALUMINIUM RIM - RH REAR	Cut	658.00 F	*526.00 F
13	1		*1/4 GLASS SEALANT	Not Necessary	100.00 F	*- F
14	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 F	*- F
15	1		*ACRYLIC SEALER	Necessary	180.00 F	*180.00 F
16	1		*CAVITY WAX	Not Necessary	140.00 F	*- F
17	1		*STONE CHIP	Not Necessary	180.00 F	*- F
18	1		*METAL FILLER POWDER	Not Necessary	280.00 F	*- F
19	1		*SUNDRIES	Not Necessary	400.00 F	*- F

F=Franchise part.

Total Parts (S\$) 7,455.00 706.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	New	280.00	280.00
2	TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	New	600.00	0.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	700.00
4	TO REMOVE AND REINSTALL REAR SEAT, BACK TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
5	TO DISMANTLE REAR BUMPER AND REAR LID. CUT OUT AND REWELD RHS REAR FENDER. RENEW REAR BUMPER. REINSTALL ALL PARTS REMOVED	New	4,800.00	2,000.00
6	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL PANEL, DOOR ENTRANCE, DRAIN PANEL, ROOF CHANNEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	4,100.00	1,650.00
7	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
8	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			13,052.00	5,102.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >