

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Wednesday, 10 October, 2018 11:27 AM
To: Gary Shi
Cc: Admin A; Vic (LKKAUTO)
Subject: RE: LOD / Accident involving SHD1847B & SHB9901K on 09.02.18 (AXA case)
Attachments: SHD1847B - LOD.PDF

Without Prejudice

Dear Gary,

We refer further to our below email.

We would like to request for any evidence your client have to support his version.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Vic (LKKAUTO)
Sent: Monday, 16 July, 2018 10:05 AM
To: Gary Shi
Cc: Admin A; Vic (LKKAUTO)
Subject: RE: LOD / Accident involving SHD1847B & SHB9901K on 09.02.18 (AXA case)

Without Prejudice

Dear Gary,


We refer to your below email.

Our Insured Driver reported that he was within the lane when collided by your client's vehicle. Please refer to the below statement for your reference.

As such, we would like to request for any evidence your client have to support his version.

Thank you.

SKETCH PLAN



Brief Details.

On 09/02/2018 at about 2220hrs, I was driving my taxi bearing the plate number SHB9901K along Sungei Rd towards ECP. My taxi was stationary at the traffic junction of Sungei Rd and Jln Besar. Suddenly a silver taxi bearing the plate number SHD1847B collided onto the rear end of my taxi and the taxi continued to move to my right side. Which caused the right rear end of my bumper to be damaged as well. There was a vehicle bearing the plate number SJJ7302L which was about 3 to 4 car length behind me. The driver told me that the in car camera footage in his vehicle had capture the accident and he was willing to be my witness if needed. However, after taking photos of the accident I felt pain on my chest and body. Hence, I sat in my taxi while I was waiting for the ambulance. Later on, I was conveyed to Tan Tock Seng hospital and I was given 4 days of MC. I was also contacted by a traffic police and the officer told me to lodge a police report and to report to Traffic Police HQ on Monday.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Gary Shi [<mailto:gary.shi@premiertaxi.com>]

Sent: Friday, 6 July, 2018 3:55 PM

To: Asher Sng (LKKAuto); Vic (LKKAuto)

Cc: CS A Team; Admin A

Subject: FW: LOD / Accident involving SHD1847B & SHB9901K on 09.02.18 (AXA case)

WITHOUT PREJUDICE

Dear Both,

Any offer for this case?

Regards

Gary Shi
Senior Executive, Claims
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 **Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION**

From: Gary Shi
Sent: Friday, 23 March, 2018 1:06 PM
To: Asher Sng | LKK Auto (AsherSng@lkkauto.com); 'vicalpeh@lkkauto.com'
Cc: AccReport; 'cs-a@lkkauto.com'
Subject: LOD / Accident involving SHD1847B & SHB9901K on 09.02.18 (AXA case)

WITHOUT PREJUDICE

Dear Asher & Vic,

Your Ref: SHB9901K
Our Ref: SHD1847B/GS
Date of accident: 09/02/2018

We refer to the above mentioned accident.

Hereby we would like to append our losses from AXA Insurance Pte Ltd, as insurers of vehicle number SHB9901K which their insured driver's negligence driving in the above accident.

Enclosed herewith our letter of demand and supporting documents for your kind perusal.

Kindly look into the matter and let us have your favourable reply as soon as possible.

To expedite this claim settlement, please reply to us by email.

Regards

Gary Shi
Senior Executive, Claims
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 **Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION**

