

185740

INS. CASE OWNER:

Stacey

CC 4 / AXA 1800

3016

K. M. 1/2/18

LKK:
IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

22/2/18

Date / Time:

14/2/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFZ 5025M

Claim No.:

68M00853 / 30901

Name of Insured:

UMKOK SENG

Policy No.:

6816-0001

Insured Tel No.:

HP:

97438149

Make / Model:

Toyota

Excess Sec II : \$\$

D.O.A.:

09/02/18

Place of Accident:

Tuas Rd Roundabout

Is driver the owner?

(YES) / NO

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

S86 N49L

INSRS:
WSP:
Tel:
Liability:
RMKS:

TAT

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

22/2/18

JMS

7/3/18

S86 N49L - P
* sumit claimcalled OI confirm accident detail. OI
view ended TP. inform about TP claim
OI AMARE NCD will be affected letter
sent to OI.

RECEIVED 12 MAR 2018

RECEIVED 03 APR 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

Repair Cost:

\$\$

1479.50 (w/ust)

Loss of Rental (LOR):

\$\$

200

(

2

days)

140/:

Loss of Use (LOU):

\$\$

-

(\$

x

days)

Loss of Income (LOI):

\$\$

-

(\$

x

days)

LOR only

☒

LOU only

☐

LOR + LOU

☐

LOR + LOI

☐

(Tick only one)

GIA/LTA Search

\$\$

745

Medical:

\$\$

-

Disbursement:

\$\$

-

(e.g. Tow/ Independent)

Legal Cost

\$\$

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

#350.00

Total:

\$\$

2186.95

Global Sum \$\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$\$

2186.95

Name 1:

T & T

AUTO

SERVICES PTE LTD

Payee 2: (Strike if N.A.)

\$\$

Name 2:

Payee 3: (Strike if N.A.)

\$\$

Name 3:

2/4/18

ASS. REC. BY:

REF:

A2A/

ASSIGNMENT

From:

Date:

Estimated Cost:

QD/TP/WS/TP RES/QD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STG 21492

Yr Regn:

06, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

BMW A 320i

c.c.

1993

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

283204

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBAVG 76030262776

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

5

mm

L/Bal.

6

mm

L/Bal.

5

mm

D.O.A.

9/2/18

D.O.I.

28/2/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/3 File pass to Customer

C/S \$1850

(reel \$2745.30 / 59.7%)

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18003016/yb3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 14-02-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFZ 5025M	Veh. Inspected	SJG 2149L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	14/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	09/02/2018	Inspection Date	
Survey held at	T&T AUTO SERVICES PTE LTD BLK 160 SIN MING DRIVE #08-14 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

km

T & T Auto Services Pte Ltd

160 Sin Ming Drive
#08-14 Sin Ming AutoCity
Singapore 575722
Tel: 6266 6876 Fax: 6266 6861

ECK SHEN CONSTRUCTION & TRADING PTE LTD
10 BUKIT BATOK CRESCENT
#09-06 THE SPIRE
SINGAPORE 658079

ESTIMATE

DATE : 19/02/2018
VEHICLE NO : SJG 2149 L
MAKE/MODEL : BMW 320I
ACC DATE : 09/02/2018

Not Authored
61 Bys & 18504
Return After Point

PARTICULAR AMOUNT S\$

LIST ITEMS:				
1	1 REAR BUMPER			1,375.00 ✓
2	1 REAR BUMPER REINFORCEMENT			488.00 ✗
3	1 REAR BUMPER SIDE BRACKET	87.00		87.00 ✗
4	1 REAR BUMPER CENTER BRACKET			134.00 ✗
5	2 REAR REVERSE SENSOR	185.00		370.00 ✗
6	1 REAR TAIL LAMP - RH			341.00 ✓
7	1 REAR END PANEL			742.00 ✗
				3,537.00
Less Discount:		10%		353.70
				3,183.30

SPECIAL NETT ITEMS:


1	12 REAR BUMPER CLIPS			60.00 ✓
				60.00

LABOUR CHARGES:

1	TO CHECK WIRING			50.00 150
2	TO REMOVE/REFIX REVERSE SENSOR			100.00 600
3	TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS			600.00 2500
4	TO SPRAY PAINTING ON AFFECTED AREA			600.00 2500
				1,350.00

GRAND TOTAL: 4,593.30

Singapore Dollars: Four Thousand Five Hundred And Ninety Three And Cents Thirty Only.


T & T Auto Services Pte Ltd



T & T Auto Services Pte Ltd

160 Sin Ming Drive
#08-14 Sin Ming AutoCity
Singapore 575722
Tel: 6266 6876 Fax: 6266 6861

ESTIMATE

ECK SHEN CONSTRUCTION & TRADING PTE LTD
10 BUKIT BATOK CRESCENT
#09-06 THE SPIRE
SINGAPORE 658079


DATE : 19/02/2018
VEHICLE NO : SJG 2149 L
MAKE/MODEL : BMW 320I
ACC DATE : 09/02/2018

PARTICULAR

AMOUNT S\$

LIST ITEMS:					
1	1	REAR BUMPER	2 days	BT/cpt	1,375.00 ✓
2	1	REAR BUMPER REINFORCEMENT			488.00 7
3	1	REAR BUMPER SIDE BRACKET		87.00	87.00 7
4	1	REAR BUMPER CENTER BRACKET			134.00 7
5	2	REAR REVERSE SENSOR		185.00 Shen	370.00 4
6	1	REAR TAIL LAMP - RH			341.00 7
7	1	REAR END PANEL		R	742.00 X
					3,537.00
Less Discount:					10% 353.70
					3,183.30
SPECIAL NETT ITEMS:					
1	12	REAR BUMPER CLIPS		M	60.00 ✓
					60.00
LABOUR CHARGES:					
1		TO CHECK WIRING			50.00 15L
2		TO REMOVE/REFIX REVERSE SENSOR			100.00 60L
3		TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS			600.00 250L
4		TO SPRAY PAINTING ON AFFECTED AREA			600.00 250L
					1,350.00
GRAND TOTAL:					4,593.30

Singapore Dollars: Four Thousand Five Hundred And Ninety Three And Cents Thirty Only.


T & T Auto Services Pte Ltd





Re:RE: <SEEK MANDATE> - S8M008S3 [ACCIDENT INVOLVING SFZ 5025M(OI) /SJG 2149L (TP) ON 09/02/2018]

Type

i Information

Message

Please proceed.

Reply

Bevan Lim (LKK Auto)

From: Bevan Lim (LKK Auto)
Sent: Thursday, 29 March 2018 4:03 PM
To: T & T Auto Services Pte Ltd
Cc: Admin A; Hsiao Tong (LKKAuto); Vic (LKKAuto)
Subject: RE: Accident Involving SFZ5025M / SJG2149L on 09/02/2018 *LKK REF: CC4/ASM18003016/Kmb3
Attachments: SJG 2149L DV.pdf

Your Ref: **SJG2149L** Without Prejudice
Our Ref: CC4/ASM18003016/Kmb3s2

Dear Sirs/Madam,

ACCIDENT INVOLVING SFZ5025M(AXA) & SJG2149L ON 09/02/2018

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 1,979.50
2. Loss of Rental (2days x \$100.00)	\$ 200.00
3.LTA SEARCH	\$ 7.45
Total	\$ 2,186.95

Kindly Sign the attached DV and revert back to us together with the ATA for our necessary action.

Thank you.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

From: Bevan Lim (LKK Auto)
Sent: Thursday, 29 March 2018 3:13 PM
To: T & T Auto Services Pte Ltd <tntautoservices@gmail.com>
Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>
Subject: RE: Accident Involving SFZ5025M / SJG2149L on 09/02/2018 *LKK REF: CC4/ASM18003016/Kmb3

Your Ref: **SJG2149L** Without Prejudice
Our Ref: CC4/ASM18003016/Kmb3s2

Dear Sirs/Madam,

ACCIDENT INVOLVING SFZ5025M(AXA) & SJG2149L ON 09/02/2018

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 1,979.50
2. Loss of Rental (2days x \$100.00)	\$ 200.00
Total	\$ 2,179.50

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Bevan Lim | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: BevanLim@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Hsiao Tong (LKKAuto)

Sent: Friday, 9 March 2018 9:50 AM

To: Bevan Lim (LKK Auto) <bevanlim@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; T & T Auto Services Pte Ltd <tntautoservices@gmail.com>

Subject: FW: Accident Involving SFZ5025M / SJG2149L on 09/02/2018 *LKK REF: CC4/ASM18003016/Kmb3

Hi Bevan,

FYNA. CC4/ASM18003016/Kmb3

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: T & T Auto Services Pte Ltd [<mailto:tntautoservices@gmail.com>]

Sent: Wednesday, 7 March 2018 4:44 PM

To: CS A Team <cs-a@lkkauto.com>

Subject: Accident Involving SFZ5025M / SJG2149L on 09/02/2018

Dear Bevan,

We refer to the above matter.

Attached herewith the respective documents of vehicle no: SJG2149L for your perusal.

Kindly revert as soon as possible.

Thank you.

Best regards.

Vincent Tan
T & T Auto Services Pte Ltd
Tel: 6266 6876 Fax: 6266 6861
Hp: 9145 9776

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SFZ 5025M (Insd veh)	Model:	B.M.W.
	SJG 2149L (TP veh)		320I AUTO ABS D/AIRBAG
Date of Accident:	09/02/2018		2WD

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	4,914.83
Final Repair Cost	:	\$	1,979.50
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	200.00 2 days
LTA / GIA Search Fee	:	\$	7.45

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	2,186.95

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown			
1)	T&T AUTO SERVICES PTE LTD	:	\$ 2,186.95

NUR SHAQILAH BTE ABDOL
WAHAB

03/04/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

<<

Service Request Details

Claim	S8M008S3
Reference	
CC4/ASM18003016/KYbas Date	
February 9, 2018	Request Date
February 14, 2018	Due Date
February 14, 2019	Vendor Name
LKK AUTO CONSULTANTS PTE Loss LTD (TP)	Type of
Third Party Vehicle Damage	Services

Actions	Vehicle Information
Next Step	Incident Vehicle
Finish the work	SJG2149L
Complete Work	Registration #
More	Make
	Service Address
	TPVD BMW
	Model
	320 I
	Primary Contact/Insured
	LIM KOK SENG
	BLK 115 HO CHING ROAD, #04-100, 610115, Singapore
	Claim Handler

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
TP LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	March 16, 2018
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	March 16, 2018
LKK Resurvey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	March 12, 2018
LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	March 12, 2018
TP ESTIMATE-MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	March 1, 2018
Preliminary Advice.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	March 1, 2018
REPLY FROM TP.msg	Other	Other	SHAH Kushal	February 14, 2018
SJG2149L GIA REPORT.PDF	Reports & Statement	GIA Report	SHAH Kushal	February 14, 2018

<<

Service Request Details

Claim	S8M008S3	Vehicle Information	
Reference		Incident Vehicle	SJG2149L
CC4/ASM18003016/Kybas Date		Registration #	TPVD BMW
February 9, 2018	Request Date	Make	320 I
February 14, 2018	Due Date	Primary Contact/Insured	
February 14, 2019	Vendor Name	LIM KOK SENG	
LKK AUTO CONSULTANTS PTE Loss LTD (TP)	Type of	BLK 115 HO CHING ROAD, #04-100, 610115, Singapore	
Third Party Vehicle Damage	Services	Claim Handler	

<< Assessment Details

General & Workshop Details

Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

General Details

Workshop Details

Summary

Involving

TPVD BMW 320 I (SJG2149L)

Total Rebate Amount

Date of Loss

February 9, 2018

Nett Loss Amount

\$0.00

Time of Loss

18.15

Loss Description

Assigned Workshop

SFZ5025M (INSURED)

Comment

COLLIDED ONTO SJG2149L

LKK AUTO CONSULTANTS PTE LTD (TP) Target Date of Completion *

mm/dd/yyyy

of work completion *

SERVICE REQUESTS

MESSAGES

CLAIMS

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Vehicle & Driver Details

Summary

Vehicle

SJG2149L

Registration#

Registration
State

Purchase Date

mm/dd/yyyy

Registration
Date *

mm/dd/yyyy

Mileage

Age of Vehicle

9

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATION

Manufacturing
Year

2005

Make

TOYOTA

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	NEOH HENG TONG	
Date of Birth	January 1, 1900	mm/dd/yyyy
Age	118	
Occupation	Unknown	
Education Qualification	Other	Primary
Driving Experience	0	
Driver License #		
License Type		1
License Issue Date		mm/dd/yyyy

SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Tax Eligibility & Additional Deduction for Parts

Summary

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour
Ratio

Paint Material
Ratio

Cash Loss

SERVICE REQUESTSMESSAGESCLAIMS

Assessment Details

General & Workshop Details			Vehicle & Driver Details			Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary		Parts	
EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNTY%	SALV AGE%	PART PRICE(NET)				
	1	1			REAR BUMPER			Bent	1375		10		1237.5				
	2	1			REAR BUMPER REINFORCEMENT			Repair	0		10		0				
	3	1			REAR BUMPER SIDE BRACKET			Repair	0		10		0				
	4	1			REAR BUMPER CENTER BRACKET			Repair	0		10		0				
	5	2			REAR REVERSE SENSOR (1PC ONLY)			Shorted	92.5		10		166.5				
	6	1			REAR TAIL LAMP - RH			Cracked	341		10		306.9				
	7	1			REAR END PANEL			Repair	0		10		0				
Labour																	
EDIT	SR NO	REPAIR/REPLACE (LABOUR)			PART NAME		LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)		COMMENT					
	1				TO CHECK WIRING.		15	0	0	Reviewing							
	2				TO REMOVE/REFIX REVERSE SENSOR.		60	0	0	Reviewing							

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
------	-------	------	--------	--------	---------	--------

☐		1	DAYS OF REPAIR	Reviewing	2	
--------------------------	--	---	----------------	-----------	---	--

☐		2	REAR BUMPER CLIPS	Reviewing	60	NECESSARY
--------------------------	--	---	-------------------	-----------	----	-----------

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary	Claim Amount	\$2,345.90			

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$575.00	\$575.00
Spare Parts	\$1,710.90	\$1,710.90
Miscellaneous	\$60.00	\$60.00

English (default)

LKK AUTO CONSULTANTS PTE LTD (TP)

SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

FINAL
LUMP
SUM

Reviewing

1850

