


NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18003033/K1td3n2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 21-02-2018	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 3201Y	Veh. Inspected	SHC 8020D	
Policy No.	5088109536	Coverage (\$)	0.00	
Claim No.	MT/0982304-002	Excess (\$)	0.00	
Assign From		Assign Date	14/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E220	c.c	2143	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WDD2120012B158559	Colour	WHITE	
Odometer	407173	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R16	WEST LAKE	7 mm	
L/H Front Tyre	225/55 R16	WEST LAKE	7 mm	
R/H Rear Tyre	225/55 R16	WEST LAKE	7 mm	
L/H Rear Tyre	225/55 R16	WEST LAKE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S WING MIRROR. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/02/2018	Inspection Date	14/02/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days		