

18/02/2018

INS. CASE OWNER:

CC 3 / AIG1800

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :\$S

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

(V/L) YES / NO

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SJM 8771T



INSRS:

WSP:

Tel:

Liability:

RMKS:

performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
20/2/18	SJM 8771T - Y	Non-Reporting ltr (1st):	
21/2/18	CAUSED ON OVERSEA TUNE	Non-Reporting ltr (2nd):	
3/3/18 e Nam.	CAUSED ON CONFUSED ACCIDENT. ON REVERSED INTO THE MAIN ROAD	Non-Reporting ltr (Final):	
	HIT TO VEH. INFORM TO CLAIM AGREE TO SETTLE AND AWARD	Notification ltr (if non-pickup):	
	FROM NED BOULE	Call OI:	EMAIL 9/3/18
	EMAIL WSP LIABILITY CLAIM.	After call ltr to OI:	
31.3.18	FILE PASS TO TYPIST TO PREPARE REPORT.	Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	<input type="checkbox"/>
		After call ltr to OI:	<input checked="" type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input type="checkbox"/>
		Towing Invoice:	<input type="checkbox"/>
		LTA / GIA:	<input checked="" type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PIR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
		LOD:	<input type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>

RECEIVED 31 MAY 2018

RECEIVED 20 JUN 2018

PRELIMINARY ADVICE		Date/Time: -	Sent By: -
FINALIZATION		Date/Time: 31.3.18	Confirm with: CPM/ONE
Repair Cost:	PP \$S9,322.60	(7 days) Reduction:	2% %
FINAL SETTLEMENT		Date/Time: 18.6.18	Confirm with: CPM/ONE
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	MV-
Repair Cost:	\$S10,189.18	ON REVERSED INTO THE MAIN ROAD.	
Loss of Rental (LOR):	\$S -	(days)	
Loss of Use (LOU):	\$S 300.00	(\$ 60 x 5 days)	
Loss of Income (LCI):	\$S -	(\$ x days)	
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> (Tick only one)		
GIA/LTA Search	\$S 2.00		
Medical:	\$S -		
Disbursement:	\$S -	(e.g. Tow/ Independent)	
Legal Cost	\$S -		
Total:	\$S 10,491.18	Global Sum \$S:	
FINAL PAYMENT		Date/Time: 18.6.18	Confirm with: CPM/ONE
Payee 1:	\$S10,191.18	Name 1:	PERFORMANCE MODELS LIMITED
Payee 2: (Strike if N.A.)	\$S 300.00	Name 2:	LOH CHYE LING
Payee 3: (Strike if N.A.)	\$S -	Name 3:	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18003073/eb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 15-02-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKD 2T	Veh. Inspected	SJM 8771T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	15/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	11/02/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159943
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438188
Tel. 63190888 (AfterSales)
Fax. 63445773313, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

17 FEB 2018

Estimate No. : b1 45934
Date Estimated : 14/02/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Loh Chye Ling (Luo CaiLing)
119 Pemimpin Place

Singapore 576116

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJM8771T	P836666	27/11/2015	216d G TOURER	0

DESCRIPTION

To replace rear right door, attachment, repair front right door, rear right fender and rear bumper.

2975 / 4,250.00

Painting front right door, rear right door, rear right fender and rear bumper.

3323 / 3,693.00

To check electrical wiring systems for proper function

150 / 177.00

To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).

451 / 531.00

To supply and install rear left or right window glass solar film.

X 425.00

To carry out body cavity preservation (Per panel).

100 / 118.00

Sundries.

150.00

Claims Of 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time _____ Excess \$ _____

Surveyor's Name _____ Sign _____

Surveyor's Tel. _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RECEIVED PARTS PHOTO BY SURVEYOR Yes / No (RM, Yes / No)

Surveyor's Email _____ Total Labour 1: _____

No. of Working Days Recommend _____

9,344.00

DESCRIPTION

ALLOY RIM 7.5X17 DOUBLE SPK 385
RR RH DOOR
RH FIXED DOOR WINDOW
REAR DOOR EDGE PROTECTION

QTY	PRICE
1	759.55
1	1,103.65
1	127.30
1	153.30

VALUE

out 759.55

ht 1,103.65

add 127.30

total 153.30

Total Parts : 2,143.80



Survey & repair
12.03 @ 9.00am

AKG insured GIM
Filed as claiming TP
AKG is trying to contact
their insured to discuss
28/02/18

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159947
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63445773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/538 (Motorrad)
Fax. 64796501 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45934
Date Estimated : 14/02/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJM8771T	P836666	27/11/2015	216d G TOURER	0

by / Uninsured losses / Direct Settlement

13/3/18
Taufik
97493749
- WP

Quoted
Excess \$
Sign
Authorised Yes/No
Type

TO BE SIGNED BY THE VEHICLE
Taufik @ lukant.com
7 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	9,344.00
Parts	:	2,143.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	804.15
Grand Total	:	12,291.95

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



SUPPLEMENTARY

Estimate No. : b1 45934
Date Estimated : 14/02/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Loh Chye Ling (Luo Cailing)
119 Pemimpin Place

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 576116

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SJM8771T	P836666	27/11/2015	216d G TOURER	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00 ✓
# To replace tyre wheel rim include balancing (1x)	80.00		80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR DOOR JOINT SEAL *	30.40	1.00		30.40 <i>NEL</i>

Total Labour :	531.00
Total Parts :	30.40
Total Labour & Parts :	561.40



FINAL REPORT

Estimate No. : b1 45934
Date Estimated : 14/02/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Loh Chye Ling(Luo CaiLing)
119 Pemimpin Place

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 576116

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SJM8771T	P836666	27/11/2015	216d G TOURER	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear RH door and attachments include making good the front RH door, rear RH fender, rear bumper and knocking out dents caused by the accident	2975.00		2,975.00	
To spray paint front RH door, rear RH door, rear RH fender and rear bumper	3323.00		3,323.00	
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00	
To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function (1x)	451.00		451.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
# To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00	
# To replace tyre wheel rim include balancing (1x)	80.00		80.00	
Sundries	80.00		80.00	

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
ALLOY RIM 7.5X17 DOUBLE SPK 385	778.55	1.00		778.55
RR RH DOOR	1,103.65	1.00		1,103.65
# REAR DOOR JOINT SEAL *	30.40	1.00		30.40

SUPPLEMENTARY ITEMS

Total Labour :	7,610.00
Total Parts :	1,912.60
Total Labour & Parts :	9,522.60
Deduction for Excess :	0.00
Total Repair Costs less Excess:	9,522.60
GST @7%:	666.58
Grand Total :	10,189.18

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Monday, 5 March 2018 2:24 PM
To: 'PBSP'; Shu Pei (LKKAuto)
Cc: Admin A
Subject: RE: REQ FOR DIRECT SETTLEMENT SJM8771T & SKD2T (AIG) ON 11.02.2018 *****LKK
REF:CC3/AIG18003073/eb3

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents for us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Monday, 5 March 2018 10:11 AM
To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Shu Pei (LKKAuto) <shupe@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: Re: REQ FOR DIRECT SETTLEMENT SJM8771T & SKD2T (AIG) ON 11.02.2018 *****LKK
REF:CC3/AIG18003073/eb3

Dear Asher,

Please let us have your reply on liability.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Sent: Thursday, 1 March 2018 10:32:01 AM
To: PBSP; Shu Pei (LKKAUTO)
Cc: 甯琚 ©
Subject: RE: REQ FOR DIRECT SETTLEMENT SJM8771T & SKD2T (AIG) ON 11.02.2018 *****LKK
REF:CC3/AIG18003073/eb3

Without Prejudice

Hi Caroline,

We refer to the email below.

We are still in the midst of engaging our insured, shall revert to you in due course.

Thank You.

Best Regards,
Asher Sng | Case Handler
LKK Auto Consultants Pte Ltd
phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]
Sent: Thursday, 1 March 2018 10:29 AM
To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Shu Pei (LKKAUTO) <shupeil@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: Re: REQ FOR DIRECT SETTLEMENT SJM8771T & SKD2T (AIG) ON 11.02.2018 *****LKK
REF:CC3/AIG18003073/eb3

Dear Asher,

Please let us have your reply on liability.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Sent: Monday, 26 February 2018 5:57:37 PM
To: PBSP; Shu Pei (LKKAUTO)
Cc: 甯琨 ©
Subject: RE: REQ FOR DIRECT SETTLEMENT SJM8771T & SKD2T (AIG) ON 11.02.2018 *****LKK
REF:CC3/AIG18003073/eb3

Without Prejudice

Hi Caroline,

We refer to the email below.

We are still in the midst of engaging our insured, shall revert to you in due course.

Thank You.

Best Regards,
Asher Sng | Case Handler
LKK Auto Consultants Pte Ltd
phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]
Sent: Monday, 26 February 2018 4:41 PM
To: Shu Pei (LKKAUTO) <shupeil@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: Re: REQ FOR DIRECT SETTLEMENT SJM8771T & SKD2T (AIG) ON 11.02.2018 *****LKK
REF:CC3/AIG18003073/eb3

Dear Asher,

Please let us have your reply on liability.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Thursday, 15 February 2018 9:50:02 AM
To: PBSP
Cc: 甯珺 ©; CS A Team
Subject: RE: REQ FOR DIRECT SETTLEMENT SJM8771T & SKD2T (AIG) ON 11.02.2018 *****LKK
REF:CC3/AIG18003073/eb3

Dear Caroline,

We refer to the below email.

Please be informed that we are currently **pending for our insured's report.**

Kindly note that for liability, claim negotiation and settlement, please contact Asher at 6841 6051.

Our respective case handler will look into the matter and revert to you in due course.

Thank you

To check availability of the case handler , you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]
Sent: Wednesday, 14 February 2018 6:40 PM
To: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: REQ FOR DIRECT SETTLEMENT SJM8771T & SKD2T (AIG) ON 11.02.2018

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Friday, 8 June 2018 2:56 PM
To: 'Wui, Shawnkaijye'
Subject: Your ref : 9393233348SG, ACCIDENT ON 11/02/2018 INVOLVING SKD 2T (OI) & SJM 8771T (TP)

Your ref : **9393233348SG**
Our ref : CC3/AIG18003073/T1eb3

Dear Sirs,

ACCIDENT ON 11/02/2018 INVOLVING SKD 2T (OI) & SJM 8771T (TP)

We refer to the above matter.

The accident occurred when our insured reversed and hit third party vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer " **PERFORMANCE MOTORS LTD**" at **\$ 10,491.18 (all-in).**

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repairs (with GST)	\$ 12,912.97	\$ 10,189.18
2. Loss of Use (5days x \$60)	\$ 300.00	\$ 300.00 (5days x \$60)
3. LTA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 13,214.97	<u>\$ 10,491.18</u>

For your approval in merimen please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher@sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***SJM8771T (9393233348SG)**
[SKD2T]
TP
LOH CHYE LING
Feb 11 2018 6:00PM
[Low Yen Fong]
Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 11/06/2018 08:32 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10491.18) - SJM8771T - Claim Handler: Wui, Shawn-KJ

Approved:10491.18.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)

Vehicle No:	SIM 8771 T	Model:	
Date of Accident:	11-2-2018		

Global Sum Settlement	[] Yes	[] No	
Repair Estimate	: \$	12291.95	
Final Repair Cost	: \$	10189.18	
Loss of Use	: \$	3000	5 days at \$60 per day
Rental (if any)	: \$		days
LTA / GIA Search Fee	: \$	200	
Others:	: \$		
	: \$		
Final Settlement Sum	: \$	10491.18	
Is Third Party Workshop GIA Registered? [] YES [] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop: Agreed Liability _____ (%)			
B) For GIA Registered Workshop: BOLA Applicable: Yes/ No			
BOLA Scenario No: _____			
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks			

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Ltd	: \$	10189.18
2)	Performance Motors Ltd	: \$	200
3)	Loh Chye Ling	: \$	3000

Signed by appointed surveyor _____

Date _____

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
 Survey Report; Medical Report/ Bill (if any))



SINGAPORE
POLICE FORCE

Pass Date
Class 3 - 27/9/1997

TRAFFIC POLICE
SINGAPORE POLICE FORCE
10, UBI AVENUE 3
SINGAPORE 408865
Tel : 65470000
www.police.gov.sg

Private & Confidential

LOH CHYE LING

119 PEMIMPIN PLACE
SINGAPORE 576116



You will receive your photocard driving licence by registered post within 10 ~~to~~ ¹⁴ working days from the date of application unless you made a special request to collect at Traffic Police at the time of application.

You can drive while awaiting the delivery of your photocard driving licence

Please turn overleaf for important notes:

S7242105A
(3)

C001336022

\$25/-
(Please do not detach)

YOU CAN DRIVE WHILE AWAITING THE
DELIVERY OF YOUR PHOTOCARD
DRIVING LICENCE

**SOMPO****Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Tel: 6461 6555 | Fax: 6221 3302 | Website: www.sompo.com.sg

Co. Reg. No.: 198905490E | GST Reg. No.: M200903196

PRIVATE CAR POLICY SCHEDULE

Intermediary Code : 11F02408

Policy No. : D17MTPV01014371

This Schedule is issued in accordance and should be read in conjunction with the terms, conditions and exceptions of the PRIVATE CAR Policy wordings, ref. MTP.27

Insured : LOH CHYE LING
Address : 115 JALAN PEMIMPIN PLACE
SINGAPORE 576116

Business/Profession : VALUER

INSURED DETAILS

Date of Birth & Age : 07 NOV 1972 & 45 years old

Marital Status : MARRIED

Driving Experience in : 20 years

Gender : Female

Singapore

Identification Type : NRIC(Singaporean)

Identification No. : S7242105A

Period of Insurance : 27 NOVEMBER 2017 00:00 TO 26 NOVEMBER 2018 23:59

Persons or Classes of Persons entitled to drive : Refer to Certificate of Insurance

Limitations as to use : Refer to Certificate of Insurance

VEHICLE DETAILS

Vehicle Registration No. : SJM8771T
Chassis No. : NIL
Engine No. : NIL
Vehicle Make & Model : BMW 216D GRAN
TOURER
Cc : 1496
Type of Body : MPV
Year of Registration : 2015
Seating Capacity : 7
(Including driver)
Estimated value of : Market value at time of loss
Vehicle
Hire Purchase Owner : NIL

PREMIUM DETAILS

Premium	1,594.00
Less No Claim Discount (50%)	(797.00)
Less Offence free Discount (5%)	(39.85)
Total	S\$ 757.15
GST	S\$ 53
Premium (incl. GST)	S\$ 810.15

Coverage : Comprehensive - ExcelDrive PRESTIGE

Excess : \$ 500 - Section I
(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)

Voluntary Excess : N.A

Additional Excess : Named Young and/or Inexperienced Drivers or Elderly Drivers - \$1,500
Un-named Young and/or Inexperienced Drivers or Elderly Drivers - \$3,000
Un-named All Other Drivers - \$500

The terms shall be defined as follows:

'Young Drivers' shall be defined as drivers (including the Insured) who are below 25 years old.

'Inexperienced Drivers' shall be defined as drivers (including the Insured) who have less than 2 years of driving experience in Singapore

'Elderly Drivers' shall be defined as drivers (including the Insured) who are above 70 years old.

Paragraph 2 of Endorsement E in the policy will not apply to Insured's spouse provided he/she is 25 years old & above but less than 70 years old &/or has 2 or more years driving experience.

Windscreen Excess : S\$100.00 - Waived if Repair at ExcelDrive Workshop

Endorsements Applicable : Endorsement D - Young and/or Inexperienced or Elderly Drivers Excess
Endorsement E - Excess Clause
Endorsement H - Total Loss
Endorsement M - Inclusion Of Special Perils
Endorsement P6 - Riot And Strike Endorsement
Endorsement V - No Claim Discount Protection

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Friday, 9 March 2018 2:33 PM
To: 'CRYSTALLOW22@ICLOUD.COM'
Subject: ACCIDENT INVOLVING SKD 2T AND SJM 8771T ON 11/02/2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3/AIG18003073/eb3

09 MAR 2018

LOW YEN FONG

Dear Sir/Madam,

ACCIDENT INVOLVING SKD 2T AND SJM 8771T ON 11/02/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Loh Chye Ling (the third party claimant) of 119 Pemimpin
place S (576116) (address), owner of SJM8771T (vehicle no.)
hereby authorize Performance Motors Ltd ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SJM8771T that was damaged pursuant to the accident which occurred on 11.2.2018
(date) along Pemimpin Place (location) involving vehicle no/s
SKD2T ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 03 (day) of 03 (month) 20 18 (year)

Loh
Signed by "the third party claimant"
(with chop if applicable)

[Signature]
Signed by "the workshop"
Inthiran A/L Thurasamy
(with chop) Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for S\$10189.18 (Repair Cost), S\$ 300 (Loss of rental/use), S\$ 2 (Disbursement), for vehicle no. SM8771T that was damaged pursuant to the accident which occurred on 11.2.2018 (date) along PEMIMPIN (location) involving vehicle no/s SKD2T. This is pursuant to the inspection conducted on 13.3.18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Loh Chye Ling ("the third party claimant") of vehicle no. SM8771T make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SM8771T (vehicle no.) as a result of the accident.


We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 18 (day) of 06 (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

(A)

SERVICE TAX INVOICERepair Order No. : **B1 1250551**Date IN : **13/03/2018**Cust. Svc. Advisor: **Inthiran A/L Thurasamy**Page No. : **1 of 2**Invoice Number : **1968006 / WSB**Invoice Date : **23/05/2018**Payment Terms : **30 Days From Invoice**Invoice By : **Sharon Heng****- CUSTOMER INFORMATION -****Ms Loh Chye Ling (Luo CaiLing)**
119 Pemimpin Place**Singapore 576116****- INVOICE TO - 121****AIG Asia Pacific Insurance Pte. Ltd.**
78 Shenton Way
#08-16 Chartis Building
Singapore 079120REGN. NO.
SJM8771TCHASSIS NO.
P836666REGN. DATE
27/11/2015MODEL
216D G TOURERMILEAGE
29567**- - - - LABOUR 1 - - - -**

	NETT
To replace rear right door and door seal including to make good the front right door, rear right fender, rear bumper and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	2,975.00
To respray front right door, rear right door, rear right fender and rear bumper.	3,323.00
To check electrical wiring systems and lighting at the rear section for proper function.	150.00
To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function.	451.00
To check steering geometry and conduct wheel alignment according to BMW specification	451.00
To carry out body cavity preservation.	100.00
To replace rear right wheel rim including balancing.	80.00
Sundries.	80.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 11.2.2018. 3RD PARTY CAR : SKD2T.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO CONSULTANTS PTE LTD ON 13.3.2018. AUTHORISED REPAIR BY MS ASHER SNG FROM LKK ON 5.3.2018 VIA E-MAIL.	
PROPOSE LOSS OF USE = \$60X5. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00
GIA SEARCH FEE = \$2.00.	0.00

Total Labour 1: **7,610.00****- - - - PARTS - - - -**

	Qty	Retail Price	NETT
REAR DOOR JOINT SEAL	1	30.40	30.40
RR RH DOOR	1	1,103.65	1,103.65
ALLOY RIM 7.5X17 DOUBLE SPK 385	1	778.55	778.55
Total Parts :			1,912.60

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020001-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

200, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
FAX: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64794601 (AfterSales)
64794624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1250551	Page No. : 2 of 2
Date IN : 13/03/2018	Invoice Number : 1968006 / WSB
Cust. Svc. Advisor: Inthiran A/L Thurasamy	Invoice Date : 23/05/2018
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

- - - - L A B O U R 2 - - - -

NETT

0.00

Total Labour 2: 0.00

Labour Charges : 7,530.00	Total Labour & Parts Charges : S\$ 9,522.60
Parts Charges : 1,912.60	Less Insurance Excess : S\$ 0.00
Lubricant/Misc : 80.00	Invoice Total Amount Exclude GST : S\$ 9,522.60
	GST @ 7% : S\$ 666.58
	Invoice Total Amount Include GST : S\$ 10,189.18

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 10,189.18**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-025088

Date of Request: 14/02/2018

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 14/02/2018
Enquiry By Caroline Tan Shirui
TP Vehicle No. SKD2T
Accident Date 11/02/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKD2T	AIG Asia Pacific Insurance Pte. Ltd.	01/07/2017-30/06/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-025088

Date of Request: 14/02/2018

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 14/02/2018
Enquiry By Caroline Tan Shirui
TP Vehicle No. SKD2T
Accident Date 11/02/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Feb 2018 Edit Reg		13 Mar 2018 00:00 Edit Adj Rpt	\$59,522.60 Edit Estimates	\$59,522.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]
Insured:	Low Yen Fong, ID: S7640265E	
Main Claimant:	LOH CHYE LING, ID: S7242105A	
Vehicle Reg. No.:	SJM8771T	Date of Loss: 11/02/2018 18:00 - :59 [26 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9393233348SG	Policy/Cover Note No.: 2100263641
Vehicle Reg. No. (Insured):	SKD2T	Policy No. (Claimant): D17MTPV01014371
		Excess:
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174	
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkajye.Wui@aig.com	
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 27/02/2018]	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG_EXPRESS (11/06/2018): Alert - Adj Mandate Approved (\$510491.18) - SJM8771T - Claim Handler: Wui, Shawn... 		

ALL ASSOCIATED TASKS	View All	Search Tasks	Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJM8771T (93932333485G)
[SKD2T]
TP
LOH CHYE LING
Feb 11 2018 6:00PM
[Low Yen Fong]
Performance Motors Limited

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1 Edit	

Assessment Reports

1 per page

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	19/02/18 09:55	Accident Statement From: SC - Reg. No: SKD2T, Claimant: LOW YEN FONG	1 Load HTM	

Photos/Images


3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/05/18 16:01	Odometer Reading	1 Load JPG	
2	21/05/18 16:01	Chassis Number	1 Load JPG	
3	21/05/18 16:01	General View	1 Load JPG	
4	21/05/18 16:01	General View	1 Load JPG	
5	21/05/18 16:01	General View	1 Load JPG	
6	21/05/18 16:01	General View	1 Load JPG	
7	21/05/18 16:01	General View	1 Load JPG	
8	21/05/18 16:01	General View	1 Load JPG	
9	21/05/18 16:01	General View	1 Load JPG	
10	21/05/18 16:01	General View	1 Load JPG	
11	21/05/18 16:01	General View	1 Load JPG	
12	21/05/18 16:01	General View	1 Load JPG	
13	21/05/18 16:01	General View	1 Load JPG	
14	21/05/18 16:01	General View	1 Load JPG	
15	21/05/18 16:01	General View	1 Load JPG	
16	21/05/18 16:01	General View	1 Load JPG	
17	21/05/18 16:01	General View	1 Load JPG	
18	21/05/18 16:01	General View	1 Load JPG	
19	21/05/18 16:01	General View	1 Load JPG	
20	21/05/18 16:01	General View	1 Load JPG	
21	21/05/18 16:01	General View	1 Load JPG	
22	21/05/18 16:01	General View	1 Load JPG	
23	21/05/18 16:01	General View	1 Load JPG	
24	21/05/18 16:01	General View	1 Load JPG	
25	21/05/18 16:01	General View	1 Load JPG	
26	21/05/18 16:01	General View	1 Load JPG	
27	21/05/18 16:01	General View	1 Load JPG	
28	21/05/18 16:01	General View	1 Load JPG	

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/02/18 09:30	TP EST & GIA REPORT	1 Load PDF	
2	09/03/18 14:37	LETTER TO OI	1 Load PDF	
3	15/03/18 17:51	TP ESTIMATE- MARKED	1 Load PDF	
4	05/06/18 11:01	GIA SEARCH	1 Load PDF	
5	22/06/18 09:15	WORKSHOP INVOICE	1 Load PDF	
6	22/06/18 09:15	AUTHORISATION TO ACT FORM	1 Load PDF	

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
7	22/06/18 09:15	Release Voucher		 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKD2T (Insd veh)	Model:	BMW 216D 1.5 D GRAN
	SJM8771T (TP veh)		TOURER (F46) (A)
Date of Accident:	11/02/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	12,912.97	
Final Repair Cost	: \$	10,189.18	
Loss of Use	: \$	300.00	5.00 days at \$60.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	10,491.18	

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: _____
 _____NIL_____

BOLA Liability: _____100_____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	: \$	10,191.18
2)	Loh Chye Ling	: \$	300.00
3)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

22 Jun
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18003073/T1EB3Q2

Date: 22/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100263641
Claimant SJM8771T **Insured Vehicle No :** SKD2T
Vehicle No : SJM8771T
 Date of Loss: 11/02/2018 Nature of Claim: TP Claim No: 9393233348SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJM8771T**
 Make & Model: BMW 216D, 1.5 D Gran Tourer (F46) (A) Engine No: 34009365B37C15A
 Reg. Date: 27/11/2015 (Man. Year: 2015) Chassis No: WBA2E32060P836666
 Colour: White Odometer: 29567 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,343.20	1,992.60	350.60	14.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,725.00	7,530.00	2,195.00	22.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,068.20	9,522.60	2,545.60	21.09
+ GST 7.00/7.00% (S\$)	844.77	666.58	178.19	21.09
Nett Amount (S\$)	12,912.97	10,189.18	2,723.79	21.09
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,491.18		

INSPECTION

Date of Assignment: 13/03/2018

Date Inspected: 13/03/2018 Inspected At:

Performance Motors Limited
 (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*ALLOY RIM 7.5X17 DOUBLE SPK 385	Cut	778.55 FS	*778.55 FS
3	1		*RR RH DOOR	Bent	1,103.65 FS	*1,103.65 FS
4	1		*RH FIXED DOOR WINDOW	Not Necessary	127.30 FS	*- FS
5	1		*REAR DOOR EDGE PROTECTION	Not Necessary	153.30 FS	*- FS
6	1		*REAR DOOR JOINT SEAL	Necessary	30.40 FS	*30.40 FS
Total Parts (S\$)					2,343.20	1,992.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATION	New	451.00	451.00
2	TO REPLACE TYRE WHEEL RIM INCLUDE BALANCING	New	80.00	80.00
3	TO REPLACE REAR RIGHT DOOR ,ATTACHMENT ,REPAIR FRONT RIGHT DOOR ,REAR RIGHT FENDER AND REAR BUMPER	New	4,250.00	2,975.00
4	PAINTING FRONT RIGHT DOOR ,REAR RIGHT DOOR ,REAR RIGHT FENDER AND REAR BUMPER	New	3,693.00	3,323.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS FOR PROPER FUNCTION	New	177.00	150.00
6	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR)	New	531.00	451.00
7	TO SUPPLY AND INSTALL REAR LEFT OR RIGHT WINDOW GLASS SOLAR FILM	New	425.00	0.00
8	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (S\$)			9,725.00	7,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >