

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

14 FEB 2018

Estimate No. : b1 45944
Date Estimated : 14/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Tao Yi-Hou Mildred
38 Bin Tong Park

Singapore 269819

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKU238R	F887805	29/05/2015	435ia/2	0

DESCRIPTION

To replace rear bumper assembly & all attachments
cause by accident

VALUE880 ~~2,550.00~~

Painting on rear bumper assembly

934 ~~1,038.00~~

To check electrical wiring systems at the rear section
for proper function.

150 ~~177.00~~

Sundries.

90 ~~80.00~~Total Labour 1: **3,845.00**DESCRIPTION

TAILPIPE TRIM CHROME
RR BUMPER CARRIER ECE
REAR BUMPER CENTRE GUIDE
RR BUMPER LH SIDE GUIDE
RR BUMPER RH SIDE GUIDE
TRIM PANEL BUMPER REAR BOTTOM (ZWEI
REINFORCEMENT BUMPER REAR BOTTOM (M
FLAP TOWING EYE PRIMED (M)
REAR BUMPER PANEL PRIMED (M/PDC)
SET MOUNTS PDC SENSOR REAR (M)
RR RH REFLECTOR
DECOUPLING RING PDC TORQUE CONVERTE

QTY PRIC

2 99.65
1 432.90
1 55.40
1 48.10
1 48.10
1 212.50
1 80.25
1 42.20
1 1,264.30
1 62.95
1 35.20
4 5.05

VALUE

? 199.30
? 432.90
? 55.40
? 48.10
? 48.10
? 212.50
? 80.25
? 42.20
DE 1,264.30
NE 62.95
? 35.20
NE 20.20

Total Parts : **2,501.40**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 45944	Page No. : 2 of 2
Date Estimated	: 14/02/2018	
Prepared By	: Kevin Leong Wai Kit	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKU238R	F887805	29/05/2015	435ia/2	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 19/03/18 1440 Excess S\$ _____

Surveyor's Name Rasul Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

Labour 1	:	3,845.00
Parts	:	2,501.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	444.25
Grand Total	:	<u>6,790.65</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **