

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 3693E

DATE 14/2/2018 16:51

Fauzy

MAKE :

MODEL : MERCEDES

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bumper Assy, Frt			\$ 1,890.50
	Bumper Protector, Frt/LH			\$ 196.75
	Bumper Bracket, Frt/LH			\$ 95.00
	Bumper Absorber, Frt/LH			\$ 207.00
	Bumper Frame, Frt/LH			\$ 39.45
	Bumper Sponge, Frt/Centre			\$ 285.00
	Bumper Sponge, Frt/LH			\$ 250.00
	Bumper Sponge Extension, Frt/LH			\$ 54.00
	Bumper Grille, Frt/Centre			\$ 290.50
	Bumper Grille, Frt/LH			\$ 240.50
	Bumper Inner Clip, Frt			\$ 22.00
	Daylight (LH)			\$ 439.20
	Head Lamp Assy (LH)			\$ 2,380.00
	Head Lamp Bracket (LH)			\$ 300.00
	Front LH Fender			
	Front LH Fender Inner Liner			
	SUB TOTAL			\$ 6,689.90
	LESS 20%			\$ 1,337.98
	DISCOUNTED TOTAL			\$ 5,351.92
	Labour Charge			
	Panel Beating			\$ 500.00
	Spray Painting Charge			\$ 500.00
	Tuff Kote			\$ 50.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	TOTAL LABOUR			\$ 1,200.00
	ESTIMATE TOTAL			\$ 6,551.92
K. L. LKK 15/2/18 0855hrs. 3 Pys 4/5 After Repair photo				
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				