

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ernest Tay

Date: 21 Feb 2018

Preliminary Advice

Insured Vehicle No : SHB7705Z
TP Vehicle No : SHD1552B
Make : HYUNDAI I30 GDH 1.6 TCI 5DR DCT
Date of Inspection : 20/02/2018
Inspection At : Premier Automotive Services Pte Ltd (Changi)
23 Changi South Ave 2 #01-02
Singapore 486443

Accident Date : 16/02/2018
Assignment Date : 19/02/2018
Est. Duration of Repair : 6 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...O/S.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,365.26
Revised Amount	:S\$	3,253.98
Check Items (Estimated)	:S\$	62.40
Total	:S\$	3,316.38

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.