

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

19 FEB 2018

Estimate No. : b1 45963 Page No. : 1 of 1
 Date Estimated : 19/02/2018
 Prepared By : Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -Sridhar Venkateswaran
519 Bedok Reservoir Road
#03-70

Singapore 479276

- ACCOUNT - 40000Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS3716T	NS38301	10/04/2015	316iA/4	0

DESCRIPTIONTo remove and install right front fender, right front door,
right rear door and right rear fender and attachment include
knocking cause by the accidentPainting right front fender, right front door, right rear
fenderTo check electrical wiring systems at the front section
for proper function including adjustments of headlights.

Sundries.

VALUE

2125 4,250.00

2389 3,540.00

150 177.00

80.00

Total Labour 1: 8,047.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8,047.00

0.00

0.00

0.00

Total GST @ 7% 563.29

Grand Total 8,610.29

19/03/18 01045

Rahul

900668

5-6 days

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **