

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204

SINGAPORE 528840

TEL :67853933 FAX:67883933

R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : 53329821X

TERENCE SOON GRABCAR

BLK 282 TAMPINES ST 22

06-294

SINGAPORE

TEL : FAX :

PH : 98320962

ATTN :

ESTIMATE BILL

Number : EBK0000236

Date : 20/02/2018

Case No : ADK0000307

Vehicle No : SJG6641E

Chassis: MR053HY9305070988

Year of Mfr 2008

Policy No

Model : TOYOTA VIOS

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	RR BUMPER	1.0	487.90	25	365.93
2	RR BUMPER BRACKET LH RH	2.0	75.14	25	112.71
3	RR BUMPER CLIPS	10.0	4.90	25	36.75
4	RR BUMPER SIDE RETAINER LH RH	2.0	88.50	25	132.75
5	RR BUMPER REFLECTOR LH RH	2.0	75.37	25	113.06
6	RR TAILLAMP LH RH	2.0	295.90	25	443.85
7	RR BOOTLID	1.0	857.60	25	643.20
8	RR BOOTLID INNER RUBBER	1.0	127.80	25	95.85
9	RR BOOTLID LOCK TOP	1.0	282.50	25	211.88
10	RR BOOTLID LOCK BTM	1.0	92.92	25	69.69
11	RR BOOTLID HINGE LH RH	2.0	75.16	25	112.74
12	RR BOOTLID EMBLEM	1.0	66.37	25	49.78
13	RR BOOTLID LOGO E	1.0	75.16	25	56.37
14	RR BOOTLID LOGO VIOS	1.0	80.50	25	60.38
15	RR END PANEL	1.0	698.90	25	524.18
16	RR END PANEL TOP GARNISH	1.0	185.20	25	138.90
17	RR END PANEL TOP GARNISH CLIPS	8.0	4.90	25	29.40
18	RR SPARE TYRE PANEL TOP TRIMBOARD	1.0	157.31	25	117.98
List Price - Parts Sub Total					3,315.40
19	RR REVERSE SENSOR	1.0	250.00	0	250.00
20	RR NO PLATE W HOLDER	1.0	70.00	0	70.00
Special Nett Price - Parts Sub Total					320.00
Parts Total					3,635.40
21	RR SPARE TYRE PANEL REPAIR	1.0			
22	RR FENDER LH RH REPAIR	1.0			
23	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	1.0	1,000.00	0	1,000.00
24	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,000.00	0	1,000.00
25	WIRING	1.0	80.00	0	80.00
Labour 1 Sub Total					2,080.00
SINGAPORE DOLLARS : SIX THOUSAND ONE HUNDRED FIFTEEN AND CENTS FORTY-EIGHT ONLY			Less Excess		0.00
			SUBTOTAL		5,715.40
			GST 7.00%		400.08
			TOTAL		6,115.48

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL :67853933 FAX:67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : 53329821X
TERENCE SOON GRABCAR
BLK 282 TAMPINES ST 22
06-294
SINGAPORE
TEL : FAX :
PH : 98320962
ATTN :

ESTIMATE BILL

Number : EBK0000236
Date : 20/02/2018
Case No : ADK0000307
Vehicle No : SJG6641E
Chassis: MR053HY9305070988
Year of Mfr 2008
Policy No
Model : TOYOTA VIOS

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
Date of accident : 14/02/2018 09:15 AM. Place : JUNCTION MARINA BLVD AND SHEARES AVE					

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE