



AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way, #27-01 AXA Tower
AXA Tower
Singapore 058716

Our Client,

DANCY-ANN KHO CHA KUON

CarCrafters Singapore Pte Ltd

48 Toh Guan Road East

#05-155, Enterprise Hub

Singapore 608586

Repair Estimate

Tel: 6267 9916

Fax: 6267 9313

www.carcrafters.sg

Date : 23/2/2018

Vehicle Num :SKR3043G

Make/Model : AUDI A3 1.4

Chassis No :WAUZZZ8V3F1039456

S/N	PARTS	QTY	PRICE	TOTAL
1	MOUNTING PARTS FOR BUMPER	1 sets	\$ 114.00	\$ <i>del</i> 114.00
2	BOOT LINING BLACK LH	1 pc	\$ 560.00	\$ <i>?</i> 560.00
3	REINFORCEMENT BRACKET LH	1 pc	\$ 15.00	\$ <i>?</i> 15.00
4	BRACKET FOR EXHAUST SYSTEM	1 pc	\$ 47.00	\$ <i>?</i> 47.00
5	CONNECTING PIECE FOR FLOOR PAN LH	1 pc	\$ 75.00	\$ <i>?</i> 75.00
6	CONNECTING PIECE FOR FLOOR PAN RH	1 pc	\$ 75.00	\$ <i>X</i> 75.00
7	CONNECTING PLATE FOR SIDE MEMBER LH	1 pc	\$ 65.00	\$ <i>?</i> 65.00
8	REAR BUMPER	1 pc	\$ 1,280.00	\$ <i>del</i> 1,280.00
9	CROSS MEMBER FOR FLOOR PAN	1 pc	\$ 220.00	\$ <i>Rx</i> 220.00
10	DECKLID WEATHERSTRIP	1 pc	\$ 150.00	\$ <i>new</i> 150.00
11	DUAL CLAMP	1 pc	\$ 66.00	\$ <i>?</i> 66.00
12	END PLATE FOR SIDE MEMBER	1 pc	\$ 52.00	\$ <i>?</i> 52.00
13	EXHAUST PIPE TIPS CHROME	1 set	\$ 200.00	\$ <i>ant</i> 200.00
14	FRONT EXHAUST SILENCER	1 pc	\$ 530.00	\$ <i>?</i> 530.00
15	REAR EXHAUST SILENCER	1 pc	\$ 760.00	\$ <i>?</i> 760.00
16	FILLER PLATE END PANEL LH	1 pc	\$ 110.00	\$ <i>?</i> 110.00
16	FILLER PLATE END PANEL RH	1 pc	\$ 110.00	\$ <i>X</i> 110.00
17	FLOOR PAN	1 pc	\$ 530.00	\$ <i>Rx</i> 530.00
18	FLOOR PAN SUPPORT LH	1 pc	\$ 160.00	\$ <i>?</i> 160.00
19	REAR BUMPER GUIDE PIECE LH	1 pc	\$ 53.00	\$ <i>new</i> 53.00
20	REAR BUMPER SUPPORT BRACKET LH	1 pc	\$ 15.00	\$ <i>new</i> 15.00
21	REINFORCEMENT	1 pc	\$ 435.00	\$ <i>?</i> 435.00
22	MOUNTING EXHAUST SYSTEM	1 pc	\$ 22.00	\$ <i>?</i> 22.00
23	REAR APRON CENTRE	1 pc	\$ 275.00	\$ <i>?</i> 275.00
24	REAR TRUNK LID	1 pc	\$ 1,820.00	\$ <i>bt</i> 1,820.00
25	REFLECTOR LH	1 pc	\$ 29.00	\$ <i>gra</i> 29.00
26	END PANEL	1 pc	\$ 540.00	\$ <i>bt</i> 540.00
27	LOWER SPOILER	1 pc	\$ 180.00	\$ <i>del</i> 180.00
28	END TOP GARNISH	1 pc	\$ 124.00	\$ <i>?</i> 124.00
29	TRUNK LINING BLACK	1 pc	\$ 400.00	\$ <i>?</i> 400.00
30	BLACK TRAY LINER	1 pc	\$ 250.00	\$ <i>?</i> 250.00
31	REAR SENSOR	4 pcs	\$ 640.00	\$ <i>?</i> 640.00
32	STRIKER	1 pc	\$ 35.00	\$ <i>?</i> 35.00
33	HOOD LATCH	1 pc	\$ 150.00	\$ <i>?</i> 150.00
34	TAILLIGHT INNER LH	1	\$ 530.00	\$ <i>?</i> 530.00

35	TAILLIGHT OUTER LH	1	\$	790.00	\$ <i>One ✓</i> 790.00
36	TAILLIGHT INNER RH	1	\$	530.00	\$ <i>X</i> 530.00
37	TAILLIGHT OUTER RH	1	\$	790.00	\$ <i>X</i> 790.00
				TOTAL AMOUNT	\$ 12,727.00
MISCELLANEOUS ITEM					
	REAR CARPLATE NUMBER WITH CASING	1	\$	35.00	\$ <i>X</i> 35.00
LABOUR					
1	To remove/ replace/ refit of rear portion of realigned rear bumper, reinforcement, trunk lid, both rear fenders & other affected area				\$ <i>1250</i> 2,000.00
2	To putty & respray trunk lid, rear bumper, end panel, luggage compartment, rear both fenders & other affected area.				\$ <i>1250</i> 2,000.00
3	To remove/replace/refit of end panel & luggage compartment & taillight panel.				\$ <i>200</i> 600.00
4	To check accident affected wiring system & recover.				\$ <i>30</i> 50.00
5	To remove/replace/refit of middle & rear exhaust.				\$ <i>120</i> 300.00
6	To recode & decode engine management system & fault code clearing after repair works.				\$ <i>✓</i> 100.00
				TOTAL	\$ 17,812.00
				GST 7%	\$ 1,246.84
				GRAND TOTAL	\$ 19,058.84

Tanjil 97495749
- WP
23/2/18 @ 1750

Resuming after repair
lumpsum.

8 days.

sur@lkkauto.com

tanjil@lkkauto.com