



Bedok Motor Engineering Pte Ltd
 30 Defu Lane 9 Singapore 539270
 http://www.bedokmotor.com
 enquire@bedokmotor.com
 +65 6286 3032

Estimate To Repair CB6356M MITSUBISHI ROSA BE637

Chassis No :BE637JB00483

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
1	1pc	Rear wheel mudguard o/s	\$ 2,479.70
			\$ 2,479.70
			\$ 247.97
			\$ 2,231.73
<u>SPECIAL NETT ITEAMS</u>			
2	1pc	Rear wheel mudguard window glass repair kit	\$ 650.00
			\$ 650.00
<u>LABOUR & MISC CHARGE</u>			
1		Panel beating and weld off o/s rear wheel mudguard panel assy and renew the same.	\$ 2,200.00
2		Putty and spray painting of the affected portion.	\$ 1,800.00
3		To remove and refit seats, interior, fitting, fixture, trimmings, garnish and etc.	\$ 550.00
			\$ 4,550.00
		Total	\$ 7,431.73

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

not added
ok
take photo of the repair
 Total
 3 day.
 2/2/18
 Tel: 62563561
 Marcus.
 P/P \$ 2000/-

α
α
1000
800
200