

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBE 8014H

TP/EQ

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433
ATTN: Motor Claim Department
WS Ref: TP/EQ/YS
Claim Type: Third Party
Accident Date: 13/02/2018
TP Veh Reg No: SLF3948Y

FAX: 62243903

Claim No: ES1890155
Estimate No: ES1890155/YISHUN
Date: 14 Feb 2018
Policy No: DMCVSN3021021700
Veh Reg No: GBE8014H
Make/Model: TOYOTA DYNA 3.0M
Chassis No: KDY2318023005
Engine No: 1KD2578947
Reg. Date: 28/03/2016

Estimate Repair Cost to Vehicle No : GBE8014H

Pages: 1/1

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Cost Plus				
1 FRONT BUMPER	240.00	1 PC	240.00	✓
2 FRONT BUMPER LH BRACKET	105.00	1 PC	105.00	✓
3 LH HEADLAMP	350.00	1 PC	350.00	✓
4 FRONT PANEL	390.00	1 PC	390.00	✓
5 FRONT GRILLE	210.00	1 PC	210.00	✓
6 FRONT GRILLE LOGO	38.00	1 PC	38.00	✓
7 FRONT GRILLE CLIPS	2.00	3 PCS	6.00	✓
8 FRONT PANEL STICKER (DYNA)	39.00	1 PC	39.00	✓
9 FRONT WINDSCREEN GLASS RUBBER	95.00	1 PC	95.00	✓
10 FRONT LH CORNAL PANEL	85.00	1 PC	85.00	✓
11 FRONT LH CORNAL GARNISH	50.00	1 PC	50.00	7
12 FRONT LH STEP GARNISH	55.00	1 PC	55.00	7
13 FRONT LH DOOR	600.00	1 PC	600.00	✓
14 FRONT LH DOOR LAMP	30.00	1 PC	30.00	X
			2,293.00	
	Add 20%		458.60	2,751.60
Special Net				
15 FRONT LH DOOR COY STICKER	20.00	1 PC	20.00	✓
				20.00
Labour				
16 REMOVE AND REFIX FRONT WINDSCREEN GLASS	60.00	1 LA	60.00	✓
17 REMOVE & REFIX DASH BOARD,METER ASSY & CHECK WIRING	250.00	1 LA	250.00	✓
18 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL	100.00	1 LA	100.00	✓
19 PANEL BEATING	900.00	1 LA	900.00	750
20 PUTTY & RESPRAY ON AFFECTED AREAS	800.00	1 LA	800.00	720
21 REMOVE & REFIX FRT LH DOOR GLASS	60.00	1 LA	60.00	✓
22 RUSTPROOFING	30.00	1 LA	30.00	✓
				2,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$ 4,971.60
Add GST @ 7% 348.01
Total Amount payable S\$ 5,319.61

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE