

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 6927L

DATE 19/2/2018 22:22

MAKE :

MODEL : HYUNDAI i40

Jumani

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?		\$ 49.00	\$ 98.00	
	Rear Bumper Clips ✓			\$ 22.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover ✓			\$ 225.00	
	SUB TOTAL			\$ 1,956.35	
	LESS 20%			\$ 391.27	
	DISCOUNTED TOTAL			\$ 1,565.08	
	License Cover ✓			\$ 100.00	Nett
	Rear No.Plare ✓			\$ 25.00	Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70	Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
				\$ 510.70	
	Labour Charge				
	Panel Beating			\$ 350.00 200	
	Spray Painting Charge			\$ 200.00 180	
	Wiring Charge			\$ 50.00 x	
	Remove/Refix Reverse Sensor			\$ 120.00 20	
	TOTAL LABOUR			\$ 720.00	
	ESTIMATE TOTAL			\$ 2,795.78	
1ca lwi 16/1/18 20/2/18 1200L 20/2/18 4/3 Afke Rep-2 p Lt					
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					