

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eliza Ho Teng Boon

Date: 23 Feb 2018

Preliminary Advice

Vehicle No	: SLF349X	Accident Date	: 10/02/2018
Make	: HONDA VEZEL	Policy No.	: A28805625QMX
Assignment Date	: 21/02/2018	Excess	: S\$500.00
Date of Inspection	: 23/02/2018	Est. Duration of Repair	: 5.00
Inspection At	: PROGRESSIVE AUTOMOTIVE PTE LTD (HQ) BLK 3022A UBI ROAD 1, #01-45/46 SINGAPORE 408716		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,018.30
Revised Amount	:S\$	5,604.00
Check Items (Estimated)	:S\$	2,885.30
Total	:S\$	8,489.30

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	84,000.00
COE / PARF Rebate	:S\$	62,064.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,936.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.