



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : WEE TZE FAH Tel : Email :

Customer :	<i>Not Present</i> GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
-------------------	---

Quotation No : QO18/02-1123	Quotation Date : 20/02/2018	Terms : 30 DAYS
Vehicle No : SLM803P	Chassis No : MHFB29F3302008398	Third Party Insurer :
Model : VIOS	Date of Accident :	

Remarks : TP INSURER: LONPAC , INSURED'S VEH NO:SKL3437K , DATE OF ACCIDENT: 14.02.2018

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	BOOTLID <i>762.47</i>	1 <i>pp/bul</i>	1,662.4000	1,662.40
2	BOOTLID VIOS BADGE	1 <i>per</i>	44.1000	44.10
3	BOOTLID CENTRE EMBLEM BADGE	1 <i>per</i>	59.8000	59.80
4	BOOTLID E BADGE	1 <i>per</i>	34.4000	34.40
5	BOOTLID LOCK	1 <i>twi</i>	90.4000	90.40
6	BOOTLID LOCK STRIKER	1 <i>17</i>	18.5000	18.50
7	BOOTLID WEATHERSTRIP	1 <i>twi</i>	188.8000	188.80
8	BOOTLID LOCK CABLE CLIPS	3 <i>17</i>	4.3000	12.90
9	BOOTLID WIRE HARNESS CLIPS	3 <i>17</i>	4.3000	12.90
10	BOOTLID HINGE	2 <i>17</i>	57.8000	115.60
11	BOOTLID INNER TRIM COVER	1 <i>101</i>	234.3000	234.30
12	BOOTLID INNER TRIM COVER CLIPS	4 <i>17</i>	4.3000	17.20
13	REAR END PANEL	1	694.7000	694.70
14	REAR END PANEL INNER TRIM	1	234.3000	234.30
15	REAR BUMPER	1 <i>pp/ae</i>	504.9000	504.90
16	REAR BUMPER REINFORCEMENT	1	322.3000	322.30
17	REAR BUMPER SIDE RETAINER	2 <i>bul</i>	116.3000	232.60
18	REAR BUMPER SIDE HOLDER	2 <i>su</i>	22.3000	44.60
19	REAR BUMPER CLIPS	10 <i>ull</i>	4.3000	43.00
20	REAR BUMPER REFLECTOR	2 <i>17</i>	130.5000	261.00
21	REAR LICENCE PLATE LAMP	2 <i>17</i>	64.1000	128.20
22	REAR LAMP	2	375.8000	751.60
23	REAR LAMP CLIP HOLDER	4 <i>17</i>	4.3000	17.20

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : WEE TZE FAH Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :

Quotation No : QO18/02-1123	Quotation Date : 20/02/2018	Terms : 30 DAYS
Vehicle No : SLM803P	Chassis No : MHFB29F3302008398	Third Party Insurer :
Model : VIOS		Date of Accident :
Remarks : TP INSURER: LONPAC , INSURED'S VEH NO:SKL3437K , DATE OF ACCIDENT: 14.02.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
24	FRONT BUMPER	1	427.0000	427.00
25	FRONT BUMPER REINFORCEMENT	1	379.2000	379.20
26	FRONT BUMPER SIDE RETAINER	2	65.7000	131.40
27	FRONT BUMPER CLIPS	10	4.3000	43.00
28	FRONT BUMPER LOWER SPLASHIELD COVER	1	209.1000	209.10
29	FRONT BUMPER LOWER SPLASHIELD COVER CLIPS	8	4.3000	34.40
30	FRONT BUMPER SPOT LAMP GARNISH	2	56.6000	113.20
31	FRONT BUMPER CENTRE GRILLE	1	197.6000	197.60
32	FRONT BUMPER CENTRE GRILLE TOW COVER	1	52.4000	52.40
33	FRONT BUMPER CHROME GARNISH	2	66.8000	133.60
34	FRONT BUMPER EMBLEM BADGE	1	97.4000	97.40
35	FRONT BUMPER OUTER GARNISH	1	87.8000	87.80
36	FRONT CENTRE BRACE PANEL	1	143.6000	143.60
37	HEAD LAMP	2	588.1000	1,176.20
38	LESS 25% (ITEM 1 - 37)	1	-2,237.9000	-2,237.90
39	REAR BUMPER PARKING SENSOR	1 set	500.0000	500.00
40	REAR LICENCE PLATE	1	35.0000	35.00
41	FRONT LICENCE PLATE	1	35.0000	35.00
42	TO RUST-PROOFING OF THE AFFECTED AREAS	1	180.0000	180.00
43	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	60.0000	60.00
44	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE	1	150.0000	150.00
45	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	120.00
				C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/02-1123	Quotation Date : 20/02/2018	Terms : 30 DAYS
Vehicle No : SLM803P	Chassis No : MHFB29F3302008398	Third Party Insurer :
Model : VIOS		Date of Accident :
Remarks : TP INSURER: LONPAC , INSURED'S VEH NO:SKL3437K , DATE OF ACCIDENT: 14.02.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
46	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	150.0000	60 150.00
47	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	1,000.0000	800 1,000.00
48	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,200.0000	1100 1,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total	10,143.70
GST(7.00%)	710.06
Total (SGD)	10,853.76

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216