

INS. CASE OWNER:

CC 3, III 1800 3323, 2 Ka34

LKK:
IDAC:

Surveyor:

Rasul

DOI:

28/2/18

Date / Time:

21/2/18

Registered in Merimen:

21/2/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

PC3406M

Name of Insured:

SINGAPORE WATCH SERVICES P/L

Insured Tel No.:

HP:

D.O.A:

20/2/18

Excess Sec II :S\$

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

2440 404344
9 2473079

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

M495163

GOLDEN DRAGON

CIC AVE 4

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SFT16924



INSRS:

WSP:

Tel:

Liability:

RMKS:

Vantage
Regent



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

21/2

2440

26/2/2018

8.5.18

SFT16924-X; PC3406M-X

FILES REVIEWED. Cases of OI (prior-ended TP).
SOSG liability mandate via merimen.

FILE PASS TO TPAS TO PREPARE REPORT.

RECEIVED 10 MAY 2018

* Merimen - Regent Motors - Vantage Automotive Centre

RECEIVED 17 JUL 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

REALIZATION

Date/Time:

Confirm with:

Confirm by: MRB

Repair Cost:

S\$ 8,000

(b days) Reduction:

50 %

FINAL SETTLEMENT

Date/Time: 28.4.18

Confirm with: GUD XINANG

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

Repair Cost:

S\$ 8,260.00

Loss of Rental (LOR):

S\$ 599.20

(8 days) x +70

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ -

(\$ x days)

I.O.P. only

☒

LOU only

☐

LOR + LOU

☐

LOR + LOI

☐

(Tick only one)

GIA/LTA Search

S\$ 7.45

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/Independent)

Legal Cost

S\$ -

Total:

S\$ 9,166.65

Global Sum S\$:

FINAL PAYMENT

Date/Time: 28.6.18

Confirm with: GUD XINANG

Email ☒ Call ☐

Price 1:

S\$ 9,166.65

Name 1:

REGENT MOTORS

Price 2: (Strike if N.A.)

S\$

Name 2:

Price 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TC

3) Survey fee:

600

Business Reason

REF:

III

7457B

ASSIGNMENT

Form: Date: 28/02/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SFT 1692U
at Workshop n/s: Vantage Automotive
of: 305 Alexandra Road.

Insured

Policy No.

Claims No.

Sum Insured: Excess:


(Client's Record)

Make of Veh: Shahr

(Policy Condition)

1pm

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: 71K

ICAD Accident Report: Consistent? Yes or No

GLA / PR Seen: Consistent? Yes or No

Est. Repairs: 6 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SFT 1692U

Vr Page: 2013 Feb

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: FORD MONDEO 2.0 cc: 1999

Colour: GREY A/C: Insured / Std / NI / NA

So. Reading: 096217 T. Radio: Insured / Std / NI / NA

Eng. No.

C. No: WFOET X4BBECL12812

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / R / STD A/Rim or

Tyre Size: F: 215/50 ZR17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front

Rear

R. Bal: 6 mm R. Bal: 6 mm

L. Bal: 6 mm L. Bal: 6 mm

D.O.A: 22/02/18 D.O.I: 28/02/18

Survey held at: VANTAGE

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

28/02/18 refer to email

45: +8,000 (RED: +11,258.40 58%+)

MARKET VALUE: +71,000

LTA REPAIR: +62,537

NET VALUE: +8,463

Date/Time: File Pass to?

☐

Prel. Report

☐

Final Report

Date/Time: File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transporter:

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Technical: \$

☐

Weekend: \$

Report Format:

Lump Sum / I.Bill: \$

File No.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC3/III18003323/ka3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 21-02-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 3406M	Veh. Inspected	SFT 1692U	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	21/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/02/2018	Inspection Date		
Survey held at	VANTAGE AUTOMOTIVE LTD 305 ALEXANDRA ROAD SINGAPORE 155942			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. S3055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 3562

Page No. : 1 of 2

Date Estimated : 20/02/2018

Prepared By : Mohamed Shabir Abdul Hamid

- ESTIMATE REPAIR FOR -

Ng Kee Chong

Blk 336 Bukit Batok St 32

#04-303

Singapore 650336

- ACCOUNT - 2000

CASH - Sale service

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SFT1692U

WF0EXXGBBECC12812

20/02/2013

MON TTN 5DR

0

DESCRIPTION

VALUE

SUNDRIES

~~30~~ 150.00

ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING (NETT)

150.00

TO REMOVE AND REFIX REAR BUMPER REVERSE SENSORS (NETT)

150.00

TO REMOVE AND REPLACE/ REFIX REAR WINDSCREEN (NETT)

600.00

SEALANT FOR REAR WINDSCREEN (NETT)

60.00

INNER SEAL FOR REAR WINDSCREEN (NETT)

50.00

TO SUPPLY AND INSTALL 3M SOLAR FILM FOR REAR WINDSCREEN (NETT)

~~18~~ 350.00

TO TRANSFER REAR BOOT MECHANISMS, COMPONENTS, LOCKS, TRIMS, CLIPS (NETT)

300.00

TUFF KOTE - BODY CAVITY PRESERVATION (NETT) @ \$60.00 PER PANEL

~~60~~ 180.00

SEALANT FOR BODY PANELS (NETT) @ \$90.00 PER PANEL

~~90~~ 180.00

TO REPAIR, REPLACE REAR BOOT, REAR WINDSCREEN, REAR BUMPER REAR END PANEL, BUMPER BRACKET TAIL LAMPS, 3RD BRAKE LIGHT REINFORCEMENT, REAR BUMPER SIDE RETAINER AND ALL OTHER AFFECTED PARTS AND AREAS

~~900~~ ~~1200~~ 3,600.00

TO SPRAY PAINT REAR BUMPER, REAR END PANEL, REAR BOOT, REAR FENDER, TAIL LAMP PANEL, AND ALL OTHER AFFECTED AREAS

~~1200~~ 3,000.00

TO SUPPLY AND INSTALL REAR NUMBER PLATE WITH HOLDER (NETT)

~~X~~ 70.00

Total Labour 1:

8,840.00

PART NUMBER DESCRIPTION

QTY

PRICE

DISC

VALUE

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : -6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 3562
Date Estimated : 20/02/2018
Prepared By : Mohamed Shabir Abdul Hamid

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFT1692U	WF0EXXGBBECC12812	20/02/2013	MON TTN 5DR	0

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
PBS71A40410A	TAILGATE ASSY	1	2,650.00	10.00	2,385.00
A					
BS7117A881AD	RHR BUMPER BRACKET	1	85.00	10.00	76.50
BS7117A882AD	LHR BUMPER BRACKET	1	85.00	10.00	76.50
BS71A43400AC	BOOT LID HANDLE, PRIMED - M07	1	328.00	10.00	295.20
XWAA					
BS71A423A40B	BOOT LID LWR PANEL, PRIMED - M07	1	401.00	10.00	360.90
AXWAA					
7S71A404A06B	TAILGATE WEATHERSTRIP - M07	1	295.00	10.00	265.50
C					
BS71A42004AD	REAR WINDSCREEN - MON. 2.0L ECO 5DR	1	720.00	10.00	648.00
6M21R29760AA	WINDSCREEN SPACER	1	10.00	10.00	9.00
97BBA29760AA	SPACER	1	0.00	0.00	0.00
7U5A19H250AB	FRT & RR FORD BADGE	1	138.00	10.00	124.20
1S7142528AA	RR EMBLEM MONDEO - M07	1	130.00	10.00	117.00
BS7113A601AE	THIRD BRAKE LAMP ASSY	1	195.00	10.00	175.50
7S7113550AB	LAMP-LIC.PLATE	2	110.00	10.00	198.00
BS7113A602AE	RHR INNER LAMP ASSY	1	570.00	10.00	513.00
BS7113A603AE	LHR INNER LAMP ASSY - M07	1	570.00	10.00	513.00
BS7113404AE	LAMP ASSY RHR OUTER	1	620.00	10.00	558.00
BS7113405AE	LAMP ASSY - REAR, LH - OUTER	1	600.00	10.00	540.00
BS71A17906BB	BUMPER-REAR	1	1,562.00	10.00	1,405.80
XWAA					
7S71A17E850A	RHR BUMPER SIDE BRACKET	1	110.00	10.00	99.00
N					
7S71A17E851A	LHR BUMPER SIDE BRACKET	1	110.00	10.00	99.00
N					
BS7117A894BD	RR BPR EXTENSION DUAL EXH - M07	1	380.00	10.00	342.00
6M2117F902AD	RHR BPR REINF.BRACKET - M07	1	184.00	10.00	165.60
6M2117F903AC	LHR BPR REINF.BRACKET - M07	1	186.00	10.00	167.40
6M2117970AF5	RR BUMPER REINFORCEMENT - M07	1	1,095.00	10.00	985.50
ZCT					
7S7117B918AD	RR BUMPER LWR MTG BRACKET	2	54.00	10.00	97.20
96FG16K262AA	CLIP - F08,M07	4	8.00	10.00	28.80
AM5T15K870BB	RR PARKING AID BRACKET, UNPRIMED	4	48.00	10.00	172.80
XUAA					

Note: TO check
 28/02/18 @ 1300
 5-6 days
 Resing 64 paint
 Hp 90010068

Total Parts	:	<u>10,418.40</u>
-------------	---	------------------

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Customer Service Officer
Acknowledged by Repairer

Contact

Labour 1	:	8,840.00
Parts	:	10,418.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,348.09
Grand Total	:	20,606.49

The above estimates are based on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 7457B

Vehicle Details

Vehicle No.: SFT1692U

Vehicle to be Exported: No

Intended De-registration Date: 28 Feb 2018

Vehicle Make: FORD

Vehicle Model: MONDEO 2.0 GTDI 240PS (A) 5DR

Primary Colour: Grey

Manufacturing Year: 2012

Engine No.: CC12812

Chassis No.: WF0EXXGBBECC12812

Maximum Power Output: 176.0 kW (236 bhp)

Open Market Value: \$21,490.00

Original Registration Date: 20 Feb 2013

First Registration Date: 20 Feb 2013

Transfer Count: 0

Actual ARF Paid: \$21,490.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 19 Feb 2023

PARF Rebate Amount: \$15,043.00

Intended COE Rebate Details

COE Expiry Date: 19 Feb 2023

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$97,889.00

COE Rebate Amount: \$47,494.00

Total Rebate Amount: \$62,537.00

The information contained herein is correct as at 28 Feb 2018

OK

71,000
62,537
8,463
8K

Zaini (LKK Auto)

From: Zaini (LKK Auto)
Sent: Thursday, 1 March 2018 4:57 PM
To: 'Mohamed Shabir Abdul Hamid'
Cc: Rasul (LKKAuto); Wong Guo Xiang; Natarajan Kavidha Rajan; Olivia Lau (LKKAuto); Hsiao Tong (LKKAuto)
Subject: RE: SFT 1692U

WITHOUT PREJUDICE

Dear Shabir,

We refer to our previous tele-conversation.

For COR, we confirmed L/sum - \$8000.00 (before GST) all in with no further supplementary.

*** Kindly arrange for "After Repair" photos and forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) for our necessary action.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mohamed Shabir Abdul Hamid [<mailto:shabir.abdul.hamid@simedarby.com.sg>]

Sent: Wednesday, 28 February 2018 7:45 PM

To: Zaini (LKK Auto) <Zaini@lkkauto.com>

Cc: Rasul (LKKAuto) <Rasul@lkkauto.com>; Wong Guo Xiang <wong.guo.xiang@simedarby.com.sg>; Natarajan Kavidha Rajan <natarajan.k.rajan@simedarby.com.sg>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>

Subject: RE: SFT 1692U

Hi Zaini,

After calculating the marked estimate.

Parts -	\$6137.10
Labour -	\$3590.00
Total -	<u>\$9727.10 (before GST)</u>

There will additional charges for diagnostic and ECU programming \$600.00 NETT .

Which then brings the total amount to \$10,327.10 (before GST)

Based on the limit repair, are we agreeable to proceed on a lump sum repair - \$8000.00 (before GST) all in with no further supplementary?

Awaiting your confirmation on this.

Thank You

Regards,
Mohamed Shabir
Operations Executive
AutoFrance (PEUGEOT) / Regent Motors (FORD)
C/O Vantage Automotive Limited
DID: 6477 7375 HP: 9278 2711

From: Rasul (LKKAuto) [<mailto:Rasul@lkkauto.com>]
Sent: Wednesday, February 28, 2018 6:02 PM
To: Mohamed Shabir Abdul Hamid <shabir.abdul.hamid@simedarby.com.sg>
Cc: Zaini (LKK Auto) <Zaini@lkkauto.com>
Subject: SFT 1692U

Hi Shabir,

As spoken, the NETT amount to repair this vehicle is 8K

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 Auto Consultants Pte Ltd *Save the Earth. Print only when necessary.*

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	21 Feb 2018 17:49	Clim Veh Model Changed	(205428) FORD MONDEO 2.0 GTDI 240PS (A).		[A] HOW MEI KWAN
2	21 Feb 2018 17:49	Clim Created	Reg No: SFT1692U. Acct Date: 2018/02/20. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Vantage Automotive Centre (HQ)		[A] HOW MEI KWAN
3	21 Feb 2018 17:49	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] HOW MEI KWAN
4	21 Feb 2018 17:49	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/02		[A] HOW MEI KWAN
5	21 Feb 2018 17:49	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides:		[A] HOW MEI KWAN
6	21 Feb 2018 17:49	Label Added	(30651):Vehicle Not In,(30653):Direct Settlement.		[A] HOW MEI KWAN
7	21 Feb 2018 17:49	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID		[A] HOW MEI KWAN
8	26 Feb 2018 09:36	Label Removed	(30650):Non-Reporting.		[A] HOW MEI KWAN
9	26 Feb 2018 11:04	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% Remarks: FILES REVIEWED. Case of O/D rear end d TP. For your approval in merimen.		[A] Zaini Bin Kusaini
10	26 Feb 2018 14:42	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/02		[I] Lalitha Krishnan
11	26 Feb 2018 14:42	Adj Mandate Set	Approved:0.00.		[I] Lalitha Krishnan
12	01 Mar 2018 16:30	Adj Adjuster Assigned	MOHD TAUFIKH BIN HAMID -> MOHD RASUL		[A] HOW MEI KWAN
13	01 Mar 2018 16:30	Label Removed	(30651):Vehicle Not In.		[A] HOW MEI KWAN
14	01 Mar 2018 16:34	Adj Rpt Initiated			[A] HOW MEI KWAN
15	01 Mar 2018 16:34	Clim Dtl Modified	Claimant's Name: -> SINGAPORE COACH SERVICES PTE L. Claimant's ID: -> 201227110H.		[A] HOW MEI KWAN
16	01 Mar 2018 16:34	Clim Details Notified			[A] HOW MEI KWAN
17	08 Jun 2018 14:34	Adj Mandate Request	Cur.Req:9166.65:PODS: LIABILITY: 100% QUANTUM: (a) COR w/GST : \$8,560.00 + (b) LOR w/GST: \$599.20 (8days x \$70) + (c) LTA : \$7.45 Total: a+b+c = \$9,166.65 VEH MODEL: FORD MONDEO 1999cc PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF		[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Full Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1736704	01/03/2018 16:34	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SFT1692U		10.70

Print Received Message

This mail is associated with :

***SFT1692U (MC2018/2166)**
[PC3406M]

TP

NG KEE CHONG

Feb 20 2018 8:00AM

[SINGAPORE COACH SERVICES PTE LTD]

Vantage Automotive Limited

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 08/06/2018 14:44 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$9166.65) - SFT1692U - Claim Handler: Lalitha Krishnan

Approved:9166.65.

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
 Tel +65 6827 7888, Fax +65 6827 7800
 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

SIME DARBY INSURANCE BROKERS (SINGAPORE) PTE. LTD.
 300 Beach Road
 #12-01/02 The Concourse
 Singapore 199597
 Tel: 6222 2244 Fax: 6294 8810

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
 Individual Ownership

SIME VANTAGE PRIVATE
 Comprehensive

Certificate No. B 27472943 SVP

Excess : SGD700

1. Index Mark and Registration Number of Vehicle

SFT1692U

2. Name of Policyholder

Ng Kee Chong

3. Effective Date of the Commencement of Insurance for the purposes of the Act

20/02/2018

4. Date of Expiry of Insurance

19/02/2019

5. Persons or Classes of Persons entitled to drive*

Ng Kee Chong

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT VANTAGE AUTOMOTIVE LTD OR AT ANY WORKSHOP OF YOUR CHOICE.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
 Approved Insurers

for Chief Executive Officer

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2507457B



Name
NG KEE CHONG

黄其聰

Race
CHINESE

Date of Birth
26-07-1966

Sex
M

Country of Birth
JOHORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S2507457B

Name
NG KEE CHONG

Birth Date: 26 Jul 1966

Issue Date: 06 Aug 2003




2034432



NRIC No: S2507457B



Blood Group: O+

Date of issue: 17-05-1994

APT BLK 336 BUKIT BATOK STREET 32 #04-303
SINGAPORE 650336


NRIC No: S2507457B Date: 15/04/1991 (R)

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE
01 Oct 1996

Licence No: S2507457B



NP 429A

SATISFACTION CUM DISCHARGE VOUCHER

Date: _____

To: India International Insurance Pte Ltd

MOTOR VEHICLE CLAIM

Vehicle Owner's Name: Ng Lee Chong

Vehicle Registration No.: SFT/6924

Make / Model: Ford Mondeo

Motor Policy Number: _____

Date of Accident: 20/02/2018

Owner's Excess: NIL

Repairs Cost: _____

I/We certify that the repairs to my/our vehicle number SFT/6924 have been completed by Regent Motors, a division of Vantage Automotive Limited, of 305 Alexandra Road, Singapore 159942, to my/our entire satisfaction. Payment of the repair charges that are claimable under the Policy will be deemed and settled by me/us.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Owner/Insured Signature: 

Date: 13/3/18

Job No.: BG 152790

Regent Motors

A division of Vantage Automotive Limited
BUSINESS REGN NO 93055549L

305 Alexandra Road Singapore 159942
Tel: 65-6376 2233 Fax: 65-6477 7300

India Int'l Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711
Attention: Motor Claims

"Without Prejudice"

03 May 2018

ACCIDENT INVOLVING VEHICLES SFT1692U & PC3406M ON 20.02.2018

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:

Cost of repair	: S\$ 8560.00
Car rental	: S\$ 599.20
LTA search fee	: S\$ 7.45
Total	: S\$ 9166.65

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill, LTA search slip, Car Rental Invoice & Rental Agreement
3. Copy of Certificate of Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@simedarby.com.sg.

Yours sincerely




Kavidha Rajan (Kavi)
Assistant Executive

Regent Motors

A division of Vantage Automotive Limited
BUSINESS NEGOT. NOT SECRET

305 Alexandra Road Singapore 159942
Tel: 65-6376 2233 Fax: 65-6477 7300

 A member of
Sime Darby Motors



LETTER OF AUTHORISATION

ACCIDENT INVOLVING SFT1692U & PC3406M ON 20/02/2018.


I, NG KEE CHONG owner of Vehicle Registration No. SFT1692U
hereby authorise Regent Motor to submit, correspond, negotiate and settle
my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise Regent Motor to execute, sign, seal and deliver all
documents whatsoever in relation to this matter and to accept and receive any payment due to
me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my
behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same
had been done or executed by me in person.

I further confirm that the acceptance by Regent Motor of the settlement
amount in respect of such claim shall constitute the full discharge of my claim in respect of such
loss and damage.

Signed by:


Name: NG KEE CHONG (Date) 28/02/2018
NRIC No.: S250745713

In the presence of:


Name: Mr Shahrir (Date) 28/02/2018
NRIC No.: S652917114

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MC2018/2166
Claimant Ref: SFT 1692U

We/I, REGENT MOTORS ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 8,560.00 (repair cost), S\$ 599.20 (loss of use/rental), S\$ 7.45 (search fee), vehicle 'no SFT 1692U that was damaged pursuant to the accident which occurred on 20/02/2018 (date) at JUNCTION OF CHOIA CHU KANG AVE & CHOIA CHU KANG LOOP (location) involving vehicle no. PC 3406M (insured vehicle). This is pursuant to the inspection conducted on 28/02/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner NG KEE CHONG ("the third party claimant") of vehicle no. SFT 1692U to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SFT 1692U (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 9,166.65 to REGENT MOTORS

Dated this 17 day of 07 2018

CLAIMANT:
Signature: [Signature]
Name: WONG GUO XIANG
NRIC: 6263833L
Address: 305 ALEXANDRA ROAD (S) 159942
Nationality: -
Occupation: -

WITNESS:

Signature: [Signature] MRB
Name: LKK AUTO CONSULTANTS PTE LTD
NRIC: 199607198R
Address: 51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK
#02-25 SINGAPORE 408933
Nationality: -
Occupation: -



REGENT MOTORS

A Division of Vantage Automotive Limited)
Co. Regs. No. 53055563L GST Regs. No. M2-0000551-1
305 Alexandra Road
Vantage Automotive Centre
Singapore 159942
Service Booking: 6477 7399
Parts: 6477 7420
Vantage 24-Hour Assist: 6473 8588
Fax: 6477 7300



SERVICE TAX INVOICE

REPAIR ORDER NO. BG 152790	Date IN 05/03/2018	Invoice Number 5318973 / WSH	Page No. 1 of 1		
	Payment Term 30 Days From Invoice	Invoice Date 27/03/2018	Invoice By Natarajan Kavidha Rajan		
CUSTOMER INFORMATION		INVOICE TO 35			
Ng Kee Chong Blk 336 Bukit Batok St 32 #04-303 Singapore 650336		India Int'l Insurance Pte Ltd 64 Cecil Street #04/05 IOB Building Singapore 049711			
REGISTRATION No. SFT1692U	CHASSIS No. WF0EXXGBBECC12812	STOCK No. 14048	REGISTRATION DATE 20/02/2013	MODEL MON TTN 5DR	MILEAGE 96498

CODE	DESCRIPTION	UNITS	NETT
	LUMP SUM REPAIR DOA: 20.02.2018	1	8,000.00
Sub-Total :			8,000.00

Attending CSO : Mohamed Shabir Abdul Hamid
Should you require further explanation, please reach me at

Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$	8,000.00
Labour Charges	8,000.00	Less Insurance Excess	S\$	0.00
Parts Charges	0.00	GST @ 7%	S\$	560.00
Lubricant/Misc	0.00	Invoice Total Amounts	S\$	8,560.00
		Less Deposit/Voucher	S\$	0.00
Computer generated invoice. No signature is required.		Amount Payable	S\$	8,560.00

All amounts are in Singapore Dollars.
Work was carried out subject to the Company's Terms and Conditions of Service.
No complaints will be entertained unless reported within seven (7) days of the date of this invoice.
For credit purchases, interest @1% per month will be debited on overdue amounts.





TAX INVOICE

Invoice No. 55 - 510990

Page 1 of 1

MR NG KEE CHONG

BLK 336 BUKIT BATOK STREET 32 #04-303
650336 SINGAPORE

SIME DARBY SERVICES PTE LTD

Thrifty International Licensee

305 Alexandra Road, #03-01

Vantage Automotive Centre, Singapore 159942

p (65) 6447.3388 f (65) 6345.7247

Co. Reg. No. 197501065W GST Reg. No. M2-0021986-4

INVOICE DATE : 13-MAR 2018

R.A. No. 55004581 / Muhammad Lukman bin Mohamed Sidek

TITLE	: MR	KILOMETER OUT/IN	: 29967 / 30480
AUTHORIZED DRIVER	: NG KEE CHONG	KILOMETER DRIVEN	: 513
NRIC/PASSPORT NO.	: S2507457B	PETROL LEVEL OUT/IN	: FULL / FULL
MAKE & MODEL	: MAZDA 3 HB 5 DR	DATE & TIME OUT	: 05-MAR 2018 13:45
CAR REGISTRATION NO.	: SKX3272E / UNIT # : 0002727	DATE & TIME IN	: 13-MAR 2018 13:20
CAR GROUP GIVEN	: G	CHECK IN LOCATION	: SHORT TERM-HQ (SIN55)-THRIFTY
CAR GROUP CHARGED	: F	NO. OF DAY(S) CHARGED	: 8 DAY(S)

DESCRIPTION	UNIT PRICE (SGD)	UNIT	AMOUNT BEFORE GST (SGD)	GST @ 7%	AMOUNT (SGD)
INSURANCE CLAIMS RATES 2017					
8 DAY(S) @ \$70.00 / DAY			560.00	39.20	599.20
SUB-TOTAL			560.00	39.20	599.20
REMARKS: SFT1692U CSA: SHABIR (CLAIMS)					
		TOTAL (SGD) :	560.00	39.20	599.20
* ITEMS NOT SUBJECT TO GST					
		MC XXXXXXXXXXXXX2882			-599.20
		BALANCE DUE			0.00

NOTE:

I/ WE HEREBY AGREE TO THE TERMS AND CONDITIONS AND BE HELD LIABLE FOR ALL AMOUNT DUE UNDER THIS AGREEMENT; ALL TRAFFIC FINES INCLUDING ADMIN FEES INCURRED DURING PERIOD OF HIRE; ANY COSTS INCURRED BY SIME DARBY SERVICES PTE LTD FOR MY FAILURE TO REPORT ANY ACCIDENT WITHIN 24 HOURS. FINAL CHARGES IS SUBJECT TO FULL INSPECTION OF THE VEHICLE BY A COMPANY REPRESENTATIVE.

HIRER'S AND/OR ADDITIONAL DRIVER'S SIGNATURE

Printed on 13-Mar-2018 13:25

Entered by Muhammad Lukman bin Mohamed

**SIME DARBY SERVICES PTE LTD**

Thrifty International Licensee

305 Alexandra Road, #03-01
Vantage Automotive Centre, Singapore 159942
p (65) 6447.3388 f (65) 6345.7247
Co. Reg. No. 197501065W GST Reg. No. M2-0021986-4

TO BE PAID BY

PAYMENT : MC - XXXXXXXXXXXXXXX2882

HIRER'S DETAILS

TITLE : MR
NAME : NG KEE CHONG
ADDRESS : BLK 336 BUKIT BATOK STREET 32
#04-303
650336
SINGAPORE

NRIC/PASSPORT NO. : S2507457B ISSUE: 17/05/1994
ISSUED BY : SINGAPORE
LICENSE : S2507457B EXPIRY: 30/12/2999
ISSUED BY : SINGAPORE
NATIONALITY : SINGAPOREAN D.O.B.: 26/07/1986
FREQUENT FLYER NO. :
LOCAL CONTACT : 9800 9629
HOTEL :
COMPANY'S DETAILS
NAME :
ADDRESS :

IMPORTANT NOTICE

- Hirer is liable for all traffic fines including admin fees that are issued by Singapore or Malaysia authorities for a grace period of 12 months from the date of car return.
- A security deposit depending on the respective car group rented will be withheld on the Hirer's credit card.
- Any accident has to be reported within the next working day to Sime Darby Services Pte Ltd. In the event of failure to report, hirer shall be liable for any costs incurred by Sime Darby Services Pte Ltd or claims made by the other party.
- Smoking, durians and pets are not allowed in the vehicle. An additional 3 day's rental would be imposed if smoking and durian smell/pet's fur is detected upon car return.
- Hirer must inform Sime Darby Services Pte Ltd in advance for vehicle drop-off in Thrifty Malaysia renting location. A one-way rental fee and Malaysia surcharge are applicable as stated in our One Way Rental policy.
- Hirer is responsible for any missing items/car accessories or loss of keys will be charged accordingly.
- The excess do not cover i) Car accessories ii) Loss of key iii) Vandalism iv) Alcohol/intoxicants/drugs.
- Vehicles are prohibited to be driven into Thailand.

The vehicle is rented subject to all terms and conditions on this page and on the reverse side whether printed or handwritten. Hirer represents that they have read, understand and agree with the conditions of the rental agreement. The hirer authorises all amounts due under the rental agreement to be charged to the hirer's credit card shown on this form.

x

Hirer

x

Additional Driver

ADDITIONAL DRIVERS:

RENTAL AGREEMENT NUMBER : 55004581
RENTAL LOCATION : SHORT TERM-HQ (SIN55)-THRIFTY

CHECKOUT

UNIT # / REGN NO. : 00002727 / SKX3272E
MAKE & MODEL : MAZDA 3 HB 5 DR
CAR GROUP GIVEN : G CHARGE: F
KILOMETER OUT : 29,967
PETROL LEVEL OUT : FULL
DATE & TIME OUT : 05/03/2018 13:45
EST.DUE DATE & TIME IN : 12/03/2018 13:45
CHECKIN LOCATION : SHORT TERM-HQ (SIN55)-THRIFTY

RENTAL RATES

AS: INSURANCE CLAIMS RATES 2017
DAILY @ S\$ 70.00
EXTRA DAY @ S\$ 70.00
EXTRA HOUR @ S\$ 14.00

FOR RATES TO APPLY

MINIMUM 24 HOURS. CAR MUST BE RETURNED TO RENTING LOCATION ON THE DUE DATE

INSURANCE

BY INITIALS, THE HIRER
ACCEPTS SPS @ S\$ 45.00 PER DAY
NON-WAIVERABLE DAMAGE EXCESS: S\$ 0.00 (SIN USE)

ACCEPTS PAI @ S\$ 5.00 PER DAY

ACCEPTS WSC @ S\$ 5.00 PER DAY

THIS CAR IS FOR SINGAPORE USE ONLY. THERE IS NO INSURANCE COVERAGE FOR USE OUTSIDE SINGAPORE

OTHER CHARGES

FUEL SERVICES @ S\$2.70 / LITRE

CASH & CHEQUE DEPOSIT**REMARKS**

SFT1692U
CSA: SHABIR (CLAIMS)

HI RESERVATION

RES. ID# SD000003334 TACO#:
Muhammad Lukman bin Mohamed Sik REF SRC: INSCLAIMS

Printed on 05-Mar-2018 13:42
Entered by: Muhammad Lukman bin Mohamed

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 21 Feb 2018 / 14:59:48

Receipt Date/Time : 21 Feb 2018 / 14:59:31

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180221-001329

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Result of Insurance Enquiry - PC3406M As at 20 Feb 2018/08:35:00 Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - PC3406M Enquiry Fee 20180221145827566445	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx5164	Credit Card: Visa /MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)






































Direct Settlement




























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Feb 2018 Edit Reg		28 Feb 2018 00:00 Edit Adj Rpt	S\$8,000.00 Edit Estimates	S\$8,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	SINGAPORE COACH SERVICES PTE LTD, Co, Reg. No.: 201227110H								
Main Claimant:	NG KEE CHONG, ID: S2507457B								
Vehicle Reg. No.:	SFT1692U	Date of Loss:	20/02/2018 08:00 - :59 [60 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MC2018/2166	Policy/Cover Note No.:	M495163						
Vehicle Reg. No. (Insured):	PC3406M	Policy No. (Claimant):	B27472943SVP						
		Excess:							
Repairer:	Regent Motors - 305 Alexandra Road (HQ) 305 Alexandra Road, 159942 Alexandra - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Lalitha Krishnan - 6347 6139]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 02/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (08/06/2018): Alert - Adj Mandate Approved (S\$9166.65) - SFT1692U - Claim Handler: Lalitha Kri... III_SG (26/02/2018): Alert - Adj Mandate Approved (S\$0.00) - SFT1692U - Claim Handler: Lalitha Krishn... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SFT1692U (MC2018/2166)**
[PC3406M]
TP
NG KEE CHONG
Feb 20 2018 8:00AM
[SINGAPORE COACH SERVICES PTE LTD]
Regent Motors - 305 Alexandra Road

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/05/18 10:20	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	09/05/18 10:20	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
3	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
4	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
5	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
6	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
7	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
8	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
9	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
10	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
11	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
12	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
13	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
14	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
15	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
16	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
17	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
18	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
19	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
20	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
21	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
22	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
23	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
24	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
25	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
26	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
27	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
28	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
29	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
30	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
31	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
32	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
33	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
34	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
35	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
36	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
37	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
39	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
40	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
41	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
42	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
43	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
44	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
45	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
46	09/05/18 10:20	General View	 Load JPG	<input checked="" type="checkbox"/>
47	09/05/18 10:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	09/05/18 10:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	09/05/18 10:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	09/05/18 10:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	09/05/18 10:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	09/05/18 10:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	09/05/18 10:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	09/05/18 10:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/02/18 17:54	TP ESTIMATE	 Load PDF	
2	21/02/18 17:54	TP GIA REPORT	 Load PDF	
3	26/02/18 09:36	OI GIA REPORT	 Load PDF	
4	06/06/18 08:51	WORKSHOP INVOICE	 Load PDF	
5	06/06/18 08:51	RENTAL RECEIPT	 Load PDF	
6	06/06/18 08:51	LTA SEARCH	 Load PDF	
7	06/06/18 08:51	LOD	 Load PDF	
8	08/06/18 14:37	LTA REBATE	 Load PDF	
9	18/07/18 09:22	DISCHARGE VOUCHER	 Load PDF	
10	18/07/18 09:22	AUTHORISATION TO ACT FORM	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18003323/R1EA3Q2

Date: 18/07/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: M495163

Claimant Vehicle No: SFT1692U

Insured Vehicle No: PC3406M

Date of Loss: 20/02/2018

Nature of Claim: TP

Claim No: MC2018/2166

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFT1692U

Make & Model: FORD MONDEO, 2.0 GTDI 240PS (A)

Engine No: CC12812

Reg. Date: 20/02/2013 (Man. Year: 2012)

Chassis No: WF0EXXGBBECC12812

Colour: Grey

Odometer: 96217 km

Engine Capacity: 1999 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50Z R17

Rear Tyre Size: 215/50Z R17

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,638.40	6,167.10	4,471.30	42.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,620.00	3,910.00	4,710.00	54.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,258.40	10,077.10	9,181.30	47.67
Approved Total (Overridden) (S\$)		8,000.00		
(S\$)	19,258.40	8,000.00	11,258.40	58.46
+ GST 7.00/7.00% (S\$)	1,348.09	560.00	788.09	58.46
Nett Amount (S\$)	20,606.49	8,560.00	12,046.49	58.46
+ Car Rental (8.0 x S\$70.00/day + 7.00% GST) (S\$)		599.20		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,166.65		

INSPECTION

Date of Assignment: 28/02/2018

Date Inspected: 28/02/2018

Inspected At:

Regent Motors (HQ)
305 Alexandra Road
Singapore 159942

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jun 2018)
Parts:	143	FORD MONDEO 2.0 GTDI 240PS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFT1692U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*30.00 FS
2	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	70.00 FS	*- FS
3	1		*TAILGATE ASSY	Buckled	2,385.00 FS	*2,385.00 FS
4	1		*RHR BUMPER BRACKET	Not Necessary	76.50 FS	*- FS
5	1		*LHR BUMPER BRACKET	Not Necessary	76.50 FS	*- FS
6	1		*BOOT LID HANDLE ,PRIMED -M07	Deformed	295.20 FS	*295.20 FS
7	1		*BOOT LID LWR PANEL ,PRIMED -M07	Deformed	360.90 FS	*360.90 FS
8	1		*TAILGATE WEATHERSTRIP -M07	Necessary	265.50 FS	*265.50 FS
9	1		*REAR WINDSCREEN -MON .2.0L ECO 5DR	Necessary	648.00 FS	*648.00 FS
10	1		*WINDSCREEN SPACER	Necessary	9.00 FS	*9.00 FS
11	1		*SPACER (NPA)	Necessary	0.00 FS	*- FS
12	1		*FRT & RR FORD BADGE	Necessary	124.20 FS	*124.20 FS
13	1		*RR EMBLEM MONDEO-M07	Necessary	117.00 FS	*117.00 FS
14	1		*THIRD BRAKE LAMP ASSY	Cracked	175.50 FS	*175.50 FS
15	2		*LAMP -LIC .PLATE	Not Necessary	198.00 FS	*- FS
16	1		*RHR INNER LAMP ASSY	Broken	513.00 FS	*513.00 FS
17	1		*LHR INNER LAMP ASSY -M07	Broken	513.00 FS	*513.00 FS
18	1		*LAMP ASSY RHR OUTER	Cracked	558.00 FS	*558.00 FS
19	1		*LAMP ASSY -REAR ,LH -OUTER	Not Necessary	540.00 FS	*- FS
20	1		*BUMPER -REAR	Repair	1,405.80 FS	*- FS
21	1		*RHR BUMPER SIDE BRACKET	Not Necessary	99.00 FS	*- FS
22	1		*LHR BUMPER SIDE BRACKET	Not Necessary	99.00 FS	*- FS
23	1		*RR BPR EXTENSION DUAL EXH-M07	Not Necessary	342.00 FS	*- FS
24	1		*RHR BPR REINF .BRACKET -M07	Not Necessary	165.60 FS	*- FS
25	1		*LHR BPR REINF .BRACKET -M07	Not Necessary	167.40 FS	*- FS
26	1		*RR BUMPER REINFORCEMENT -M07	Not Necessary	985.50 FS	*- FS
27	2		*RR BUMPER LWR MTG BRACKET	Not Necessary	97.20 FS	*- FS
28	4		*CLIP -F08,M07	Not Necessary	28.80 FS	*- FS
29	4		*RR PARKING AID BRACKET ,UNPRIMED	Necessary	172.80 FS	*172.80 FS
					Total Parts (S\$)	10,638.40 6,167.10

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ELECTRICAL WIRING CHECK FOR RPOPER FUNCTIONING	New	150.00	150.00
2	TO REMOVE AND REFIX REAR BUMPER REVERSE SENSORS	New	150.00	150.00
3	TO REMOVE AND REPLACE /REFIC REAR WINDSCREEN	New	600.00	600.00
4	SEALANT FOR REAR WINDSCREEN	New	60.00	60.00
5	INNER SEAL FOR REAR WINDSCREEN	New	50.00	50.00
6	TO SUPPLY AND INSTALL 3M SOLAR FILM FOR REAR WINDSCREEN	New	350.00	350.00
7	TO TRANSFER REAR BOOT MECHANISMS ,COMPONENTS,LOCKS ,TRIMS ,CLIPS	New	300.00	300.00
8	TUFF KOTE-BODY CAVITY PRESERVATION	New	180.00	60.00
9	SEALANT FOR BODY PANELS	New	180.00	90.00
10	TO REPAIR ,REPLACE REAR BOOT ,REAR WINDSCREEN ,REAR BUMPER REAR END PANEL,BUMPER BRACKET TAIL LAMPS ,3RD BRAKE LIGHT REINFORCEMENT ,REAR BUMPER SIDE RETAINER AND ALL OTHER AFFECTED PARTS AND AREAS	New	3,600.00	900.00
11	TO SPRAY PAINT REAR BUMPER ,REAR END PANEL,REAR BOOT ,REAR FENDER ,TAIL LAMP PANEL ,AND ALL OTHER AFFECTED AREAS	New	3,000.00	1,200.00
Gross Labour Cost (\$\$)			8,620.00	3,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >