

22/03/2002

ASS. REC. BY:

REF:

CS/MS418003384/119d302

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Vimala

of

MUSG

Date/Time:

21/2/18

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKD 1716K

Insured:

at Workshop m/s

CSC

Tel:

91865300

of

188 Pandan Loop

Policy No:

A 29038958 RMY

Claim No:

55033

Sum Insured:

Excess:

1000

Make of Veh:

(Client's Record)

D.O.A.

19/2/18

CA/REV

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction ()

Estimate

SKD 1716K &

21/2/18 @ 4.53pm revert to Vimala via Meimen.

23/2/18 @ 9.05am Huey Ni informed C/A via Meimen.

23/2/18 @ 1.20pm informed Eric C/A & EX: \$1000 by email.

12/2/18 @ 3.09pm 2nd revert to Vimala via Meimen. (supplementary).

16/2/18 @ 5.27pm Huey Ni informed C/A at \$14478.34 via Meimen.

Surveyor Taylor

REF:

m826

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 1000

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<div style="text-align: center;">X</div>	
N/S	O/S

Bal. or Market Value: 41081

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / ☒ EV / REP. / 24 HRS

Date: _____ Person Contacted: Eric Vehicle: IN / OUT

Veh No: SKD1716K Yr Regn: 2011 Nov

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz S300L cc 2997

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 69469 T. Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2211542A325792

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 255/45R18

R: 255/45R18

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 21/6/2018 4pm

Survey held at QC Ponder Corp

Des. of Damages: ☒ Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/7/18 @ 4.58pm confirmed with Eric final fig 14478.34, 5 days.
Used 4 9285.21, 34%

RECEIVED 20 JUL 2018

[Signature]
20/7/2018

Date/Time File Pass to?

☐ : Preli. Report

17/7/18 turnover

☐ : Final Report

Date/Time File Return to?

2) _____

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation

3 + RG 51

Photos

Others

TOTAL

Add Fee: ☐ Site Insp 5

☐ Interview 5

☐ Tech. Invs 5

☐ Weekend 5

Report Format: MEP-00

Lump Sum / I.B.I. (S) 14478.34

300

10

310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003384/T1qd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 22-02-2018



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKD 1716K
Policy No.	A29038958QMY	Coverage (\$)	0.00
Claim No.	550033	Excess (\$)	1,000.00
Assign From	MERIMEN (VIMMALA)	Assign Date	21/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	19/02/2018	Inspection Date	21/02/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Feb 2018		21 Feb 2018 10:19 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LEE CHIN PHENG, ID: S2561913G, Tel: +6593396530, Email: NOEMAIL		
Vehicle Reg. No.:	SKD1716K	Date of Loss:	19/02/2018 10:00 - :59
Claim Type:	OD / 550033	Policy/Cover Note No.:	A29038958QMY (Comprehensive) Coverage: 08/11/2017 - 07/11/2018
		Excess:	S\$1,000.00
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/02/2018]		
Driver/Custodian:	LEE CHIN PHENG (59 / Male), NRIC: S2561913G, Tel: +6593396530		
Adj Asg. Remarks:	Please revert and survey the vehicle by today. Surveyor-please check on the market value and rebates to determine if the vehicle is economical to repair. Thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 17 July 2018 4:58 PM
To: Eric Lee Ming Hui; SUR
Subject: RE: SKD1716K Finalize

Dear Eric,

Confirm final fig \$14,478.34 before excess \$1,000.00 & GST and 5 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Shiau Chan (LKKAuto)

Sent: Monday, 9 April 2018 9:31 AM

To: Eric Lee Ming Hui <eric.lee@cyclecarriage.com.sg>; SUR <sur@lkkauto.com>

Cc: Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Subject: RE: SKD1716K Finalize

Dear Eric,

Received with thanks.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Eric Lee Ming Hui [<mailto:eric.lee@cyclecarriage.com.sg>]

Sent: Saturday, 7 April 2018 8:36 AM

To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Subject: RE: SKD1716K Finalize

Dear Shiau,

As per attached.

Thank you

Your Sincerely,

Eric Lee Ming Hui

Service Advisor - Body Care & Repair

Mercedes-Benz Body Care & Repair Center

Cycle & Carriage Industries Pte Ltd

188 Pandan Loop Service Center

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	20 Feb 2018 14:36	Clim Veh Model Changed	(203704) MERCEDES-BENZ S300L 3.0 (A).	[I] Vimmala D/O Raja Singam	
2	20 Feb 2018 14:36	Clim Created	Reg No: SKD1716K, Policy No: A29038958QMY, Acct Date: 2018/02/19, Claim Type: S C, Insurer: MSIG Insurance (Singapore) Pte. Ltd, (HQ), Ins.Status => Notification, Created from SAS:MCC418024428	[I] Vimmala D/O Raja Singam	
3	21 Feb 2018 09:44	Notification Status Changed	Ins.Status => Incoming Claim	[I] Vimmala D/O Raja Singam	
4	21 Feb 2018 09:44	Clim Registration Modified	Setl.Type:3->0, Rep:1137->200065, Claim Type:SC->OD, Init.Est.:>20,000 - 25,000.	[I] Vimmala D/O Raja Singam	
5	21 Feb 2018 09:49	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please revert. Surveyor-please check on the market value and rebates to determine if the vehicle is economical to repair. Thank you.	[I] Vimmala D/O Raja Singam	
6	21 Feb 2018 09:49	Adj Next Rpt Changed	Next Rpt:Im, Advice.Due Date:2018/02/22	[I] Vimmala D/O Raja Singam	
7	21 Feb 2018 09:49	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Vimmala D/O Raja Singam	
8	21 Feb 2018 09:58	Assignment 1st Accessed		[A] Ho Pei Fang	
9	21 Feb 2018 10:17	Adj Assignment Cancelled	IHS ON LEAVE	[I] Vimmala D/O Raja Singam	
10	21 Feb 2018 10:17	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Vimmala D/O Raja Singam	
11	21 Feb 2018 10:19	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert and survey the vehicle by today. Surveyor-please check on the market value and rebates to determine if the vehicle is economical to repair. Thank you.	[I] Vimmala D/O Raja Singam	
12	21 Feb 2018 10:19	Adj Next Rpt Changed	Next Rpt:Im, Advice.Due Date:2018/02/22	[I] Vimmala D/O Raja Singam	
13	21 Feb 2018 10:19	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Vimmala D/O Raja Singam	
14	21 Feb 2018 15:54	Assignment 1st Accessed		[A] CELINE FONG	
15	22 Feb 2018 16:28	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] SHIAU CHAN	
16	22 Feb 2018 16:30	Adj Rpt Initiated		[A] SHIAU CHAN	
17	22 Feb 2018 16:52	Adj Im, Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/03/23	[A] SHIAU CHAN	
18	22 Feb 2018 16:52	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/23	[A] SHIAU CHAN	

AUDIT TRAIL				
Nb.	On	Audit	Remarks	By
19	22 Feb 2018 16:53	Adj Mandate Request	Cur.Req:20851.16:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
20	23 Feb 2018 09:05	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/23. Mandate Remarks: approved mandate \$817 0.11 (before excess \$1000). Check items of \$12681.05 to be verified	[I] Eng Huey Ni
21	23 Feb 2018 09:05	Adj Mandate Set	Approved:8170.11:approved mandate \$8170.11 (before excess \$1000). Check items of \$12681.05 to be verified	[I] Eng Huey Ni
22	12 Jul 2018 15:08	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/03/23	[A] SHIAU CHAN
23	12 Jul 2018 15:09	Adj Mandate Request	Cur.Req:14478.34:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. KINDLY APPR OVE ON CHECK ITEMS & SUPPLEMENTARY.	[A] SHIAU CHAN
24	16 Jul 2018 17:22	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/23. Mandate Remarks: approved mandate \$817 0.11 (before excess \$1000). Check items of \$12681.05 to be verified	[I] Eng Huey Ni
25	16 Jul 2018 17:22	Adj Mandate Set	Approved:14478.34:approved mandate \$8170.11 (before excess \$1000). Check items of \$12681.05 to be verified	[I] Eng Huey Ni

Date From Date To Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1729559	22/02/2018 16:30	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKD1716K		10.70

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimmala D/O Raja Singam

Date: 12 Jul 2018

Preliminary Advice

Vehicle No	: SKD1716K	Accident Date	: 19/02/2018
Make	: MERCEDES-BENZ S300L	Policy No.	: A29038958QMY
Assignment Date	: 21/02/2018	Excess	: S\$1,000.00
Date of Inspection	: 21/02/2018	Est. Duration of Repair	: 5.00
Inspection At	: CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP) 188 PANDAN LOOP SINGAPORE 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,763.55	(ESTIMATE \$21,995.09 + SUPPLEMENTARY \$1,768.46)
Revised Amount	:S\$	14,478.34	(INCLUSIVE OF CHECK ITEMS & SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	14,478.34	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	108,000.00
COE / PARF Rebate	:S\$	78,500.00
Salvage Value	:S\$	
Margin for Repair	:S\$	29,500.00

Remarks

- (X) The vehicle is economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVE CHECK ITEMS & SUPPLEMENTARY.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 23 February 2018 1:20 PM
To: Eric Lee Ming Hui
Cc: Cheong Chin Leong; SUR
Subject: VEHICLE SKD 1716K (DOA: 19/02/2018)

Dear Eric,

As instructed by our client MSIG , please proceed to repair the insured vehicle **SKD 1716K (Excess \$1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUDIT TRAIL				
No.	On	Audit	Remarks	By
18	22 Feb 2018 16:52	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/23	[A] SHIAU CHAN
19	22 Feb 2018 16:53	Adj Mandate Request	Cur.Req:20851.16:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
20	23 Feb 2018 09:05	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/23. Mandate Remarks: approved mandate \$8170.11 (before excess \$1000). Check items of \$12681.05 to be verified	[I] Eng Huey Ni
21	23 Feb 2018 09:05	Adj Mandate Set	Approved:8170.11:approved mandate \$8170.11 (before excess \$1000). Check items of \$12681.05 to be verified	[I] Eng Huey Ni

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1729559	22/02/2018 16:30	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKD1716K		10.70

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	20 Feb 2018 14:36	Clim Veh Model Changed	(203704) MERCEDES-BENZ S300L 3.0 (A).	Vimmala D/O Raja Singam [I]
2	20 Feb 2018 14:36	Clim Created	Reg No: SKD1716K. Policy No: A29038958QMY. Acct Date: 2018/02/19. Claim Type: SC. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => Notification. Created from SAS:MCC418024428	Vimmala D/O Raja Singam [I]
3	21 Feb 2018 09:44	Notification Status Changed	Ins.Status => Incoming Claim	Vimmala D/O Raja Singam [I]
4	21 Feb 2018 09:44	Clim Registration Modified	Setl.Type:3->0. Rep:1137->200065. Claim Type:SC->OD. Init.Est.->20,000 - 25,000.	Vimmala D/O Raja Singam [I]
5	21 Feb 2018 09:49	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please revert. Surveyor-please check on the market value and rebates to determine if the vehicle is economical to repair. Thank you.	Vimmala D/O Raja Singam [I]
6	21 Feb 2018 09:49	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/02/22	Vimmala D/O Raja Singam [I]
7	21 Feb 2018 09:49	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	Vimmala D/O Raja Singam [A] Ho Pei Fang
8	21 Feb 2018 09:58	Assignment 1st Accessed		[I]
9	21 Feb 2018 10:17	Adj Assignment Cancelled	IHS ON LEAVE	Vimmala D/O Raja Singam [I]
10	21 Feb 2018 10:17	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	Vimmala D/O Raja Singam [I]
11	21 Feb 2018 10:19	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert and survey the vehicle by today. Surveyor-please check on the market value and rebates to determine if the vehicle is economical to repair. Thank you.	Vimmala D/O Raja Singam [I]
12	21 Feb 2018 10:19	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/02/22	Vimmala D/O Raja Singam [I]
13	21 Feb 2018 10:19	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	Vimmala D/O Raja Singam [A]
14	21 Feb 2018 15:54	Assignment 1st Accessed		CELINE FONG
15	22 Feb 2018 16:28	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] SHIAU CHAN
16	22 Feb 2018 16:30	Adj Rpt Initiated		[A] SHIAU CHAN
17	22 Feb 2018 16:52	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/03/23	[A] SHIAU CHAN

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimimala D/O Raja Singam

Date: 22 Feb 2018

Preliminary Advice

Vehicle No	: SKD1716K	Accident Date	: 19/02/2018
Make	: MERCEDES-BENZ S300L	Policy No.	: A29038958QMY
Assignment Date	: 21/02/2018	Excess	: S\$1,000.00
Date of Inspection	: 21/02/2018	Est. Duration of Repair	: 5.00
Inspection At	: CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP) 188 PANDAN LOOP SINGAPORE 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,691.16
Revised Amount	:S\$	8,170.11
Check Items (Estimated)	:S\$	12,681.05
Total	:S\$	20,851.16
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	108,000.00
COE / PARF Rebate	:S\$	78,500.00
Salvage Value	:S\$	
Margin for Repair	:S\$	29,500.00

Remarks

- (X) The vehicle is economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.
WE HAVE NOT AUTHORISE REPAIR.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1913G
Vehicle Details	
Vehicle No.:	SKD1716K
Vehicle to be Exported:	No
Intended De-registration Date:	22 Feb 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	S300L
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	27294631807112
Chassis No.:	WDD2211542A393792
Maximum Power Output:	170.0 kW (227 bhp)
Open Market Value:	\$85,255.00
Original Registration Date:	02 Nov 2011
First Registration Date:	02 Nov 2011
Transfer Count:	1
Actual ARF Paid:	\$85,255.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Nov 2021
PARF Rebate Amount:	\$55,415.00
Intended COE Rebate Details	
COE Expiry Date:	01 Nov 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$62,502.00
COE Rebate Amount:	\$23,085.00
Total Rebate Amount:	\$78,500.00

The information contained herein is correct as at 22 Feb 2018

OK

- SIA crew appraisal system
- Public Alcohol consumption bill-Cannot have a beer at...
- UCL 17/18 : The European Elite Football Clubs

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2015 Subaru Forester XT 2L Turbocharged.



Low Mileage And W Lots Of
Accessories.
Direct Owner StarAd

KA-HUP

**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997 [view our cars](#)

Browse by Category ▾

Sort by Date Posted ▾

20 results/page ▾

7 vehicles

MERCEDES S300

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	MERCEDES S300		Any	Any	2011	Any	Any	Any	Available
	Mercedes-Benz S-Class S300L		\$109,000	\$17,670 /yr	24-Nov-2011	2,997 cc	122,000 km	Luxury	Available
Open During CNY, AMG Line Sunroof, Auspicious Plate Number, Immaculate Condition, Accident Free, Bank Loan 84K Available, Low Down Payment, Price Inclusive Of GST									
Posted: 14-Feb-2018 Tags: 2011 Mercedes-Benz S300L, Mercedes-Benz S300L, Mercedes-Benz, S300L, Used Mercedes-Benz									
	Mercedes-Benz S-Class S300L		\$107,800	\$19,220 /yr	17-Jun-2011	2,997 cc	76,000 km	Luxury	Available
Graded B by STA 1 And Only Year 2011 1 Owner Unit In Market. From Agent C&C. Maintained By Agent With Accident Free And Low Mileage Done.Own This Luxurious, Comfortable And Spacious Sedan Now. Condition Close To Perf...									
Posted: 13-Feb-2018 Tags: 2011 Mercedes-Benz S300L, Mercedes-Benz S300L, Mercedes-Benz, S300L, Used Mercedes-Benz									
	Mercedes-Benz S-Class S300L		\$101,500	\$19,620 /yr	26-Jan-2011	2,997 cc	114,000 km	Luxury	Available
Chinese New Year Promo, Only 1.98% Interest! Advance Installment! Price Reduced! Down Payment \$10150 Monthly At \$1,855, C&C Maintained Unit, Comfortable And Spacious Sedan Now. Condition Close To Perf...									
Privilege Motors Pte Ltd Posted: 06-Feb-2018 Tags: 2011 Mercedes-Benz S300L, Mercedes-Benz S300L, Mercedes-Benz, S300L, Used Mercedes-Benz									
	Mercedes-Benz S-Class S300L		\$110,800	\$19,620 /yr	18-Jul-2011	2,997 cc	78,200 km	Luxury	Available
Looking For Something Large, Comfort Drive? Come And Test It. Come With 6 Months Warranty For Peace Of Mind! Very Well Maintain, Excellent Black Interior And Exterior Conditions! Immaculate Condition,...									
Atlantic Automobile Pte Ltd Posted: 06-Feb-2018 Tags: 2011 Mercedes-Benz S300L, Mercedes-Benz S300L, Mercedes-Benz, S300L, Used Mercedes-Benz									
Car Buying Car Selling Car Aftermarket									
Car Ownership On The Move Lifestyle									
Buy Tyres Online! Latest Special Offers from Tyrepac!									
	Mercedes-Benz S-Class S300L		\$109,800	\$17,550 /yr	20-Dec-2011	2,997 cc	139,900 km	Luxury	Available
One Life, Two Joys - The Grey S300L Features Everything You Want In A Luxury Sedan - Comfort, Style, Technology. Decked Out In Cream Interior, And Well Taken Of By Its Owner, It Is In An Excellent Con...									
Cars & Yachts Pte Ltd Posted: 02-Feb-2018 Tags: 2011 Mercedes-Benz S300L, Mercedes-Benz S300L, Mercedes-Benz, S300L, Used Mercedes-Benz									
	Mercedes-Benz S-Class S300L		\$103,800	\$18,600 /yr	10-May-2011	2,997 cc	142,000 km	Luxury	Available
1 Owner And Fully Serviced By C&C! Exterior And Interior In Excellent Condition. Luxurious And Spacious, Perfect For 5 Adults To Lounge In Comfort! 100% Accident Free And STA Evaluations Are Welcome! ...									
Posted: 26-Jan-2018 Tags: 2011 Mercedes-Benz S300L, Mercedes-Benz S300L, Mercedes-Benz, S300L, Used Mercedes-Benz									
	Mercedes-Benz S-Class S300L		\$112,800	\$20,420 /yr	05-Jul-2011	2,997 cc	68,127 km	Luxury	Available
Classic Black Brings Exterior. Bring Out The Essence Of Luxury. Well Maintained. Call Now To View.									
Posted: 21-Dec-2017 Tags: 2011 Mercedes-Benz S300L, Mercedes-Benz S300L, Mercedes-Benz, S300L, Used Mercedes-Benz									

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view **Expired ads**

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagon, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used MERCEDES S300 Singapore, used MERCEDES S300 Singapore, used MERCEDES S300, used vehicles Singapore or even buy used MERCEDES S300 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/02/2018 13:57
Date Of Accident	19/02/2018 10:30
Exact Location Of Accident	ALONG KOTA TINGGI ULU SUNGAI SEDILI BESAR
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD1716K
Insured/Policyholder	
Name Of Registered Owner	LEE CHIN PHENG
NRIC No	S2561913G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93396530
Alternative Phone No	OFFICE-93396530

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	S300

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29038958QMY
Cover Note Number	

Driver

Name of Driver	LEE CHIN PHENG
NRIC No	S2561913G
Date Of Birth	20/05/1958
Occupation	INDOOR
Date Of Driving Pass	18/06/1988
Driving Experience	29 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93396530
Fax Number	
Contact Number	OFFICE-93396530
Email Address	NOEMAIL

Address	32 JALAN RAJAH #02-03 RAJA TOWER
Postcode	329141
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT BY FALLEN TREE / OTHER OBJECTS
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : MALE
Passenger 4	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG WHEN A WILD BOAR SUDDENLY DASH ACROSS. MY VEHICLE HIT AND WENT OVER THE WILD BOAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Eric Lee Ming Hui
DID : 6771 4336 HP : 9181 7717
Email : eric.lee@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Reporting Centre Personnel's
Name:
NRIC/FIN No.:

I WAS DRIVING ALONG WHEN A WILD BOAR SUDDENLY DASH ACROSS. MY VEHICLE HIT & WENT OVER THE WILD BOAR.

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

DID : 6771 4336 HP : 9181 7717

Email : eric.lee@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Policyholder's Signature

Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's

Name: _____

NRIC/FIN No.:

**MSIG****MSIG Insurance (Singapore) Pte. Ltd.**

4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807

Tel +65 6827 7888, Fax +65 6827 7800

Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

MOTOR MAX PLUS
Comprehensive

Certificate No. A 29038958 QMY

Excess : SGD1,000

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SKD1716K

2. Name of Policyholder
Lee Chin Pheng

3. Effective Date of the Commencement of Insurance for the purposes of the Act
08/11/2017

4. Date of Expiry of Insurance
07/11/2018

5. Persons or Classes of Persons entitled to drive*

Lee Chin Pheng

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers

for Chief Executive Officer

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S2561913G**
Name:

LEE CHIN PHENG

Birth Date: **20 May 1958**

Issue Date: **15 Apr 2003**

FOR C&C USE ONLY



000404937A

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 2B	Motorcycles not exceeding 200 cc
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE
18 Jun 1988
18 Jun 1988

FOR C&C USE ONLY

NP 428A



Licence No: S2561913G



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKD1716K

Mr Lee Chin Pheng

32 Jalan Rajah
#02-03 Raja Tower
Singapore 329141

Vehicle & Document Information

WIP No **21435**
Reg No/Reg Date **SKD1716K / 02/11/2011**
Date In/Mileage **/ 0**
Chassis No **WDD2211542A393792**
Engine No **27294631807112**
Make/Model **MB/S 300 LONG SEDAN (V221)**
Colour/Trim **021 183 Magnetite B/ 042 211 Leather Ant**

Account No	Terms	Date/Time Printed	CSE	Operator				
CSM00128	Cash	20/02/2018/ 15:08	EL	350 / Eric Lee Ming Hui				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN								
POLICY NO/ACC DATE : A29038958QMY // 19-2-18								
TOW IN/EXCESS : 20-2-18 // \$1000								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
A BPILAB								✓ 480.00
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT								
A BPIRES								600 960.00
RESPRAY FRONT BUMPER.								
A BPILAB								1440 1920.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.								
A BPILAB							0.07	✓ 500.00
REMOVE, REPLACE RADIATOR, CONDENSER COOLING SYSTEM & FITTINGS- VACUUM AND REGAS . NETT								
S BPNSUB								mis 60.00
SUPPLY 1 SET NUMBER PLATE WITH HOUSING.NETT								
M FRONT BUMPER					1.00	1739.69	00.00	des 1739.69
M CTR IMPACT ABSORBER					1.00	89.45	00.00	? 89.45
M RIGHT IMPACT ABSORBER					1.00	68.15	00.00	? 68.15
M LEFT IMPACT ABSORBER					1.00	68.15	00.00	? 68.15
M LEFT DRL GRILLE COVER					1.00	39.61	00.00	des ? 39.61
M LEFT DRL COVER					1.00	140.95	00.00	des ? 140.95
M LEFT BUMPER CHROME TRIM					1.00	108.14	00.00	cm 108.14
M CENTRE BUMPER CHROME TRIM					1.00	128.39	00.00	cut 128.39
M RIGHT BUMPER CHROME TRIM					1.00	108.14	00.00	cut 108.14
M FRONT BUMPER REINFORCEMENT					1.00	106.52	00.00	an R 106.52
M CTR BOTTOM BUMPER GRILLE					1.00	188.44	00.00	mis 188.44
M LICENCE PLATE MOULDING					1.00	92.47	00.00	mis 92.47
M RADIATOR GRILLE					1.00	882.69	00.00	cut 882.69
M REFRIGERANT CONDENSER					1.00	794.70	00.00	bt 794.70
M AIR-COND. CAPACITOR					1.00	1666.04	00.00	bt ? 1666.04
M RADIATOR LOWER AIR BAFFLE					1.00	83.60	00.00	des ? 83.60

Confirmed & accepted by

Eric Lee Ming Hui

DID : 6771 4336 HP : 9181 7717

Email : eric.lee@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKD1716K

Mr Lee Chin Pheng

32 Jalan Rajah
#02-03 Raja Tower
Singapore 329141

Vehicle & Document Information

WIP No **21435**
Reg No/Reg Date **SKD1716K / 02/11/2011**
Date In/Mileage **/ 0**
Chassis No **WDD2211542A393792**
Engine No **27294631807112**
Make/Model **MB/S 300 LONG SEDAN (V221)**
Colour/Trim **021 183 Magnetite B/ 042 211 Leather Ant**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	20/02/2018/ 15:08	EL	350 / Eric Lee Ming Hui

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RADIATOR	1.00	1784.13	00.00	1784.13
M RADIATOR BLOWER	1.00	1316.21	00.00	1316.21
M LEFT DAYTIME RUNNING LIGHT	1.00	508.45	00.00	508.45
M FRONT BUMPER UNDERCARRIAGE COVER	1.00	539.00	00.00	539.00
M LEFT HEADLAMP UNIT	1.00	3659.12	00.00	3659.12
M RIGHT HEADLAMP UNIT	1.00	3659.12	00.00	3659.12

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Eric Lee Ming Hui

DID : 6771 4336 HP : 9181 7717
Email : eric.lee@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Confirmed & accepted by

Authorized signatory and company stamp

7% GST on **Nett 21,691.16**
1518.38

Total Payable 23,209.54

23,209.54

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKD1716K

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information

WIP No **21435**
Reg No/Reg Date **SKD1716K / 02/11/2011**
Date In/Mileage **23/02/2018 / 69469**
Chassis No **WDD2211542A393792**
Engine No **27294631807112**
Make/Model **MB/S 300 LONG SEDAN (V221)**
Colour/Trim **021 183 Magnetite B/ 042 211 Leather Ant**

Account No	Terms	Date/Time Printed	CSE	Operator
WI000558	Credit	07/04/2018/ 08:31		350 / Eric Lee Ming Hui

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S BPNTOW AGGIDENT TOWING FROM 160 SIN MING DR TO RLSC USING KING DOLLEY WO: 144310				130.00
X ANTIFREEZE	2.00	42.22	00.00	84.44
X RADIATOR FASTENING BOTTOM CONSOLE	1.00	441.12	00.00	441.12
X RIGHT MAIN FLOOR COVER	1.00	430.92	00.00	430.92
X COVER F ENGINE COMP. BM	1.00	258.60	00.00	258.60
X SCREW	5.00	5.50	00.00	27.50
X CLIP-TYPE NUT	5.00	3.05	00.00	15.25
X SPARE WHEEL WELL SCREENING	1.00	380.63	00.00	380.63

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

Nett **1,768.46**
7% GST on **1768.46** **123.79**
Total Payable 1,892.25

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKD1716K

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information

WIP No **21435**
Reg No/Reg Date **SKD1716K / 02/11/2011**
Date In/Mileage **23/02/2018 / 69469**
Chassis No **WDD2211542A393792**
Engine No **27294631807112**
Make/Model **MB/S 300 LONG SEDAN (V221)**
Colour/Trim **021 183 Magnetite B/ 042 211 Leather Ant**

Account No	Terms	Date/Time Printed	CSE	Operator					
WI000558	Credit	04/04/2018/ 18:16		350 / Eric Lee Ming Hui					
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
M BPNSUN POLICY NO/ACC DATE : A2903895BQMY // 19-2-18 TOW IN/EXCESS : 20-2-18 // \$1000 DATE IN/DATE SURVEY: 21-2-18 // TAUFIKH - LKK BY/AUTHORIZED ON : 23-2-18 // 1320 // SHIAU CHAN - LKK									
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT									480.00
A BPIRES RESPRAY FRONT BUMPER.									600.00
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.									1440.00
A BPILAB REMOVE, REPLACE RADIATOR, CONDENSER COOLING SYSTEM & FITTINGS VACUUM AND REGAS . NETT							0.07		500.00
S BPNSUB SUPPLY 1 PC NO PLATE DN: 7009									60.00
S BPNTOW ACCIDENT TOWING FROM 160 SIN MING DR TO PLSC USING KING DOLLEY WO: 144310									130.00
X BPNEXC INSURANCE EXCESS									-1000.00
X FRONT BUMPER					1.00	1739.69	00.00		1739.69
X LEFT DRL GRILLE COVER					1.00	39.61	00.00		39.61
X LEFT DRL COVER					1.00	140.95	00.00		140.95
X LEFT BUMPER CHROME TRIM					1.00	108.14	00.00		108.14
X CENTRE BUMPER CHROME TRIM					1.00	128.39	00.00		128.39
X RIGHT BUMPER CHROME TRIM					1.00	108.14	00.00		108.14
X CTR BOTTOM BUMPER GRILLE					1.00	188.44	00.00		188.44
X LICENCE PLATE MOULDING					1.00	92.47	00.00		92.47
X RADIATOR GRILLE					1.00	882.69	00.00		882.69

Confirmed & accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKD1716K

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information

WIP No **21435**
Reg No/Reg Date **SKD1716K / 02/11/2011**
Date In/Mileage **23/02/2018 / 69469**
Chassis No **WDD2211542A393792**
Engine No **27294631807112**
Make/Model **MB/S 300 LONG SEDAN (V221)**
Colour/Trim **021 183 Magnetite B/ 042 211 Leather Ant**

SKD1716K

Account No	Terms	Date/Time Printed	CSE	Operator			
WI000558	Credit	04/04/2018/ 18:16		350 / Eric Lee Ming Hui			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
X	AIR-COND. CAPACITOR			1.00	1666.04	00.00	1666.04
X	RADIATOR LOWER AIR BARFLE			1.00	83.60	00.00	83.60
X	RADIATOR			1.00	1784.13	00.00	1784.13
X	BLOWER			1.00	1620.14	00.00	1620.14
X	LEFT DAYTIME RUNNING LIGHT			1.00	508.45	00.00	508.45
X	FRONT BUMPER UNDERCARRIAGE COVER			1.00	539.00	00.00	539.00
X	ANTIFREEZE			2.00	42.22	00.00	84.44
X	RADIATOR FASTENING BOTTOM CONSOLE			1.00	441.12	00.00	441.12
X	RIGHT MAIN FLOOR COVER			1.00	430.92	00.00	430.92
X	COVER F ENGINE COMP. BM			1.00	258.60	00.00	258.60
X	SCREW			5.00	5.50	00.00	27.50
X	CLIP-TYPE NUT			5.00	3.05	00.00	15.25
X	SPARE WHEEL WELL SCREENING			1.00	380.63	00.00	380.63

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Finalization

Confirmed & accepted by

Nett **13,478.34**
7% GST on **13478.34** **943.48**
Total Payable 14,421.82

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Feb 2018		21 Feb 2018 10:19 Edit Adj Rpt	S\$14,478.34 Edit Estimates	S\$14,478.34 View Rpt		Pending for Survey Report Cancel Case































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LEE CHIN PHENG , ID: S2561913G, Tel: +6593396530, Email: NOEMAIL									
Vehicle Reg. No.: SKD1716K		Date of Loss: 19/02/2018 10:00 - :59 [75 Months and 17 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 550033		Policy/Cover Note No.: A29038958QMY (Comprehensive) Coverage: 08/11/2017 - 07/11/2018							
		Excess: S\$1,000.00							
Repairer: Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 23/03/2018]									
Driver/Custodian: LEE CHIN PHENG (59 / Male), NRIC: S2561913G, Tel: +6593396530									
Adj Asg. Remarks: Please revert and survey the vehicle by today. Surveyor-please check on the market value and rebates to determine if the vehicle is economical to repair. Thank you.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (16/07/2018): Alert - Adj Mandate Approved (S\$14478.34) - SKD1716K - Claim Handler: Vimmala D/... MSIG_SG (07/06/2018): SKD1716K (550033) MSIG_SG (23/02/2018): Alert - Adj Mandate Approved (S\$8170.11) - SKD1716K - Claim Handler: Vimmala D/O... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKD1716K (550033)
OD
Feb 19 2018 10:00AM
[LEE CHIN PHENG]
Cycle & Carriage Industries Pte Ltd





Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)							Thumbnail			Print		
1	20/02/18 14:02	Accident Statement										Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail			Print		
1	22/02/18 16:52	Adjuster Immediate Advice										Load HTM		
2	12/07/18 15:08	Adjuster Immediate Advice										Load HTM		
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)							Thumbnail			Print		
1	20/02/18 14:02	Accident Photo [Linked Accident Report Documents]										Load JPG		
2	20/02/18 14:02	Accident Photo [Linked Accident Report Documents]										Load JPG		
3	20/02/18 14:02	Accident Photo [Linked Accident Report Documents]										Load JPG		
4	20/02/18 14:02	Accident Photo [Linked Accident Report Documents]										Load JPG		
5	20/02/18 14:02	Accident Photo [Linked Accident Report Documents]										Load JPG		
6	20/02/18 14:02	Accident Photo [Linked Accident Report Documents]										Load JPG		
7	20/02/18 14:02	Accident Photo [Linked Accident Report Documents]										Load JPG		
8	20/02/18 14:02	Accident Photo [Linked Accident Report Documents]										Load JPG		
9	20/02/18 14:02	Accident Photo [Linked Accident Report Documents]										Load JPG		
10	20/02/18 14:02	Accident Photo [Linked Accident Report Documents]										Load JPG		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail			Print		
1	22/02/18 16:39	Odometer Reading										Load JPG		
2	22/02/18 16:39	Chassis Number										Load JPG		
3	22/02/18 16:39	General View										Load JPG		
4	22/02/18 16:39	General View										Load JPG		
5	22/02/18 16:39	General View										Load JPG		
6	22/02/18 16:39	General View										Load JPG		
7	22/02/18 16:39	General View										Load JPG		
8	22/02/18 16:39	General View										Load JPG		
9	22/02/18 16:39	General View										Load JPG		
10	22/02/18 16:39	General View										Load JPG		
11	22/02/18 16:39	General View										Load JPG		
12	22/02/18 16:39	General View										Load JPG		
13	22/02/18 16:39	General View										Load JPG		
14	22/02/18 16:39	General View										Load JPG		
15	22/02/18 16:39	General View										Load JPG		
16	22/02/18 16:39	General View										Load JPG		
17	22/02/18 16:39	General View										Load JPG		
18	22/02/18 16:39	General View										Load JPG		
19	22/02/18 16:39	General View										Load JPG		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
				<input checked="" type="checkbox"/>
20	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
21	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
22	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
23	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
24	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
25	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
26	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
27	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
28	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
29	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
30	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
31	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
32	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
33	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
34	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
35	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
36	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
37	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
38	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
39	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
40	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
41	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
42	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
43	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
44	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
45	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
46	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
47	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
48	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
49	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
50	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
51	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
52	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
53	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
54	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
55	22/02/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
56	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
69	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	12/07/18 14:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	12/07/18 14:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/02/18 09:48	Estimate from C&C - Pandan Loop	 Load PDF	
2	21/02/18 09:48	Email from C&C to arrange survey soon. Vehicle is in the workshop now	 Load PDF	
3	21/02/18 09:51	PARF/COE rebate details	 Load PDF	
4	07/06/18 09:22	Signed DV	 Load PDF	
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	20/02/18 14:02	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	20/02/18 14:02	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	20/02/18 14:02	Sketch Plan #3 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	20/02/18 14:02	Sketch Plan #4 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/02/18 16:38	ESTIMATE	 Load PDF	
2	12/07/18 14:58	REVISED ESTIMATE	 Load PDF	
3	12/07/18 14:58	SUPPLEMENTARY	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	20/02/18 14:02	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	20/02/18 14:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	20/02/18 14:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	20/02/18 14:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	20/02/18 14:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	20/02/18 14:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	20/02/18 14:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
7	20/02/18 14:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	20/02/18 14:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	20/02/18 14:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	20/02/18 14:02	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	20/02/18 14:02	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	20/02/18 14:02	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	20/02/18 14:02	Sketch Plan #3	 Load JPG	<input checked="" type="checkbox"/>
4	20/02/18 14:02	Sketch Plan #4	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18003384/T1QD3E2

Date: 01/08/2018

REFERENCE

Insured/Claimant:	LEE CHIN PHENG	Policy No:	A29038958QMY	
Date of Loss:	19/02/2018	Nature of Claim:	OD	Claim No: 550033

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD1716K		
Make & Model:	MERCEDES-BENZ S300L, 3.0 (A)	Engine No:	27294631807112
Reg. Date:	02/11/2011 (Man. Year: 2011)	Chassis No:	WDD2211542A393792
Colour:	Black	Odometer:	69469 km
Engine Capacity:	2997 cc		
Market Value/New Car Price:	S\$108,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45 R18	Rear Tyre Size:	255/45 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,773.55	11,328.34	8,445.21	42.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,990.00	3,150.00	840.00	21.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,763.55	14,478.34	9,285.21	39.07
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	22,763.55	13,478.34	9,285.21	40.79
+ GST 7.00/7.00% (S\$)	1,593.45	943.48	649.97	40.79
Nett Amount (S\$)	24,357.00	14,421.82	9,935.18	40.79

INSPECTION

Date of Assignment: 21/02/2018

Date Inspected: 21/02/2018 Inspected At:

Cycle & Carriage Industries Pte Ltd
(Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2018)
Parts: 143	MERCEDES-BENZ S300L 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKD1716K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET NUMBER PLATE WITH HOUSING	Missing	60.00 FS	*60.00 FS
2	1		*FRONT BUMPER	Deformed	1,739.69 FS	*1,739.69 FS
3	1		*CTR IMPACT ABSORBER	Not Necessary	89.45 FS	*- FS
4	1		*RIGHT IMPACT ABSORBER	Not Necessary	68.15 FS	*- FS
5	1		*LEFT IMPACT ABSORBER	Not Necessary	68.15 FS	*- FS
6	1		*LEFT DRL GRILLE COVER	Deformed	39.61 FS	*39.61 FS
7	1		*LEFT DRL COVER	Deformed	140.95 FS	*140.95 FS
8	1		*LEFT BUMPER CHROME TRIM	Cracked	108.14 FS	*108.14 FS
9	1		*CENTRE BUMPER CHROME TRIM	Cut	128.39 FS	*128.39 FS
10	1		*RIGHT BUMPER CHROME TRIM	Necessary	108.14 FS	*108.14 FS
11	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	106.52 FS	*- FS
12	1		*CTR BOTTOM BUMPER GRILLE	Missing	188.44 FS	*188.44 FS
13	1		*LICENCE PLATE MOULDING	Missing	92.47 FS	*92.47 FS
14	1		*RADIATOR GRILLE	Cracked	882.69 FS	*882.69 FS
15	1		*REFRIGERANT CONDENSER	Not Necessary	794.70 FS	*- FS
16	1		*AIR-COND, CAPACITOR	Bent	1,666.04 FS	*1,666.04 FS
17	1		*RADIATOR LOWER AIR BAFFLE	Deformed	83.60 FS	*83.60 FS
18	1		*RADIATOR	Bent	1,784.13 FS	*1,784.13 FS
19	1		*RADIATOR BLOWER	Cracked	1,620.14 FS	*1,620.14 FS
20	1		*LEFT DAYTIME RUNNING LIGHT	Missing	508.45 FS	*508.45 FS
21	1		*FRONT BUMPER UNDERCARRIAGE COVER	Torn	539.00 FS	*539.00 FS
22	1		*LEFT HEADLAMP UNIT	Not Necessary	3,659.12 FS	*- FS
23	1		*RIGHT HEADLAMP UNIT	Not Necessary	3,659.12 FS	*- FS
24	2		*ANTIFREEZE	Necessary	84.44 FS	*84.44 FS
25	1		*RADIATOR FASTENING BOTTOM CONSOLE	Distorted	441.12 FS	*441.12 FS
26	1		*RIGHT MAIN FLOOR COVER	Distorted	430.92 FS	*430.92 FS
27	1		*COVER F ENGINE COMP. BM	Deformed	258.60 FS	*258.60 FS
28	5		*SCREW	Necessary	27.50 FS	*27.50 FS
29	5		*CLIP-TYPE NUT	Necessary	15.25 FS	*15.25 FS
30	1		*SPARE WHEEL WELL SCREENING	Cut	380.63 FS	*380.63 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	19,773.55	11,328.34
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	480.00	480.00
2	RESPRAY FRONT BUMPER	New	960.00	600.00
3	REMOVE, REPLACE RADIATOR, CONDENSER COOLING SYSTEM & FITTINGS-VACUUM AND REGAS	New	500.00	500.00
4	ACCIDENT TOWING FROM 160 SIN MING DR TO PLSC USING KING DOLLEY	New	130.00	130.00
5	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	1,920.00	1,440.00
Gross Labour Cost (\$\$)			3,990.00	3,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >