

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO	: AXA INSURANCE	DATE	20/02/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	T/P CLAIM
ESTIMATE REPORT :			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SGE2007J	vic	
MODEL	: AUDI A4		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 15-Feb-18
		TIME	: 15:10HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR LH <i>Dented</i>	1	\$ 1,955.00	\$ 1,955.00
2	ROCKER PANEL LH <i>Repair</i>	1	\$ 1,680.00	\$ 1,680.00
3	REAR DOOR LH <i>Dented</i>	1	\$ 2,100.00	\$ 2,100.00
4	REAR DOOR LOCK LH <i>Repl</i>	1	\$ 520.00	\$ 520.00
5	REAR DOOR WEATHERSTRIPE <i>new</i>	1	\$ 311.00	\$ 311.00
6	REAR DOOR INNER BOARD LH <i>cracked</i>	1	\$ 850.00	\$ 850.00
7	REAR DOOR POWER WINDOW MOTOR <i>new</i>	1	\$ 455.30	\$ 455.30
8	REAR DOOR POWER WINDOW REGULATION <i>Best</i>	1	\$ 480.90	\$ 480.90
9	REAR BUMPER <i>rehand</i>	1	\$ 1,420.00	\$ 1,420.00
10	REAR BUMPER SIDE RETAINER LH <i>new</i>	1	\$ 62.00	\$ 62.00
6	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 280.00	\$ 280.00
11	REAR FENDER LH <i>Distorted</i>	1	\$ 1,820.00	\$ 1,820.00
12	REAR FENDER INNER COWLINH LH <i>new</i>	1	\$ 180.00	\$ 180.00
15	REAR LOWER ARM (STRAIGHT) LH <i>Best new</i>	1	\$ 597.00	\$ 597.00
16	REAR LOWER ARM (ARCED) LH <i>Best</i>	1	\$ 756.00	\$ 756.00
17	REAR KNUCKLE ARM LH <i>Best</i>	1	\$ 970.00	\$ 970.00
18	REAR KNUCKLE ARM BEARING LH <i>new</i>	1	\$ 546.00	\$ 546.00
19	REAR WHEEL HUP LH <i>Repl</i>	1	\$ 367.00	\$ 367.00

20	REAR SHOCK ABSORBER LH <i>Ren</i>	1	\$ 1,155.00	\$ 1,155.00	<i>+</i>
21	REAR UPPER ARM LH <i>Bent</i>	1	\$ 498.00	\$ 498.00	<i>+</i>

12085.90

10877.31

TOTAL PRICE \$ 17,003.20

LESS 0% \$ -

SUB TOTAL PRICE \$ 17,003.20

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR DOOR INNER BOARD CLIPS(SET) <i>Ren</i>	1	\$ 20.00	\$ 20.00	<i>+</i>
2	REAR BUMPER CLIP (SET) <i>Ren</i>	1	\$ 20.00	\$ 20.00	<i>+</i>
3	REAR FENDER INNER COWLING CLIPS (SET) <i>Ren</i>	1	\$ 20.00	\$ 20.00	<i>+</i>
4	REAR WINDSCREEN SEALANT <i>Ren</i>	1	\$ 120.00	\$ 120.00	<i>40</i>
5	REAR WINDSCREEN INNER SEAL <i>Ren</i>	1	\$ 100.00	\$ 100.00	<i>40</i>
6	REAR WHEEL RIM <i>Lot</i>	1	\$ 2,000.00	\$ 2,000.00	<i>850</i>
7	REAR WHEEL TYRE <i>Ren</i>	1	\$ 1,000.00	\$ 1,000.00	<i>+</i>

970

TOTAL \$ 3,280.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	<i>1100</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	<i>1000</i>	
3	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET	\$ 120.00	<i>100</i>	
4	TUFF COAT	\$ 120.00	<i>50</i>	
5	TO REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	<i>✓</i>	
6	TO REMOVE AND REFIX FRONT & REAR DOOR FITTING	\$ 280.00	<i>160</i>	
7	TO REMOVE AND REFIX QUANTER GLASS	\$ 100.00	<i>60</i>	
8	FOUR WHEEL ALIGNMENT	\$ 120.00	<i>80</i>	
9	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 350.00	<i>220</i>	

TOTAL

\$4,210.00

2890

ESTIMATE REPORT

TOTAL PARTS COST : \$ 20,283.20

TOTAL LABOUR COST : \$ 4,210.00

TOTAL REPAIR COST : \$ 24,493.20

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

PART BY PART / LUMP SUM

NO OF DAYS :

LKK Auto Consultants hence no the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during repair
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-surveyed
- This estimate is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FAX :

Tel: 14737.31

H/s: 11.71C.

Adrian Ling
K/s 22/02/18.

07 Days.