



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for MR URM7, vehicle registration SLN6528P, and chassis/engine numbers.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: CSM00081, Cash, 22/02/2018/ 09:50, QUA, 265 / AndreChow, 23630

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes items like PNT98000 (RESpray FRONT BUMPER) and PNT88000 (RENEW FRONT BUMPER).

Estimate

Handwritten notes: N/A Author, PIP Repair, Before paint jobs, LKK Auto, 3w/ days

Form fields: SURVEYOR NAME: LKK Auto, SURVEYOR SIGNATURE: [Signature], DATE: 28/3/2018, REMARKS:

LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting, To display damaged part(s) during resurvey, Parts prices are subject to confirmation, Third party survey is on a "Without Prejudice" basis, No illegal modification(s) is allowed, Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company. Acknowledged by Repairer Signature: Date:

Summary table with columns: Confirm & accepted by, Net, GST, Total Payable. Totals: Net 2,913.00, GST 203.91, Total Payable 3,116.91

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.