



Your Ref : S8M0095O

Date: 20th April 2018

Our Ref : CS/ASM18003398/Ktd3s2

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Yvonne Ang

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GY 830G
ACCIDENT ON 16/02/2018**

Instruction was received to inspect the vehicle Reg. No. GY 830G. The inspection was conducted on 21/02/2018 at the premises of M/s Comfortdelgro Engineering Pte Ltd, 205 Braddell Road Blk C, 3rd Floor Singapore 579701.

The following vehicle information was recorded:

Registration Number	: GY 830G
Make/Model	: Kia Frontier
Year of Registration	: 2004
Body Colour	: Blue
Chassis Number	: KNCSE011257049147
Engine Capacity	: 2665 cc

The lorry caught fire. The cause of fire probably due to short-circuit at the battery terminal.
(Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$ 13,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 10,540.00)
Nett Liability	<u>S\$ 2,460.00</u>

Vehicle Inspected By:



KONG SENG CHEONG
Licensed Appraiser



K.K.LAU
*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.