

# J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,  
 Defu Industrial Park C, Singapore 539186  
 Tel : 6343-0934 Fax : 6343-0921  
 Email : jmartauto@gmail.com  
 Registration No: 201400246D  
 GST Reg. No: 201400246D

14-Feb-18

Our ref : TP/4462/18

TPAXA  
Thin Thin

KNAFU411MAS228070

Aw Yang Hong

**RE : estimate cost for vehicle no : SLU 2782K**

1 pc	rear lh door <i>folded</i>	\$	1,360.40	✓ 872	
2 pcs	rear lh door hinges <i>new</i>		98.00	+	
1 pc	rear lh door lock <i>new</i>		113.00	✓	
1 pc	rear lh door w/strip <i>at</i>		131.00	✓	
1 pc	rear lh door channel <i>new</i>		112.00	+	
1 pc	rear lh door houter handle <i>new</i>		98.60	+	
1 pc	rear lh door outer moulding <i>new</i>		87.40	+	
1 pc	rear lh door trimboard <i>for</i>		678.00	✓ 481	3457.5
1 pc	rear lh door regulator gear <i>new</i>		367.00	✓	
1 pc	rear lh door regulator gear motor <i>new</i>		392.30	+	3111.75
1 pc	rear lh fender <i>Distorted</i>		1,680.50	✓ 907	
1 pc	rear bumper <i>for</i>		968.40	✓ 586.50	
1 pc	rear lh fender inner shield <i>new</i>		117.40	+	
1 pc	lh rocker garnish <i>new</i>		768.40	+	
			<u>6,972.40</u>		
		less 10%	697.24		
			<u>6,275.16</u>		
1 pc	rear lh door fibre sticker <i>new</i>		100.00	snrett 60	
1 pc	rear w/screen gum <i>new</i>		50.00	✓	410
1 pc	rear bumper lower spoiler <i>new</i>		1,000.00	+	
1 pc	rear lh tyre <i>new</i>		300.00	+	
1 pc	rear lh rim <i>at</i>		300.00	✓	
	Panel beating.		1000.00	600	
	Spray painting.		1400.00	800	1660
	Transfer door parts.		80.00	✓	
	Alignment.		80.00	✓	
	Remove & refit rear w/screen.		120.00	100	
			<u>10705.16</u>		
		Plus 7% GST	749.36		
			<u>11454.52</u>		

SD : Eleven thousand four hundred fifty-four & cents fifty-two only.

total: 5181.75  
 R/S: 4150  
 Admin Lj  
 H/S 21/02/18  
 06 days.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Accepted by Repairer

Signature: