



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

SUPPLEMENTARY

ESTIMATE FOR SKM79A

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information
WIP No 21484
Reg No/Reg Date SKM79A / 05/10/2017
Date In/Mileage 26/02/2018 / 5665
Chassis No WDD2050402R318035A
Engine No 27491031091944
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 021 197 Obsidian B1/ 041 101 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator				
WI000558	Credit	22/06/2018/ 11:46	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M. BPNSUN POLICY NO/ACC DATE : GA273985 / 21-02-2018 TOW IN: 21-02-2018 016:25PM // TP CAR NO: SU6211R (MSIG INSURANCE) DATE IN/DATE SURVEY: 23-02-2018 // LKK TAUFIKH BY/AUTHORIZED ON : LIONEL TAN // 23-02-2018 X RH/F TIRE PRESSURE SENSOR					1.00	183.23	00.00	183.23

NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 MP: 9186 5112 Fax: 6772 1272
Email: alanquek@c-and-c.com.sg

Confirmed & accepted by

7% GST on **Nett** 183.23 183.23 12.83
Total Payable 196.06

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 120376
Tel: 6777 8398
Fax: 6779 5383
www.mercedes-benz.com.sg