

ASS. REC. BY:

REF: CS/FCI18003453/ R17d3<sup>n2</sup>

Special Instruction:

Surveyor: Rasul  
CWS

ASSIGNMENT (Office)

From (Person): Joanne Yong

of FCI

Date/Time: 2/2/18 @ 9:23am

Estimated Cost:

Bill to:

OD (IP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLG 6920B

Insured: SHA 6047B

at Workshop m/s: Cycle & Carriage Automotive  
of 209 Pandan Gardens

Tel: 65684501

Policy No:

Claim No: D18001459MFSH

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A 14/2/2018

CA / REV / REP. / REV 24 HRS 1wp

H.O.D. Endorsement:

Date/Time: 9:15am @ 2/2/18

Person Contacted: Edwin

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 6920B-X
	SHA 6047B - CS/FCI.16023890 / T19h 3m2 D.O.A: 6/12/16
	Part by Part \$8964 - (Red. 3410; 27%)

Form

FCI

4597K

ASSIGNMENT

Date: 22/2/18

Estimate No: TP WS / TP RES / OD RES / EVA / INV / MV

To: Insured/Vendor: SLG 69 20 B

at: Warehouse: Cycle & Carriage

of: 209 Penden Garden

Insured: \_\_\_\_\_


Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Claims Record) Edwin

Make of Veh: \_\_\_\_\_



Remark: The veh had commenced its repair at the time of inspection.

Sell. or Market Value: \_\_\_\_\_

ICAD Accident Form: \_\_\_\_\_ Consistent? : Yes or No

GIA / RP Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repair: \_\_\_\_\_ days Real: Yes or No

Lim Sum: \_\_\_\_\_ (\$) 3 Val: Yes or No

QA / REV / REP: / 24 HRS lwp

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT

Veh No: SLG 6920B Page: 2016 OUT

Type: M/Car / M/Cycle / Bus/Van / Lorry / Taxi / Prime Mover

Truck / Trailer: \_\_\_\_\_

Make: MITSUBISHI ATTARAGE 1.2 : 1193

Color: Green

So. Reg. No: 082583

Engine: \_\_\_\_\_

C/N: MMBSTA13AH7003013

Gen. Cond: Good  Poor  Burnt

Steering:  Jammed  Leaked  Burnt

Brake:  Jammed  Leaked  Burnt

Mod: Nil  STD APR

Tyre Size: F 185/55R15

R \_\_\_\_\_

BS / DUN / EKOVVA / GY / PS / LIZA / MID / OHTSU / PR / SUMI

TOYO / YOKO of AOTELI

Eng: \_\_\_\_\_ Pass: \_\_\_\_\_

R/Ba: 5 --- R/Ba: 5 ---

L/Ba: 5 --- L/Ba: 5 ---

D/O: 14/02/18 D/O: 22/02/18

Survey held at: CBC (PA)

Des. of Damages: Fr  OS  NS  UO  Roof/hood of \_\_\_\_\_

The U/O / Chassis frame / Body Structure affected/undamaged

Date / Time / Action / Instruction

RECEIVED 27 JUL 2018

Date Time File Recd:  Prelim. Report

27/7 Typst  Final Report

Date Time File Recd: \_\_\_\_\_

Days Of Repair: 12

Resurvey No. of Trip: 1

Report Format: TP

Lim Sum: 8964

Add Fee:  Site Fee: \$ \_\_\_\_\_

Rep. Fee: \$ \_\_\_\_\_

Rep. Fee: \$ \_\_\_\_\_

Rep. Fee: \$ \_\_\_\_\_

2x15 = 30

170 + 30

50

50

64

---

364

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	19-02-2018	<b>Our Ref No.</b> D18001459MFSH
<b>Accident Date</b>	14-02-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA6047B	<b>Third Party Vehicle.</b> SLG6920B
<b>Survey Location</b>	209 PANDAN GARDENS	
<b>Contact Person.</b>	EDWIN CAINA	
<b>Contact No.</b>	65684501/ 0	<b>Fax No.</b> 65651240
<b>Survey Type</b>	DIRECT SETTLEMENT:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	JOANNEY	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235125)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D18001459MFSH	<b>Policy No</b>	D-18088936MFSH	<b>Claimant S.No &amp; Name</b>	1 & CYCLE & ( LTD
<b>Workshop Name</b>	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (Contact Person : EDWIN CAINA )	<b>Survey Location &amp; Contact Details</b>	209 PANDAN GARDENS <b>Mobile: 0 , Phone: 65684501 , Fax: 65651240</b> <b>EmailId: EDWIN.CAINA@CYCLECARRIAGE.COM.SG</b>		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	DIRECT SETTLEMENT:		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SHA6047B	<b>TP Vehicle No</b>	SLG6920B
<b>PRI Recieved Date</b>	20-02-2018 05:10:20 PM	<b>Surveyor Appointed Date</b>	21-02-2018 09:22:09 AM	<b>Surveyor Accept Date</b>	23-02-2018 0

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	23-02-2018	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--------------------------------------------

## Vehicle Particulars

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select Year"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18003453/R1td3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 23-02-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 6047B	Veh. Inspected	SLG 6920B
Policy No.		Coverage (\$)	0.00
Claim No.	D18001459MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	23/02/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	14/02/2018	Inspection Date	22/02/2018
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
----------------------------------------------------------------------------------------------------------------------------------------

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Friday, 27 July 2018 12:02 PM  
**To:** Cheng Jo Jo; Rasul (LKKAuto); Mei Kwan (LKKAuto); Admin-D (LKKAuto); Admin A  
**Cc:** Loi Ai Ting; Lauro Araos Songcuan Jr; Andre Chow En De; Yusof Bin Hashim  
**Subject:** RE: FINALISE - SLG6920B (MIT) - 1ST CAPITAL

Dear Jo Jo,

Confirm final figure at \$8964/-, 12days. Before GST

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Cheng Jo Jo [<mailto:jojo.cheng@cyclecarriage.com.sg>]  
**Sent:** Tuesday, 10 July 2018 6:20 PM  
**To:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>; Mei Kwan (LKKAuto) <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>; Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Cc:** Loi Ai Ting <[aiting.loi@cyclecarriage.com.sg](mailto:aiting.loi@cyclecarriage.com.sg)>; Lauro Araos Songcuan Jr <[lauro.songcuan@cyclecarriage.com.sg](mailto:lauro.songcuan@cyclecarriage.com.sg)>; Andre Chow En De <[andre.chow@cyclecarriage.com.sg](mailto:andre.chow@cyclecarriage.com.sg)>; Yusof Bin Hashim <[yusof.hashim@cyclecarriage.com.sg](mailto:yusof.hashim@cyclecarriage.com.sg)>  
**Subject:** FINALISE - SLG6920B (MIT) - 1ST CAPITAL

Hi Rasul,

Attached here with the file and photo for your kind perusal.

Kindly confirm finalised amount at \$ 9,591.48 after GST.

Best Regards,

**JoJo Cheng**  
Customer Service



Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339  
T: +65 6568 4554 • F: +65 6565 1240 • [www.cyclecarriage.com.sg](http://www.cyclecarriage.com.sg)

 A member of the Jardine Cycle & Carriage Group

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any

REPUBLIC OF SINGAPORE DRIVING LICENSE

License Number: **S0156042E**

Name: **HO KOON HIANG**

Birth Date: 25 Jun 1952  
Issue Date: 19 Sep 2003

000547749C



REPUBLIC OF SINGAPORE  
IDENTITY CARD NO: S0156042E

HO KOON HIANG

何君强

CHINESE  
Date of Birth: 25-06-1952 M  
Country of Birth: SINGAPORE



FOR CAC USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

Class	Description	PASS DATE
Class 3A	Motor cars without clutch pedals <= 2000 kg with <= 7 passengers, exclusive of the driver; and motor tractors/vehicles without clutch pedals <= 2500 kg	12 Aug 1994

S / No. 9000290357

S0156042E

NP 427A

License No: S0156042E



9273401



S0156042E

Printed Name: HO KOON HIANG  
Date of Issue: 13-08-1994

Address: 310 WOODLANDS STREET 31  
SINGAPORE 2573



FOR CAC USE ONLY



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Lion City Rentals Pte Ltd	Cust No/Name	/Lion City Rentals Pte Ltd
60 Anson Road	Reg No/Reg Date	SLG6920B / 11/10/201
#11-01 Mapletree Anson	Date In/Mileage	/ 82583
Singapore 079914	Chassis No	MMBSTA13AHH003013
Contact No Mobile: 67420984	Engine No	3A92UDL5473
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
CSM00041	Cash	20/02/2018/ 12:51	QUE	261 / Edwin Caina	21642				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E PNT88000	RENEW & RE-ALIGN RR DAMAGED PORTION: RENEW BOOTLID,RR BUMPER & RR END PNL REPAIR RR FENDER LH,RR FENDER RH & RR FLR PNL					2750	3850.00		<del>3850.00</del>
E PNT98000	RESPRAY RR BUMPER,BOOTLID,RR END PNL,RR FENDER LH,RR FENDER RH & RR FLR PNL					2520	2940.00		<del>2940.00</del>
E PNT88000	REMOVE & REFIT BOOTLID COMPONENTS					120	150.00		<del>150.00</del>
E PNT88000	REMOVE & REFIT RR FLR BOARD,TRIM,CARPET & SEAT					80	200.00		<del>200.00</del>
A 54900099	CHECK WIRING & ELECTRICAL SYSTEM					20	50.00		<del>50.00</del>
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								200.00
M SUNDRY	APPLY ANTI CORROSION AND BODY SEALANT ON AFFECTED AREAS					100	200.00		<del>200.00</del>
M SUNDRY	SUPPLY RR NUMBER PLATE WITH CASING					1	80.00		<del>80.00</del>
E PNT88000	RENEW REVERSE SENSOR					80	100.00		<del>100.00</del>
M SUNDRY	SUPPLY REVERSE SENSOR DM					220	280.00		<del>280.00</del>
M SUNDRY	Sundries					20	50.00		<del>50.00</del>
M SUNDRY	SUPPLY C&C BADGE								40.00
M PANEL,TRUNK LID						1.00	865.00	00.00	865.00
M WEATHERSTRIP,TRUNK LID						1.00	155.00	00.00	155.00
M HINGE,TRUNK LID,LH						1.00	201.00	00.00	201.00
M HINGE,TRUNK LID,RH						1.00	201.00	00.00	201.00
M LATCH,TRUNK LID						1.00	216.00	00.00	216.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for Lion City Rentals Pte Ltd and vehicle specifications like Reg No/Reg Date, Date In/Mileage, Chassis No, Engine No, Make/Model, and Colour/Trim.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: CSM00041, Cash, 20/02/2018/ 12:51, QUE, 261 / Edwin Caina, 21642

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various car parts like STRIKER, TRUNK LID LATCH, MARK, THREE-DIA, etc. Includes handwritten notes and a large 'Estimate' watermark.

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval from insurance

SURVEYOR NAME: Rasmi - Hp 90010068
SURVEYOR SIGNATURE: [Signature]
DATE: 22/02/18 @ 1500
REMARKS: 12 days
Repy by part

Confirm & accepted by

Summary table with columns: Description, Amount. Rows: 7% GST on 12367.00 (865.69), Total Payable 13,232.69

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



Exceptional Journeys

Surveyor : Rasul  
Company : LKK

VEHICLE NO : SLG6920B  
MODEL : MIT/17MY ATTRAGE 1.2 CVT  
WIP : 21642

Material	:	\$	<u>2,814.00</u>
Labour	:	\$	<u>6,150.00</u>
Sub-Total	:	\$	<u>8,964.00</u>
	:		
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>8,964.00</u>
GST 7%	:	\$	<u>627.48</u>
Grand Total	:	\$	<u>9,591.48</u>
Finalise By/Date	:	<u>JoJo dtd 10/07/2018</u>	

Email :

REVERT BACK WITHIN 7 DAYS,  
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 12 WORKING DAYS + 4 Days ( 2 ) Weekends  
+          Days (          ) Public Holiday  
TOTAL DAYS REPAIR TOOK = 16


TP Claim 1ST CAPITAL - SHA6047B

Claim GIA / LTA fee         

Claim Loss  Use  Rental

Claim Medical Fee / Others         

Third Party Report



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**PRO-FORMA INVOICE**

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X


Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
Lion City Rentals Pte Ltd  60 Anson Road #11-01 Mapletree Anson Singapore 079914  Contact No Mobile: 67420984 22/02/	Cust No/Name /Lion City Rentals Pte Ltd Reg No/Reg Date SLG6920B / 11/10/2016 Date In/Mileage 22/02/2018/ 82583 Chassis/Package MMBSTA13AHH003013 Engine No 3A92UDL5473 Make/Model MIT/17MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	10/07/2018/ 18:10	BLE	881 / Jojo Cheng	21642

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW & RE-ALIGN RR DAMAGED PORTION:RENEW BOOTLID,RR BUMPER & RR END PANEL,REPAIR RR FENDER LH,RR FENDER RH & RR FLR PANEL				✓2750.00
E PNT98000 RESPRAY RR BUMPER,BOOTLID,RR END PANEL,RR FENDER LH.RR FENDER RH & RR FLR PANEL				✓2520.00
E PNT88000 REMOVE & REFIT BOOTLID COMPONENTS				✓120.00
E PNT88000 REMOVE & REFIT RR FLOOR BOARD,TRIM,CARPET & SEAT				✓80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				✓20.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓200.00
M SUNDRY APPLY ANTI CORROSION AND BODY SEALANT ON AFFECTED AREAS				✓100.00
E PNT88000 LABOUR TO RENEW REVERSE SENSOR				✓80.00
M SUNDRY SUNDRIES				✓20.00
M SUNDRY SUPPLY C&C BADGE				✓40.00
S SPECIALISTJOB SUPPLY REVERSE SENSOR MIT ATTRAGE / U17				✓220.00
X PANEL,TRUNK LID	1.00	865.00	00.00	✓865.00
X WEATHERSTRIP,TRUNK LID	1.00	155.00	00.00	✓155.00
X LATCH,TRUNK LID	1.00	216.00	00.00	✓216.00
X STRIKER,TRUNK LID LATCH	1.00	20.00	00.00	✓20.00
X MARK,THREE-DIA	1.00	43.00	00.00	✓43.00
X MARK,ATTRAGE	1.00	21.00	00.00	✓21.00
X FACE,RR BUMPER	1.00	740.00	00.00	✓740.00
X BRACKET,RR BUMPER,RH	1.00	27.00	00.00	✓27.00

This is not an official tax invoice.  
 This is a computer generated document, no signature is required.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lion City Rentals Pte Ltd	Cust No/Name /Lion City Rentals Pte Ltd
60 Anson Road	Reg No/Reg Date SLG6920B / 11/10/2016
#11-01 Mapletree Anson	Date In/Mileage 22/02/2018/ 82583
Singapore 079914	Chassis/Package MMBSTA13AHH003013
Contact No Mobile: 67420984	Engine No 3A92UDL5473
22/02/	Make/Model MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	10/07/2018/ 18:10	BLE	881 / Jojo Cheng	21642			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	BRACKET,RR BUMPER,LH				1.00	27.00	00.00	✓27.00
X	PANEL,RR END				1.00	421.00	00.00	✓421.00
X	TRIM,RR END				1.00	65.00	00.00	✓65.00
X	BOARD,TRUNK ROOM FLOOR				1.00	193.00	00.00	✓193.00
X	REFLECTOR RH				1.00	21.00	00.00	✓21.00
Z	TEXT							
	FIRST CAPITAL TP CLAIM							
	DOA :14/02/2018							
	SURVEYOR: RASUL DTD 22.02.2018							
<h1>Pro Forma</h1>								
<i>"Guarantee your warranty, maintain with Cycle &amp; Carriage."</i>								

Parts	2,814.00	Nett	8,964.00
Labour	5,770.00	7% GST on	8964.00
Standard Menu	0.00		
Specialist Job	220.00	Total Payable	9,591.48
Diagnostics Job	0.00		
Sundry/Others	160.00		
Total(w/o GST)	8,964.00		

This is not an official tax invoice.  
This is a computer generated document, no signature is required.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003453/R1td3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 30-07-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 6047B	Veh. Inspected	SLG 6920B	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001459MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	21/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI ATTRAGE 1.2	c.c	1193	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MMBSTA13AHH003013	Colour	GREY	
Odometer	82583	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R15	AOTELI	5 mm	
L/H Front Tyre	185/55 R15	AOTELI	5 mm	
R/H Rear Tyre	185/55 R15	AOTELI	5 mm	
L/H Rear Tyre	185/55 R15	AOTELI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/02/2018	Inspection Date	22/02/2018	
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>12 Working Days</b>		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 6920B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	RR NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	80.00	-
1	REVERSE SENSOR (SN)	DAMAGED	280.00	220.00
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	C&C BADGE (SN)	NECESSARY	40.00	40.00
1	PANEL,TRUNK LID (SN)	BUCKLED	865.00	865.00
1	WEATHERSTRIP ,TRUNK LID (SN)	NECESSARY	155.00	155.00
1	HINGE ,TRUNK LID ,LH (SN)	SERVICEABLE	201.00	-
1	HINGE ,TRUNK LID ,RH (SN)	SERVICEABLE	201.00	-
1	LATCH ,TRUNK LID (SN)	BENT	216.00	216.00
1	STRIKER ,TRUNK LID LATCH (SN)	BENT	20.00	20.00
1	MARK ,THREE-DIA (SN)	NECESSARY	43.00	43.00
1	MARK ,ATTRAGE (SN)	NECESSARY	21.00	21.00
1	FACE,RR BUMPER (SN)	DEFORMED	740.00	740.00
1	BRACKET ,RR BUMPER ,RH (SN)	NECESSARY	27.00	27.00
1	BRACKET ,RR BUMPER ,LH (SN)	NECESSARY	27.00	27.00
1	PANEL ,RR END (SN)	BENT	421.00	421.00
1	TRIM ,RR END (SN)	DEFORMED	65.00	65.00
1	BOARD ,TRUNK ROOM FLOOR (SN)	CRACKED	193.00	193.00
1	MUD GUARD ,RR LH (SN)	SERVICEABLE	40.00	-
1	MUD GUARD ,RR RH (SN)	SERVICEABLE	40.00	-
1	DUCT ,RR VENTILATOR (SN)	SERVICEABLE	29.00	-
1	COVER ,RR VENTILATOR (SN)	SERVICEABLE	38.00	-
1	BUZZER ,KEYLESS OPERATIO,RR (SN)	SERVICEABLE	88.00	-
1	ANT,KEYLESS OPERATION ,RR (SN)	SERVICEABLE	91.00	-
1	LAMP ASSY ,COMB,RR LH (SN)	SERVICEABLE	332.00	-
1	LAMP ASSY ,COMB,RR RH (SN)	SERVICEABLE	332.00	-
1	REFLECTOR LH (SN)	SERVICEABLE	21.00	-
1	REFLECTOR RH (SN)	SCRATCHED	21.00	21.00
			<b>4,677.00</b>	<b>3,094.00</b>



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	RENEW & RE-ALIGN RR DAMAGED PORTION, RENEW BOOTLID, RR BUMPER & RR END PNL REPAIR RR FENDER LH, RR FENDER RH & RR FLR PNL.		3,850.00	2,750.00
	RESPRAY RR BUMPER, BOOTLID, RR END PNL, RR FENDER LH, RR FENDER RH & RR FLR PNL.		2,940.00	2,520.00
	REMOVE & REFIT BOOTLID COMPONENTS.		150.00	120.00
	REMOVE & REFIT RR FLR BOARD, TRIM, CARPET & SEAT.		200.00	80.00
	CHECK WIRING & ELECTRICAL SYSTEM.		50.00	20.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		200.00	200.00
	APPLY ANTI CORROSION AND BODY SEALANT ON AFFECTED AREAS.		200.00	100.00
	RENEW REVERSE SENSOR.		100.00	80.00
			7,690.00	5,870.00
	<b>GRAND TOTAL</b>		<b>12,367.00</b>	<b>8,964.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>8,964.00</b>

Report Ref No. CS/FCI18003453/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng., AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.