



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18003473/Dvd3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 13-08-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 3302Z	Veh. Inspected	SLU 3928B
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1800780/NSW	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	20/02/2018

2. Vehicle Particulars & Condition

Make & Model	KIA CERATO FORTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KNAFW411MC5618748	Colour	GREY
Odometer	89626	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	YOKOHAMA	7 mm
L/H Front Tyre	215/45 R17	YOKOHAMA	7 mm
R/H Rear Tyre	215/45 R17	YOKOHAMA	7 mm
L/H Rear Tyre	215/45 R17	YOKOHAMA	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/02/2018	Inspection Date	23/02/2018
Survey held at	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
--	-----------------------