Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Friday, 23 February 2018 4:21 PM

To:

Claims; SUR

Subject:

RE: SKK 5340 Y Own Damage Claim

Dear Jeffrey,

Please proceed to repair the insured vehicle SKK 5340Y (Excess TBA).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]

Sent: Friday, 23 February 2018 4:08 PM

To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg

Subject: RE: SKK 5340 Y Own Damage Claim

Dear all,

Any update on the approval?

Thank you.

Best Regards, Tony Foong

Claims Advisor

Premium Automobiles Pte Ltd (Neg No 1999012771W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID:	4513D	
Vehicle Details		
Vehicle No.:	SKK5340Y	
Vehicle to be Exported:	No	
Intended De-registration Date:	26 Feb 2018	
Vehicle Make:	AUDI	
Vehicle Model:	A3 SB 1.4 TFSI (AMBITION)	
Primary Colour:	White	
Manufacturing Year:	2013	
Engine No.:	CMB135331	
Chassis No.:	WAUZZZ8V9DA057408	
Maximum Power Output:	90.0 kW (120 bhp)	
Open Market Value:	\$27,935.00	
Original Registration Date:	29 Jul 2013	
First Registration Date:	29 Jul 2013	
Transfer Count:	0	
Actual ARF Paid:	\$16,109.00	
Intended PARF Rebate Details		
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	28 Jul 2023	
PARF Rebate Amount:	\$12,081.00	
Intended COE Rebate Details		
COE Expiry Date:	28 Jul 2023	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	10	
QP Paid:	\$73,989.00	
COE Rebate Amount:	\$40,117.00	
Total Rebate Amount:	\$52,198.00	

The information contained herein is correct as at 26 Feb 2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

 By the loagement of this report to the insurers, you hereby consistences. 	tent to the archiving of this report at the certife and to copies of the report using made archiving
	ACCIDENT STATEMENT
Date Of Report	14/02/2018 13:11
Date Of Accident	14/02/2018 08:10
Exact Location Of Accident	11 SHIPYARD CRESCENT
Country/State of Loss	SINGAPORE
Control of the contro	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SKK5340Y
Insured/Policyholder	
Name Of Registered Owner	TAN KUOK KEONG
NRIC No	S7624513D
Email Address	KUOKFRED@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97622529
Alternative Phone No	OFFICE-97622529
Vehicle Particulars	
Manufacturer	AUDI
Model	A3 SB 1.4 TF
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 2100346731-04000

Cover Note Number

Driver

Name of Driver TAN KUOK KEONG

 NRIC No
 \$7624513D

 Date Of Birth
 17/08/1976

 Occupation
 INDOOR

 Date Of Driving Pass
 26/12/1997

Driving Experience 20 YEARS AND 1 MONTH

Gender MALE

Mobile Number (LOCAL) +65-97622529

Fax Number

Contact Number OFFICE-97622529

EMail Address KUOKFRED@HOTMAIL.COM

* Address

12 TAI THONG CRESCENT

#09-17

Postcode

347846

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

.

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

NO

Turned of Turned International

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s)

I have been approached by unknown person(s soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS REVERSING INTO A CARPARK LOT BUT MY VEHICLE ACCIDENTALLY HIT INTO A STATIONARY TRUCK BESIDE ME.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Make/Model/Colour

UNKNOWN

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful merepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the Insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of incolved.
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by mic.
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages): and/or
 - [v] complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents/including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- [d] my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (n) the information so collected under (d) above may be shared / disclosed.
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time Driver's Signature (If driver is not the policyholder) Date & Time: (LL)

Reporting Centre Personnel's Signature Name: Ton, Edway NRIC/FIN No.: Lety deb & #

Sketch Plan #2

SKETCH PLAN

I B D

A= 5kk5340Y B=Unknown

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I won in	essing	into in	Company	lot	but	my	vehicle	sailete
hit into	24 95	Timory	toute	Suchs	me			
						_		

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time

Reporting Centre Personnel's Signature Name: Tony PROAS
NRIC/FIN No. - Et 34 VI 14 75
















CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.I

AUDI AUTO PROTECTOR

OWN DAMAGE EXCESS WINDSCREEN EXCESS

S\$600.00(1) \$\$100.00

CERTIFICATE NO. 2100346731-04000

Market Value

INSURING WITH COE/PARF

Yes

SKK5340Y 1) VEHICLE REGISTRATION NO.

NAME OF INSURED

TAN KUOK KEONG(CHEN GUOQIANG)

SUM INSURED

3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT 29 Jul 2017

4) DATE OF EXPIRY OF INSURANCE

28 Jul 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE * SUBJECT TO AGE CONDITION :All Age Condition

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of \$53,000.00, in additional to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, furtion, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)
4. Ethoz - 50 Bukit Batok Cres Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only
6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)
8. Mova Automotive - 1008 Bukit Metab Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)
10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER

NA

HIRE PURCHASE COMPANY MayBank / EMPLOYER'S LOAN

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

3 Jun 2017 Issued At Singapore

AIG Asia Pacific Insurance Pte. Ltd.

504125-200 PREMIUM LEASING - AP 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE SINGAPORE 159938

AUTHORISED REPRESENTATIVE

24-hours AIG Auto Hotline: (65) 6338 6200

Important: Keep this document in your car

What to do in the event of an accident?

Report the accident to us with your accident vehicle (whether

approved workshops within 24 hours or the next working day

Submit Writ/Summons/Correspondences from third party to

damaged or not) via our approved reporting centres or

Keep calm and move to a safe place

of the accident.

AIG immediately.

Do not admit or discuss fault or blame

What can the 24-hour AIG Auto Hotline do for you?

- Immediate assistance after an accident
- Emergency breakdown service
- . Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured:

- You are not required to make any police report.
- . Record vehicle number, name and address, insurance company and policy number of the other vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or approved
 workshops within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the Police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other vehicle(s) if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or approved
 workshops within 24 hours or the next working day of the accident.

15 DAYS LOSS OF USE / CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details.

Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certification of Insurance (CI) should be produced without demand when collecting the Rental Car and Premium Automobiles. Pie Ltd reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the Policy issued to the policyholder. The validity of this benefit is conditional upon the Motor Policy insured herein being in force.

Steps to activate Loss of Use / Car Replacement Benefit and Important Information

- To activate your loss of use car replacement, please call Premium Automobiles Pte Ltd at 64741223 after filing/reporting your accident claim.
- 2. Your rental car will be made available within 3 hours of activation with Premium Automobiles Pte Ltd. subject to availability
- At the time of collection of the Rental Car, the original insurance policy and scheduled issued by AIG, a copy of the Accident Report from the Authorised Workshop must be produced.
- 4. The number of days of loss of use entitlement is based on the period your vehicle is in the repair workshop subject to a maximum of 15 days.
- 5. A refundable security deposit of S\$350 is required by the rental company during each rental period.
- The rental car will be picked up and returned at Premium Automobiles Pte Ltd upon activation of the benefit.
- Rental cars are strictly for use in Singapore only. Additional premium of S\$35/- per day is applicable if the rental car is to be driven to Malaysia.
- 8. Extension of rental beyond repair period approved by AIG surveyor will be chargeable to customer by the rental company on per day basis.
- Upgrade of Rental Car is available upon request subject to additional charges by the rental company.
- Excess liability for all Rental Cars is \$\$3,000. Customers may choose to reduce the liability to \$\$1,600 per day and by paying the Collision Damage Waiver of \$\$25 per day.

For use of Rental Car in Malaysia, additional excess liability of \$2,000 applies.

If owner fails to inform Premium Automobiles Pte Ltd that he is travelling into Malaysia using the Rental Car and if any accident happens, the entire cost of repair will be the owner's sole responsibility. Premium Automobiles Pte Ltd reserves the right to pursue the full repair cost against the owner.

Additional age requirement

Minimum 23 years old to maximum 65 years old with at least 2 years of driving experience

Premium Automobiles Pte Ltd Operations Hours

Monday to Friday: 0900hrs - 1800hrs

Saturday: 0900hrs to 1300hrs except Sundays and Public Holidays

Oustomer Service Line: 64741223 Facsimile: 67457823

55 Ubi Road 1 Singapore 408699

*Premium Automobiles' Terms & Conditions apply

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Insured is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

The Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agree to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/OD/0200/2018/CCS

Date : 14-Feb-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tan Kuok Keong

Address : 12 Tai Thong Crescent

#09-17

Singapore 347846

Telephone : HP +65 97622529

Type of Claim : Own Damage Claim

Policy No. : 2100346731-04000

 Vehicle No
 : SKK 5340 Y

 Model Code
 : Audi A3 SB 1.4 TFSI

Model / Year : Jul-13
Engine No : CMB 135331

Chassis No : WAUZZZ8V9DA057408

Mileage : Date In :

Liability : Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 14-Feb-18

Place of Accident : 11 Shipyard Crescent

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKK 5340 Y.

S/N	Nature of Jobs			Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	s	360.00	
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.		\$	2,100.00	1250
3	To respray front bumper and rhs front fender.		\$	1,500.00	1,00
4	To carry out diagnostic checks.	5/N	\$	192.00	
	TOTAL LABOUR CHARGES		\$	4,152.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 5340 Y.

			Damage Parts & Prices
Parts Description			S/NETT REMARKS
FRONT BUMPER Delaned		\$	1,613.00 - 1290 48
FRONT FOG LAMP MOUNTING - LH MEL		\$	42.00 × 7
FRONT BUMPER GUIDE - LH Z		\$	54.00 2
FRONT BUMPER GRILLE - LH		\$	164.00 *
FRONT FENDER - LH Deuted		\$	746.00 - 594 - 90
FRONT FENDER BRACKET - LH FRONT 747 Nec		\$	41.00 3
FRONT FENDER BRACKET - LH REAR AND AND		5	24.00 % . +
FRONT FENDER RIVET SET No.		s	29.00 - 23.70
FRONT FENDER BRACE - LH 76 Nec		\$	84.00 7
FRONT WHEEL HOUSING LINER - LH MY M-		\$	151.00 * / /
HEADLIGHT - LH 64		\$	1,764.00 - 1411.70
SUNDRIES THE NO		\$	300.00
TOTAL SPARE PARTS		\$	5,012.00
TOTAL LABOUR CHARGES	8	\$	4,152.00
GRAND TOTAL	1	\$	9,164.00
	FRONT BUMPER SCIENCE FRONT FOG LAMP MOUNTING - LH MELL FRONT BUMPER GUIDE - LH FRONT BUMPER GRILLE - LH FRONT FENDER - LH FRONT FENDER BRACKET - LH FRONT FRONT FENDER BRACKET - LH REAR FRONT FENDER BRACKET - LH REAR FRONT FENDER BRACE - LH FRONT WHEEL HOUSING LINER - LH SUNDRIES TOTAL SPARE PARTS TOTAL LABOUR CHARGES	FRONT BUMPER GUIDE - LH FRONT BUMPER GUIDE - LH FRONT BUMPER GRILLE - LH FRONT BUMPER GRILLE - LH FRONT FENDER - LH FRONT FENDER BRACKET - LH FRONT FENDER BRACKET - LH REAR FRONT FENDER BRACKET - LH REAR FRONT FENDER BRACKET - LH REAR FRONT FENDER BRACE - LH FRONT FENDER BRACE - LH FRONT WHEEL HOUSING LINER - LH HEADLIGHT - LH SUNDRIES TOTAL SPARE PARTS TOTAL LABOUR CHARGES	FRONT BUMPER PRIME S FRONT FOG LAMP MOUNTING - LH Mer S FRONT BUMPER GUIDE - LH S FRONT BUMPER GRILLE - LH S FRONT FENDER - LH PRIME S FRONT FENDER BRACKET - LH FRONT No

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

More Authorised, 05 Duys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey defore latter solary painting.
- To display corruped parties during resurvey
- Parts prices are 1 coercito confirmation.
- Third party survey is on a "Virtibut Projudica" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/OD/0200/2018/CCS

Date : 14-Feb-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tan Kuok Keong
Address : 12 Tai Thong Crescent

#09-17

Model Code : Audi A3 SB 1.4 TFSI

Model / Year : Jul-13 Engine No : CMB 135331

Chassis No : WAUZZZ8V9DA057408

Mileage :

Date In : Liability :

Excess Cost : Estimated By : Johnny Boo / Allan Wu

Accident Date : 14-Feb-18

Place of Accident : 11 Shipyard Crescent

Hi Adrian

5 days - ok - jb - 26 Mar 18

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKK 5340 Y.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendatio		
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$	360.00	\$	360.00
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.		S	2,100.00	5	1,250.00
3	To respray front bumper and rhs front fender.		\$	1,500.00	3	1,100.00
4	To carry out diagnostic checks.	S/N	\$	192.00	s	192.00
	TOTAL LABOUR CHARGES	1	\$	4,152.00	s	2,902.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 5340 Y.

				Damage Pa	ırts	& Prices
S/N	Parts Description			S/NETT		REMARKS
	•					
1	FRONT BUMPER		\$	1,613.00	5	1,290.40
2	FRONT FOG LAMP MOUNTING - LH		\$	42.00		
3	FRONT BUMPER GUIDE - LH		5	54.00		
4	FRONT BUMPER GRILLE - LH		\$	164.00		
5	FRONT FENDER - LH		\$	746.00	\$	596.80
6	FRONT FENDER BRACKET - LH FRONT		\$	41.00		
7	FRONT FENDER BRACKET - LH REAR		\$	24.00		
8	FRONT FENDER RIVET SET		\$	29.00	\$	23.20
9	FRONT FENDER BRACE - LH		\$	84.00		
10	FRONT WHEEL HOUSING LINER - LH		\$	151.00		
11	HEADLIGHT - LH		\$	1,764.00	\$	1,411.20
12	SUNDRIES		\$	300.00		
	TOTAL SPARE PARTS		\$	5,012.00	\$	3,321.60
	TOTAL LABOUR CHARGES	2	\$	4,152.00	\$	2,902.00
	GRAND TOTAL	- 3	\$	9,164.00	\$	6,223.60

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Liability

Name :
Surveyed Date :
Authorised Date :
Excess Cost :

Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept Yr Ref: SKK 5340 Y Norah Khai 6768 9911 6841 1183 Nora.khai@premiumauto.com.sg Body & Paint Dept PA/OD/0200/2018/MAS

2th May 2018

from

Telephone +65-Telefax +65-

EMail

Our department

Our Ref Your Ref

Date

total pages

Dear Sir.

RE: INSURANCE CLAIM FOR SKK 5340 Y, Audi A3 SB 1.4 TFSI

With reference to the above-mentioned vehicle, no. SKK 5340 Y, claimant, Mr. Tan Kuok Keong, please find the related document per attached.

- A copy of the Original invoice no. 85012387 SS6,017.25
- 2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encls

AIG - SKK 5340 Y

Comment of the same

Premium Automobiles Pte Ltr Showroom 9 Leng Kee Road Singapore 159090 Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183

REPUBLIC OF SINGAPORE * (DERTITY CARC NO \$7624513D



TAN KUOK KEONG (CHEN GUOQIANG)

143

CHINESE

17-08-1976 SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE S7624513D TAN KUOK KEONG (CHEN GUOGIANG) Non Date 17 Aug 1976 # Date 16 Dec 2002

S7624513D

30-08-2006

APT BLK 352 HOUGANG AVENUE 7 #08-729 SINGAPORE 530352

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES!

Motor Cars and Motor Trackers the weight of serich unleden does not exceed 2500 kilogram

NP ATEA



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.I

AUDI AUTO PROTECTOR

OWN DAMAGE EXCESS

S\$600.00(1)

CERTIFICATE NO. 2100346731-04000

WINDSCREEN EXCESS

\$\$100.00

SUM INSURED INSURING WITH COE/PARF

Market Value

VEHICLE REGISTRATION NO.

Yes

SKK 5340V

TAN KUOK KEONG(CHEN GUOQIANG)

NAME OF INSURED 3) EFFECTIVE DATE OF THE COMMENCEMENT

29 Jul 2017

OF INSURANCE FOR THE PURPOSES OF THE ACT 4) DATE OF EXPIRY OF INSURANCE

28 Jul 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *

SUBJECT TO AGE CONDITION :All Age Condition

a) The Insured

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of \$\$3,000.00, in additional to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing. the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok CrestTel:66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Metali Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER.

HIRE PURCHASE COMPANY / EMPLOYER'S LOAN

MayBank

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1967 (Malaysia).

ORIGINAL

Issued At Singapore 3 Jun 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-200 PREMIUM LEASING - AP 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE SINGAPORE 159938

AUTHORISED REPRESENTATIVE

Premium Automobiles Pte Ltd



281 Alexandra Road Singapore 159938 Main Selephone, 6836 2223 Alexandra Servica Centra 281 Alexand's Road Singapore 199938 Selephore 6388 2223

SSAM No. 6

Service Appointment

8386 2523 8828 1733 nauto.com se

Main Telefas 5471 3733 Telefax 6475 1025 16:04 Page 1

AIG ASIA PACIFIC INSURANCE PTE LTD

INS TAX INVOICE Cospany Reg. Na. 199902271W BST Reg. No. 199902271W

Invoice: 85012387

Account: A0006

(T 03

MOTOR CLAIM DEPT

ATE BUILDING 78 SHENTON WAY Date : 27/04/2018

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT

Order : SM5340Y

AIG BUILDING 78 SHENTON WAY

#87-15

SINGAPORE 079120

#07-15

SINGAPORE 079120 079120

Term : 38

Mileage: 54490

WIP No.: 55957

Model: A3 SPORTSBACK 1.4 TFSI (AMBITI Chassis: WAUZZZBV9DA057408

Regn No.: SKK5340Y (V 20095)

Regn Date: 29/07/2013

Engine: DMB 135331

Dept: U

VSB No. :

You have been assisted by :- UB-Carrine

(33 |

TO DISMANTLE AND REMEN FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-DRGANISE FRONT CRASH. MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED S BODYWORK TO RESPRBY FRONT BUMPER AND RHS FRONT FENDER. X ABUR941043A HEADLAMP X ABUR941043A HEADLAMP X ABUR821105L FENDER X ABUR821105L FENDER X ABUR82105A GRU X ABUR887065A GRU COVER X ABUR88706	Amount	Unit Price	Qty	Details			
HEADLIGHTS, HORNS, DUTSIDE TEMPERATURE SENSOR AND HEADLIGHT MASHER ASSY. M: 8888 BODYWORK TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-DREAMISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED BODYWORK TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER. M: 1180.00 1.00 TO CARRY OUT DIAGNOSTIC CHECKS. HEADLAMP Less 828% ABV082118SL FENDER Less 828% ABV0807065A GRU TO CARRY OUT DIAGNOSTIC CHECKS. HEADLAMP Less 828% Less 828% 1.00 1764.00 746.00 ABV0807065A GRU TO CORRECT Less 828% 1.00 1613.00 2.90 Parts 3,321.60 Less 828% Sub-Total	360.00	1.00	350.00	Ma		DYWORK.	S 800
BODYWORK					HEADLIBHTS, HORNS, DUTSIDE)	
TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-DREANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED S BODYWORK TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER. ITO CARRY OUT DIAGNOSTIC CHECKS. X ABV0841043A X ABV082110SL X ABV0807065A GRU X ABV0807065A GRU X AN 0161857 POP-RIVET Parts 3,321.60 Labour 0.00 1.00 1.00 1.00 1.00 1.00 1.00 1.0	-680.00	1.00	-688.00	M: 8888		XC.	Q EXC
TO DISMANTLE AND REMEN FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT, RE-DRGANISE FRONT CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED S BODYWORK TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER. X ABV0941043A HEADLAMP Less 020% 1.00 1764.00 X ABV082110SL FENDER Less 020% 1.00 746.00 X ABV0807065A GRU COVER Less 020% 1.00 1613.00 X RN 0161857 POP-RIVET Less 020% 10.00 2.90 Parts 3,321.60 Labour 0.00 Sub-Total	17	2 20		,	Insurance Excess/Liability		
FENDER AND LHS HEADLIGHT, RE-DRGANISE FRONT CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED S BODYWORK TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER. I D CARRY DUT DIAGNOSTIC CHECKS. X ABV0941043A HEADLAMP Less 820% 1.00 1764.00 X ABV082118SL FENDER Less 820% 1.00 746.00 X ABV0807065A GRU COVER Less 820% 1.00 1613.00 X RN 0161857 POP-RIVET Less 820% 10.00 2.90 Parts 3,321.60 Labour 8.00 Sub-Total	1,250.00	1.00	1258.00				S 800
TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER. 192.00 1.00				RE-DREAMISE FRONT CRASH	FENDER AND LHS HEADLIGHT.)	
S BODYWORK M: 192.00 1.00 X ABV0941043A	1,100.00	1.00	1100.00	M:		DDYMORK	S BOD
TD CARRY DUT DIAGNOSTIC CHECKS.				ID RHS FRONT FENDER.	TO RESPRAY FRONT BUMPER AND		
X A8V0821105L FENDER Less 820% 1.00 1764.00 X A8V0821105L FENDER Less 820% 1.00 746.00 X A8V0807065A GRU COVER Less 820% 1.00 1613.00 X AN 0161857 POP-RIVET Less 820% 18.00 2.90 Sub-Total	192,00	1.00	192.00			10 to 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5 B00
X A8V0821185L FENDER Less 828% 1.00 746.00 X A8V0807065A GRU COVER Less 828% 1.00 1613.00 X AN 0161857 POP-RIVET Less 828% 10.00 2.90 Sub-Total Labour 8.00							
X A8V0807065A GRU COVER Less 820% 1.00 1613.00 X PAN 0161857 POP-RIVET Less 820% 10.00 2.90 Sub-Total Labour 8.00	1,411.20		1977 2 1 1 1 1 1 1		HEADLAMP	BV0941043A	X ABV
X PN 0161857 POP-RIVET Less 020% 10.00 2.90 Parts 3,321.60 Labour 0.00	596.80	11 TO SAN TO A TO A	1000000	Less 020%	FENDER	8V0621185L	X ABV
Parts 3,321.58 Labour 8.88	1,298,48	11.100 000 0000000000000000000000000000	1000000	Less 828%	COVER	8V0807065A GRU	
Parts 3,321.68 Labour 8.88	53, 58	2.90	19,99	Less 020%	POP-RIVET	N 0161857	X AN
Labour 9, 99	5,623.60	Sub-Total				3, 321, 68	Parts
Sublet 2,982.88	393, 65	7% GST	(2)	ASSHUM.		0.00	Labour
Menus 8.88 shricant 9.88 (# CE) 6	5,817.25	Count Total	OWO	(-LXE		8.88	Menus

Received by

For 4 on behalf of Premium Automobiles Pte Ltd

Telefax

to AIG Asia Pacific Insurance Pte Ltd Norah Khai 78 Shenton Way 6768 9828 #07-16 AIG Building 6841 1183 Singapore 079120 Motor Claims Dept Body Repair Yr Ref: SKK 5340 Y PA/OD/0200/2018/TF 12 March 2018 RE: CLAIM - OWNER'S SATISFACTION/DISCHARGE VOUCHER Audi A3 SPORTSBACK 1.4 TFSI Make & Model : Vehicle Chassis No. WAUZZZ8V9DA057408 SKK 5340 Y Vehicle Regn No. : Vehicle Mileage : 54490 KM Vehicle Owner Mr. Tan Kuok Keong : Certificate No 2100346731-04000 : Policy Excess : S\$642.00 (inclusive 7% GST) Accident Date : 14 February 2018 Place Junction of North Bridge Rd & Bras Basah Rd : \$ 6,017.25 Repair Cost : WIP No. 55957 : Premium Automobiles Pte Ltd Repairer's Name :

from

Mobile

Date

total pages

Showroom

9 Leng Kee Road Singapore 159090

Telephone +65-

Telefax +65-

Our department

Your Claim Ref Our Ref

+65-

Premium Automobiles Pte Ltd

Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres

Telephone (65) 6366 2323 Telefax (65) 6841 1183

55 Ubi Road 1 Singapore 408699

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : Model
Time : 1415

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBF	OLDER TRA	CKING									
Case	Natified	Est Submitted	Adj Assigned	Adj Rpt		Adj Submitted	Ins Auth'e	d Sta	Pending for Survey Report Cancel Case		
Main	19 Feb 2018		23 Feb 2018 17:56 Edit Adj Rpt	S\$6,223 Edit Esti	200000000000000000000000000000000000000	\$\$6,223.60 View Rpt		Re			
,	tain	R	eference	CI	aim Det	ails	Docum	ents	٦.	Show All	
CLAIM SUE	FOLDER DE	TAILS				[Create	d by insurer]				
Insured:	TAN KUO	K KEONG, ID: S	7624513D, Tel: +	6597622529	, Email	: KUOKFRED@R	HOTMAIL.COM				
Vehicle Reg. No.:	SKK534	OY			Date of L		018 08:00 - :59 ths and 16 Day		Reg Date	(Man Yr)]	
Claim Type:	Type: OD / 5892790721SG Policy/Cover 2100346731-04000 (Comprehensive)			insive)							
					Excess:	5\$600.0	D				
Repairer:	Premium	Automobiles Pte	Ltd (UBI) 55 Ubi	Road 1, 408	699 Ubi -	Tel: 67689828	3/9827/9911				
Handling Insurer:	AIG Asia	Pacific Insuranc	e Pte. Ltd. (SG) ·	Tel: 65-6419	-3000	[Handled by T	r, Tinesh] Tine	sh.Tr@aig.c	mor		
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561	Handled	by ADRIAN L	ING] [Fina	Rpt due	06/03/20	018]	
Driver/Custo dian:	TAN KUCK	KEONG (41 / Mai	e), NRIC: 576245	13D, Tel:	+659762	2529					
ASSOCIATI	ED MAIL RE	CEIVED						View All	Campos	e Case Mail	
 AIG_SG (26/02/2018)	SKK5340Y / O	0 / 14/02/2018 /	Coverage I	k Excess	update					
ALL ASSO	CIATED TAS	ks≅				View All	Search Tasks	Create N	ew Task	Complete	
Due Date	Priority	Type Task	Group Subjec	t Handle	er As	ssigned By	Completed	On C	reated On	Done?	

Claim Documents

*SKK5340Y (5892790721SG)
OD
Feb 14 2018 8:10AM
[TAN KUOK KEONG]
Premium Automobiles Pte Ltd

Uş	pload Documents Up	pload Photos Compose New Letter Upload Video Upload Audio	View	View in Brow	ser Y
Pho	otos/Images		3 per i	page 🔽	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/02/18 10:09	General View	0	Load JPG	V
2	26/02/18 10:09	General View	0	Load JPG	~
3	26/02/18 10:09	General View	0	Load JPG	2
4	26/02/18 10:09	General View	0	Load JPG	V
5	26/02/18 10:09	General View	0	Load JPG	V
6	26/02/18 10:09	General View	0	Load 3PG	2
7	26/02/18 10:09	General View	0	Load JPG	~
8	26/02/18 10:09	General View	0	Load 3PG	V
9	26/02/18 10:09	General View	0	Load JPG	V
10	26/02/18 10:09	General View	0	Load JPG	Z
11	26/02/18 10:09	General View	0	Load JPG	V
12	26/02/18 10:09	General View	0	Load JPG	~
13	26/02/18 10:09	General View	0	Load JPG	2
14	26/02/18 10:09	General View	0	Load JPG	V
Doc	umentation		1 per p	age. V	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/02/18 10:09	Singapore Accident Statement	0	Load PDF	
2	26/02/18 10:09	Certificate of Insurance	0	Load PDF	
3	26/02/18 10:09	Driver's Driving License	0	Load PDF	
4	26/02/18 10:09	ESTIMATE	0	Load PDF	
5	07/05/18 09:21	WORKSHOP INVOICE	0	Load PDF	
6	07/05/18 09:21	DISCHARGE VOUCHER	0	Load PDF	

Linked Accident Report Documents

	View View in the		
Ass	essment Reports		1 per page
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail Pri
1	14/02/18 13:32	Accident Statement	● Load HTM
Pho	otos/Images		3 per page ✓ ✓
No.	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail Prin
1	14/02/18 13:30	Accident Photo	1.oad JPG: ✓
2	14/02/18 13:30	Accident Photo	■ Load JPG
3	14/02/18 13:30	Accident Photo	■ Load JPG
4	14/02/18 13:30	Accident Photo	■ Load JPG
5	14/02/18 13:30	Accident Photo	■ Load JPG
6	14/02/18 13:30	Accident Photo	■ Load 3PG
7	14/02/18 13:30	Accident Photo	■ Load JPG
8	14/02/18 13:30	Accident Photo	Load JPG

Ass	essment Reports		1 per	page V	S.
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	td (UBI)		Print
Doc	umentation		1 per	page 🔽	2
No.	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	14/02/18 13:19	Sketch Plan	0	Load 3PG	Z
2	14/02/18 13:19	Sketch Plan #2	0	Load JPG	V

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg. No. 199607196R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way #07-16

Our File No:

CC3/AIG18003491/ATBQ2

Singapore 079120

Date:

07/05/2018

REFERENCE

Insured/Claimant:

TAN KUOK KEONG

Policy No:

2100346731-04000

Date of Loss:

14/02/2018

Nature of Claim:

OD

Claim No: 5892790721SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKK5340Y

Make & Model:

AUDI A3, 1.4 TFSI S tronic Ambiente (A)

Engine No:

CMB135331

Reg. Date:

29/07/2013 (Man. Year: 2013)

Chassis No:

WAUZZZ8V9DA057408

Colour:

White

Odometer:

53875 km

Engine Capacity:

1395 cc Market Value/New Car Price: S\$73,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

225/45 R17

Rear Tyre Size:

225/45 R17

Front Tyre Size: Front Left Side:

Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side:

Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,012.00	3,321.60	1,690.40	33.73
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,152.00	2,902.00	1,250.00	30.11
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	9,164.00	6,223.60	2,940.40	32.09
	- Excess (S\$)	600.00	600.00	0.00	0.00
	(S\$)	8,564.00	5,623.60	2,940.40	34.33
	+ GST 7.00/7.00% (S\$)	599.48	393.65	205.83	34.33
	Nett Amount (S\$)	9.163.48	6.017.25	3,146.23	34.33

INSPECTION

Date of Assignment:

23/02/2018

Date Inspected:

23/02/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair:

5.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,613.00 FS	*1,290.40 FS
2	1		*FRONT FOG LAMP MOUNTING-LH	Not Necessary	42.00 FS	*-FS
3	1		*FRONT BUMPER GUIDE-LH	Not Necessary	54.00 FS	*-FS
4	1		*FRONT BUMPER GRILLE -LH	Not Necessary	164.00 FS	*-FS
5	1		*FRONT FENDER -LH	Dented	746.00 FS	*596.80 FS
6	1		*FRONT FENDER BRACKET -LH FRONT	Not Necessary	41.00 FS	*-FS
7	1		*FRONT FENDER BRACKET -LH REAR	Not Necessary	24.00 FS	*-FS
8	1		*SET FRONT FENDER RIVET	Necessary	29.00 FS	*23.20FS
9	1		*FRONT FENDER BRACE -LH	Not Necessary	84.00 FS	*-FS
10	1		*FRONT WHEEL HOUSING LINER -LH	Not Necessary	151.00 FS	*-FS
11	1		*HEADLIGHT -LH	Cut	1,764.00 FS	*1,411.20FS
12	1		*SUNDRIES	Not Necessary	300.00 FS	*-FS
F=Fra	nchise	part. S=SpcN	lett.			
				Total Parts (S\$)	5,012.00	3,321.60
			Report was unsubmitted duri	ng this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,100.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	1,500.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
	Gross Labor	ur Cost (S\$)	4,152.00	2,902.00
	Gross Labor Report was unsubmitted during	88/ 5/2		4,152.00

< END OF ESTIMATES >