. 5	1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1	NMENT (Office)		00 10 10 B 11.530m
From (Person)	nuce 760	SMO	Date/Time: _	22/2/1884.53pm
Estimated Cost:		Bill to:		
OD (TF) WS/TP F	CIL	IV 7 CS	sured: Sk	P9139K
at Workshop m/s		10	Tel: 635	8 303 1
of	1 0	ui Crotar		
Policy No		Claim No:	CM701800	0682/AGC
Sum Insured		Ryrapp		
Make of Veh:			D.O.A.	9 2 2018
(Client's Record)	luin	26/2/201	8 @ Mulyning	10 00 000000000000000000000000000000000
CA / REV / REP	/ REV 24 HRS Wp)		H.O.D. En	
Date/Tune: -/'37	m@23 218 Person Cont	acted PAULO		3701
	on/Instruction () Est	mate		
Date/Time Acti	A A CONTRACTOR OF THE CONTRACT			
S	X-0FCFE01			N A GUILL
S		017000245	Rlvbn	D-0-A: 20 12 6
S	103727D-X	017000245/1	Rivon	D-0-A: 20/12/16

350



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

No.		Affiliated to Federation Internation	onale Des Experts En Autom	nobile
SOM	IPO INSURANCE S	SINGAPORE PL	Ref : CS/SMO18003	505/R1rd3
#05-	AFFLES PLACE 01/06 GAPORE LAND TO	WERSINGAPORE 048623	Date: 23-02-2018 Code: SMO	
1.		Policy Particulars	:- THIRD PARTY CLA	IM
	Insured Veh.	SKP 9139K	Veh. Inspected	SLD 3727D
	Policy No.		Coverage (\$)	0.00
	Claim No.	SMTD1800682/AGC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	23/02/2018
2.		Vehicle Part	iculars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer		Steering	
	Brakes		Modification	
	General			
3.		Condi	tions of Tyres	
8-		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		Descript	tion of Damages	
5.		Gener	ral Information	
J.	Accident Date	09/02/2018	Inspection Date	
	Survey held at	VERMOGEN ACE PTE LTD	_ costs • 2000 (co econology)	
	34.19, 11014 41	1 BUKIT BATOK CRESCENT #04-54/55 WCEGA PLAZA SINGAPORE 658064		
5a.			Remarks	
	A)THE INSPECTION	ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS,	/ITHOUT PREJUDICE" BA WE HAVE NOT AUTHOR	SIS. ISED REPAIRS.



Auto Consultants Pte Ltd

Company Registration No. 199607198R

51 UBLAVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

CMTD1800682/AGC

Our ref:

CS/SMO18003505/R1rd3

Date: 12/3/2018

The Motor Claims Department

M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLD 3727D

We thank you for your instruction on

22/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on

27/2/2018

at the premises of M/s

VERMOGEN ACE PTE LTD

and have the following to report:-

Workshop Estimate Amount

Revised Estimate Amount

"Check" Items Amount

Market Value

LTA Reimbursement Value

Nett Value

: S\$11,393.16

: S\$2,258.56

: S\$447.20

: S\$

: S\$

: S\$


nearside

Description of Damage:

The vehicle sustained damages at the

rear n/s portion

rear



front

Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMMED RASUL

Automotive Assessor

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Monday, 12 March 2018 10:56 AM

To:

'Chan, Shu Hui Agnes'; SUR

Subject:

RE: CMTD1800682/AGC - ACCIDENT INVLG SKP9139K & SLD3727D ON 09/02/2018

Attachments:

SLD 3727D PRELI ADVISED.pdf

Dear Agnes,

Enclosed preliminary revised of vehicle SLD 3727D

Date of survey: 27/2/2018 Number of days:4 days

Best Regards,

Veron Chen | Case Handler on behalf of Janice Lee

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 12 March 2018 10:30 AM

To: 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>; SUR <sur@lkkauto.com>

Cc: assignments <assignments@lkkauto.com>

Subject: RE: CMTD1800682/AGC - ACCIDENT INVLG SKP9139K & SLD3727D ON 09/02/2018

Dear Agnes,

Thank you for your email.

Dear Janice,

FYNA. Our Ref: CS/SMO18003505/R1rd3

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chan, Shu Hui Agnes [mailto:agnes.chan@sompo.com.sg]

Sent: Saturday, 10 March, 2018 10:31 AM

To: admin-d@lkkauto.com; assignments@lkkauto.com

Subject: RE: CMTD1800682/AGC - ACCIDENT INVLG SKP9139K & SLD3727D ON 09/02/2018

Dear LKK

Any preliminary advice for this matter.

Thank you.

Best Regards

Agnes Chan

Claims Divison

D: 6329 5327 | T: 6461 6555 | F: 6221 3302

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy.

From: Teo, Grace

Sent: Thursday, 22 February, 2018 4:53 PM

To: juan paulo baldoz <<u>paulovermogenace@gmail.com</u>>; <u>admin-d@lkkauto.com</u>; <u>assignments@lkkauto.com</u>
Cc: vmg.vermogenace <<u>vmg.vermogenace@gmail.com</u>>; Eric Glorioso <<u>ericvermogenace@gmail.com</u>>; ezel tejano

<ezelvermogenace@gmail.com>; Minoko <minokovermogenace@gmail.com>; pila.vermogenace

<pila.vermogenace@gmail.com>; Edmond Lim jian zhi <edmondvermogenace@gmail.com>; Lina Rosli

linavermogenace@gmail.com; Luis Tan <luis.vermogenace@gmail.com; Paul <Paul@v-auto.com.sg; Chan, Shu

Hui Agnes agnes.chan@sompo.com.sg

Subject: CMTD1800682/AGC - ACCIDENT INVLG SKP9139K & SLD3727D ON 09/02/2018

Our Claim Reference: CMTD1800682/AGC

Your Reference: SLD3727D

Hi Paulo,

We acknowledged receipt of your claim documents.

Please be informed that Agnes Chan is the handler of this case.

We have appointed LKK AUTO to conduct the survey.

Aside to LKK AUTO/ TAUFIKH,

Please make arrangement to conduct the survey for SLD3727D tomorrow, 23/02/18.

Aside to Agnes,

Please advise on the liability request from Vermogen Ace Pte Ltd.

Best Regards **Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sq | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: juan paulo baldoz [mailto:paulovermogenace@gmail.com]

Sent: Thursday, February 22, 2018 3:51 PM

To: Claims - Motor Survey

Cc: vmg.vermogenace; Eric Glorioso; ezel tejano; Minoko; pila.vermogenace; Edmond Lim jian zhi; Lina Rosli; Luis

Tan; Paul

Subject: Sompo Insurance Singapore Pte. Ltd: Our Ref: SLD3727D; Your Ref: SKP9139K (DOA: 09/02/2018 / LOA:

ESPLANADE DR) - PLEASE ARRANGE TP SURVEY

Dear Sir / Madam,

Kindly arrange our client's vehicle for pre-repair survey at Vermogen A ce Pte Ltd here at 6 Benoi Sector S(629904). on 23/02/2018 (Friday).

Please refer to the attachment and revert to us soon.

Dear Officer In-charge,

Please let us know what is the liability?

Kindly check & revert to us as soon as possible.

Thank you.

Best Regards,



Paulo Baldoz Vermogen Ace Pte Ltd 6358 3031

Nivitha (LKK Auto)

From:

Teo, Grace < grace.teo@sompo.com.sg>

Sent:

Thursday, 22 February 2018 4:53 PM

To:

juan paulo baldoz; admin-d@lkkauto.com; assignments@lkkauto.com

Cc:

vmg.vermogenace; Eric Glorioso; ezel tejano; Minoko; pila.vermogenace; Edmond

Lim jian zhi; Lina Rosli; Luis Tan; Paul; Chan, Shu Hui Agnes

Subject:

CMTD1800682/AGC - ACCIDENT INVLG SKP9139K & SLD3727D ON 09/02/2018

Attachments:

SLD3727D 09FEB2018 TP - ADD 2.pdf

Our Claim Reference: CMTD1800682/AGC

Your Reference: SLD3727D

Hi Paulo,

We acknowledged receipt of your claim documents.

Please be informed that Agnes Chan is the handler of this case.

We have appointed LKK AUTO to conduct the survey.

Aside to LKK AUTO/ TAUFIKH,

Please make arrangement to conduct the survey for SLD3727D tomorrow, 23/02/18.

Aside to Agnes,

Please advise on the liability request from Vermogen Ace Pte Ltd.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: juan paulo baldoz [mailto:paulovermogenace@gmail.com]

Sent: Thursday, February 22, 2018 3:51 PM

To: Claims - Motor Survey

Cc: vmg.vermogenace; Eric Glorioso; ezel tejano; Minoko; pila.vermogenace; Edmond Lim jian zhi; Lina Rosli; Luis

Tan; Paul

Subject: Sompo Insurance Singapore Pte. Ltd: Our Ref: SLD3727D; Your Ref: SKP9139K (DOA: 09/02/2018 / LOA:

ESPLANADE DR) - PLEASE ARRANGE TP SURVEY

Dear Sir / Madam,

Kindly arrange our client's vehicle for pre-repair survey at Vermogen A ce Pte Ltd here at 6 Benoi Sector S(629904). on 23/02/2018 (Friday).

Please refer to the attachment and revert to us soon.

Dear Officer In-charge,

Please let us know what is the liability?

Kindly check & revert to us as soon as possible.

Thank you.

Best Regards,



Paulo Baldoz Vermogen Ace Pte Ltd 6358 3031

Janice Lee (LKKAuto)

From:

Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com>

Sent:

Tuesday, July 10, 2018 3:59 PM

To:

Asher Sng (LKKAuto); Admin-D (LKKAuto); Janice Lee (LKKAuto); Hsiao Tong (LKKAuto);

Veron Chen (LKKAuto); Rasul (LKKAuto)

Cc:

Vmg admin; Glorioso Eric Paul Patambang; Tejano Exequiel Dawal; Minoko Chan; Pila

Ng; Desmond Kor; Edmond Lim; Lina Rosli; Luis Tan; Paul Tan

Subject: Attachments: Fwd: SLD3727D DOA: 09/02/2018 TO FINALISE (SOMPO TP)

Of90f01e-c568-480a-943c-017aee90c14a.jpg;

4cf3e311-0cb0-4271-94c9-50aecceb616f.jpg; 6d3ddd0b-e87d-4cfca4b5-28e971b8ee00.jpg; 11c8d982-852f-4efe-803a-8e9c1630d282.jpg;

85d97528-17d2-498a-b8f3-961017273e46.jpg;

b9d8c6f3-35d8-4f53-9908-95305414f166.jpg; ffa21cf2-b8c2-4ecf-821b-

a2388eda5a7e.jpg; SLD3727D FINALISE.pdf

Dear Officer-in-charge,

SLD3727D DOA: 09/02/2018

Kindly check & revert to us as soon as possible, to expedite the claim.

Please send us your calculation.

Thank you

Best Regards,

Paulo Baldoz Vermogen Ace Pte Ltd Operation Address:

6 Benoi Sector Singapore 629904

Tel: 6358 3031 Fax: 6694 4929

Mailing Address:

1 Bukit Batok Crescent #04-54 Wcega Plaza Singapore 658064

----- Forwarded message -----

From: Baldoz Juan Paulo Bongon paulo.b@vermogen-group.com>

Date: Fri, Apr 27, 2018 at 12:29 PM

Subject: SLD3727D DOA: 09/02/2018 TO FINALISE (SOMPO TP)

To: "Asher Sng (LKKAuto)" < AsherSng@lkkauto.com >, "Vic (LKKAuto)" < vicalpeh@lkkauto.com >, guoqiang@lkkauto.com, "Ai Phing (LKKAuto)" <aiphing@lkkauto.com>, "Shiau Chan (LKKAuto)" <siewsc@lkkauto.com>, "Taufikh (LKK Auto)" <taufikh@lkkauto.com>, "Rasul (LKK Auto)"

<Rasul@lkkauto.com>

Cc: Vmg admin < vmg@vermogen-group.com >, Glorioso Eric Paul Patambang < eric.g@vermogengroup.com>, Tejano Exequiel Dawal < ezel.t@vermogen-group.com>, Minoko Chan < minoko@vermogengroup.com>, Pila Ng <pila@vermogen-group.com>, Edmond Lim <edmond@vermogen-group.com>, Lina Rosli < linarosli@vermogen-group.com >, Luis Tan < luis@vermogen-group.com >, Paul Tan < paul@vermogen-

CYPCALL!	p.com>
2. Uu	J.COIII

Hi Razul,

Please check and confirm finalise COR @ \$1,950 bef gst (lump sum) 4 working days.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you

Best Regards,



Paulo Baldoz Vermogen Ace Pte Ltd 6358 3031

Enquire Transfer Fee

Vehicle Details

Vehicle No.:

SLD3727D

Vehicle Type:

Z10 - Private Hire (Chauffeur) Motor Car

Vehicle Attachment 1:

No Attachment

Vehicle Scheme:

Normal

Vehicle Make:

HONDA

Vehicle Model:

VEZEL 1.5X HYBRID CVT ABS D/AIRBAG 2WD

Chassis No.:

RU31202414

Propellant:

Petrol-Electric

Engine No.:

LEB5902424

Motor No.:

H12303451

Engine Capacity:

1496 cc

Power Rating:

22.0 kW

Maximum Power

112.0 kW (150 bhp)

Output:

Maximum Laden

Weight:

1555 kg

Unladen Weight:

1280 kg

Year Of Manufacture:

2015

Original Registration

Date:

15 Jun 2016

Lifespan Expiry Date:

E - Open Category

Quota Premium:

COE Category:

\$46,667.00

COE Expiry Date:

14 Jun 2026

Road Tax Expiry Date:

14 Dec 2018

PARF Eligibility Expiry

14 Jun 2026

Date:

MVMG18020631-02 / Vermogen Ace Pte Ltd - HQ EMFRY DATE & TIME: 10/02/2018 14:27 SUBMITTED BY: Nur Asyira Binte AB Rahman

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT	
Date Of Report	10/02/2018 14:27	
Date Of Accident	09/02/2018 18:55	
Exact Location Of Accident	ESPLANADE DR	
Country/State of Loss	SINGAPORE	

DETAILS OF OWN VEHICLE	
------------------------	--

SLD3727D Vehicle Registration Number

Insured/Policyholder

LCRF PTE LTD Name Of Registered Owner

201624597K Co Reg No NOEMAIL

Email Address

Mobile Phone No

OFFICE-66944919 Alternative Phone No

Vehicle Particulars

HONDA Manufacturer VEZEL Model

Exact Purpose for which vehicle was being used at HIRER

Are you claiming under your own insurance policy

NO for repair to your vehicle?

THIRD PARTY If No, Please state action to be taken PRIVATE CAR Vehicle Category

Insurance Company

AIG ASIA PACIFIC INSURANCE PTE, LTD. Name of Insurance Company

COMPREHENSIVE Type Of Coverage

YES Fleet Policy

999995065 Policy Number

Cover Note Number

Driver

JAMALUDIN BIN HASSAN Name of Driver

S6814281D NRIC No 11/04/1968 Date Of Birth OUTDOOR Occupation 26/11/2007 Date Of Driving Pass

10 YEARS AND 2 MONTHS **Driving Experience**

MALE Gender

(LOCAL) +65-90106639 Mobile Number

Fax Number Contact Number

NOEMAIL EMail Address

Address

44 BENOI RD BLOCK B

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

....

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO PHOTOS ATTACHED, THANK YOU.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKP9139K

Vehicle Make/Model/Colour

VEH. B

Details Of Properties

PRIVATE CAR

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Oriver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)

lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapure ("GiA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the daims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time:

NRIC/FIN No.:

Reporting Q

el's Signature

Page 3 of 21

Accident Sketch Plan Pg. 2

	SKETCH PLAN	Esplanade Dr		
A)	SLD3727D			
(B)S	KP9139K		<	
		A 20	*	The state of the state of
	DESCRIBE CIRCUMSTANCES O	F THE ACCIDENT		
	I WO	is driving along Espic	rugde Ch, I was	
		it in my lane. Ha		- 1
	The state of the s	d and I managed	47	4
		felt a slight ing		
4	Dump into 1	ny voew pation o		
	Sanoyed.			
	DECLARATION I/We declare the foregoing pacitive property of the property of t	J	Alle	
	Policyholder Signature * Date & Time:	Oriver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:	

IDENTIFICATION CARD & DRIVING LICENCE











SLD3727D

Vehicle Reg. No.: SLD3727D

Vehicle Reg. Date: 15-Jun-2016

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

SOMPO

AIG

6 Benoi Sector, Singapore (629904) Tel: 6358 3031 | Fax No: 6694 4929

This claim is handled by :

TP INSURER:

OWN INSURER:

ACCIDENT REPAIR ESTIMATE

CLAIM TYPE :	TP		Make / Model :	H. VEZEL 1.5X HYBRID CV
Date of Accident :	9/2/2018	_	Engine No. :	LEB5902424
			Chassis No. :	RU31202414
COST OF CLAIR	MS			
Parts Cost / List Items :	\$	9,060.20	Surveyor I	Name and Company:
Plus/Less 20%	\$	1,812.04	RASUL	- CLKK7
Total Cost / List :	\$	7,248.16	Date of survey :	27/02/18
Special Nett Items :	\$	825.00	Part by Part / Lur	mp Sum) days
Total Parts Amount :	\$	8,073.16	Resurvey Before	Paint / After Paint
Total Labour Amount	: \$	3,320.00	Authorize/Not A	uthorize/Without Prejudice
Gross Total :	\$	11,393.16	Email:	sul@ikkauto.com
GST % : 7%	\$	797.52	Fax No :	
Nett Amount :	Ś	12.190.68	HP No: 9	0010068

PAULO BALDOZ

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904) Tel: 6358 3031 | Fax No: 6694 4929

Vehicle Reg. No. :

SLD3727D

Vehicle Reg. Date: 15/6/2016

Make / Model:

H. VEZEL 1.5X HYBRID CVT

Engine No.:

LEB5902424

Chassis No.:

RU31202414

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1		Tailgate	Regair	\$ 1,860.00		- 4
2	1	Tailgate outer garnish	X	\$ 285.00	YK ZVI	
3		Tailgate outer garnish clips	1	\$ 40.00)	
4	1	Tailgate logo	ner/	\$ 52.00	/	
5	1	Tailgate emblem "VEZEL"	ne'	\$ 56.20	/	
6	2	Tailgate lamp LH/RH	*	\$ 980.00)	
7	70.0	Tailgate lamp clips	*	\$ 50.00		
8	1	Tailgate buzzer	*	\$ 150.00		
9	1	Tailgate inner handle	*	\$ 74.00		
	-	Tailgate inner lock	7	\$ 245.00	11	
10	1	Tailgate lock sensor	7	\$ 220.00		
11	1	Tailgate striker	+	\$ 32.00		
12	_	Tailgate trimboard	7	\$ 295.00	LX QUE	
13	1 1set	Tailgate trimboard	7	\$ 45.00		
14		Tailgate weatherstrip	*	\$ 145.00		
15	1	Tailgate weatherstrip Tailgate windscreen moulding	7	\$ 164.00		II.
16	1	Tail lamp LH/RH	×	\$ 978.00		
17	2	Tail lamp clips	4	\$ 36.00	/	
18			Dr -	\$ 950.00	/	
19	1	Rear bumper	New /	\$ 50.00	1	0.35
20	_	Rear bumper clips	~	\$ 144.00	XSVL	
21	2	Rear bumper retainer LH/RH	nec/(Ipc)	\$ 116.00	58 /	
22	71	- On-to-1	NEC / (III)		167	
23	15		survito	\$ 420.00	1	
24	2	Rear bumper cover LH/RH		\$ 50.00	1	
25	1set		*	\$ 84.00	LX SVL	
26	2	Rear bumper cover retainer LH/RH	R	\$ 585.00	7X 34-	
27	1	Rear end panel outer	- 5	\$ 396.00	-	
28	1	Rear end panel inner	7-7	\$ 184.00		
29	1	Rear end panel top garnish		\$ 40.00		
30	1set		nec /	3 40.00	\$ 45.00	
31	1	Rear number plate with frame	×,		\$ 80.00	-
32	1	Tailgate windscreen sealant	X		\$ 80.00	1x SVC
33	1	Tailgate windscreen inner seal	×		- I	- delication
34	1	Rear end panel sealant	7		\$ 80.00	
35	1	Reverse sensor	7			200/NV
36	1	Spare tyre panel sealant	*		\$ 80.00	
37	1	Spare tyre panel padding			\$ 100.00	-
38	1	Sundries	*		\$ 60.00	1
39	0	0			-	
40	0	0				

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904) Tel: 6358 3031 | Fax No: 6694 4929

Vehicle Reg. No.:

SLD3727D

Vehicle Reg. Date:

15/6/2016

Make / Model:

H. VEZEL 1.5X HYBRID CVT

Engine No.:

LEB5902424

Chassis No.:

RU31202414

PAGE 1

Estimates on Labour

TARANT LABOUR	Ι.	MOUNT	ADJUSTED
MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	7.75		3004
To straighten and panel beating accident area. Rear Portion.	3	1,000.00	, ,
TAILGATE, TAILGATE GANISH, RR BUMPER, RR BUMPER SIDE COVER LH/RH,	-		
RR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL LH/RH, REAR FENDER LH/RH,	\vdash		
	ė	1 200 00	600
To putty, respray painting and polish accident area. Rear Portion.	12	1,00.00	
TAILGATE, TAILGATE GANISH, RR BUMPER, RR BUMPER SIDE COVER LH/RH,	+		
RR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL LH/RH, REAR FENDER LH/RH,	+		
To remove and transfer tailgate components.	\$	150.00	×
	\$	150.00	×
		120.00	
To remove and refit reverse sensor.	13	120.00	60
To rust proof affected areas.	\$	250.00	40
To check and rectify wiring after disconnect and connect.	\$	100.00	X
	\$	150.00	60
To remove and refit interior parts to give way the repair.	1		
	+		
	-		
	-		
			4 =
LVV Auto Consultante hence notify	+		
	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR To straighten and panel beating accident area. Rear Portion. TAILGATE, TAILGATE GANISH, RR BUMPER, RR BUMPER SIDE COVER LH/RH, RR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL LH/RH, REAR FENDER LH/RH, To putty, respray painting and polish accident area. Rear Portion. TAILGATE, TAILGATE GANISH, RR BUMPER, RR BUMPER SIDE COVER LH/RH, RR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL LH/RH, REAR FENDER LH/RH, To remove and transfer tailgate components. To remove and refit tailgate windscreen. To remove and refit reverse sensor. To rust proof affected areas. To check and rectify wiring after disconnect and connect. To remove and refit interior parts to give way the repair.	MECHANICAL / ELECTRICAL / PARKET PARKET PARKET STORES OF THE STORES OF T	To straighten and panel beating accident area. Rear Portion. TAILGATE, TAILGATE GANISH, RR BUMPER, RR BUMPER SIDE COVER LH/RH, RR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL LH/RH, REAR FENDER LH/RH, To putty, respray painting and polish accident area. Rear Portion. TAILGATE, TAILGATE GANISH, RR BUMPER, RR BUMPER SIDE COVER LH/RH, RR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL LH/RH, REAR FENDER LH/RH, To remove and transfer tailgate components. \$ 150.00 To remove and refit tailgate windscreen. \$ 150.00 To remove and refit reverse sensor. \$ 120.00 To remove and rectify wiring after disconnect and connect. \$ 100.00 To remove and refit interior parts to give way the repair. \$ 150.00 LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
- Acknowledged by Repairer
- = gnatule;
- ite:



SLD3727D

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C) 6 Benoi Sector, Singapore (629904)

Tel: 6358 3031 | Fax No: 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER :	SOMPO	= %	Vehicle Reg. No. :	SLD3727D
OWN INSURER :	AIG	- 9	Vehicle Reg. Date:	15-Jun-2016
CLAIM TYPE :	TP	<u></u>	Make / Model :	H. VEZEL 1.5X HYBRID CVI
Date of Accident :	9/2/2018	_	Engine No. :	LEB5902424
			Chassis No. :	RU31202414
COST OF CLAIMS	5			
Parts Cost / List Items :	\$	9,060.20	Surveyor N	ame and Company:
Plus/Less 20%	\$	1,812.04	RASUL	CLKK7_
Total Cost / List :	\$	7,248.16	Date of survey :	27/02/18
Special Nett Items :	\$	825.00	Part by Part / Lum	p Sum days
Total Parts Amount :	\$	8,073.16	Resurvey Before P	aint /After Paint
Total Labour Amount :	\$	3,320.00	Authorize/Not Au	thorize/Without Prejudice
Gross Total :	\$	11,393.16	Email: vas	a leikkauto-com
GST %:	\$	797.52	Fax No :	
Nett Amount :	\$	12,190.68	HP No : 9	0010068
				P=1373.20
				1098.56
This claim is handled b	y:	PAULO BALDOZ		SN= 200 L= 1160
				2458.56
				1966.85
				15= 1950
			L	//

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904) Tel: 6358 3031 | Fax No: 6694 4929

Vehicle Reg. No.:

SLD3727D

Vehicle Reg. Date: 15/6/2016

H. VEZEL 1.5X HYBRID CVT

Make / Model :

LEB5902424

Engine No.: Chassis No.:

RU31202414

PAGE 1

Estimates on Parts

						ADJUSTED
No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	AMOUNT
1	_	Tailgate	Repair	\$ 1,860.00		
2	1	Tailgate outer garnish	7	\$ 285.00		
3	1 set	Tailgate outer garnish clips	*	\$ 40.00		
4		Tailgate logo	ner!	\$ 52.00		
5	1	Tailgate emblem "VEZEL"	m'	\$ 56.20		
6	2	Tailgate lamp LH/RH	×	\$ 980.00		
7		Tailgate lamp clips	*	\$ 50.00		
8	1	Tailgate buzzer	7	\$ 150.00		
9	1	Tailgate inner handle	*	\$ 74.00		
10	1	Tailgate inner lock	7	\$ 245.00		
11	1	Tailgate lock sensor	7	\$ 220.00		
12	1	Tailgate striker	+	\$ 32.00		
13	1	Tailgate trimboard	7	\$ 295.00		
14		Tailgate trimboard clips	7	\$ 45.00		
15	1	Tailgate weatherstrip	*	\$ 145.00		
16	1	Tailgate windscreen moulding	7	\$ 164.00		
17	2	Tail lamp LH/RH	X	\$ 978.00		
_		Tail lamp clips	×	\$ 36.00		lean a
19	1 set	Rear bumper	De-	\$ 950.00		
20		Rear bumper clips	Ne /	\$ 50.00		
21	2	Rear bumper retainer LH/RH	×	\$ 144.00		
22	Zi		nec/(Ipc)	\$ 146.00		
23	21	a On-this	curillo	\$ 334.00	\$ 102	
24	2	Rear bumper cover LH/RH	X	\$ 420.00	1777	
25	1set	-	*	\$ 50.00		
26	2	Rear bumper cover retainer LH/RH	Ž	\$ 84.00		
27	1	Rear end panel outer	R	\$ 585.00		
_	-	Rear end panel inner	X	\$ 396.00		
28	1	Rear end panel top garnish	77 X	\$ 184.00		7
29	1		nee /	\$ 40.00		1 - 1
30	1set	Rear number plate with frame	×		\$ 45.00	
31	1	Tailgate windscreen sealant	Ŕ		\$ 80.00	
32	1	Tallgate windscreen inner seal	×		\$ 80.00	
33	1	Rear end panel sealant	×		\$ 80.00	
34	1	Reverse sensor	7	*	\$ 309.00	200
35	1	Spare tyre panel sealant	*	"	\$ 80.00	
36	1		*		\$ 100.00	
37	1	Spare tyre panel padding	×		\$ 60.00	
38	1	Sundries			1	
39	0	0	-	1		
40	0	0				

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904) Tel: 6358 3031 | Fax No: 6694 4929

Vehicle Reg. No. :

SLD3727D

Vehicle Reg. Date:

15/6/2016

Make / Model:

H. VEZEL 1.5X HYBRID CVT

Engine No.:

LEB5902424

Chassis No.:

RU31202414

PAGE 1

Estimates on Labour

	/ /		MOUNT	ADJUSTED AMOUNT
No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR		1,280.00	200 40
1	To straighten and panel beating accident area. Rear Portion.	7	1,00.00	N T I
	TAILGATE, TAILGATE GANISH, RR BUMPER, RR BUMPER SIDE COVER LH/RH,	-		
	RR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL LH/RH, REAR FENDER LH/RH,	1		
_	To putty espray painting and polish accident area. Rear Portion.	\$	1,200.00	600
2	TAILGATE, TAILGATE GANISH, RR BUMPER, RR BUMPER SIDE COVER LH/RH,			
	RR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL LH/RH, REAR FENDER LH/RH,	F		
3	To remove and transfer tailgate components.	\$	150.00	×
4	To remove and refit tailgate windscreen.	\$	150.00	×
5	To remove and refit reverse sensor.	\$	120.00	60
6	To rust proof affected areas.	\$	250.00	40
7	To check and rectify wiring after disconnect and connect.	\$	100.00	X
	To remove and refit interior parts to give way the repair.	\$	150.00	60
8	To remove and refit interior parts to give way the repair	F		
		-		
		+		
		+		
		Ŧ		
	LKK Auto Consultants hence notify	1		

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
- Acknowledged by Repairer
- = gnatule:

ie:

L=1160



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale	Des Experts En Automobile
---	---------------------------

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18003505/R1rd3n2

0 RAFFLES PLACE 05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date: 16-07-2018		
INGAPORE	E LAND TO	WERSINGAPORE 040023	Code: SMO	
	NE-Shirt	Policy Particulars	:- THIRD PARTY CLAIR	M.
	d Veh.	SKP 9139K	Veh. Inspected	SLD 3727D
Policy		SCHOOL STORY SECOND	Coverage (\$)	0.00
Claim		CMTD1800682/AGC	Excess (\$)	0.00
200000000000000000000000000000000000000	n From	GRACE TEO	Assign Date	22/02/2018
2.		Vehicle Parti	culars & Condition	
	& Model	HONDA VEZEL 1.5X	c.c	1496
200000000000000000000000000000000000000	e No.	HIDDEN	Year of Reg.	2016
	sis No.	RU31202414	Colour	BLUE
Odon	0	132342	Steering	IN ORDER
Brake		IN ORDER	Modification	SPORTS RIM
Gene	1,000	FAIR		
3.		Condit	tions of Tyres	
		Size	Make	Balance
R/H F	ront Tyre	215/60 R16	YOKOHAMA	5 mm
	ront Tyre	215/60 R16	YOKOHAMA	5 mm
P-20-00	Rear Tyre	215/60 R16	YOKOHAMA	5 mm
2000	Rear Tyre	215/60 R16	YOKOHAMA	5 mm
4.	Description of Damages			
THE	/EHICLE SU	STAINED DAMAGES AT THE R	EAR N/S PORTION.	
DAMA	AGES SEE D	ETAILS.		
5.	General Information			
Acci	dent Date	09/02/2018	Inspection Date	27/02/2018
Surv	ey held at	VERMOGEN ACE PTE LTD		
	ener e en antecas escapada.	1 BUKIT BATOK CRESCENT #04-54/55 WCEGA PLAZA SINGAPORE 658064		
5a.	and the same		Remarks	
Learn	E INSPECTI ACCORDAN	ON WAS CONDUCTED ON A"WICE TO YOUR INSTRUCTIONS,	WE HAVE NOT AUTHOR	ISIS. ISED REPAIRS.
5b.		Estima	te Days of Repair	
EST	MATED NO	RMAL PERIOD FOR REPAIR:	4 Working D	ays



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 3727D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	TO REPAIR SEE LABOUR	1,860.00	
1	TAILGATE OUTER GARNISH	SERVICEABLE	285.00	0.5
	SET TAILGATE OUTER GARNISH CLIPS	SERVICEABLE	40.00	1:=
	TAILGATE LOGO	NECESSARY	52.00	52.00
1	TAILGATE EMBLEM "VEZEL"	NECESSARY	56.20	56.20
2	TAILGATE LAMP LH/RH	SERVICEABLE	980.00	(c-
	SET TAILGATE LAMP CLIPS	SERVICEABLE	50.00	-
1	TAILGATE BUZZER	SERVICEABLE	150.00	
1	TAILGATE INNER HANDLE	SERVICEABLE	74.00	
1	TAILGATE INNER LOCK	SERVICEABLE	245.00	
-	TAILGATE LOCK SENSOR	SERVICEABLE	220.00	
4	TAILGATE STRIKER	SERVICEABLE	32.00	
3	TAILGATE TRIMBOARD	SERVICEABLE	295.00	
	SET TAILGATE TRIMBOARD CLIPS	SERVICEABLE	45.00	
9	TAILGATE WEATHERSTRIP	SERVICEABLE	145.00	
	TAILGATE WINDSCREEN MOULDING	SERVICEABLE	164.00	
	TAIL LAMP LH/RH	SERVICEABLE	978.00	
	SET TAIL LAMP CLIPS	SERVICEABLE	36.00)
-	1 REAR BUMPER	DEFORMED	950.00	950.00
	1 SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
	REAR BUMPER RETAINER LH/RH	SERVICEABLE	144.00	o l
	2 REAR BUMPER BRACKET LH/RH	N/S NECESSARY	116.00	58.0
	2 REAR BUMPER REFLECTOR LH/RH	N/S SCRATCHED	334.0	167.0
	2 REAR BUMPER COVER LH/RH	SERVICEABLE	420.0	o l
	1 SET REAR BUMPER COVER CLIPS	SERVICEABLE	50.0	D
	2 REAR BUMPER COVER RETAINER LH/RH	SERVICEABLE	84.0	0
	1 REAR END PANEL OUTER	TO REPAIR SEE LABOUR	585.0	0
	1 REAR END PANEL INNER	SERVICEABLE	396.0	0
	1 REAR END PANEL TOP GARNISH	SERVICEABLE	184.0	0
	1 SET REAR END PANEL TOP GARNISH CLIPS	NECESSARY	40.0	0 40.0
	LESS 20% DISCOUNT		-1,812.0	4 -274.6
	LEGG 20% DIGGOOM!	1	7,248.1	6 1,098.5

Report Ref No. CS/SMO18003505/R1rd3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
		SERVICEABLE	45.00	-
	TAILGATE WINDSCREEN SEALANT (SN)	SERVICEABLE	80.00	
200	TAILGATE WINDSCREEN INNER SEAL (SN)	SERVICEABLE	80.00	
	REAR END PANEL SEALANT (SN)	SERVICEABLE	80.00	-
	REVERSE SENSOR (SN)	NOTWORKING	300.00	
	SPARE TYRE PANEL SEALANT (SN)	SERVICEABLE	80.00	-
	SPARE TYRE PANEL PADDING (SN)	SERVICEABLE	100.00	
	SUNDRIES (SN)	SERVICEABLE	60.00	
	55,15.425 (4.7)		825.00	200.00
	LABOUR		WW.0045U7224	400.00
	TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA.REAR PORTION.TAILGATE, TAILGATE GARNISH, RR BUMPER, RR BUMPER SIDE COVER LH/RH, RR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL LH/RH, REAR FENDER LH/RH.INCLUSIVE OF THE REPAIR OF TAILGATE AND REAR END PANEL OUTER.		1,200.00	
	TO PUTTY, RESPRAY PAINTING AND POLISH ACCIDENT AREA. REAR PORTION. TAILGATE, TAILGATE GARNISH, RR BUMPER, RR BUMPER SIDE COVER LH/RH, RR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL LH/RH, REAR FENDER LH/RH.		1,200.00	
	TO REMOVE AND TRANSFER TAILGATE COMPONENTS.	NOT NECESSARY	150.0	8
	TO REMOVE AND REFIT TAILGATE WINDSCREEN.	NOT NECESSARY	150.0	
	TO REMOVE AND REFIT REVERSE SENSOR.		120.0	The H2000
	TO RUST PROOF AFFECTED AREAS.	100-000-000-000-000-000-000-000-000-000	250.0	
	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT.	NOT NECESSARY	100.0	
	TO REMOVE AND REFIT INTERIOR PARTS TO GIVE WAY		150.0	0 60.00
	THE REPAIR.		3,320.0	0 1,160.00
	GRAND TOTAL		11,393.1	6 2,458.50

THE CONTROL OF LUMP SUM PEPAIRS	are to the property of the last	1,950.00
RECOMMENDED COST OF LUMP SUM REPAIRS		
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO18003505/R1rd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.