

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Clara Li Zi Rong

Date: 02 Mar 2018

## **Preliminary Advice**

Insured Vehicle No	: SKS153L	Accident Date	: 15/02/2018
TP Vehicle No	: S3262CD	Assignment Date	: 23/02/2018
Make	: TOYOTA WISH	Est. Duration of Repair	: 9 days
Date of Inspection	: 26.02.2018		
Inspection At	: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ....rear... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,561.68
Revised Amount	:S\$	12,667.98
Check Items (Estimated)	:S\$	2,819.70
Total	:S\$	15,487.68

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We have not authorized repairs.