

STUTTGART AUTO
NO:12 SUNGEI KADUT AVE (S) 729648 (FAX NO. 63602899)
ESTIMATED COST OF REPAIRS

FWD Insurance- Singapore 6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986	NAME : Mr Leck Kwang Hwee Andy ADDRESS : 38 Trevoe Crescent #02-05 Singapore 297722	WIP : 31842 DATE: 23.02.2018
ATTN : MOTOR CLAIMS DEPT	TEL :	
FAX :		
VEH NO : SBU788B	DATE IN :	CONTACT PERSON : RICK 63602445
CHASSIS NO : WP0ZZZ99ZFS113461	MILEAGE :	TYPE OF CLAIM : TP AGAINST FBB9861M
MODEL : 911 Carrera GTS	DATE REG.: 21-05-15	POLICY NO. :

NATURE OF WORKS

S/NO	Parts Description	QTY	PART NO	(NETT) PRICES
1	REAR LINING C4	1	P991-505-020-62-	X \$ 2,010.30
2	BLIND RIVET	1	P999-190-191-30-	nee \$ 5.20
3	COVERING, INSTALLATION FRAME LH	1	P991-504-661-01-	nee \$ 12.90
4	COVERING, INSTALLATION FRAME RH	1	P991-504-662-01-	nee \$ 12.90
5	LOGO PORSCHE, BLACK	1	P991-559-235-90-	nee \$ 189.50
6	LOGO "CARRERA" BLACK	1	P991-559-237-02-	nee \$ 130.40
7	LOGO "911" BLACK	1	P991-559-231-03-	nee \$ 130.40
8	LOGO "GTS" BLACK	1	P991-559-261-00-	nee \$ 153.70

SUB TOTAL \$ 2,645.30

LESS 10% \$ 264.53

Total Parts \$ 2,380.77

Labour Description

1	TO REMOVE / REPLACE REAR DAMAGED BUMPER & OTHER AFFECTED BODY PARTS INCLUDING PANEL BEAT / STRAIGHTEN BODY PANELS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE.	1560	\$ 3,120.00
2	TO SPRAY PAINT REAR BUMPER.	1300	\$ 1,500.00
3	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABILITY INCLUDING PARKING ASSIST SENSORS.	200	\$ 250.00
4	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR.	480	\$ 600.00
5	SUNDRIES.	50	\$ 100.00
TOTAL LABOUR			\$ 5,570.00
TOTAL PARTS			\$ 2,380.77
GRAND TOTAL			\$ 7,950.77

Please note that this is **only an estimate**, base on our visual inspection. However should there be any additional work be found necessary in the course of repair and thus additional parts, materials and labor cost will be deem necessary, you will be inform accordingly prior to any action taken. In view of this, expected delays will be indivertible and therefore additional

working days will be required. As such the loss of use and other incidentals will be adjusted accordingly.

Prepared By

Acknowledge By

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

RASUL
Hp 90010068
3 days
27/02/18 @ 1400
Reg after repair