

12/03/2002

ASS. REC. BY:

REF:

CS/MSG/18003607/Cpb02

Special Instruction:

Surveyor:

GD

ASSIGNMENT (Office)

From (Person):

Ang Shu Xiong

of

MSLH

Date/Time: 22/02/2018 3:45pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKR 1476D

Insured:

Public Liability

at Workshop m/s

Trans Eumkars

Tel:

of

5 Ubi Close

Policy No:

Claim No:

544551 PLY

Sum Insured:

Excess:

Make of Veh:

D.O.A. 02.01.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

26/02/2018 2pm

Person Contacted:

Via

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKR 1476D - X

Public Liability - X

22/2/18 @ 4:48pm revised to Shu Xiong by email.

30/8/18 @ 4:43pm confirmed with Catherine final fig \$12073.34, 7 days.

(Add \$1320, 10%.)

Signature: Xhd.

REF: MS16.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Trans Eurokars

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKR1476D

Yr Regn: 20 Jan 2015

Type: ☒ M/Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 5 C.C. 1998

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 79019 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6CW107150120961

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / ☒ Rim or

Tyre Size: F: 205/55R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Survey held at w/s

Des. of Damages: Frt / Rear / ☒ S / ☒ N / UIC / Rooftop or

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 26-02-18

5:30 pm

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 03 SEP 2018

31/8/2018

Date/Time, File Pass to?

☐ : Preli. Report

1) 03/9 11:15

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 7

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Photos: _____

Others: _____

TOTAL

300

Report Format: mer-TP

Lump Sum / I.B.I: (\$ 17073.34)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003607/Gqb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 26-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SKR 1476D
Policy No.		Coverage (\$)	0.00
Claim No.	544551 PLY	Excess (\$)	0.00
Assign From	ONG SHU XIANG	Assign Date	22/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/02/2018	Inspection Date	26/02/2018
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 544551PLY

Date: 27th February 2018

Our Ref: CS/MSG18003607/Gqb

The Motor Claims Department
MSIG Insurance

Attn: Shu Xiang

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SKR 1476D


We thank you for the instruction on 22/02/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 26/02/2018 at the premises of M/s TRANS EUROKARS and have the following to report:-

Workshop Estimate Amount	: S\$ <u>10,534.76</u>
Revised Estimate Amount	: S\$ <u>9,214.76</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the
o/s & n/s body.



Comments/ Present Status:

Damages consistent.

We have not authorized repair.

Yours faithfully

Guo Qiang
Automotive Assessor

Nivitha (LKK Auto)

From: Ong Shu Xiang <shuxiang_ong@sg.msig-asia.com>
Sent: Thursday, 22 February 2018 3:45 PM
To: assignments; SUR
Subject: New Matter: Survey on SKR1476D - MSIG Ref: 544551 PLY
Attachments: EST.PDF; RPT.PDF

Importance: High

63957877 vion
4:01pm
No answer
calling from
Thursday
and emailed

Dear Sirs

Happy lunar new year to all!

This is a new matter.

We would like LKK to arrange for a survey on SKR1476D on a Without Prejudice basis.

Circumstances of accident

Our Insured is Pertapis Education and Welfare Centre. On 2 January 2018, our Insured's staff accidentally closed the main gate via remote when SKR1476D was coming into the main gate. The impact caused scratches at the sides of SKR1476D.

Enclosed is the driver's accident statement and the repair quotation from Trans Eurokars Pte Ltd.

Please let us have your advice regarding repair costs, number of days of repair and if the damages sustained by SKR1476D is consistent with the circumstances of accident.

We hope to hear from you soon.

Thank you.

Ong Shu Xiang
Executive, Claims Services
D: +65 6643 1337 | F: +65 6643 1349 | shuxiang_ong@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 30 August 2018 5:43 PM
To: catherinechua@eurokars.com.sg
Cc: vion.lim@eurokars.com.sg; SUR; Guo Qiang (LKKAUTO)
Subject: RE: SKR1476D - FINALIZATION OF COR

Dear Catherine,

WITHOUT PREJUDICE

Confirm final fig \$12,073.34 before GST and 7 repair days.

Kindly send the relevant documents to MSIG insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: catherinechua@eurokars.com.sg <catherinechua@eurokars.com.sg>
Sent: Wednesday, 27 June 2018 3:01 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: vion.lim@eurokars.com.sg; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Subject: RE: SKR1476D - FINALIZATION OF COR

Re-sent with attachment.

Sorry about the omission.

Thanks n Regards
Catherine Chua
Insurance Claims Executive
Trans Eurokars Pte Ltd
DID: 6603 6121
FAX: 6476 7417

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Siew Guek Catherine Chua
Sent: Wednesday, June 27, 2018 2:55 PM
To: 'Shiau Chan (LKKAUTO)' <siewsc@lkkauto.com>
Cc: Vion Lim <vion.lim@eurokars.com.sg>; 'Guo Qiang (LKKAUTO)' <GuoQiang@lkkauto.com>
Subject: RE: SKR1476D - FINALIZATION OF COR

Dear Shiau Chan

Here is the supplementary list required by you.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 27 February 2018 4:48 PM
To: 'Ong Shu Xiang'
Cc: assignments; SUR
Subject: RE: New Matter: Survey on SKR1476D - MSIG Ref: 544551 PLY
Attachments: CSMMSG18003607qb.pdf

Dear Shu Xiang,

Enclosed herewith preliminary advice of SKR 1476D.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 26 February 2018 2:29 PM
To: 'Ong Shu Xiang' <shuxiang_ong@sg.msig-asia.com>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: New Matter: Survey on SKR1476D - MSIG Ref: 544551 PLY

Dear Shu Xiang,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ong Shu Xiang [mailto:shuxiang_ong@sg.msig-asia.com]
Sent: Thursday, 22 February, 2018 3:45 PM
To: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: New Matter: Survey on SKR1476D - MSIG Ref: 544551 PLY
Importance: High

Dear Sirs

Happy lunar new year to all!

This is a new matter.

We would like LKK to arrange for a survey on SKR1476D on a Without Prejudice basis.

Circumstances of accident

Our Insured is Pertapis Education and Welfare Centre. On 2 January 2018, our Insured's staff accidentally closed the main gate via remote when SKR1476D was coming into the main gate. The impact caused scratches at the sides of SKR1476D.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3498B
Vehicle Details	
Vehicle No.:	SKR1476D
Vehicle to be Exported:	No
Intended De-registration Date:	27 Feb 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	PE30740365
Chassis No.:	JM6CW1071F0120961
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$17,542.00
Original Registration Date:	20 Jan 2015
First Registration Date:	20 Jan 2015
Transfer Count:	0
Actual ARF Paid:	\$12,542.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jan 2025
PARF Rebate Amount:	\$9,406.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jan 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$75,200.00
COE Rebate Amount:	\$51,851.00
Total Rebate Amount:	\$61,257.00

The information contained herein is correct as at 27 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/02/2018 18:53
Date Of Accident	02/01/2018 16:00
Exact Location Of Accident	PERTAPIS CHILDREN HOME 993B KOVAN RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR1476D
Insured/Policyholder	
Name Of Registered Owner	HUAN SOO HAI
NRIC No	S1303498B
Email Address	QCPAUL@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-91251883
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MAZDA
Model	5-2.0 5 DR WAGON (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	HUAN SOO HAI
NRIC No	S1303498B
Date Of Birth	12/12/1958
Occupation	INDOOR
Date Of Driving Pass	29/12/1980
Driving Experience	37 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91251883
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	QCPAUL@SINGNET.COM.SG

Address	BLK 474 SEGAR ROAD #07-308
Postcode	670474
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NG YONG JIAN MUHD HAEKAL
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	MAIN GATE OF PERTAPIS HOME
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA) I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: (if driver is not the policyholder)

Driver's Signature

Name: (Paul) Hoon Sui Hai


Date & Time: 20/2/2018, 1400

Reporting Centre Personnel's Signature

NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE NO: SKR1476D

ACCIDENT DATE: 2nd January 2018

CONTACT NUMBER: 9125 1883

ACCIDENT TIME: 4pm

EMAIL: huanpaul@yahoo.com / acpaul@singnet.com.sg

LOCATION: Pertapis Children Home, 993B Kovan Road, Singapore 545676

On 2nd January 2018 at about 4pm, I arrived at Pertapis Children home with Ng Yong Jian Muhd Haikal (a resident of Pertapis Children Home) in my car but main gate was shut as usual. I came out of my car to signal to staff at Pertapis Children Home to open the main gate to let my car in, which their staff, Ikhwen, did. Ikhwen, who is not familiar with the remote control, closed the main gate before my car had cleared the main gate completely.

Unfortunately, the main gate smashed hard against the side of my moving car when it closed, resulting in the flwg damages (upon closer inspection) to my car: **SKR1476D Mazda 5 MPV**:

1. Left rear door, 3rd row panel & bumper badly scratched.
2. Left rear door handle scratched
3. Left skirt below door loosened
4. Right front door & rear door scratched
5. Right bumper scratched
6. Right skirt door loosened.

Enclosed are 15 pictures of the damages to my car for your perusal.

This unfortunate accident was witnessed by Ng Yong Jian Muhd Haikal who was in my car and several other staff & residents of Pertapis Children Home. Ikhwen and other staff of Pertapis Children Home had also apologised to me for their mistake in this accident. **Pertapis Children Home is not disclaiming liability had asked me to submit claims to your company, MSIG (who I understand is the insurance company for their premise) to settle this matter.**

I wish to send my car to Mazda Singapore for the repairs (should take about 5 days +/-) ASAP. I will also be hiring a replacement MPV during the duration that my car is in workshop for the repair. Kindly confirm that MSIG Insurance will:

1. Fully bear the cost of the repair at Mazda Singapore
2. Fully pay for replacement MPV car during the duration of the repair.

If MSIG is agreeable to (1) & (2) above, I will not be claiming for inconvenience caused. If I have to go through my car insurance company, I will also be claiming for inconvenience caused as well, besides legal fee.

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIMS UNDER YOUR OWN POLICY

PLEASE CHECK YOUR POLICY FOR MORE INFORMATION

PLEASE STATE ☐ CLAIM OWN POLICY ☒ CLAIM THIRD PARTY ☐ REPORTING ONLY

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature

Date & Time (if driver is not the policyholder)

Driver's Signature

Name: (Paul) Huan Seng Hui

Date & Time: 20/2/2018 1400 hours

Reporting Centre Personnel's Signature

NRIC/FIN No.:



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



MSIG INSURANCE SINGAPORE P/L 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Huan Soo Hai ADDRESS: Blk 474 Segar Road #07-308 Singapore 670474 TEL: 91251883	<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged parts during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No "legal modification(s)" is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>WIP: 63748 EXCESS: DATE: 22-Feb-18</p> <p>Acknowledged by Repairer</p>		
VEH NO:	SKR1476D	DATE IN:		CONTACT PERSON:	VION 6395 7877
CHASSIS NO:	JM6CW1071F0120961	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA5	DATE REG.:	20-Jan-15	POLICY NO.:	

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	MOULD(LHS), SIDE STEP / <i>cut</i>	1	MC236-51-P50D53 \$ 1,055.40
2	MOULD(RHS), SIDE STEP / <i>cut</i>	1	MC236-51-P40D53 \$ 1,055.40
3	FASTENER, MOULD / <i>ABC</i>	2	MB45A-56-146A \$ 5.60
Near Bumper / <i>cut</i>			TOTAL PARTS \$ 2,116.40
Near Door LH / <i>DD</i>			LESS 10% \$ 211.64
			TOTAL PARTS COST \$ 1,904.76

Labour Description

1	TO REPLACE LHS AND RHS SIDE STEP MOULD. TO REPAIR LHS REAR FENDER AND ALL AREAS AFFECTED BY THE ACCIDENT.	1980 <i>1320</i>	\$ 2,640.00
2	TO RESPRAY LHS REAR DOOR, LHS REAR FENDER, REAR BUMPER, LHS SIDE STEP MOULD, RHS SIDE STEP MOULD, RHS FRONT DOOR, AND RHS REAR DOOR.	<i>660</i>	\$ 5,040.00
3	MZ-BR-CAVITY TO CARRY-OUT BODY CAVITY PRESERVATION.	<i>NN</i>	\$ 250.00
4	MZ-BR-ELECTR TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	<i>120</i>	\$ 250.00
5	MZ-BR-REPROG TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	<i>150</i>	\$ 350.00
6	MZ-BR-SUNDRI SUNDRIES.	<i>20</i>	NETT \$ 100.00

7 Days.

before paint photos.

Eric Qiao - 8288 0282 28/2/18
26/2/18

TOTAL LABOUR	\$ -	\$ 8,630.00
TOTAL PARTS	\$ -	\$ 1,904.76
TOTAL	\$ -	\$ 10,534.76
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -

13393.34



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
SUPPLEMENTARY ESTIMATE COST OF REPAIRS



MSIG INSURANCE SINGAPORE P/L 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Huan Soo Hai ADDRESS : Blk 474 Segar Road #07-308 Singapore 670474 TEL : 91251883		WIP : 63748 EXCESS : DATE: 22-Feb-18	
VEH NO :	SKR1476D	DATE IN :		CONTACT PERSON :	VION 6395 7877
CHASSIS NO :	JM6CW1071F0120961	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG.:	20-Jan-15	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	MC513-50-221EBB		\$ 915.40
2	1	MC5Y3-73-02XE		\$ 1,364.50
3	2	MGD7A-50-EA1		\$ 6.00
4	4	MBN8F-50-355		\$ 21.60
5	1	M9991-00-501		\$ 2.80
6	4	MBHN1-50-021A		\$ 10.00
7	2	MC235-50-ES1		\$ 8.80
8	2	MC513-72-762		\$ 9.80
9	1	MBP4K-58-762		\$ 3.40
10	1	MC513-72-918		\$ 8.90
11	1	MC514-72-918		\$ 10.00
12	2	MA001-56-053		\$ 6.60
13	3	MC235-58-975		\$ 8.10
14	6	MGJ6A-58-975		\$ 16.80
15	1	MGD7A-50-EA1		\$ 3.00
16	1	MC273-72-864A		\$ 2.50
17	1	MC513-72-864A		\$ 2.50
18	1	MG043-62-864A		\$ 3.30
19	2	MS05B-72-512		\$ 5.40
20	1	MC513-50-8W2B		\$ 29.10
21	1	MC513-50-8W4A		\$ 33.40
22	1	MC235-72-512		\$ 4.30
TOTAL PARTS				\$ 2,476.20
LESS 10%				\$ 247.62
TOTAL PARTS COST				\$ 2,228.58

Labour Description

1	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	NETT	\$ 315.00
---	--------------	---------------------------------	------	-----------

1	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	NETT	\$ 315.00	<i>Repaired</i>
2	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	NETT	\$ 315.00	✓
			TOTAL LABOUR	\$ -	\$ 630.00
			TOTAL PARTS	\$ -	\$ 2,228.58
			TOTAL	\$ -	\$ 2,858.58
			LESS EXCESS	\$ -	\$ -
			TOTAL AFTER EXCESS	\$ -	
			GST 7%	\$ -	\$ -
			GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



MSIG INSURANCE SINGAPORE P/L 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807 ATTN : FAX :		NAME : Mr Huan Soo Hai ADDRESS : Blk 474 Segar Road #07-308 Singapore 670474 TEL : 91251883		WIP : 63748 EXCESS : DATE: 22-Feb-18	
VEH NO :	SKR1476D	DATE IN :		CONTACT PERSON :	VION 6395 7877
CHASSIS NO :	JM6CW1071F0120961	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG.:	20-Jan-15	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	MC236-51-P50D53	\$ 1,055.40	\$ 1,055.40
2	1	MC236-51-P40D53	\$ 1,055.40	\$ 1,055.40
3	2	MB45A-56-146A	\$ 5.60	\$ 5.60
SUPPLEMENTARY ITEMS				
1	1	MC513-50-221EBB	\$ 915.40	\$ 915.40
2	1	MC5Y3-73-02XE	\$ 1,364.50	\$ 1,364.50
3	2	MGD7A-50-EA1	\$ 6.00	\$ 6.00
4	4	MBN8F-50-355	\$ 21.60	\$ 21.60
5	1	M9991-00-501	\$ 2.80	\$ 2.80
6	4	MBHN1-50-021A	\$ 10.00	\$ 10.00
7	2	MC235-50-ES1	\$ 8.80	\$ 8.80
8	2	MC513-72-762	\$ 9.80	\$ 9.80
9	1	MBP4K-58-762	\$ 3.40	\$ 3.40
10	1	MC513-72-918	\$ 8.90	\$ 8.90
11	1	MC514-72-918	\$ 10.00	\$ 10.00
12	2	MA001-56-053	\$ 6.60	\$ 6.60
13	3	MC235-58-975	\$ 8.10	\$ 8.10
14	6	MGJ6A-58-975	\$ 16.80	\$ 16.80
15	1	MGD7A-50-EA1	\$ 3.00	\$ 3.00
16	1	MC273-72-864A	\$ 2.50	\$ 2.50
17	1	MC513-72-864A	\$ 2.50	\$ 2.50
18	1	MG043-62-864A	\$ 3.30	\$ 3.30
19	2	MS05B-72-512	\$ 5.40	\$ 5.40
20	1	MC513-50-8W2B	\$ 29.10	\$ 29.10
21	1	MC513-50-8W4A	\$ 33.40	\$ 33.40
22	1	MC235-72-512	\$ 4.30	\$ 4.30
TOTAL PARTS			\$ 4,592.60	\$ 4,592.60
LESS 10%			\$ 459.26	\$ 459.26
TOTAL PARTS COST			\$ 4,133.34	\$ 4,133.34

Labour Description				
1		TO REPLACE LHS AND RHS SIDE STEP MOULD. TO REPAIR LHS REAR FENDER AND ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1,980.00	\$ 2,640.00
2		TO RESPRAY LHS REAR DOOR, LHS REAR FENDER, REAR BUMPER, LHS SIDE STEP MOULD, RHS SIDE STEP MOULD, RHS FRONT DOOR, AND RHS REAR DOOR.	\$ 5,040.00	\$ 5,040.00
3	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
7	SUPP	TO TRANSFER THE DOOR MECHANISM ✓	\$ 315.00	\$ 315.00
8	SUPP	TO TRANSFER REVERSE SENSORS. ✓	\$ 315.00	\$ 315.00
TOTAL LABOUR			\$ 7,940.00	\$ 9,260.00
TOTAL PARTS			\$ 4,133.34	\$ 4,133.34
TOTAL			\$ 12,073.34	\$ 13,393.34
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ 12,073.34	
GST 7%			\$ 845.13	\$ -
GRAND TOTAL			\$ 12,918.47	\$ -

REMARKS:

7 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003607/Gqbn2

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 04-09-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SKR 1476D
Policy No.		Coverage (\$)	0.00
Claim No.	544551 PLY	Excess (\$)	0.00
Assign From	ONG SHU XIANG	Assign Date	22/02/2018

2. Vehicle Particulars & Condition

Make & Model	MAZDA 5	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JM6CW1071F0120961	Colour	GREY
Odometer	79019	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/01/2018	Inspection Date	26/02/2018
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 1476D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	MOULD (LHS),SIDE STEP	CUT	1,055.40	1,055.40
1	MOULD (RHS),SIDE STEP	CUT	1,055.40	1,055.40
2	FASTENER,MOULD	NECESSARY	5.60	5.60
1	REAR BUMPER (ADDITIONAL)	CUT	915.40	915.40
1	LHS REAR DOOR (ADDITIONAL)	DENTED	1,364.50	1,364.50
2	FASTENER,REAR BUMPER (ADDITIONAL)	NECESSARY	6.00	6.00
4	RIVET,REAR BUMPER (ADDITIONAL)	NECESSARY	21.60	21.60
1	GROMMET,REAR BUMPER (ADDITIONAL)	NECESSARY	2.80	2.80
4	GROMMET,REAR BUMPER (ADDITIONAL)	NECESSARY	10.00	10.00
2	GROMMET,REAR BUMPER (ADDITIONAL)	NECESSARY	8.80	8.80
2	FASTENER,REAR DOOR (ADDITIONAL)	NECESSARY	9.80	9.80
1	FASTENER,REAR DOOR (ADDITIONAL)	NECESSARY	3.40	3.40
1	GROMMET,REAR DOOR (ADDITIONAL)	NECESSARY	8.90	8.90
1	GROMMET,REAR DOOR (ADDITIONAL)	NECESSARY	10.00	10.00
2	GROMMET,REAR DOOR (ADDITIONAL)	NECESSARY	6.60	6.60
3	GROMMET,REAR DOOR (ADDITIONAL)	NECESSARY	8.10	8.10
6	GROMMET,REAR DOOR (ADDITIONAL)	NECESSARY	16.80	16.80
1	FASTENER,REAR DOOR (ADDITIONAL)	NECESSARY	3.00	3.00
1	TAPE PROTECTOR,REAR DOOR (ADDITIONAL)	NECESSARY	2.50	2.50
1	TAPE PROTECTOR,REAR DOOR (ADDITIONAL)	NECESSARY	2.50	2.50
1	TAPE PROTECTOR,REAR DOOR (ADDITIONAL)	NECESSARY	3.30	3.30
2	TAPE SEAL,REAR DOOR (ADDITIONAL)	NECESSARY	5.40	5.40
1	STRIPE SIDE (LHS),REAR DOOR (ADDITIONAL)	NECESSARY	29.10	29.10
1	STRIPE UPPER (LHS),REAR DOOR (ADDITIONAL)	NECESSARY	33.40	33.40
1	VALVE ONEWAY,REAR DOOR (ADDITIONAL)	NECESSARY	4.30	4.30
	LESS 10% DISCOUNT		-459.26	-459.26
			4,133.34	4,133.34
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			100.00	20.00
<u>LABOUR</u>				
	TO REPLACE LHS AND RHS SIDE STEP MOULD.TO REPAIR LHS REAR FENDER AND ALL AREAS AFFECTED BY THE ACCIDENT.		2,640.00	1,980.00

Report Ref No. CS/MSG18003607/Gqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY LHS REAR DOOR.LHS REAR FENDER,REAR BUMPER.LHS SIDE STEP MOULD,RHS SIDE STEP MOULD,RHS FRONT DOOR AND RHS REAR DOOR.		5,040.00	5,040.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	250.00	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	120.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	150.00
	TO TRANSFER THE DOOR MECHANISM (ADDITIONAL).		315.00	315.00
	TO TRANSFER THE DOOR MECHANISM (ADDITIONAL).	REPEATED	315.00	-
	TO TRANSFER REVERSE SENSORS (ADDITIONAL).		315.00	315.00
			9,475.00	7,920.00
	GRAND TOTAL		13,708.34	12,073.34
RECOMMENDED COST OF REPAIRS				12,073.34

Report Ref No. CS/MSG18003607/Gqbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.