

ESTIMATED COST OF REPAIRS

ATTN :	MOTOR CLAIMS	TEL :				
FAX :						
VEH NO :	SFM3636G	DATE IN :		CONTACT PERSON :	RICK	63602445
CHASSIS NO :	WP0ZZZ99ZFS111067	MILEAGE :		TYPE OF CLAIM :	TP AGAINST SHC8122T	
MODEL :	911 Carrera S	DATE REG.:	12-05-15	POLICY NO. :		

NATURE OF WORKS

[illegible]

Labour Description

1	TO REMOVE / REPLACE DAMAGED REAR BUMPER, 1560/day LH REAR FENDER & OTHER AFFECTED BODY PARTS, INCLUDING PANEL BEAT / STRAIGHTEN BODY PANELS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE.		\$ 10,920.00 6240
2	TO SPRAY PAINT REAR BUMPER, LH REAR FENDER, LH Bumper 1300 ROCKER PANEL. Fender 1100		\$ 3,800.00 2400
3	TO CARRY OUT BODY CAVITY PRESERVATION TO ALL AFFECTED AREAS.		\$ 400.00 200

4	TO APPLY THEROSTAT SEALANT TO AFFECTED AREAS		×	\$ 400.00	
5	TO REMOVE / REFIT SEATS, CARPETS, TRIM BOARDS, PILLAR TRIMSTO FACILITATE THE REPAIR.		×	\$ 3,120.00	
6	TO REMOVE / REPLACE REAR WINDSCREEN, NETT QUARTER GLASS TO FACILITATE REPAIRS		×	\$ 480.00	
7	TO SUPPLY WINDSCREEN SEALANT NETT		×	\$ 160.00	
8	TO SUPPLY /INSTALL SUN SHIELD TO WINDSCREEN. NETT		×	\$ 300.00	
9	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT ACCORDING TO SPECIFICATIONS. NETT			\$ 680.00	✓
10	TO REMOVE REPLACE REFIT TYRES & RIMS @ \$60/-			\$ 60.00	✓
11	TO SUPPLY 1 PCS TYRE \$980.00 ea		×	\$ 980.00	
12	TO SUPPLY PROTECTIVE FILM ON ROCKER PANEL. NEC.	✓		TBA	
13	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR. NETT			\$ 600.00	✓
14	TOWING CHARGES	TBA		\$ 300.00	✓
15	SUNDRIES.			\$ 100.00	
				50	
		TOTAL LABOUR		\$ 22,300.00	
		TOTAL PARTS		\$ 11,830.77	
		GRAND TOTAL		\$ 34,130.77	

Please note that this is **only an estimate**, base on our visual inspection. However should there be any additional work be found necessary in the course of repair and thus additional parts, materials and labor cost will be deem necessary, you will be inform accordingly prior to any action taken. In view of this, expected delays will be indivertible and therefore additional working days will be required. As such the loss of use and other incidentals will be adjusted accordingly.

Prepared By

Acknowledge By

Sebastian.
26/2/18.
- Part by part repair.
- Question mark Item Photo
- Photo Before Paint
90036121
sebastianyeang@lkkauto.com.

7 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: