

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ernest Tay

Date: 27 Feb 2018

Preliminary Advice

Insured Vehicle No	: SHD244Y		
TP Vehicle No	: SHD6776P	Accident Date	: 21/02/2018
Make	: HYUNDAI I40	Assignment Date	: 26/02/2018
Date of Inspection	: 26/02/2018	Est. Duration of Repair	: 2/Days
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...Rear N/S.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,661.58
Revised Amount	:S\$	1,310.48
Check Items (Estimated)	:S\$	845.40
Total	:S\$	2,155.88

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :We have not authorized repairs.