



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 17/7/2018

Survey Details:

Date of loss	23-Feb-18
Date of appointment	23-Feb-18
Date of survey	26-Feb-18
Location of survey	RYDER AUTO PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SDU 1818T
Make and Model	PORSCHE PANAMERA 3605cc
Date of registration	May-16
Excess	
Market Value	\$ -
Parf Rebate	\$ -
Nett Loss	\$ -

Repair details:

Initial Estimate	\$ 10,249.93
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ -
Check items (estimate)	\$0
Labour	\$ 5,920.00
Total	\$ 5,920.00
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>5 days</u>
---------------------------	---------------



Remarks:

We had spoken to OI Mdm Ng and she confirmed accident details and agreed to settle TP claim at best and is aware of NCD issues on 07/03/2018. A letter was sent out to Insured. BOLA 22 - OID collided to a stationary TP. Furthermore, TP repairer had forwarded a supplementary for the repair as uploaded in smartclaims. TP claiming for LOU @ \$180/7 days (including weekends).

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 6,334.40	w/gst
Loss of use	\$ 1,260.00	\$180 X 7 days
Loss of rental	\$ -	No. of days
Loss of income	\$ -	No. of days
GIA/LTA search fees	\$ 7.49	TBC
Others	\$ -	
Proposed Total	\$ 7,601.89	